S/N: WAM76322V00F02845 - FT720G6RC
2022 Fendt (DC) Tractor High Range

PRAIRIE FARMS PARTNERSHIP
No: 0679710 (A) City: HASTINGS

SMU: 902H(Journal) on Oct 08, 2026
Stock No.: EQ0020830 Unit #:

: 6 : 0 : 0
Service Letters:0 Score: 0

Segment View | ice View

Total Work Orders:	13		**Total Labor Hours:**	87.9	**Total Amount:**
Total Parts:	130.60	**Total Labor:** 4,736.03	**Total Misc:**	306.16	**Total Flat Rate Amount:** 19,916.87

Seg No.	Hours	A/I	Job	Component	Pt Cust.	Lbr Cust.	Misc Cust.	Seg Total	Notes
WO No SC00933715 (ACTI: I) (Dec 18, 2025) - PRAIRIE FARMS PARTNERSHIP (0679710) SMU: 903H Jan 13, 2026									
002	10.75	C	035 - Troubleshoot	0599 - Service Tools/Equip Codes	I000104	I000104	I000104	2,711	Customer complaint: a error code that the gateway controller was not communicating would come up when you turned the key on. there was no feature file on the dashboard. Resultant damage: when the gateway controller was installed the hour meter went back to 0. started a case with technical and they started one with agco. case #6537821 Cause of failure: The gateway controller crashed as we were trying to update the tractor. Repair process comments: removed the side console and accessed the gateway controller. checked the wiring of the controller. looked for pinched or cut wires. removed and replaced the gateway controller. hooked up the computer that i got from technical and programmed the tractor. operated the tractor and made sure everything worked. the tractor is set back to zero hours.
								Total: $2,711.34	
WO No SC00883675 (ACTI: I) (Sep 11, 2025) - PRAIRIE FARMS PARTNERSHIP (0679710) SMU: 902H Dec 18, 2025									
001	8.75	C	041 - Perform Maintenance On	7526 - 1000 Service Hour Maintenance	I000104	I000104	I000104	2,538	Customer complaint: Perform 1000 hour service on tractor. Resultant damage: . Cause of failure: . Repair process comments: did a dpf regeneration. Changed fuel filters. changed engine oil and filter. changed primary air filter. changed front differential oil. changed front final drive oils. changed cab filters. inspected and greased tractor. changed transmission oil filter. filled out inspection on tech connect.
002	2	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	377	
003	0	C	557 - Order Parts	0645 - Grease/Oils/Lube/Fluids	I001007	I001007	I001007	274	
								Total: $3,189.53	
WO No SC00641145 (ACTI: I) (Jun 20, 2024) - PRAIRIE FARMS PARTNERSHIP (0679710) SMU: 540H Jun 21, 2024									
001	1.5	C	056 - Travel To/From	7000 - Machine				499	Travel costs to Flash new software into monitor.
002	2.5	C	023 - Repair	1901 - Electronic Control Module	I000104	I000104	I000104	448	Customer complaint: Customer need tractor to be up to date with software for issues with the third party controller. Resultant damage: . Cause of failure: . Repair process comments: Downloaded the latest software to my computer for tech connect. hooked up to the machine and updated the software. did a power shutdown on the machine and made sure that everything worked.
								Total: $947.12	
WO No SC00472908 (ACTI: I) (Sep 06, 2023) - PRAIRIE FARMS PARTNERSHIP (0679710) SMU: 363H Sep 19, 2023									
001	3	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	1000	
002	2.5	C	023 - Repair	9073 - Couplers W A Snap Ring	I000104	I000104	I000104	618	Customer complaint: The oil overflow bottle of the remote couplers was filling with oil without unplugging couplers. Resultant damage: Unhooked all couplers. removed covers from the couplers. installed a jumper hose into all couplers and checked for leakage. Cause of failure: The red - coupler was leaking externally. Repair process comments: removed coupler from the port. inspected coupler. replaced coupler with new one. installed jumper hose and checked for leakage. installed caps on all ports.
003	4	C	510 - Replace	6129 - Quick Coupler	I000104	I000104	I000104	741	Customer complaint: The yellow positive cover was missing a screw and would fall off of the valve. Resultant damage: Dirt filled the coupler and plugged the drain ports. Cause of failure: The screw unscrewed from the housing and fell off. Repair process comments: Removed cover and inspected. removed the outer valve from the tractor and cleaned dirt from the drain ports. removed the cross tubes between the valves and cleaned. reinstalled the valve onto the tractor and installed a new cover. ran tractor and checked for leaks.
								Total: $2,358.97	
WO No SC00471266 (ACTI: I) (Aug 31, 2023) - PRAIRIE FARMS PARTNERSHIP (0679710) SMU: 359H Sep 08, 2023									
001	7	C	041 - Perform Maintenance On	7525 - 500 Service Hour Maintenance	I000104	I000104	I000104	2,086	Customer complaint: Do a 500 hour service Resultant damage: . Cause of failure: . Repair process comments: Started tractor up and warmed it up. did a parked regeneration. took a engine oil, left and right rear axle oil samples. drained rear axle oils and filled back up. drained and changed engine oil a nd filter. changed the cab air filters. changed the def filter. checked all fluids. greased the tractor. blew out the air filter. filled the hydraulic oil reservoir. filled

									the coolant reservoir and pressure tested the system looking for leaks. filled out inspection sheet and turned in oil samples.
002	3	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	977	
003	0	C	557 - Order Parts	9824 - *USE CODE 7567*	I001007	I001007	I001007	427	
								Total: $3,489.80	

WO No SC00431605 (ACTI: I) (Jun 22, 2023) - PRAIRIE FARMS PARTNERSHIP (0679710) SMU: 281H Jun 28, 2023

001	2	C	056 - Travel To/From	7000 - Machine	I002845	I002845	I002845	560	
002	0.5	C	012 - Install	1395 - Engine Coolant	I002845	I002845	I002845	116	Customer complaint: The customer complained of a error code for low coolant. Resultant damage: . Cause of failure: The customer was operating the tractor in a hilly area on a side slope. The coolant was at or just below the add mark. Repair process comments: Raised hood to the machine. inspected the coolant reservoir and topped off. removed the side shields and inspected for leaks. couldn't find any leaks. advised the customer to keep a eye on the coolant level and let me know if it went back down.
								Total: $676.26	

WO No SC00427151 (ACTI: I) (Jun 15, 2023) - ZRS RNTL HEAVY AGRI REPAIR & MAINT (I001723) SMU: 244H Jun 21, 2023

001	2.97	C	012 - Install	7620 - Software				475	Customer complaint: -Customer wanted Variable rate control and Spread control monitoring unlocked Resultant damage: -NA Cause of failure: -NA Repair process comments: -Verified the unlocks were purchased -Went to the main menu to verify the unlocks were successful -The options were not present -Updated the firmware and software in the tractor -After the lengthy update, the options were now available and functioning -Cleaned up tools and equipment -Filled out report
002	1.86	C	025 - Adjust	4300 - Steering System				297	Customer complaint: -Turning radius was not tight enough Resultant damage: -NA Cause of failure: -Steering stops were not opened up completely Repair process comments: -Loosened the steering stops -Turned the wheel to the left and held it there while adjusting stops to their max without rubbing -Repeated for the right -Test drove the tractor and verified proper operation -Cleaned up tools and equipment -Filled out report
								Total: $772.25	

WO No SC00394103 (ACTI: I) (Apr 26, 2023) - ZRS RNTL HEAVY AGRI REPAIR & MAINT (I001723) SMU: 125H Apr 27, 2023

001	10.38	C	551 - Move	0730 - Wheels & Tires				1,675	Customer complaint: Tractor needs to be set for 30 inch rows Resultant damage: None Cause of failure: None Repair process comments: Removed front wheels Switched the inner dish tightened the dish torqued the dish bolts to spec Reinstalled front wheels Rear inner wheels all ready set to 30 inch rows Outer rear duels had to switch inner dish Tightened and torqued dish bolts to spec installed and set rear duels to 30 inch row spacings adjusted front wheel stops so tires wouldn't rub check to make sure nothing rubbed when articulated
								Total: $1,675.12	

WO No SC00325580 (ACTI: I) (Dec 08, 2022) - ZRS RNTL HEAVY AGRI REPAIR & MAINT (I001723) SMU: 109H Dec 08, 2022

001	2.44	C	115 - Prepare	9830 - Rental Delivery				377	Customer complaint: set up for rental Resultant damage: none Cause of failure: none Repair process comments: I was told to make sure the tractor had a 540 PTO, remove the clevis and rear duels so I brought it inside and removed the duels every thing else was the way it was supposed to be. Lug nuts and spacers are in the toolbox.
								Total: $377.37	

WO No SC00284232 (ACTI: I) (Sep 29, 2022) - ZRS RNTL HEAVY AGRI REPAIR & MAINT (I001723) SMU: 61H Oct 14, 2022

001	7.75	C	041 - Perform Maintenance On	9532 - Initial 50 Hr Service				1,251	Customer complaint: Needs intial 50HR service. Resultant damage: none Cause of failure: none Repair process comments: Performed Maintenance(intial 50HR service) and checked all fluid levels following checklist on tech connect.
								Total: $1,251.37	

WO No SC00277702 (ACTI: I) (Sep 21, 2022) - MACHINE INVENTORY ADD TO BV - AGRI (I002845) SMU: 18H Sep 20, 2022

001	2	C	540 - Perform	7520 - 10 SMU Maintenance				358	
002	2	C	070 - Clean	7000 - Machine				309	
								Total: $667.60	

WO No SC00273161 (ACTI: I) (Sep 14, 2022) - MACHINE INVENTORY ADD TO BV - AGRI (I002845) SMU: 7H Sep 14, 2022

001	1	C	035 - Troubleshoot	7431 - Warning/Indicator Light				155	Customer complaint: code for the EGR actuator Resultant damage: code

						Cause of failure: wire harness on the actuator Repair process comments: I hooked into the engine and found that the actuator was not closing properly. I looked at the EGR and found the problem
002	1	C	023 - Repair	7431 - Warning/Indicator Light	155	Customer complaint: I hooked into the engine and found that the actuator was not closing properly. I looked at the EGR and found the problem Resultant damage: none Cause of failure: wire harness Repair process comments: moved the wiring harness off of the EGR actuator so that it could move all the way. I ran the EGR actuator several times it looks to be ok. the code cleared and drove for 30 min.
					Total: $309.32	

– WO No SC00267368 (ACTI: I) (Sep 01, 2022) - MACHINE INVENTORY ADD TO BV - AGRI (I002845) SMU: 3H Sep 01, 2022

001	8	C	041 - Perform Maintenance On	7588 - Pre-Delivery Inspection	1,312	
002	1	C	012 - Install	0653 - Decals	179	
					Total: $1,490.82	

S/N: WAM76322V00F02845 - FT720G6RC
2022 Fendt (DC) Tractor High Range

PRAIRIE FARMS PARTNERSHIP
No: 0679710 (A) City: HASTINGS

SMU: 902H(Journal) on Oct 08, 2026
Stock No.: EQ0020830 Unit #:

▲: 6 ((•)): 0 ☑: 0
Service Letters:0 Score: 0

Segment View | ice View

Total Work Orders:	13		**Total Labor Hours:**	87.9	**Total Amount:**
Total Parts:	130.60	**Total Labor:** 4,736.03	**Total Misc:**	306.16	**Total Flat Rate Amount:** 19,916.87

Seg No.	Hours	A/I	Job	Component	Pt Cust.	Lbr Cust.	Misc Cust.	Seg Total	Notes
WO No SC00933715 (ACTI: I) (Dec 18, 2025) - PRAIRIE FARMS PARTNERSHIP (0679710) SMU: 903H Jan 13, 2026									
002	10.75	C	035 - Troubleshoot	0599 - Service Tools/Equip Codes	I000104	I000104	I000104	2,711	Customer complaint: a error code that the gateway controller was not communicating would come up when you turned the key on. there was no feature file on the dashboard. Resultant damage: when the gateway controller was installed the hour meter went back to 0. started a case with technical and they started one with agco. case #6537821 Cause of failure: The gateway controller crashed as we were trying to update the tractor. Repair process comments: removed the side console and accessed the gateway controller. checked the wiring of the controller. looked for pinched or cut wires. removed and replaced the gateway controller. hooked up the computer that i got from technical and programmed the tractor. operated the tractor and made sure everything worked. the tractor is set back to zero hours.
								Total: $2,711.34	
WO No SC00883675 (ACTI: I) (Sep 11, 2025) - PRAIRIE FARMS PARTNERSHIP (0679710) SMU: 902H Dec 18, 2025									
001	8.75	C	041 - Perform Maintenance On	7526 - 1000 Service Hour Maintenance	I000104	I000104	I000104	2,538	Customer complaint: Perform 1000 hour service on tractor. Resultant damage: . Cause of failure: . Repair process comments: did a dpf regeneration. Changed fuel filters. changed engine oil and filter. changed primary air filter. changed front differential oil. changed front final drive oils. changed cab filters. inspected and greased tractor. changed transmission oil filter. filled out inspection on tech connect.
002	2	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	377	
003	0	C	557 - Order Parts	0645 - Grease/Oils/Lube/Fluids	I001007	I001007	I001007	274	
								Total: $3,189.53	
WO No SC00641145 (ACTI: I) (Jun 20, 2024) - PRAIRIE FARMS PARTNERSHIP (0679710) SMU: 540H Jun 21, 2024									
001	1.5	C	056 - Travel To/From	7000 - Machine				499	Travel costs to Flash new software into monitor.
002	2.5	C	023 - Repair	1901 - Electronic Control Module	I000104	I000104	I000104	448	Customer complaint: Customer need tractor to be up to date with software for issues with the third party controller. Resultant damage: . Cause of failure: . Repair process comments: Downloaded the latest software to my computer for tech connect. hooked up to the machine and updated the software. did a power shutdown on the machine and made sure that everything worked.
								Total: $947.12	
WO No SC00472908 (ACTI: I) (Sep 06, 2023) - PRAIRIE FARMS PARTNERSHIP (0679710) SMU: 363H Sep 19, 2023									
001	3	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	1000	
002	2.5	C	023 - Repair	9073 - Couplers W A Snap Ring	I000104	I000104	I000104	618	Customer complaint: The oil overflow bottle of the remote couplers was filling with oil without unplugging couplers. Resultant damage: Unhooked all couplers. removed covers from the couplers. installed a jumper hose into all couplers and checked for leakage. Cause of failure: The red - coupler was leaking externally. Repair process comments: removed coupler from the port. inspected coupler. replaced coupler with new one. installed jumper hose and checked for leakage. installed caps on all ports.
003	4	C	510 - Replace	6129 - Quick Coupler	I000104	I000104	I000104	741	Customer complaint: The yellow positive cover was missing a screw and would fall off of the valve. Resultant damage: Dirt filled the coupler and plugged the drain ports. Cause of failure: The screw unscrewed from the housing and fell off. Repair process comments: Removed cover and inspected. removed the outer valve from the tractor and cleaned dirt from the drain ports. removed the cross tubes between the valves and cleaned. reinstalled the valve onto the tractor and installed a new cover. ran tractor and checked for leaks.
								Total: $2,358.97	
WO No SC00471266 (ACTI: I) (Aug 31, 2023) - PRAIRIE FARMS PARTNERSHIP (0679710) SMU: 359H Sep 08, 2023									
001	7	C	041 - Perform Maintenance On	7525 - 500 Service Hour Maintenance	I000104	I000104	I000104	2,086	Customer complaint: Do a 500 hour service Resultant damage: . Cause of failure: . Repair process comments: Started tractor up and warmed it up. did a parked regeneration. took a engine oil, left and right rear axle oil samples. drained rear axle oils and filled back up. drained and changed engine oil a nd filter. changed the cab air filters. changed the def filter. checked all fluids. greased the tractor. blew out the air filter. filled the hydraulic oil reservoir. filled

									the coolant reservoir and pressure tested the system looking for leaks. filled out inspection sheet and turned in oil samples.
002	3	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	977	
003	0	C	557 - Order Parts	9824 - *USE CODE 7567*	I001007	I001007	I001007	427	
								Total: $3,489.80	

WO No SC00431605 (ACTI: I) (Jun 22, 2023) - PRAIRIE FARMS PARTNERSHIP (0679710) SMU: 281H Jun 28, 2023

001	2	C	056 - Travel To/From	7000 - Machine	I002845	I002845	I002845	560	
002	0.5	C	012 - Install	1395 - Engine Coolant	I002845	I002845	I002845	116	Customer complaint: The customer complained of a error code for low coolant. Resultant damage: . Cause of failure: The customer was operating the tractor in a hilly area on a side slope. The coolant was at or just below the add mark. Repair process comments: Raised hood to the machine. inspected the coolant reservoir and topped off. removed the side shields and inspected for leaks. couldn't find any leaks. advised the customer to keep a eye on the coolant level and let me know if it went back down.
								Total: $676.26	

WO No SC00427151 (ACTI: I) (Jun 15, 2023) - ZRS RNTL HEAVY AGRI REPAIR & MAINT (I001723) SMU: 244H Jun 21, 2023

001	2.97	C	012 - Install	7620 - Software				475	Customer complaint: -Customer wanted Variable rate control and Spread control monitoring unlocked Resultant damage: -NA Cause of failure: -NA Repair process comments: -Verified the unlocks were purchased -Went to the main menu to verify the unlocks were successful -The options were not present -Updated the firmware and software in the tractor -After the lengthy update, the options were now available and functioning -Cleaned up tools and equipment -Filled out report
002	1.86	C	025 - Adjust	4300 - Steering System				297	Customer complaint: -Turning radius was not tight enough Resultant damage: -NA Cause of failure: -Steering stops were not opened up completely Repair process comments: -Loosened the steering stops -Turned the wheel to the left and held it there while adjusting stops to their max without rubbing -Repeated for the right -Test drove the tractor and verified proper operation -Cleaned up tools and equipment -Filled out report
								Total: $772.25	

WO No SC00394103 (ACTI: I) (Apr 26, 2023) - ZRS RNTL HEAVY AGRI REPAIR & MAINT (I001723) SMU: 125H Apr 27, 2023

001	10.38	C	551 - Move	0730 - Wheels & Tires				1,675	Customer complaint: Tractor needs to be set for 30 inch rows Resultant damage: None Cause of failure: None Repair process comments: Removed front wheels Switched the inner dish tightened the dish torqued the dish bolts to spec Reinstalled front wheels Rear inner wheels all ready set to 30 inch rows Outer rear duels had to switch inner dish Tightened and torqued dish bolts to spec installed and set rear duels to 30 inch row spacings adjusted front wheel stops so tires wouldn't rub check to make sure nothing rubbed when articulated
								Total: $1,675.12	

WO No SC00325580 (ACTI: I) (Dec 08, 2022) - ZRS RNTL HEAVY AGRI REPAIR & MAINT (I001723) SMU: 109H Dec 08, 2022

001	2.44	C	115 - Prepare	9830 - Rental Delivery				377	Customer complaint: set up for rental Resultant damage: none Cause of failure: none Repair process comments: I was told to make sure the tractor had a 540 PTO, remove the clevis and rear duels so I brought it inside and removed the duels every thing else was the way it was supposed to be. Lug nuts and spacers are in the toolbox.
								Total: $377.37	

WO No SC00284232 (ACTI: I) (Sep 29, 2022) - ZRS RNTL HEAVY AGRI REPAIR & MAINT (I001723) SMU: 61H Oct 14, 2022

001	7.75	C	041 - Perform Maintenance On	9532 - Initial 50 Hr Service				1,251	Customer complaint: Needs intial 50HR service. Resultant damage: none Cause of failure: none Repair process comments: Performed Maintenance(intial 50HR service) and checked all fluid levels following checklist on tech connect.
								Total: $1,251.37	

WO No SC00277702 (ACTI: I) (Sep 21, 2022) - MACHINE INVENTORY ADD TO BV - AGRI (I002845) SMU: 18H Sep 20, 2022

001	2	C	540 - Perform	7520 - 10 SMU Maintenance				358	
002	2	C	070 - Clean	7000 - Machine				309	
								Total: $667.60	

WO No SC00273161 (ACTI: I) (Sep 14, 2022) - MACHINE INVENTORY ADD TO BV - AGRI (I002845) SMU: 7H Sep 14, 2022

001	1	C	035 - Troubleshoot	7431 - Warning/Indicator Light				155	Customer complaint: code for the EGR actuator Resultant damage: code

						Cause of failure: wire harness on the actuator Repair process comments: I hooked into the engine and found that the actuator was not closing properly. I looked at the EGR and found the problem
002	1	C	023 - Repair	7431 - Warning/Indicator Light	155	Customer complaint: I hooked into the engine and found that the actuator was not closing properly. I looked at the EGR and found the problem Resultant damage: none Cause of failure: wire harness Repair process comments: moved the wiring harness off of the EGR actuator so that it could move all the way. I ran the EGR actuator several times it looks to be ok. the code cleared and drove for 30 min.
					Total: $309.32	

– WO No SC00267368 (ACTI: I) (Sep 01, 2022) - MACHINE INVENTORY ADD TO BV - AGRI (I002845) SMU: 3H Sep 01, 2022

001	8	C	041 - Perform Maintenance On	7588 - Pre-Delivery Inspection	1,312	
002	1	C	012 - Install	0653 - Decals	179	
					Total: $1,490.82	