S/N: AGCF1151HNNNG1101 - FT1151
2022 Fendt (DC) Tractor Tracked Tillage

BESKAU TRANSPORT LLC
No: C010193 (A) City: HASTINGS

SMU: 2,918H(Journal) on Oct 08. 2026
Stock No.: EQ0009372 Unit #:

: 9 : 0 : 3
Service Letters:5 Score: 3075

Segment View | **Invoice View**

Total Work Orders:	38			**Total Labor Hours:**	403.0	**Total Amount:**	
Total Parts:	4,068.96	**Total Labor:**	16,206.74	**Total Misc:**	1,578.58	**Total Flat Rate Amount:**	144,211.37

Seg No.	Hours	A/I	Job	Component	Pt Cust.	Lbr Cust.	Misc Cust.	Seg Total	Notes
– WO No SC00987886 (ACTI: I) (Apr 16, 2026) - BESKAU TRANSPORT LLC (C010193) SMU: 2914H Apr 20, 2026									
001	2	C	056 - Travel To/From	7000 - Machine				578	
002	5	C	035 - Troubleshoot	5050 - Hydraulic System				1,175	Customer complaint: The tractor would nc the planter fertilizer would work correctly Resultant damage: . Cause of failure: The fertilizer tubes were p fertilizer to be dispensed. Repair process comments: Ran tractor and checked out the way that the hydraulics w verified the problem. talked with I & d ab meters around and made sure it wasn't th monitor for the flow meters. all electroni inspected and found that most of the in fur plugged. removed the orifices and flushed installed all the orifices and tried it again. again and flush. once the system was flush worked.
								Total: $1,753.14	
– WO No SC00976650 (ACTI: I) (Mar 25, 2026) - BESKAU TRANSPORT LLC (C010193) SMU: 2914H May 13, 2026									
001	4.25	C	023 - Repair	731S - Seat Air Compressor				1,513	Customer complaint: The seat leaks down and the compressor isn't strong enough to Resultant damage: . Cause of failure: the air compressor was fa Repair process comments: Pumped up the removed the storage tank. the threades v threads. ordered and isntalled a new air t air compressor. the leaks stopped but the build pressure. checked for leaks and orde
002	2.5	C	056 - Travel To/From	7000 - Machine				615	
003	1.5	C	001 - Repair for Warranty	731S - Seat Air Compressor	I001144	I001144	I001144	581	Customer complaint: The seat wouldn't pu seat. Resultant damage: sprayed soapy water a trying to find leaks. Cause of failure: The new compressor was Repair process comments: Removed the se raised postion. removed the air compress compressor. pumped up seat. sprayed wa for leaks. installed seat bottom. sat in th seat worked as it should.
004	1	C	056 - Travel To/From	7000 - Machine	I001144	I001144	I001144	189	
								Total: $2,897.93	
– WO No SC00975929 (ACTI: I) (Mar 23, 2026) - BESKAU TRANSPORT LLC (C010193) SMU: 2892H Mar 26, 2026									
001	2	C	595 - Perform Product Update on	9712 - Bracket	I000107	I000107	I000107	591	Customer complaint: Perform product supp Resultant damage: The air tube clamp wa Cause of failure: The air tube clamp would around. Repair process comments: Raised hood an the air tube clamp and mounting bracket. assembly. adjusted the clamp. installed s
002	2	C	056 - Travel To/From	7000 - Machine	I000107	I000107	I000107	377	
								Total: $968.04	

– WO No SC00933230 (ACTI: I) (Dec 16, 2025) - BESKAU TRANSPORT LLC (C010193) SMU: 2890H Jan 13, 2026

001	6	C	595 - Perform Product Update on	4343 - Steering Control	I000107	I000107	I000107	3,054	Customer complaint: Perform product supp Resultant damage: the clips that hold the flying had to replace some of the clips. Cause of failure: replace steerig motor per Repair process comments: locked out the t wheel. removed the steering column shie dash. removed the steering column and sl unit. replaced the steering motor. install calibrated the steering motor. checked op
002	1	C	595 - Perform Product Update on	4310 - Steering Column	I000107	I000107	I000107	189	Customer complaint: Perform product supp Resultant damage: . Cause of failure: factory requested rework. Repair process comments: Hooked up the up edt and verified the steering position se good.
003	1	C	056 - Travel To/From	7000 - Machine	I000107	I000107	I000107	189	
								Total: $3,431.44	

– WO No SC00893494 (ACTI: I) (Sep 30, 2025) - BESKAU TRANSPORT LLC (C010193) SMU: 2683H Oct 21, 2025

002	3.25	C	023 - Repair	9163 - DEF Filter	I000104	I000104	I000104	983	Customer complaint: Def was leaking out Resultant damage: def was flowing past th Cause of failure: There was def leaking out Repair process comments: hooked up the build up pressure test and inspected for lea disassembled. inspected housing for cracks rubber gaskets. installed module on tract ran tractor and checked for leaks.
								Total: $983.07	

– WO No SC00819113 (ACTI: I) (May 08, 2025) - BESKAU TRANSPORT LLC (C010193) SMU: 2382H May 08, 2025

001	0	C	B30 - Cancelled Segment	7000 - Machine				0	
002	0	C	B30 - Cancelled Segment	9130 - Oil Leak				0	
								Total: $0.00	

– WO No SC00809274 (ACTI: I) (Apr 17, 2025) - BESKAU TRANSPORT LLC (C010193) SMU: 2319H May 01, 2025

002	5.51	C	023 - Repair	4304 - Steering Lines/Hoses	I001144	I001144	I001144	1,415	Customer complaint: There was oil sprayir machine. Resultant damage: The tractor needed to l Cause of failure: The steering line bolts car Repair process comments: removed shield ran tractor and verified were the leak was and installed new orings on the fittings. cl bolt holes. installed lines onto the machin of the clamp bolts. torqued clamp bolts. f tractor. rechecked the torque on the clam
003	1.49	C	014 - Replace Gasket/Reseal	6000 - Implements	I001144	I001144	I001144	324	Customer complaint: Oil was leaking out c Resultant damage: . Cause of failure: The orings weren't sealing Repair process comments: Removed the cc installed new orings on the inside of the cc for leaks.
								Total: $1,739.02	

– WO No SC00761720 (ACTI: I) (Jan 15, 2025) - BESKAU TRANSPORT LLC (C010193) SMU: 2268H Mar 17, 2025

001	6.25	C	041 - Perform Maintenance On	9537 - 2500 Service Hour Maintenance	I000104	I000104	I000104	2,080	Customer complaint: Performed the 2500 Resultant damage: . Cause of failure: . Repair process comments: Inspected the tr filter. changed the fuel filters. changed th oils. changed the front idler wheel oil. fill
002	4.5	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	806	
003	0	C	557 - Order Parts	0645 - Grease/Oils/Lube/Fluids	I001007	I001007	I001007	580	
004	9.75	C	023 - Repair	9130 - Oil Leak	I000104	I000104	I000104	1,848	Customer complaint: There was oil leaking Resultant damage: Washed up the tractor. and checked for leaks. checked leakage fr Cause of failure: The couplers had failed ca from the couplers. the grommet on the fa coupler valve block was not seated correct out of it and all over the back of the tractc Repair process comments: Removed the cc

									cleaned up the area. checked pioneer cou the return line from the couplers and activ return line to see when a larger amount o return line and activated these couplers. f far left coupler where the grommet gets li assembly from the valve stack. installed a assembly. *installed a new seal kit into the and coupler assembly. removed and repla new coupler seals into the couplers that w
005	2.25	C	510 - Replace	7119 - Swinging Drawbar	I000104	I000104	I000104	4,835	Customer complaint: The left drawbar cyli Resultant damage: The rod couldn't be rep epsilon so we ordered a new cylinder. Cause of failure: see agco case number 582 the cylinder. Repair process comments: Removed the st removed the hoses from the cylinders. rei tractor. removed fittings from the cylinde new cylinder. installed the cylinder onto t the cylinder. ran the drawbar back and fo Customer complaint: The left drawbar cyli Resultant damage: The rod couldn't be rep epsilon so we ordered a new cylinder. Cause of failure: see agco case number 582 the cylinder. Repair process comments: Removed the st removed the hoses from the cylinders. rei tractor. removed fittings from the cylinde new cylinder. installed the cylinder onto t the cylinder. ran the drawbar back and fo
006	24.75	C	510 - Replace	4304 - Steering Lines/Hoses	I000104	I000104	I000104	13,511	Customer complaint: The steering lines on Resultant damage: The lines were worn ar needed to be replaced. Agco tech connect Cause of failure: The steering lines had wo where oil could leak past. Repair process comments: drained the trai removed the side shields from the tractor. the pump and inspected. found worn steei technical ticket and got agco involved. dra removed the hoses off of the fan pump an tractor. removed all the lines from the st steering pump from the tractor. swapped new pump and installed the pump. install pump onto the machine. installed the hos pump with oil and bleed the system. insta the pump to the motor. hooked up all hos transmission with oil. started up the tract system. drove tractor and the tractor wo and adjusted track tracking. checked and adjusted the tractor so it would drive strai
007	6	C	010 - Remove & Install	4187 - Reaction Arm	I000104	I000104	I000104	1,075	Customer complaint: There was metal in t the right reaction arm. Resultant damage: . Cause of failure: The locking tab was assen allowed the bearing to spin. Repair process comments: Jacked up the tr removed the tension on the track. remov wheel. removed the outside drive wheel. drive wheel. removed the inside drive wh the hoist up to the reaction arm and remo wedges. removed the mounting bolts on t arm. Sent the arm up to ZRC to be fixed. installed the drive wheels and weights. In removed tractor from the jackstands.
008	7	C	001 - Repair for Warranty	4187 - Reaction Arm	I000104	I000104	I000104	7,619	Customer Complaint: Repair for Warranty Customer found metal in oil. Resultant Damage: 556999D1 - 200 Bearing Cone was cut into tab, sending metal debris throughout the s Due to the need to match bearings, it was 200 Housing (E Bearing). 403389X1 - 200 Dowels were loose and ha holes in 556986D1 - 200 Hub and 556987D Cause of Failure: 557001D2 - 200 Wave Spring was installed tucked underneath the other.

									Repair Process Comments: The left side Reaction Arm was in the ZRC Disassembled the arm and inspected all cc Noticed the outer hub dowel had come off, had spun due to the wave spring being ins All other parts that met the reusability gu During assembly, all new parts were insta All bolts were torqued to Cat specifications The Reaction Arm duo cone seals were air Filled the arm with SAE50 full synthetic oil Final inspection and preparation for paint Warranty Tag: #411272
009	5.25	C	024 - Align	4198 - Track Belt	I000104	I000104	I000104	940	Customer complaint: The tracks were not reaction arm was replaced. Resultant damage: . Cause of failure: the tracks weren't alignec Repair process comments: Drove tractor u temperature of the track guide lugs. rem the tracking bolts accordingly. installed lo repeated the process three times to get tr
010	0	C	023 - Repair	9130 - Oil Leak	I000104	I000104	I000104	0	
								Total: $33,293.45	

– WO No SC00725422 (ACTI: I) (Oct 28, 2024) - BESKAU TRANSPORT LLC (C010193) SMU: 2195H Nov 06, 2024

001	0.5	C	056 - Travel To/From	7000 - Machine				160	travel for going out to replace battery
002	1.75	C	035 - Troubleshoot	1450 - Starting System	I000104	I000104	I000104	493	Customer complaint: The tractor would nc sat for a couple of days. Resultant damage: The battery had to be ate away. Cause of failure: Both batty cables were lo negative terminal was worn away. Repair process comments: verified the con checked the voltages in the batteries. fou voltage. removed the cables and load tes batteries cables were loose. found rear ba amps. tightened the cables and jumped th use the tractor. got a new battery. went that the battery cable had loosened itself cables from the batteries. removed the h removed the rear battery. installed the n cables and clamps. installed the cables ba machine out and it started and charged lik
								Total: $653.07	

– WO No SC00721343 (ACTI: I) (Oct 21, 2024) - BESKAU TRANSPORT LLC (C010193) SMU: 2096H Oct 24, 2024

001	0.5	C	595 - Perform Product Update on	135D - Diverter Valve (Coolant)	I000107	I000107	I000107	91	Customer complaint: Perform service bulle Resultant damage: . Cause of failure: Replace the coolant drain Repair process comments: Raised hood. re handle from the coolant valve. installed n installed shield and closed hood.
002	2.5	C	595 - Perform Product Update on	1316 - Oil Filler Pipe/Cap	I000107	I000107	I000107	1,287	Customer complaint: Perform service bulle Resultant damage: The oil tube needed to hours on the machine. Cause of failure: factory recall. Repair process comments: Open the engin support. Remove the left side engine panel. Install the bracket (2). Cut the cable ties that hold the wiring har one side. Remove the fasteners and then the initial will be installed with the new bracket. Install the ACP0895990 bracket with the ir lbf ft). Install the wiring harness to the bracket a Remove the fasteners from the 2 clamps (Remove the spring clamp, then remove th Install the new hose arch, fill-tube, cap, an (26 lbf ft). Do a check to make sure that the oil level Install the left side engine panel. Remove the support and close the engine
003	1	C	595 - Perform Product Update on	1813 - Radiator Hose	I000107	I000107	I000107	249	Customer complaint: Perform service bulle

									Resultant damage: . Cause of failure: Factory rework on radiat Repair process comments: Raised the hooc installed new guide with bracket. installe adjusted hood guide. shut hood and made
004	3.5	C	056 - Travel To/From	7000 - Machine	I000107	I000107	I000107	1,555	
								Total: $3,181.94	

– WO No SC00718259 (ACTI: I) (Oct 17, 2024) - BESKAU TRANSPORT LLC (C010193) SMU: 2176H Nov 01, 2024

002	7.75	C	023 - Repair	1052 - Turbocharger	I000104	I000104	I000104	5,207	Customer complaint: Customer complaine appeared on display and the machine was Resultant damage: unhooked the turbo an connector. all voltages were good. checke plugged the turbo back in and everything and than the codes came back on. Cause of failure: Hooked up to the tractor 50% and would not move. Repair process comments: Raised the hooc unhooked the batteries. removed the enc engine harness. installed the shields. clea tractor and verified that it operated norm
003	5.25	C	023 - Repair	4306 - Steering Pump	I000104	I000104	I000104	989	Customer complaint: There was oil leaking machine. Resultant damage: removed the side shiel blew all dirt and leaves out of the tractor. was leaking from. ran tractor to find oil le road to heat up the hydraulic oil. inspecte Cause of failure: The oring on the upper ste Repair process comments: Drained the tra steering hoses and installed new orings. r. installed all cover plates and shields.
								Total: $6,196.13	

– WO No SC00708929 (ACTI: I) (Oct 03, 2024) - BESKAU TRANSPORT LLC (C010193) SMU: 2097H Oct 24, 2024

001	23.75	C	041 - Perform Maintenance On	7527 - 2000 Service Hour Maintenance	I000104	I000104	I000104	8,986	Customer complaint: Perform 2000 hour s Resultant damage: . Cause of failure: . Repair process comments: Changed engine changed air filters. changed def filter. cha hydraulic breathers. changed hydraulic oil changed the boogie wheel oil. changed th reaction arm oil. changed the fan hydrauli changed the hydraulic pilot oil filter in the adjusted valves. filled out inspection in te
002	2	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	774	
003	0	C	557 - Order Parts	0645 - Grease/Oils/Lube/Fluids	I001007	I001007	I001007	2,830	
								Total: $12,590.10	

– WO No SC00701938 (ACTI: I) (Sep 24, 2024) - BESKAU TRANSPORT LLC (C010193) SMU: 1905H Oct 03, 2024

001	1.25	C	056 - Travel To/From	7000 - Machine				169	travel for going out to repair the air filter
002	2	C	035 - Troubleshoot	7452 - Air Filter Indicator	I000104	I000104	I000104	478	Customer complaint: Customer complaine but the alarm never went off. Resultant damage: opened up the hood. d measured for voltage and ground at the s made sure that the passage way was clea inspected. Cause of failure: The filter plugged switch pressure differential. Repair process comments: removed senso system.
003	1	C	035 - Troubleshoot	4338 - Adjustable Steering Col.	I000104	I000104	I000104	179	Customer complaint: Customer complaine adjust all the time. Resultant damage: Removed the steering the adjuster pedal and watched cable mov Cause of failure: The cable wasn't adjusted release lever. Repair process comments: Adjusted cable s release lever. installed all steering colum
								Total: $826.26	

– WO No SC00642876 (ACTI: I) (Jun 24, 2024) - BESKAU TRANSPORT LLC (C010193) SMU: 1809H Jul 05, 2024

002	8.75	C	510 - Replace	7308 - Cab Door	I000104	I000104	I000104	2,243	Customer complaint: The cab door wouldn Resultant damage: .

									Cause of failure: The door was warped mo Repair process comments: took pictures of started a Ziegler case and got dimensions. removed door from hinges and took to the handle, and door hinges to the new door. latch.,
								Total: $2,242.80	
– WO No SC00637522 (ACTI: I) (Jun 13, 2024) - BESKAU TRANSPORT LLC (C010193) SMU: 1795H Jun 21, 2024									
001	1.75	C	056 - Travel To/From	7000 - Machine				278	Travel costs to repair fuel tank cap.
002	0.75	C	510 - Replace	1273 - Fuel Tank	I000104	I000104	I000104	227	Customer complaint: customer couldn't al Resultant damage: . Cause of failure: The ratchet in the cap wa cap would spin free of the threads. Repair process comments: Removed the c threaded insert. installed new cap and te
								Total: $504.80	
– WO No SC00614786 (ACTI: I) (May 08, 2024) - BESKAU TRANSPORT LLC (C010193) SMU: 1661H May 07, 2024									
001	0	C	056 - Travel To/From	7000 - Machine				0	
002	0	C	023 - Repair	7308 - Cab Door				0	
003	0	C	023 - Repair	1429 - Light(S)				0	
								Total: $0.00	
– WO No SC00613490 (ACTI: I) (May 06, 2024) - BESKAU TRANSPORT LLC (C010193) SMU: 1795H May 31, 2024									
001	0.75	C	595 - Perform Product Update on	1087 - Air Inlet	I000107	I000107	I000107	202	eaned out the fittings. installed new air t tractor and checked for air leaks. installec perform product support #23818 Resultant damage: . Cause of failure: factory recall. Repair process comments: remove side scr air intake tube. cl
002	1.5	C	056 - Travel To/From	7000 - Machine	I000107	I000107	I000107	450	
								Total: $651.30	
– WO No SC00545745 (ACTI: I) (Jan 05, 2024) - BESKAU TRANSPORT LLC (C010193) SMU: 1549H Feb 20, 2024									
002	1	C	510 - Replace	7251 - Hood	I000104	I000104	I000104	359	Customer complaint: the hood would not fall shut. Resultant damage: . Cause of failure: The shocks were weak an Repair process comments: Raised hood. h it all the way open. removed shocks from tested hood operation.
003	0.5	C	023 - Repair	7119 - Swinging Drawbar	I000104	I000104	I000104	170	Customer complaint: The stop was missin drawbar. Resultant damage: . Cause of failure: the rubber delaminated fr Repair process comments: Removed hard removed the rubber stop from the drawb installed hard stop.
								Total: $529.06	
– WO No SC00538960 (ACTI: I) (Dec 19, 2023) - BESKAU TRANSPORT LLC (C010193) SMU: 1548H Jan 05, 2024									
002	4	C	023 - Repair	105A - Primary Air Filter	I000104	I000104	I000104	1,497	Customer complaint: the air filter was get Resultant damage: The air filter was plugg Cause of failure: The air cleaner assembly Repair process comments: raised the hood sprayed water on the air cleaner housing the sensor from the air cleaner. removed and replaced. reinstalled all parts. ran m
003	3	C	023 - Repair	9150 - Hydraulic Leak	I000104	I000104	I000104	761	Customer complaint: The eco drain bottle time. Resultant damage: . Cause of failure: one of the couplers was b Repair process comments: removed plasti couplers. installed hose into couplers and valves and heated oil. inspected couplers were oil was coming out of the base of the coupler. installed plastic covers on to the for leaks.

004	0.5	C	023 - Repair	9260 - Fuel Filter	I000104	I000104	I000104	171	Customer complaint: The water in fuel coc Resultant damage: . Cause of failure: The sensor shorted out ca Repair process comments: Drained fuel ou electrical connector. removed the sensor. sensor. filled fuel filter with fuel. ran trac code cleared.
005	1.5	C	023 - Repair	7308 - Cab Door	I000104	I000104	I000104	251	Customer complaint: The door would vibra there was a whistle around the door. Resultant damage: The hinge hardware w. adjusted properly. Cause of failure: The hardware on the door Repair process comments: Removed the c tightened hardware. Tightened the hardw rear of the door. tried to shut the door an properly. adjusted the striker on the door sure it latched.
								Total: $2,680.32	

– WO No SC00522038 (ACTI: I) (Nov 17, 2023) - BESKAU TRANSPORT LLC (C010193) SMU: 1543H Dec 22, 2023

001	6.75	C	041 - Perform Maintenance On	7538 - 1500 Service Hour Maintenance	I000104	I000104	I000104	2,893	Customer complaint: Perform 1500 hour s Resultant damage: . Cause of failure: . Repair process comments: Started up the took oil samples of the engine oil and cool engine oil and filter. drained and changed fuel filters. changed the reaction arm oils. other fluids.
002	4	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	1,156	
003	0	C	557 - Order Parts	7579 - Fluid	I001007	I001007	I001007	787	
								Total: $4,836.59	

– WO No SC00506038 (ACTI: I) (Oct 23, 2023) - BESKAU TRUCKING1 (C010193) SMU: 1543H Dec 22, 2023

001	2.5	C	056 - Travel To/From	7000 - Machine	I000107	I000107	I000107	905	
002	1	C	595 - Perform Product Update on	9010 - Tractor Accelerator Pedal	I000107	I000107	I000107	359	Customer complaint: complete product su Resultant damage: . Cause of failure: Factory recall Repair process comments: Removed shielc replaced foot pedal. went into the console checked operation of the foot pedal.
								Total: $1,263.90	

– WO No SC00487113 (ACTI: I) (Sep 26, 2023) - BESKAU TRUCKING1 (C010193) SMU: 1229H Oct 19, 2023

001	0.5	C	056 - Travel To/From	7000 - Machine				142	
002	1	C	023 - Repair	108J - Diesel Exhaust Fluid Pump	I000104	I000104	I000104	168	Customer complaint: The def pump would the key switch was shut off. Resultant damage: . Cause of failure: updated software and che Repair process comments: Updated softwa harnesses. def pump may run and circulat nozzle.
								Total: $309.19	

– WO No SC00471824 (ACTI: I) (Aug 31, 2023) - BESKAU TRUCKING1 (C010193) SMU: 1085H Sep 08, 2023

001	2.5	C	056 - Travel To/From	7000 - Machine	I000107	I000107	I000107	897	
002	1	C	595 - Perform Product Update on	1408 - Wiring Harness	I000107	I000107	I000107	160	Customer complaint: PSP 23-0092 check w Resultant damage: The screws that held th loose. Cause of failure: Assembled at factory wro Repair process comments: Removed the fl access doors. removed the wiring from th screws that held the box together. tighte they were loose. installed wires back ont tightened. installed florr plates and mat. operation.
003	1.5	C	023 - Repair	6129 - Quick Coupler	I000104	I000104	I000104	264	Customer complaint: Oil collection bottle v hydraulics. Resultant damage: . Cause of failure: The oring on green negati Repair process comments: Removed the di installed a jumper hose in the couplers an for leaks. removed hose on green coupler

									installed hose and checked for leaks. insta
								Total: $1,320.98	
– WO No SC00434835 (ACTI: I) (Jun 28, 2023) - BESKAU TRUCKING1 (C010193) SMU: 1054H Jun 30, 2023									
001	2.25	C	510 - Replace	1426 - Start Relay	I000104	I000104	I000104	983	Customer complaint: The machine wouldn Resultant damage: The relay was replacec Cause of failure: The 24 volt relay malfunc starter. Repair process comments: Tried to start tl happen. checked the fuses on the 24 volt r bad fuse. tried to start machine again. all noise from the steps. removed battery co relay. checked voltage down to the starte on constant. removed and replaced relay. machine ran.
								Total: $982.76	
– WO No SC00416712 (ACTI: I) (May 31, 2023) - BESKAU TRUCKING1 (C010193) SMU: 1054H Jun 30, 2023									
001	16	C	041 - Perform Maintenance On	7526 - 1000 Service Hour Maintenance	I000104	I000104	I000104	4,270	Customer complaint: Due a 1000 hour serv Resultant damage: . Cause of failure: . Repair process comments: followed the fer service job. Changed engine oil and filter. outer air filter. changed fuel tank and def transmission high pressure filter. remove valves. installed a new valve cover gaske tech connect inspection. hydraulic oil level customer is going to keep a eye on them. wearing on the inside. changed the boogie reaction arm oils were glittered. TCP168E
002	6.75	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	2,224	
003	0	C	557 - Order Parts		I001007	I001007	I001007	445	
004	1.5	C	510 - Replace	4050 - Final Drive	I000104	I000104	I000104	284	Customer complaint: Oil was leaking from Resultant damage: . Cause of failure: There was a burr in the or Repair process comments: Removed drain cleaned up the area and inspected. wire b burrs from the area. installed new plug in axle with oil and checked for leaks.
								Total: $7,223.43	
– WO No SC00407394 (ACTI: I) (May 15, 2023) - BESKAU TRUCKING1 (C010193) SMU: 1045H May 27, 2023									
002	3.5	C	035 - Troubleshoot	4050 - Final Drive	I000104	I000104	I000104	546	Customer complaint: Oil drain plug on left Resultant damage: oil leak Cause of failure: o-ring failed on plug. Part Repair process comments: Removed drain without draining all oil. Cleaned residual c plug installed. Parts of o-ring on new plug was slightly damaged upon installation. D completely drain and refill final, customer return to machine, drain left final drive oil
								Total: $546.17	
– WO No SC00390824 (ACTI: I) (Apr 19, 2023) - BESKAU TRUCKING1 (C010193) SMU: 823H Apr 26, 2023									
001	1	C	595 - Perform Product Update on	1405 - Alternator	I000107	I000107	I000107	160	Customer complaint: Performed bulletin 2 instructions. Re-torqued alternator mount Resultant damage: . Cause of failure: Repair process comments:
002	1	C	595 - Perform Product Update on	1071 - Air Line(s)/Pipe	I000107	I000107	I000107	160	Customer complaint: Performed bulletin 2 instruction. Inspected air intake pipe. Adj Resultant damage: . Cause of failure: Repair process comments:
003	0.5	C	595 - Perform Product Update on	1071 - Air Line(s)/Pipe	I000107	I000107	I000107	228	Customer complaint: Performed bulletin 2 instructions. Replaced charge air cooler hc Resultant damage: . Cause of failure: Repair process comments:
004	2	C	056 - Travel To/From	7000 - Machine	I000107	I000107	I000107	736	
								Total: $1,284.20	

– WO No SC00387261 (ACTI: I) (Apr 13, 2023) - BESKAU TRUCKING1 (C010193) SMU: 818H Apr 24, 2023

001	3.5	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	1,184	
002	2.5	C	023 - Repair	9130 - Oil Leak	I000104	I000104	I000104	649	
005	1	C	023 - Repair	1380 - Coolant Hose/Lines	I000104	I000104	I000104	222	Customer complaint: Coolant level low fau Resultant damage: coolant level low Cause of failure: loose hose clamps leaking Repair process comments: Inspected mach hose clamps are wet. Checked hose clamp Tightened hose clamps. Topped off coolant checked for leaks, no leaks. Cleared fault c
								Total: $2,055.74	

– WO No SC00304901 (ACTI: I) (Oct 31, 2022) - BESKAU TRUCKING1 (C010193) SMU: 687H Nov 11, 2022

001	4.33	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	1,347	
002	3.5	C	023 - Repair	1400 - Electric System	I000104	I000104	I000104	541	Customer complaint: code of.1.35 would ap Resultant damage: None Cause of failure: The ground stud wasn't tig Repair process comments: turned on all th tractor to see which lights weren't workin checked all the connection of the lights and the connectors. Found a ground cable on t resistance where low. checked software a operated tractor and code came back. rec become active and stored as the tractor w and checked the ground cable on the groun wiper motor. reached up and found the gr tight. held the nut on the inside and tighte reassembled tractor. ran tractor and chec
003	2	C	023 - Repair	1616 - Seat Switch	I000104	I000104	I000104	394	Customer complaint: The tractor would st lock up. Resultant damage: removed seat cushion a switch. ran tractor to try to duplicate the with a new switch. installed the switch int seat cushion to see if that would help. ohr and let the customer try tractor again. cu but it still acted up once. Cause of failure: The operator present swit was in the seat. Repair process comments: removed seat c switch. made up a harness for the second switch. installed it into the tractor and ra problem.
004	7.42	C	041 - Perform Maintenance On	7525 - 500 Service Hour Maintenance	I000104	I000104	I000104	2,631	Customer complaint: Perform 500 hour se Resultant damage: . Cause of failure: . Repair process comments: filled out and su inspection. changed engine oil and filter. c drive fluids. checked all fluids. checked tra codes. checked lights. went through and c check sheet.
005	0	C	937 - Order Parts (Use 557)	9824 - *USE CODE 7567*	I001007	I001007	I001007	977	
								Total: $5,889.50	

– WO No SC00260704 (ACTI: I) (Aug 23, 2022) - BESKAU TRUCKING1 (C010193) SMU: 335H Aug 23, 2022

001	2.5	C	012 - Install	7602 - GPS	I000104	I000104	I000104	403	Customer complaint: Unlock contour assist Resultant damage: None. Cause of failure: Tractor was supposed to h Repair process comments: Made a technica and hooked up to the tractor. let technica programmed the tractor for contour assist out tractor.
								Total: $403.30	

– WO No SC00221935 (ACTI: I) (Jun 07, 2022) - BESKAU TRUCKING (C010193) SMU: 335H Aug 23, 2022

002	29.75	C	012 - Install	508F - Steering & Trans Pump	I002845	I002845	I002845	12,739	Customer complaint: Install dual hydraulic Resultant damage: . Cause of failure: . Repair process comments: Drained hyd. oil transmission oil from tractor. removed sh tractor. removed the hydraulic lines from pump and set aside. removed hydraulic p pump. installed lines and fittings onto the

									hydraulic valve block and installed a secon power beyond pressure line and screwed i way. reinstalled the pressure line. Install hydraulic tank. removed the return line fr installed it onto the second filter. Installec onto the hydraulic valve stack. filled tract system. washed the tractor off and reinst and topped off fluids and checked for leaks.
003	0	C	052 - Transport	7000 - Machine	I000104	I000104	I000104	868	
004	27.75	C	014 - Replace Gasket/Reseal	4050 - Final Drive	I000104	I000104	I000104	4,431	Customer complaint: There was oil leaking Resultant damage: checked torque on all t were torque. washed off tractor to see wh Cause of failure: The bolts were loose arou them and screw them in and out by hand. Repair process comments: jacked up tract the right hand track assembly. removed s tractor. drained remaining oil from the ri brackets around the final drive. removed removed the ring gear from the axle. clea new gasket material and resealed the fina torque the axle hardware. Filled the final and torqued the hub hardware. drove tra the tracks. rechecked the track hardware.
005	3.5	C	510 - Replace	7334 - Latch / Lock Mechanism	I000104	I000104	I000104	613	Customer complaint: The customer compl hard to open Resultant damage: Customer was bending Cause of failure: The latch wouldn't unlock the button Repair process comments: Opened up the l assembly. Lubed up the key hole. loosen realign the hood. removed the latching br holes trying to align the hood.. Raised hoc installed a new key latch and verified the
								Total: $18,650.62	

– WO No SC00212802 (ACTI: I) (May 18, 2022) - BESKAU TRUCKING (C010193) SMU: 233H May 24, 2022

001	7	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	2,796	
003	2	C	510 - Replace	9260 - Fuel Filter	I000104	I000104	I000104	704	Customer complaint: Fuel was leaking on t Resultant damage: fuel was all over the le be washed. Cause of failure: The filter housing was leal Repair process comments: raised hood anc filter housing and ran tractor looking for le removed torx screws and inspected the ga ordered a new housing. installed new hou for leaks. cleaned up the tractor.
004	6	C	023 - Repair	4267 - Parking Brake	I000104	I000104	I000104	840	Customer complaint: The park brake light driving the tractor. Resultant damage: . Cause of failure: A faulty park brake pressu turn on the park brake light. Repair process comments: Hooked comput the codes. Found that the park brake was moving. EXT Park Brake 34.2.15. Hooke the park brake pressure. pressure was no to the sensor. operated the tractor for a v ordered a new sensor. removed the panel operated the tractor to check the operatic
006	4	C	041 - Perform Maintenance On	9532 - Initial 50 Hr Service	I000104	I000104	I000104	842	Customer complaint: Do the 50 hour servi Resultant damage: . Cause of failure: . Repair process comments: Inspected the m list on tech connect. TCP830078 changed t filter. relocated a hyd. line by the filter ho
								Total: $5,182.31	

– WO No SC00206410 (ACTI: I) (May 06, 2022) - BESKAU TRUCKING (C010193) SMU: 33H May 07, 2022

001	1.5	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	741	
002	10.25	C	023 - Repair	4306 - Steering Pump	I000104	I000104	I000104	1,712	Customer complaint: tractor would not ste Resultant damage: The tractor pumped ou period of time. Cause of failure: The oring on hose# ACW7 against the ACW3585570 steering pump. out in the pump before there was correct

									Repair process comments: inspected the tr underneath and the right side to see if i co from. Put 10 gallons of oil into the tractor the oil was leaking from. Started tractor hose going from the steering pump to the steering pump. removed the clamp and fi went to shakopee and ZRC to get parts. w installed new oring on hose and removed t orings. replaced the orings because they h were not tight on that hose either. install the correct torque onto the hose and pum with oil and ran tractor. drove tractor anc for leaks. installed all shields.
003	0	C	557 - Order Parts	9824 - *USE CODE 7567*	I001007	I001007	I001007	1,348	
								Total: $3,802.15	

– WO No SC00204326 (ACTI: I) (May 03, 2022) - BESKAU TRUCKING (C010193) SMU: 23H May 04, 2022

001	2	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	827	
002	2.5	C	023 - Repair	1380 - Coolant Hose/Lines	I000104	I000104	I000104	408	Customer complaint: tractor was low on c Resultant damage: coolant had leaked out tank to drain sounding an alarm in the cat Cause of failure: The clamp was assemblec Repair process comments: pressurized the searched system and found leak. loosenec around so that it could be tightened up cor system and pressurized it again. went arc hoses clamps. cleaned up the leaking cool till it got warm and checked for leaks.
								Total: $1,234.90	

– WO No SC00201704 (ACTI: I) (Apr 27, 2022) - BESKAU TRUCKING (C010193) SMU: 23H May 04, 2022

001	3.25	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	1,292	
002	10	C	023 - Repair	4198 - Track Belt	I000104	I000104	I000104	1,619	Customer complaint: Customer called in w Monitor was not showing track tension pre Resultant damage: . Cause of failure: The sensors shorted out bl Repair process comments: Hooked up hose cylinder and verified that there was pressu and updated the software to all controller: Ziegler technical and Agco technical remot that everything had gotten updated. Once looked into the track pressure sensors and the sensor. following the schematic we fo had blown. replaced the fuses and checkec or rubs. finding none we ohm out the sens had been shorted. ordered new sensors. I tensioned from the tracks. removed the s no damage was found so installed new ser went into the command screen and checke EDT and cleared codes. drove tractor up a that the fuses didn't blow again.
003	2	C	023 - Repair	4159 - Idler/Idler Wheel	I000104	I000104	I000104	318	Customer complaint: Oil was leaking out c Resultant damage: oil was on the idler wh Cause of failure: gasket failure Repair process comments: Removed the ca the cap with a new gasket and some seala oil. drove tractor and checked for leaks.
								Total: $3,229.25	

– WO No SC00196722 (ACTI: I) (Apr 18, 2022) - BESKAU TRUCKING (C010193) SMU: 13H Apr 20, 2022

001	1.75	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	732	
002	11.25	C	010 - Remove & Install	4198 - Track Belt	I000104	I000104	I000104	1,521	Customer complaint: The wrong tracks we Resultant damage: none Cause of failure: error on Agco part Repair process comments: removed the fe installed special jackstand mounts. jacked detensioned the tracks. removed the fron the tractor. installed new track onto the t the other side. once both tracks were on t down the road and tried to align the track eye on the tractors for alignment. installe tracks back to the shop and got them on p
								Total: $2,252.84	

WO No SC00190591 (ACTI: I) (Apr 04, 2022) - BESKAU TRUCKING (C010193) SMU: 13H Apr 20, 2022

001	2.5	C	056 - Travel To/From	7000 - Machine	I000104	I000104	I000104	952	
002	1	C	023 - Repair	3155 - Transmission Clutch	I000104	I000104	I000104	132	Customer complaint: The machine does nc Resultant damage: Tractor will not move the clutch pedal Cause of failure: Snap ring for the clutch pe linkage arm hang there. Repair process comments: removed the cc installed the pin, spacer, sensor, and the sr checked operation of the clutch pedal and
								Total: $1,084.60	

WO No SC00188000 (ACTI: I) (Mar 29, 2022) - BESKAU TRUCKING (C010193) SMU: 8H Mar 31, 2022

001	10	C	041 - Perform Maintenance On	7588 - Pre-Delivery Inspection	I002845	I002845	I002845	1,649	Customer complaint: PDI machine followir Form#TCP767368 & Check off config. shts. Install Ziegler decals and place SOS kit insi Machine is retailed and will not need Fluid away. Track Gauge to 120", Fill fuel 25%, Def 10(Resultant damage: Check over new machi Cause of failure: Sales request. Repair process comments: Staged machine configuration check off. Fueled to 25% and 120" and aligned after torqueing to spec. I machine. No SOS kit available. Segment c
002	1	C	995 - *USE CODE 600*	9004 - Ag Technologies	I002845	I002845	I002845	149	Customer complaint: Register and Activate Send email to Ag Command Team and per Resultant damage: Activate technology. Cause of failure: Sales request. Repair process comments: Sent email for A and followed activation steps. Segment co
003	1	C	995 - *USE CODE 600*	9004 - Ag Technologies	I002845	I002845	I002845	5,738	Customer complaint: Unlock TerraStar-C-P Resultant damage: Unlock technology. Cause of failure: Sales request. Repair process comments: Ordered unlock Sykora forwarded the unlock code for the waited for activation while on the phone v
								Total: $7,537.07	