

Reprint

Repair Order Customer Proof

Proof To:

INTEGRITY OILFIELD HAULING
#5 Hwy 18 East
Carnduff SK S0C 0S0
Phone: 3064823386

Integrity Oilfield Hauling

#5 Hwy 18 East
Carnduff, SK S0C 0S0
Tel: 3064823386
Tel: 3064823030

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
May 30, 2024		IOH			1 / 5
WO005071		INTEGRITY OILFIELD HAULING			
Unit BOH 13		VIN 1XKWD40X2LJ960510		ENGINE 8890 HR	
Description BOH 13 - W900 KW		ODOMETER 478163 KM			
Make		Model		Year 2019	
License BOH13		Last Cert. ()		Engine	
Activity Description					
Part #	Part Description	Quantity	Unit Charge	Total	
1. Suspension		23.00 HR	130.0000	2990.00	
REPLACE CAB SHOCKS - CARTER					
83031ACD	FRONT SHOCK	2.00 EA	56.6100	113.22	
				Activity Sub-Total:	3103.22
2. Winch		0.00 HR	0.0000	0.00	
FAST INV 86079 INSTALL LINING ON BAND BRAKE 40" X 4" BRAKE MATERIAL AND RIVETS					
PARTS	PARTS	1.00 EA	47.2000	47.20	
LAB	LABOUR	1.00 EA	160.0000	160.00	
				Activity Sub-Total:	207.20
3. Drive Shafts		0.00 HR	0.0000	0.00	
FAST INV 86079 REPLACE DRIVE SHAFT TUBE U JOINT INPUT AXLE #2					
SPL250-3X	U JOINT	1.00 EA	167.0000	167.00	
250-70-18X	U JOINT STRAP	1.00 EA	20.4700	20.47	
LAB	LABOUR	2.50 EA	160.0000	400.00	
				Activity Sub-Total:	587.47
4. Lighting System		0.00 HR	0.0000	0.00	
FAST INV 86079 PLASMA OUT LIGHT PLATE CAB LIGHTS					
PARTS	PARTS	1.00 EA	132.5000	132.50	
LAB	LABOUR	1.00 EA	160.0000	160.00	
				Activity Sub-Total:	292.50

Proof To:

INTEGRITY OILFIELD HAULING
 #5 Hwy 18 East
 Carnduff SK S0C 0S0
 Phone: 3064823386

Integrity Oilfield Hauling

#5 Hwy 18 East
 Carnduff, SK S0C 0S0
 Tel: 3064823386
 Tel: 3064823030

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
May 30, 2024		IOH			2 / 5
Activity Description					
Part #	Part Description	Quantity	Unit Charge	Total	
5. Trim & Miscellaneous Hardware		0.00	HR	0.0000	0.00
REPLACE CAB FILTER					
CFR19501	CAB AIR FILTER	1.00	EA	12.4700	12.47
				Activity Sub-Total:	12.47
6. SGI SAFETY		2.00	HR	130.0000	260.00
SGI 1 YEAR - MICHEAL EXHAUST LEAK UNDER CAB STACK BUSHINGS EXHAUST GUARD BRAKET CAB LIGHTS STEERING SHAFT U JOINTS 5TH WHEEL PINS AND BUSHINGS WHEEL ALIGNMENT HYDRO HOSES LAYING ON EXHAUST U JOINT INPUT AXLE #2 LH AND RH TIE ROD ENDS RH DRAG LINK BRAKE POT AXLE #3 RH SERVICE GREASE AND CHECK LEVELS					
SGI SAFETY STICKER	SGI SAFETY STICKER	1.00	EA	0.0000	0.00
				Activity Sub-Total:	260.00
7. PM A Service		0.00	HR	0.0000	0.00
CHANGE OIL AND FILTER CHANGE FUEL FILTERS CHECK AIR FILTER GUAGE IT WAS GOOD					
500010131D	15W40 ROTELLA T3 BULK	43.00	EA	4.9500	212.85
FS19765FLG	FUEL SEP FILTER	1.00	EA	27.4100	27.41
FF5776	FUEL FILTER	1.00	EA	42.5700	42.57
LF14001NNFLG	OIL FILTER UPGRADE	1.00	EA	63.3900	63.39
				Activity Sub-Total:	346.22

Proof To:

INTEGRITY OILFIELD HAULING
#5 Hwy 18 East
Carnduff SK S0C 0S0
Phone: 3064823386

Integrity Oilfield Hauling

#5 Hwy 18 East
Carnduff, SK S0C 0S0
Tel: 3064823386
Tel: 3064823030

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
May 30, 2024		IOH			3 / 5
Activity Description					
Part #	Part Description	Quantity	Unit Charge	Total	
8. GREASE AND CHECK LEVELS		0.00	HR	0.0000	0.00
GREASE AND CHECK LEVELS					
ADD W/W					
ADD COOLANT					
5147-004	ANTIFREEZE HD ESI (N)OAT NITRITE 50/50 RED 4L JG	1.00	EA	9.0500	9.05
15-215	W/W FLUID -40	1.00	EA	4.0900	4.09
Activity Sub-Total:					13.14
9. Exhaust System		0.00	HR	0.0000	0.00
EXHAUST LEAK UNDER CAB					
STACK BUSHINGS					
EXHAUST GUARD BRAKET					
HYDRO HOSES LAYING ON EXHAUST					
K077-352PKG	CLAMP-PIPE SHIELD	2.00	EA	92.5200	185.04
M136001K	EXHAUST BUSHING KIT	2.00	EA	22.8300	45.66
TITANIUM EXHAUST	Titanium Exhaust Header Wrap Roll 2" x 50' with Gold Heat	2.00	EA	37.6900	75.38
HEADER WRAP ROLL 2" X 50' WITH GO	Tape 2" x 16'				
EC50PLA	EXHAUST CLAMP	2.00	EA	10.7400	21.48
Activity Sub-Total:					327.56
10 Brakes		0.00	HR	0.0000	0.00
BRAKE POT AXLE #3 RH, LH					
BRAKE POT AXLE #2 LH					
HAB-6-24C	24" BRAKE LINE	2.00	EA	8.0900	16.18
GC3030LCW	CHAMBER-BRAKE 2.25"WELD CLEV 3"STROKE	3.00	EA	127.0000	381.00
Activity Sub-Total:					397.18

Proof To:

INTEGRITY OILFIELD HAULING
 #5 Hwy 18 East
 Carnduff SK S0C 0S0
 Phone: 3064823386

Integrity Oilfield Hauling

#5 Hwy 18 East
 Carnduff, SK S0C 0S0
 Tel: 3064823386
 Tel: 3064823030

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
May 30, 2024		IOH			4 / 5
Activity Description					
Part #	Part Description	Quantity	Unit Charge	Total	
11 Steering		0.00 HR	0.0000	0.00	
	STEERING SHAFT U JOINTS				
	WHEEL ALIGNMENT				
	RH DRAG LINK				
QT108SB	CROSS TUBE ASSY	1.00 EA	333.7100	333.71	
463.DS7563	Drag Link 17.000in C to C RH	1.00 EA	246.7500	246.75	
418050-1	STEER DRIVE SHAFT	1.00 EA	382.5800	382.58	
Activity Sub-Total:				963.04	
12 Axle - Non-Driven, Front		0.00 HR	0.0000	0.00	
	LH AND RH TIE ROD ENDS				
Activity Sub-Total:				0.00	
13 Coupler Assembly		0.00 HR	0.0000	0.00	
	5TH WHEEL PINS AND BUSHINGS				
RK10605	LS BRACKET PIN AND BUSH KIT	1.00 EA	82.0000	82.00	
Activity Sub-Total:				82.00	
14 Cooling System		0.00 HR	0.0000	0.00	
	REPLACE LOWER RAD HOSE				
F50-1548	BOTTOM RAD HOSE 45 DEG	1.00 EA	30.4600	30.46	
Activity Sub-Total:				30.46	

Technician: MICHEAL-MICHEAL
 CARTER-HANSON
 DEMI-DEMI

Authorized By:

Proof To:

INTEGRITY OILFIELD HAULING

#5 Hwy 18 East

Carnduff SK S0C 0S0

Phone: 3064823386

Integrity Oilfield Hauling

#5 Hwy 18 East

Carnduff, SK S0C 0S0

Tel: 3064823386

Tel: 3064823030

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
May 30, 2024		IOH			5 / 5

Total Labor: 3,250.00

Total Parts: 3,372.46

Shop Supplies: 0.00

SGI STICKER: 15.75

Sub Total: 6,638.21

GST: 331.12

PST: 0.00

Proof Total: 6,969.33

3372.46
15.75

\$ 3388.21

Power Unit/Truck/Bus Inspection

1. Customer information

Name			
Address	City/town	Province	Postal code
Email address	Phone number		

- ☒ PMP Inspection
☐ Commercial Inspection

2. Vehicle information

VIN number 1XKW040X2L3960S10	Odometer 478163 ○ km ○ mi
Make Kenworth	Model W900
Year 2020	Unit number 13
Colour Black	Fuel Diesel
Brake type ☒ Air brake ☐ Electric ☐ Hydraulic ☐ Not equipped ☐ No Brake	Is the GVWR of this vehicle greater than 4,536kg? 8890 hrs ○ Yes ○ No

Brake Type:

- ☐ Disc ☒ SCAM
☐ Wedge ☐ NO

Brake Drum/SCAM Type:

- ☐ 15" Ext. Service Cam
☐ 15" Std. Service Cam
☐ 16.5 Ext. Service Cam
☐ 16.5" Std. Service Cam
☐ 16.5" Ext. Cam/Std Lining
☐ 12.25" Brake Drum
☐ 14" Brake Drum
☐ Other _____

3. Inspection information

Start date	Completion date	Expiry date
☐ Inspection failed Reason ☐ Inspection passed ☐ FTR ☐ PMVI ☐ Police request ☐ Taxi/Rideshare ☐ TLV ☐ VSI request ☐ Other		
Station number	Station name	

Identify Rejected and REQATT Items by marking with an X When item is Passed identify with marking with a X P=PASS R=REJECTED RA=REQATT (comments required for REGATT)									
No	P	R	RA	DRIVER COMPARTMENT	COMMENTS	No	P	R	RA
01				Vehicle Identification		33			
02				Sun Visor Interior		34			
03				Horn Operation		35			
04				Mirrors		36			
05				Windshield Wipers/Washers		37			
06				Windshield Defroster/Heater		38			
07				Windshield/Other Glass		39			
08				Gear Position Indicator & Neutral Switch		40			
09				Instrument Lamps		41			
10				Accessibility Features/Equip		42			
11				Auxiliary Heaters		43			
12				Auxiliary Drive Controls		44			
13				Emergency Exits		45			
14				Floor/Step Wall Covering		46			
15				Service/Exit Doors		47			
16				Indicator Lamps		48			
17				Instruments/Gauges		49			
18				Switches		50			
19				Brake Pedal/Actuator		51			
20				Clutch/Clutch Pedal		52			
21				Fire Extinguisher/Hazard Kit		53			
22				Seats/Seat Belts/SRS		54			
23				Steering Column/Components		55			
24				Auxiliary Controls/Equip		56			
25				Speedometer/Odometer		57			
26				Steering Lash/Travel		58			
27				Accelerator Pedal/Actuator		59			
28				Engine Shut Down Control		60			
29				Engine Start Feature		61			
30				Body Interior Fixtures		62			
31				Body Exterior		63			
32				Lamps		64			
				Headlamp Aim		65			
COMMENTS						COMMENTS			
						ENGINE COMPARTMENT			
						Cab/Hood Safety Catches			
						Power Steering System			
						Fuel System			
						Battery/Wiring Condition			
						Air Suspended Cab			
						Cab Mounts			
						Drive Belts			
						CHASSIS			
						Hyd Brake System/Components			
						Air Brake Systems/Components			
						Wheel Bearings			
						King Pins/Ball Joints			
						Steering Linkage			
						Tires/Wheels			
						Self-Steering Axle			
						Engine/Transmission Mounts			
						Frame/Crossmembers/Mounts			
						Suspension/Axles			
						Drive Shaft/Universal Joints			
						Exhaust/Emission System			

Wheel Position

Tire Tread Depth (in/mm)	Drum Size / Rotor Thickness (in/mm)	Brake Cam Rotation (degree°)	Vehicle Brake Lining Thickness (in/mm)
Front 20 Rear 19	Front 12.5 Rear 1.5	Front 40 Rear 40	Front 7462 Rear 7491

INTEGRITY

Oilfield Hauling Ltd

SHOP WORK ORDER

Date:	MAY 30 th
Unit #: B0H13	License Plate #: B0H13
Odometer: 478163	Unit Hours: 8889 8890
S/N:	

☒ Maintenance	☐ PMP	☒ SGI Safety
---	------------------------------	--

Qty.	Part #	Repairs Required	Work Done	Hours
2	83031 ACO	Cab shocks	pull fuel tanks	5
1	LFH4001NN	Service	replace Cab Shocks	
1	FF5776		put Bolt in frame on P/S	
1	FS19765		Change fuel + oil filter	
1	Jug washer fluid		Check air filter gauge it was <u>GOOD</u>	
1	Jug of Coolant		Add washer fluid	
43L	15w-40		Add 1 Jug of coolant	
1	5" Clamp		Grease truck	
2	EC50PLA			
2	2ft of heat wrap			

Changed Winch Line: ☐

Slipped Line: ☐

Wheels Off: Truck

Wheels Off: Trailer

Tires have been torqued: ☐

Work Completed By: Carter Mike Deni

Mechanic's Signature: _____

Over →

[illegible]

Proof To:

INTEGRITY OILFIELD HAULING
#5 Hwy 18 East
Carnduff SK S0C 0S0
Phone: 3064823386

Integrity Oilfield Hauling

#5 Hwy 18 East
Carnduff, SK S0C 0S0
Tel: 3064823386
Tel: 3064823030

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
Oct 24, 2023		IOH			1 / 2

WO004152

INTEGRITY OILFIELD HAULING

Unit BOH 13

VIN 1XKWD40X2LJ960510

Description BOH 13 - W900 KW

Make

Model

Year 2019

License BOH13

Last Cert. ()

Engine

Activity Description

Part #	Part Description	Quantity	Unit Charge	Total
1. Air Conditioning Assembly		0.00 HR	0.0000	0.00
PETERBUILT ES27869 INSTALL WEBASTO CAB AND BUNK HEATER COMBO FROM MAXIUM Webasto Install tandem Webasto CAUSE: Customer install request. CORRECTION: Found a good spot for air top after mocking up. Cleaned drivers stuff out of the bunk where I intend to install. Mocked up mounting plate and cut a hole to fit in the floor mat. Used the supplied template to cut a hole in the cab floor using a hole saw. Mounted down the webasto and mounting plate, torqued mounting bolts to spec. Drilled another hole in the cab floor to route the harness through. Had to snip the plugs off the end of the harness and reattach once it was routed through the cab. Reattached the plugs using but connectors. Drilled another hole in a vertical panel to route the controller harness through. Mounted the controller on a pillar in the bunk after routing its harness through. Connected the controller and reinstalled all panels. Installed filter and fuel line onto standpipe and routed under cab to air top. Routed and installed fuel pump harness to air top. Installed combustion and exhaust pipes. Tried to fire up air top but kept throwing codes(WBUS and F01) helped second tech troubleshoot with webasto support. Eventually found that the issue was with supply voltage. Changed the fuses and which battery we hooked up on solved the problem. Fired up air top and ran until it was hot, ensuring no more codes. After confirming proper operation, I helped Nick tie up harnesses and vacuum the cab and put all of drivers belongings back where I found.				
SHOP	Shop Supplies	1.00 EA	180.0000	180.00
CARBON TAX	CARBON TAX	1.00 EA	40.0000	40.00
LAB	LABOUR	1.00 EA	2000.0000	2000.00
838004	1" loom	4.00 EA	1.7500	7.00
7322	1-1/4" P CLAMP	3.00 EA	3.2800	9.84
ICE-14160C	14" TIE STRAP	45.00 EA	1.2000	54.00
ETM-6	CLAMP SILICON	1.00 EA	3.5000	3.50
M1N15	FUSE-15 AMP	1.00 EA	2.0100	2.01
838002GRC	TUBING-SPLIT,3/4"(1EA=50F	4.00 EA	0.5800	2.32

Proof To:

INTEGRITY OILFIELD HAULING
#5 Hwy 18 East
Carnduff SK S0C 0S0
Phone: 3064823386

Integrity Oilfield Hauling

#5 Hwy 18 East
Carnduff, SK S0C 0S0
Tel: 3064823386
Tel: 3064823030

Date	Vendor Code	A/C	Customer PO	Payment Term	Page
Oct 24, 2023		IOH			2 / 2
Activity Description					
Part #	Part Description	Quantity	Unit Charge	Total	
CT9412TRP	CLAMP-CONSTANT TORQUE #12	5.00 EA	11.3000	56.50	
D1030-3950	HEATER HOSE #16 X 25'	1.00 EA	13.6200	13.62	
D1029-2965	HOSE-HEATER BLUE #10X400'	1.00 EA	7.9900	7.99	
D1030-3833	HOSE-HEATER #12X300' J20R	4.00 EA	9.9100	39.64	
WEB5013914A	WEBASTO COMBO HEATER KIT	1.00 EA	2249.9500	2249.95	
				Activity Sub-Total:	4666.37
2. Engine / Motor Systems Group		0.00 HR	0.0000	0.00	
PETERBUILT INV ES27874					
Speed parameters Change sped parameters to customer requested speed settings					
CORRECTION:					
Hooked up to truck with lap top changed speed to 125 km on the cruise and the foot pedal					
SHOP	Shop Supplies	1.00 EA	11.3400	11.34	
CARBON TAX	CARBON TAX	1.00 EA	2.5200	2.52	
TECHNOLOGY FEE	TECHNOLOGY FEE	1.00 EA	29.0000	29.00	
LAB	LABOUR	1.00 EA	126.0000	126.00	
				Activity Sub-Total:	168.86

Technician:

Authorized By:

Total Labor:	0.00
Total Parts:	4,835.23
Shop Supplies:	0.00
Sub Total:	4,835.23
GST:	241.76
PST:	0.00
Proof Total:	5,076.99