


TILE RECORD MAP
LOCATION PLAN OF TILE SYSTEM



NAME Santos Bros.

FARM LOCATION Levin S.E. of Building

DATE INSTALLED _____

Tract 2

AMOUNT OF TILE INSTALLED: 4" 673' 5" _____

6" _____ 8" _____ 10" _____ 12" _____

OTHER _____

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

Reinhart Tile and Trenching

James Reinhart

North English, Iowa

(319) 664-3200