

GREEN IRON EQUIPMENT

PO Box 338
520 Main St
Milnor, ND 58060-0039
(701) 427-5224
(701) 427-5232



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 401289

Deliver To:

| | | |
|---|---|--|
| THATCHER PETERSON 13603 78TH ST SE MILNOR ND 58060 Bus Phone: 701-680-1884 Prv Phone: | THATCHER PETERSON 13603 78TH ST SE MILNOR ND 58060 Bus Phone: 701-680-1884 Prv Phone: | Invoice Number: 743890 Invoice Date: 11/08/2019 Location: 4 Work Order Number: 108883 Payment Type: Finance Page: 2 of 5 |
|---|---|--|

| | | | | |
|-----------------|-------|----------------|--------|-----------|
| Make/Model: | Meter | Serial Number: | EQ Id: | Fleet No: |
| JOHN DEERE 4710 | 4342 | N04710X006159 | TP4710 | |

| Part Number | Description | Quantity | Net Price | Extended Price | Taxed Ind |
|-------------|----------------------------|----------|-----------|----------------|-----------|
| AN207104 | Battery Cable | 1.00 | \$365.25 | \$365.25 | N |
| AN207105 | Battery Cable | 1.00 | \$356.13 | \$356.13 | N |
| TY25684 | GLASS CLEANER | 1.00 | \$3.78 | \$3.78 | Y |
| TY26101 | BRAKE/CLUTCH CLEANER | 6.00 | \$4.92 | \$29.52 | Y |
| TY26812 | 85W140 GEAR LUBE 1 GAL | 1.00 | \$25.42 | \$25.42 | Y |
| TY6345 | 85W140 GL5 GEAR LUBE/QUART | 1.00 | \$7.41 | \$7.41 | Y |

Labor: \$600.00 Parts: \$868.32 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$1,468.32

GEN 5 Retail

COMPLAINT:

06 General Repairs wheel extensions

CORRECTION:

T434 Jacked up sprayer and ran tests per service advisor, believe it has a bad cylinder. Customer decided to wait on any repairs for this.

Labor: \$208.37 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$208.37

Gen-Engine Retail

COMPLAINT:

07 Engine Repairs in frame overhaul

CORRECTION:

T434 Removed head. Found bad exhaust valves, replace them. Replaced the water pump. Replaced turbo, oil pump and cylinder head. Removed fuel pump and drives. Removed pistons, sleeves and injectors. Removed and replaced main bearings. Reassembled engine with new parts. Replaced needed gaskets and hoses. Test ran

| PartNumber | Description | Quantity | Net Price | Extended Price | Taxed Ind |
|------------|------------------------|----------|-----------|----------------|-----------|
| 003494 | ENGINE ASSEMBLY GREASE | 1.00 | \$10.76 | \$10.76 | Y |
| 19H3336 | Screw | 4.00 | \$2.06 | \$8.24 | N |
| 19M7810 | M10 X 80 FLANGE BOLT | 12.00 | \$3.37 | \$40.44 | N |
| 19M8987 | Screw | 1.00 | \$2.41 | \$2.41 | N |
| 80064 | HI-TACK SPRAY CAN | 1.00 | \$11.52 | \$11.52 | N |
| AN206315 | Air Filter | 1.00 | \$32.20 | \$32.20 | N |
| AR48675 | THERMOSTAT | 1.00 | \$10.87 | \$10.87 | N |

CONTINUED ON NEXT PAGE->

GREEN IRON EQUIPMENT

PO Box 338
 520 Main St
 Milnor, ND 58060-0039
 (701) 427-5224
 (701) 427-5232



JOHN DEERE

Invoice To Account No: 401289

Deliver To:

SERVICE INVOICE

| | | |
|--|--|-------------------------------|
| THATCHER PETERSON 13603 78TH ST SE MILNOR ND 58060 | THATCHER PETERSON 13603 78TH ST SE MILNOR ND 58060 | Invoice Number: 743890 |
| Bus Phone: 701-680-1884 | Bus Phone: 701-680-1884 | Invoice Date: 11/08/2019 |
| Prv Phone: | Prv Phone: | Location: 4 |
| | | Work Order Number: 108883 |
| | | Payment Type: Finance |
| | | Page: 3 of 5 |

| Make/Model: | Meter | Serial Number: | EQ Id: | Fleet No: |
|-----------------|-------|----------------|--------|-----------|
| JOHN DEERE 4710 | 4342 | N04710X006159 | TP4710 | |

| Part Number | Description | Quantity | Unit Price | Total Price | Warranty |
|-------------|------------------------|----------|------------|-------------|----------|
| DRC4223 | 200CT BOX SHOP TOWELS | 1.00 | \$11.29 | \$11.29 | Y |
| DZ110417 | Piston-Liner Kit | 6.00 | \$286.72 | \$1,720.32 | N |
| H23125 | PLUG | 6.00 | \$1.95 | \$11.70 | N |
| H77698 | TIE BAND | 16.00 | \$0.32 | \$5.12 | N |
| PM00010 | SPRING LOCKING PIN | 3.00 | \$0.13 | \$0.39 | N |
| PM37532 | ADHESIVE | 1.00 | \$7.21 | \$7.21 | Y |
| PM38655 | SEALANT | 1.00 | \$15.19 | \$15.19 | Y |
| R114194 | Shaft | 1.00 | \$63.17 | \$63.17 | N |
| R120641 | Shaft | 1.00 | \$170.30 | \$170.30 | N |
| R121424 | O-Ring | 1.00 | \$3.66 | \$3.66 | N |
| R123177 | Piston Pin | 6.00 | \$57.55 | \$345.30 | N |
| R123295 | O-Ring | 1.00 | \$2.42 | \$2.42 | N |
| R131436 | V-Belt | 1.00 | \$104.99 | \$104.99 | N |
| R518276 | Hose | 1.00 | \$13.82 | \$13.82 | N |
| R51936 | SEALING WASH | 18.00 | \$1.33 | \$23.94 | N |
| R545882 | Gasket | 1.00 | \$21.06 | \$21.06 | N |
| R63845 | WASHER | 4.00 | \$1.27 | \$5.08 | N |
| R67092 | SEALING WASHER | 5.00 | \$3.87 | \$19.35 | N |
| R72328 | O-RING | 1.00 | \$1.24 | \$1.24 | N |
| R73864 | O-Ring | 1.00 | \$5.01 | \$5.01 | N |
| R79605 | WASHER | 6.00 | \$2.51 | \$15.06 | N |
| R85363 | CAP SCREW | 26.00 | \$6.56 | \$170.56 | N |
| RE508932 | Gear | 1.00 | \$446.08 | \$446.08 | N |
| RE526965 | Gasket Kit | 1.00 | \$220.78 | \$220.78 | N |
| RE56369 | Gear | 1.00 | \$271.28 | \$271.28 | N |
| RE59754 | OIL FILTER | 2.00 | \$13.99 | \$27.98 | N |
| RE59914 | Fuel Line | 1.00 | \$60.64 | \$60.64 | N |
| RE62419 | FUEL FILTER | 1.00 | \$21.55 | \$21.55 | N |
| RE65165 | Bearing Kit | 6.00 | \$26.46 | \$158.76 | N |
| RE65168 | Bearing Kit | 1.00 | \$58.75 | \$58.75 | N |
| RE65908 | Bearing | 6.00 | \$17.84 | \$107.04 | N |
| SE501094 | Connecting Rod Reman | 6.00 | \$420.37 | \$2,522.22 | N |
| SE501101 | Injection Nozzle Reman | 6.00 | \$90.06 | \$540.36 | N |
| SE501581 | Cylinder Head Reman | 1.00 | \$2,425.19 | \$2,425.19 | N |
| SE501609 | WATER PUMP | 1.00 | \$269.43 | \$269.43 | N |

CONTINUED ON NEXT PAGE->

GREEN IRON EQUIPMENT

PO Box 338
520 Main St
Milnor, ND 58060-0039
(701) 427-5224
(701) 427-5232



JOHN DEERE

Invoice To Account No: 401289

Deliver To:

SERVICE INVOICE

| | | |
|---|---|--|
| THATCHER PETERSON 13603 78TH ST SE MILNOR ND 58060 Bus Phone: 701-680-1884 Prv Phone: | THATCHER PETERSON 13603 78TH ST SE MILNOR ND 58060 Bus Phone: 701-680-1884 Prv Phone: | Invoice Number: 743890 Invoice Date: 11/08/2019 Location: 4 Work Order Number: 108883 Payment Type: Finance Page: 4 of 5 |
|---|---|--|

| | | | | |
|-----------------|-------|----------------|--------|-----------|
| Make/Model: | Meter | Serial Number: | EQ Id: | Fleet No: |
| JOHN DEERE 4710 | 4342 | N04710X006159 | TP4710 | |

| | | Quantity | Net Price | Extended Price | Taxed Ind |
|----------------------|------------------------------|----------|------------|----------------|-----------|
| SE501814 | Oil Pump Reman | 1.00 | \$451.29 | \$451.29 | N |
| SE502159 | Turbocharger Reman | 1.00 | \$1,192.72 | \$1,192.72 | N |
| TY22324 | 5/16" BULK FUEL HOSE | 1.00 | \$0.08 | \$0.08 | N |
| TY22466 | SAE#12 HOSE CLAMP | 2.00 | \$0.97 | \$1.94 | N |
| TY22474 | SAE#64 HOSE CLAMP | 1.00 | \$1.27 | \$1.27 | N |
| TY24752 | MEDIUM GRIT EMERY CLOTH | 1.00 | \$2.95 | \$2.95 | N |
| TY25624 | GREEN SPRAY PAINT | 1.00 | \$10.07 | \$10.07 | Y |
| TY26576 | 50-50 ANTIFREEZE 2-1/2 GAL | 1.00 | \$31.83 | \$63.66 | Y |
| TY26663 | 10W30 BREAK-IN OIL 5 GAL | 2.00 | \$93.59 | \$93.59 | Y |
| TY26678Q | 15W40 PLUS 50 II / BULK-SHOP | 1.00 | \$3.00 | \$60.00 | Y |
| TY27084 | 5/8" FLEX GUARD | 1.00 | \$4.37 | \$4.37 | N |
| X13943-4-4 | ELBOW FITTIN | 2.00 | \$14.62 | \$29.24 | N |
| X487TC-4-RL | 1/4" HYD HOSE | 6.00 | \$5.28 | \$31.68 | N |
| Miscellaneous | Description | | | | |
| P1661 | CORE CHG/CR-JOHN DEERE | 6.00 | -\$5.00 | -\$30.00 | N |
| P1661 | CORE CHG/CR-JOHN DEERE | 1.00 | -\$100.00 | -\$100.00 | N |
| P1661 | CORE CHG/CR-JOHN DEERE | 1.00 | -\$300.00 | -\$300.00 | N |
| P1661 | CORE CHG/CR-JOHN DEERE | 1.00 | -\$50.00 | -\$50.00 | N |
| P1661 | CORE CHG/CR-JOHN DEERE | 6.00 | -\$25.00 | -\$150.00 | N |
| P1661 | CORE CHG/CR-JOHN DEERE | 1.00 | -\$125.00 | -\$125.00 | N |
| P1661 | CORE CHG/CR-JOHN DEERE | 1.00 | \$33.98 | \$33.98 | N |
| P3752 | FREIGHT | 1.00 | \$15.95 | \$15.95 | N |
| P3752 | FREIGHT | 1.00 | \$150.00 | \$150.00 | N |
| P3752 | FREIGHT | | | | |

| | | |
|-------------------------------|--|---------|
| Miscellaneous Charges: | | \$85.00 |
| Service Accessory Charge | | \$3.00 |
| EPA Disposal Fee | | |

Labor: \$10,185.12 Parts: \$11,925.54 OL&M: \$0.00 Misc: -\$467.07 Sub-Total: \$21,643.59

Finance Information

| | | |
|------------------------|--|-----------------|
| Customer PO No: | Type: Farm Plan | Auth No: 677009 |
| Tax Exempt No: 1 | Merchant No: 55000282 | |
| Advisor: MARC ENDERSON | Card No: xxxxxxxxxxxxxx0376 | |
| | Bill Code: 787 - JD INSPECTION-SPRAYING | |
| | Credit Plan: 11442 - DEERE AG NO PAYMENTS/NO INTEREST WAIVER UNTIL JANUARY 1, 2021 | |

| | |
|---------------|--------------------|
| Labor: | \$11,673.89 |
| Parts: | \$12,793.86 |
| OL&M: | \$0.00 |
| Misc: | -\$467.07 |
| Sales Tax: | \$25.34 |
| Total: | \$24,026.02 |

GREEN IRON EQUIPMENT

PO Box 338
 520 Main St
 Milnor, ND 58060-0039
 (701) 427-5224
 (701) 427-5232



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 401289

Deliver To:

| | | | | |
|---|---|--|--------|-----------|
| THATCHER PETERSON 13603 78TH ST SE MILNOR ND 58060 Bus Phone: 701-680-1884 Prv Phone: | THATCHER PETERSON 13603 78TH ST SE MILNOR ND 58060 Bus Phone: 701-680-1884 Prv Phone: | Invoice Number: 743890 Invoice Date: 11/08/2019 Location: 4 Work Order Number: 108883 Payment Type: Finance Page: 1 of 5 | | |
| Make/Model: | Meter | Serial Number: | EQ Id: | Fleet No: |
| JOHN DEERE 4710 | 4342 | N04710X006159 | TP4710 | |

SPRAYER INSPECTION Retail

COMPLAINT:

01 SPRAYER INSPECTION
 THIS DOES NOT INCLUDE WINTERIZATION OF MACHINE.

CORRECTION:

T434 Went through the inspection and repairs with the customer. Didn't repair the pivot, customer decided to wait on the repair

| | | | | |
|-----------------|---------------|--------------|--------------|---------------------|
| Labor: \$399.00 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$399.00 |
|-----------------|---------------|--------------|--------------|---------------------|

GEN 1 Retail

COMPLAINT:

02 General Repairs oil pan

CORRECTION:

T434 Drained oil. Removed oil pan and valve cover, found washers in the bottom of the oil pan. Advised the customer. Repaired these issues on the engine segment

| | | | | |
|-----------------|---------------|--------------|--------------|---------------------|
| Labor: \$281.40 | Parts: \$0.00 | OL&M: \$0.00 | Misc: \$0.00 | Sub-Total: \$281.40 |
|-----------------|---------------|--------------|--------------|---------------------|

GEN 3 Retail

COMPLAINT:

04 General Repairs throttle cable and misc lights, hub oils

CORRECTION:

T434 Removed and replaced throttle cable; cable was previously charged to the customer. Replaced both positive and negative battery cables. Change all hub oils. Replaced bulbs in hazards lights.

| PartNumber | Description | Quantity | Net Price | Extended Price | Taxed Ind |
|------------|--------------------------|----------|-----------|----------------|-----------|
| 3157 | BULB | 4.00 | \$1.74 | \$6.96 | N |
| AN205832 | Elec. Connector Terminal | 1.00 | \$37.13 | \$37.13 | N |
| AN205833 | Elec. Connector Terminal | 1.00 | \$36.72 | \$36.72 | N |

CONTINUED ON NEXT PAGE →