



Harvey, ND (701) 324-4631 Williston, ND (701) 572-6724  
 Kenmare, ND (701) 385-4227 Beach, ND (701) 872-3737  
 Minot, ND (701) 852-0767 Bowman, ND (701) 523-3252  
 Mohall, ND (701) 756-6825 Dickinson, ND (701) 225-8123  
 Rugby, ND (701) 776-5727 Elgin, ND (701) 584-2681  
 Stanley, ND (701) 628-2120 Lemmon, SD (605) 374-3373  
 Velva, ND (701) 338-2828



JOHN DEERE

3117 Highway 52  
 Harvey, ND 58341  
 Phone: (701) 324-4631  
 www.gooseneckimplement.com

**SERVICE INVOICE**

Invoice To Account No: 100017906

Deliver To:

ROB MARCOTTE  
 145 53RD AVE SE  
 SYKESTON ND 58486  
  
 Bus Phone: (701)307-0645  
 Prv Phone:

ROB MARCOTTE  
 145 53RD AVE SE  
 SYKESTON ND 58486  
  
 Bus Phone: (701)307-0645  
 Prv Phone:

**Invoice Number: 11214876**  
 Invoice Date 12/30/2024  
 Location: 8  
 Work Order Number: 421634  
 Payment Type: Finance  
  
 Page: 1 of 5

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2100	1H0S680SCH0796342	1H0S680SCH0796342	

**S680H1153835 Retail**

**COMPLAINT:**

01 SEPARATOR TOP COVERS, R&R, REQUIRES 3 TECHNICIANS WITH RETHRESHER

**CORRECTION:**

**NOTE:**

- Approximate weight of rear top cover is 121 lb. (55 kg). Use three people in removal of top covers.
  - Approximate weight of front top cover is 49 lb. (22 kg). Use three people in removal of top covers.
  - Approximate weight of middle top cover is 124 lb. (56 kg). Use three people in removal of top covers.
- Open gull wing doors and remove separator covers.  
 Remove filler plates from both sides of separator.  
 Remove separator grates.  
 Remove engine covers.  
 If equipped with top cover vane adjust:  
 -Disconnect actuator and sensor connectors  
 -Move wiring harness  
 -Remove actuator and mounting brackets.  
 -Remove sensor.  
 Remove debris management system air tube.  
 With aid of others, remove cover out through engine compartment.  
 Remove feeder house top doors.  
 Remove hood.  
 Remove seal from between front and middle top covers.  
 Remove front top cover.  
 Remove spring pin from concave retainer.  
 Remove handle from each concave section.  
 Remove center concave.  
 Remove front seal from middle top cover.  
 With aid of others, remove cover out through engine compartment.  
 Inspect all parts for wear or damage.  
 Assemble in reverse order.

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
14M7299	FLANGE NUT	2.00	1.79	\$3.58	Y
19M7590	Cap Screw	1.00	5.06	\$5.06	Y
19M7784	SCREW	21.00	1.40	\$29.40	Y
19M7786	SCREW	24.00	1.63	\$39.12	Y
24M7178	WASHER	13.00	0.60	\$7.80	Y
24M7296	WASHER	16.00	1.16	\$18.56	Y
AH208966	COVER	1.00	751.26	\$751.26	N

**CONTINUED ON NEXT PAGE->**



3117 Highway 52  
 Harvey, ND 58341  
 Phone: (701) 324-4631  
 www.gooseneckimplement.com

Harvey, ND (701) 324-4631	Williston, ND (701) 572-6724
Kenmare, ND (701) 385-4227	Beach, ND (701) 872-3737
Minot, ND (701) 852-0767	Bowman, ND (701) 523-3252
Mohall, ND (701) 756-6825	Dickinson, ND (701) 225-8123
Rugby, ND (701) 776-5727	Elgin, ND (701) 584-2681
Stanley, ND (701) 628-2120	Lemmon, SD (605) 374-3373
Velva, ND (701) 338-2828	



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 100017906

Deliver To:

ROB MARCOTTE  
 145 53RD AVE SE  
 SYKESTON ND 58486  
  
 Bus Phone: (701)307-0645  
 Prv Phone:

ROB MARCOTTE  
 145 53RD AVE SE  
 SYKESTON ND 58486  
  
 Bus Phone: (701)307-0645  
 Prv Phone:

**Invoice Number: 11214876**  
 Invoice Date: 12/30/2024  
 Location: 8  
 Work Order Number: 421634  
 Payment Type: Finance  
  
 Page: 2 of 5

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2100	1H0S680SCH0796342	1H0S680SCH0796342	

Part Number	Description	Quantity	Unit Price	Total Price	Tax
AH233235	Cover	1.00	2,994.51	\$2,994.51	N
AXE18547	COVER	1.00	844.79	\$844.79	N
H135891	LOCK NUT	30.00	1.44	\$43.20	Y
H206370	FLANGE	1.00	289.60	\$289.60	N
H81330	ISOLATOR	1.00	16.78	\$16.78	N

**Labor: \$4,000.00    Parts: \$5,043.66    OL&M: \$0.00    Misc: \$0.00    Sub-Total: \$9,043.66**

**Segment 2 Retail**

**COMPLAINT:**

02 REPLACE CLEAN GRAIN CROSS AUGER, SPROCKET, KEY AND BEARINGS

**CORRECTION:**

TECH DUSTIN:  
 END OF SHAFT WAS MUSHROOMED  
 HEATED, SLICED, AND GROUND TO SMOOTH SURFACE  
 REMOVED BEARING HOUSING  
 FOUND BEARING AND HOUSING CRACKED  
 REMOVED CHAIN LINK  
 REMOVED CLEAN GRAIN HOUSING  
 REMOVED SPEED STONE  
 REMOVED CROSS AUGER  
 REPLACED BEARINGS  
 INSERTED NEW SHAFT  
 NEW BEARING HOUSING AND BEARINGS WITH LOCK COLLARS  
 INSTALLED HOUSING  
 ADJUSTED TENSION  
 RAN MACHINE  
 TESTED OK

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
03M7194	BOLT	4.00	1.71	\$6.84	Y
11M7012	COTTER PIN	3.00	0.30	\$0.90	Y
14M7296	FLANGE NUT	4.00	1.33	\$5.32	Y
19M7784	SCREW	16.00	1.40	\$22.40	Y
24M7296	WASHER	37.00	1.16	\$42.92	Y
49M6480	SHAFT KEY	1.00	3.13	\$3.13	Y

**CONTINUED ON NEXT PAGE->**



3117 Highway 52  
 Harvey, ND 58341  
 Phone: (701) 324-4631  
 www.gooseneckimplement.com

Harvey, ND (701) 324-4631	Williston, ND (701) 572-6724
Kenmare, ND (701) 385-4227	Beach, ND (701) 872-3737
Minot, ND (701) 852-0767	Bowman, ND (701) 523-3252
Mohall, ND (701) 756-6825	Dickinson, ND (701) 225-8123
Rugby, ND (701) 776-5727	Elgin, ND (701) 584-2681
Stanley, ND (701) 628-2120	Lemmon, SD (605) 374-3373
Velva, ND (701) 338-2828	



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 100017906

Deliver To:

ROB MARCOTTE  
 145 53RD AVE SE  
 SYKESTON ND 58486

Bus Phone: (701)307-0645  
 Prv Phone:

ROB MARCOTTE  
 145 53RD AVE SE  
 SYKESTON ND 58486

Bus Phone: (701)307-0645  
 Prv Phone:

<b>Invoice Number:</b>	<b>11214876</b>
Invoice Date	12/30/2024
Location:	8
Work Order Number:	421634
Payment Type:	Finance
Page:	3 of 5

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2100	1H0S680SCH0796342	1H0S680SCH0796342	

Part Number	Description	Quantity	Unit Price	Extended Price	Tax
AH133191	ECCENTRIC	1.00	16.99	\$16.99	N
AH227464	SPACER	1.00	54.93	\$54.93	N
AXE23392	BEARING WI	1.00	147.03	\$147.03	N
AXE59539	AUGER	1.00	1,200.00	\$1,200.00	N
H103264	PRESSED FL	1.00	2.50	\$2.50	N
H152940	GASKET	1.00	2.67	\$2.67	N
H208187	Screw	21.00	4.75	\$99.75	Y
H228383	CHAIN SPROCKET	1.00	57.48	\$57.48	N
JD39102	BALL BEARI	1.00	22.26	\$22.26	N

**Labor: \$900.00    Parts: \$1,685.12    OL&M: \$0.00    Misc: \$0.00    Sub-Total: \$2,585.12**

**Segment 3 Retail**

**COMPLAINT:**

03 REMOVE CHAFFER AND REPLACE MISSING LOUVERS, 4 BROKEN

**CORRECTION:**

TECH DUSTIN:  
 REMOVED MOTOR COVER  
 REMOVED CHAFFER  
 CLEANED OUT SPRING GUIDES  
 REMOVED MOTOR AND MANUAL ADJUST  
 INSPECTED FOUND NEEDED NEW GUIDES AND MORE LOUVERS  
 CONTACTED CUSTOMER SAID MORE NEEDED TO BE REPLACED  
 AGREED TO INSTALL NEW CHAFFER

REMOVED ACTUATOR  
 REMOVED DIVIDERS  
 INSTALLED DIVIDERS  
 INSTALLED MOTORS  
 INSTALLED NEW CHAFFER  
 CALIBRATED CHAFFER

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
AXE62796	Chaffer	1.00	2,578.04	\$2,578.04	N

**CONTINUED ON NEXT PAGE->**



3117 Highway 52  
 Harvey, ND 58341  
 Phone: (701) 324-4631  
 www.gooseneckimplement.com

Harvey, ND (701) 324-4631	Williston, ND (701) 572-6724
Kenmare, ND (701) 385-4227	Beach, ND (701) 872-3737
Minot, ND (701) 852-0767	Bowman, ND (701) 523-3252
Mohall, ND (701) 756-6825	Dickinson, ND (701) 225-8123
Rugby, ND (701) 776-5727	Elgin, ND (701) 584-2681
Stanley, ND (701) 628-2120	Lemmon, SD (605) 374-3373
Velva, ND (701) 338-2828	



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 100017906

Deliver To:

ROB MARCOTTE  
 145 53RD AVE SE  
 SYKESTON ND 58486  
  
 Bus Phone: (701)307-0645  
 Prv Phone:

ROB MARCOTTE  
 145 53RD AVE SE  
 SYKESTON ND 58486  
  
 Bus Phone: (701)307-0645  
 Prv Phone:

<b>Invoice Number:</b>	<b>11214876</b>
Invoice Date	12/30/2024
Location:	8
Work Order Number:	421634
Payment Type:	Finance
Page:	4 of 5

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE S680	2100	1H0S680SCH0796342	1H0S680SCH0796342	

**Labor: \$600.00    Parts: \$2,578.04    OL&M: \$0.00    Misc: \$0.00    Sub-Total: \$3,178.04**

**/S670ACTIVECONCAVE Retail**

COMPLAINT:

04 CONCAVE R&R WITH ACTIVE CONCAVE

CORRECTION:

Techs Dustin and Kyler:  
 installed each individual separator grates  
 installed concaves and leveled out  
 installed adjustment motor  
 re-leveled concaves again  
 torqued bolts to spec  
 re-assembled concave housing and covers  
 ran machine

**Labor: \$1,000.00    Parts: \$0.00    OL&M: \$0.00    Misc: \$0.00    Sub-Total: \$1,000.00**

**/PROMO\_COMBINEGOLD Retail**

COMPLAINT:

05 PREMIUM COMBINE INSPECTION (GOLD LEVEL)

CORRECTION:

TECH DUSTIN:  
 COMPLETED INSPECTION  
 CALLED CUSTOMER AND WENT THROUGH WHAT I HAD FOUND INTO THE INSPECTION  
 WE ARE ONLY GOING TO DO THE ROTOR COVERS, CLEAN GRAIN AUGER, KEY AND SPROCKET, AND FIX THE CHAFFER  
 LOUVERS  
 NO QUOTE MADE, MY INSPECTION PAPER SCANNED INTO DOCUMENTS, AND COPY LEFT WITH CUSTOMERS COMBINE AS  
 WELL  
 SEGMENTS WILL BE ADDED TO THE ROTOR COVER WORK ORDER 421634

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
00343	TOTAL POWER	1.00	21.00	\$21.00	Y
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>

**CONTINUED ON NEXT PAGE->**