



**TRUE NORTH EQUIPMENT**  
5101 Gateway Drive  
Grand Forks, ND 58203-1109  
[www.truenorthequipment.com](http://www.truenorthequipment.com)

Grafton, ND (701) 352-1401  
Grand Forks, ND (701) 746-4436  
Kennedy, MN (218) 674-4111  
Northwood, ND (701) 587-5050  
Warren, MN (218) 745-4516  
Thief River Falls, MN (218) 681-1131  
Mahnomon, MN (218) 935-2241  
Baudette, MN (218) 634-2231



**JOHN DEERE**

Invoice To Account No: 53143

Deliver To:

## SERVICE INVOICE

JOHNSON STOCK FARM WAYNE/KEITH JOHNSON 13341 16TH ST NE SHARON ND 58277	JOHNSON STOCK FARM 13341 16TH ST NE SHARON ND 58277	<b>Invoice Number:</b> 10040173
Bus Phone: 701-543-3793	Bus Phone: (701)543-3793	Invoice Date: 11/6/2019
Prv Phone:	Prv Phone:	Location: 02
		Work Order Number: 211915
		Payment Type: Finance
		Page: 1 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 7420	8967	RW7420D004371	RW7420D004371	

### \*\*SEGMENT 1 Retail

#### COMPLAINT:

01 CAN TERMINATOR WIRES ON THE RH SIDE

#### CORRECTION:

Removed the wiring harness for the back of the tractor, ran new harness and installed connectors.

T219

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AL159763	Wiring Harness	1.00	319.52	319.52	\$319.52	N
<b>Labor: \$70.00</b>	<b>Parts: \$319.52</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$0.00</b>	<b>Sub-Total: \$389.52</b>		

### 7420/7555/RPO/10 Retail

#### COMPLAINT:

03 SEAL REAR PTO OUTPUT - REMOVE & INSTALL

REMOVE & INSTALL REAR PTO OUTPUT SEAL

Drain hydraulic oil.

Pry seal protector off.

Remove seal.

Reassemble in reverse order.

Fill hydraulic system to proper level.

#### CORRECTION:

REMOVED & INSTALLED REAR PTO OUTPUT SEAL  
Drained hydraulic oil  
Pried seal protector off  
Removed seal  
Reassembled in reverse order  
Filled hydraulic system to proper level

T219

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE38725	SEAL	1.00	31.50	31.50	\$31.50	N
<b>Labor: \$231.00</b>	<b>Parts: \$31.50</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$0.00</b>	<b>Sub-Total: \$262.50</b>		

CONTINUED ON NEXT PAGE->



**TRUE NORTH EQUIPMENT**  
 5101 Gateway Drive  
 Grand Forks, ND 58203-1109  
[www.truenorthequipment.com](http://www.truenorthequipment.com)

Grafton, ND (701) 352-1401  
 Grand Forks, ND (701) 746-4436  
 Kennedy, MN (218) 674-4111  
 Northwood, ND (701) 587-5050  
 Warren, MN (218) 745-4516  
 Thief River Falls, MN (218) 681-1131  
 Mahnomen, MN (218) 935-2241  
 Baudette, MN (218) 634-2231



**JOHN DEERE**

Invoice To Account No: 53143

Deliver To:

## SERVICE INVOICE

JOHNSON STOCK FARM WAYNE/KEITH JOHNSON 13341 16TH ST NE SHARON ND 58277	JOHNSON STOCK FARM 13341 16TH ST NE SHARON ND 58277	<b>Invoice Number:</b> 10040173
Bus Phone: 701-543-3793	Bus Phone: (701)543-3793	Invoice Date: 11/6/2019
Prv Phone:	Prv Phone:	Location: 02
		Work Order Number: 211915
		Payment Type: Finance
		Page: 2 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 7420	8967	RW7420D004371	RW7420D004371	

### 7420/1501/TO/10 Retail

#### COMPLAINT:

05 DAMPNER TORSIONAL - REMOVE & INSTALL

REMOVE & INSTALL TORSIONAL DAMPNER

#### CORRECTION:

Removed & Installed Torsional Dampner

Took old damper off, cleaned up shaft on the flywheel. Installed bushings on the bearing housing. Installed bearing housing and torsional damper. Torqued bolts and cleaned up.

T219

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7938	CAP SCREW	1.00	1.02	1.02	\$1.02	Y
19M7981	CAP SCREW	6.00	1.85	1.85	\$11.10	Y
AL81266	Torsional Damper	1.00	1,014.39	1,014.39	\$1,014.39	N
L102291	Bearing Housing W/O Bearing	1.00	47.57	47.57	\$47.57	N
L112001	Bushing	2.00	8.97	8.97	\$17.94	N
<b>Labor: \$168.00</b>		<b>Parts: \$1,092.02</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$0.00</b>	<b>Sub-Total: \$1,260.02</b>	

### 7420/6603/SLL/20 Retail

#### COMPLAINT:

06 PIVOT STEERING COLUMN - RECONDITION

RECONDITION STEERING COLUMN PIVOT

(Note: Includes Remove & Install).

Disassemble steering column cowl.

Remove all HVAC duct work.

Disassemble steering column pivot assembly.

Recondition steering column pivot as required.

Reinstall in reverse order.

Adjust and test for proper operation.

CONTINUED ON NEXT PAGE->



**TRUE NORTH EQUIPMENT**  
 5101 Gateway Drive  
 Grand Forks, ND 58203-1109  
[www.truenorthequipment.com](http://www.truenorthequipment.com)

Grafton, ND (701) 352-1401  
 Grand Forks, ND (701) 746-4436  
 Kennedy, MN (218) 674-4111  
 Northwood, ND (701) 587-5050  
 Warren, MN (218) 745-4516  
 Thief River Falls, MN (218) 681-1131  
 Mahnomen, MN (218) 935-2241  
 Baudette, MN (218) 634-2231



**JOHN DEERE**

Invoice To Account No: 53143

Deliver To:

## SERVICE INVOICE

JOHNSON STOCK FARM WAYNE/KEITH JOHNSON 13341 16TH ST NE SHARON ND 58277	JOHNSON STOCK FARM 13341 16TH ST NE SHARON ND 58277	<b>Invoice Number:</b> 10040173
Bus Phone: 701-543-3793	Bus Phone: (701)543-3793	Invoice Date: 11/6/2019
Prv Phone:	Prv Phone:	Location: 02
		Work Order Number: 211915
		Payment Type: Finance
		Page: 3 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 7420	8967	RW7420D004371	RW7420D004371	

### 7420/6603/SLL/20 Retail

#### CORRECTION:

Removed the steering wheel, cowl and then the steering column assembly. Pounded out the pin and removed the shock. Installed the new shock and installed the steering column assembly. Once the assembly was in I installed the cowl and any electrical harnesses that were disconnected.

T219

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
37M7286	Screw	4.00	0.88	0.88	\$3.52	N
57M7250	Elec. Connector Terminal	3.00	0.45	0.45	\$1.35	N
AL222225	Gas Operated Cylinder	1.00	94.80	94.80	\$94.80	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
3750	FREIGHT	1.00	21.00	21.00	\$21.00	N
<b>Labor: \$462.00</b>		<b>Parts: \$99.67</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$21.00</b>	<b>Sub-Total: \$582.67</b>	

### \*\*SEGMENT 9 Retail

#### COMPLAINT:

09 MFWD CLUTCH AND DRIVE GEAR RECONDITION

#### CORRECTION:

**JOHN DEERE**



**TRUE NORTH EQUIPMENT**  
5101 Gateway Drive  
Grand Forks, ND 58203-1109  
[www.truenorthequipment.com](http://www.truenorthequipment.com)

Grafton, ND (701) 352-1401  
Grand Forks, ND (701) 746-4436  
Kennedy, MN (218) 674-4111  
Northwood, ND (701) 587-5050  
Warren, MN (218) 745-4516  
Thief River Falls, MN (218) 681-1131  
Mahnomon, MN (218) 935-2241  
Baudette, MN (218) 634-2231



**JOHN DEERE**

Invoice To Account No: 53143

Deliver To:

## SERVICE INVOICE

JOHNSON STOCK FARM WAYNE/KEITH JOHNSON 13341 16TH ST NE SHARON ND 58277	JOHNSON STOCK FARM 13341 16TH ST NE SHARON ND 58277	<b>Invoice Number:</b> 10040173
Bus Phone: 701-543-3793	Bus Phone: (701)543-3793	Invoice Date: 11/6/2019
Prv Phone:	Prv Phone:	Location: 02
		Work Order Number: 211915
		Payment Type: Finance
		Page: 4 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 7420	8967	RW7420D004371	RW7420D004371	

### \*\*SEGMENT 9 Retail

Had the mfwd clutch out when I removed the transmission. Talked the customer into rebuilding the mfwd clutch since he said it was slipping periodically. Put the clutch out on a bench and removed the outer bearing cup. Removed the shaft and then the clutch. Went to the press and pressed the belleville spring down. Removed the snap ring and let off the press. Went back to the bench and disassembled. Found some of the clutch packs were worn down but nothing that I could see of slipping much. Ordered the parts I needed and went on to removing the mfwd drive gear. Removed the eight bolts holding it onto the differential. Removed the intermediate shaft and mfwd drive gear. Looked on how to take intermediate shaft apart, had to press the shaft through the first bearing then remove the snap ring holding the gear onto the shaft. Separated the two halves so I could get the gear out. Determined that the bearings needed to be replaced so I started cleaning and measuring cone point adjustment for the differential drive shaft. As much as measured and remeasured I could not get the right cone point adjustment. Installed the .045 thousandths shims and put the rest of the housing back together. after a few attempts and setting my end play i finally got .0005 thousandths. Which was in spec. mounted up the differential drive shaft and torqued bolts. Updated the Dtac case and wondered what the measurement should be for the gap between the pinion gear and the differential gear. Went back to the mfwd clutch and started putting everything back together. Got the clutch back together and was starting to put the clutch back into the housing when I noticed the housing was bad where the end of the shaft goes. The shaft has two metal seals that had wore into the housing. Called the customer and he said to replace it. Once the new one came in I tried to install the clutch again. Installed the piston and spring. Set the snap ring and went to install the clutch into the housing. Once I got the clutch into the housing and the shaft through the clutch I lined up the bearing cone and thrust washers. Went to install the outer bearing cup and shims. Installed housing and torqued bolts.

T219

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7139	CAP SCREW	-3.00	0.95	0.95	(\$2.85)	Y
19M9370	Screw	1.00	1.20	1.20	\$1.20	Y
24M7051	WASHER	-1.00	1.31	1.31	(\$1.31)	Y
51M7041	O-RING	1.00	1.98	1.98	\$1.98	N
51M7043	O-RING	-2.00	2.22	2.22	(\$4.44)	N
AL204621	Sensor	2.00	78.71	78.71	\$157.42	N
AL71169	Bearing	1.00	47.54	47.54	\$47.54	N
AL79750	Seal	1.00	27.72	27.72	\$27.72	N
C19243	Snap Ring	1.00	10.19	10.19	\$10.19	N
JD10527	BEARING CO	1.00	29.98	29.98	\$29.98	N
JD8247	BEARING CUP	1.00	8.33	8.33	\$8.33	N

CONTINUED ON NEXT PAGE->



**TRUE NORTH EQUIPMENT**  
 5101 Gateway Drive  
 Grand Forks, ND 58203-1109  
[www.truenorthequipment.com](http://www.truenorthequipment.com)

Grafton, ND (701) 352-1401  
 Grand Forks, ND (701) 746-4436  
 Kennedy, MN (218) 674-4111  
 Northwood, ND (701) 587-5050  
 Warren, MN (218) 745-4516  
 Thief River Falls, MN (218) 681-1131  
 Mahnomen, MN (218) 935-2241  
 Baudette, MN (218) 634-2231



**JOHN DEERE**

Invoice To Account No: 53143

Deliver To:

## SERVICE INVOICE

JOHNSON STOCK FARM WAYNE/KEITH JOHNSON 13341 16TH ST NE SHARON ND 58277	JOHNSON STOCK FARM 13341 16TH ST NE SHARON ND 58277	<b>Invoice Number:</b> 10040173
Bus Phone: 701-543-3793	Bus Phone: (701)543-3793	Invoice Date: 11/6/2019
Prv Phone:	Prv Phone:	Location: 02
		Work Order Number: 211915
		Payment Type: Finance
		Page: 5 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 7420	8967	RW7420D004371	RW7420D004371	

### \*\*SEGMENT 9 Retail

JD8258	BEARING CU	1.00	17.63	17.63	\$17.63	N
JD8971	Bearing Cone	1.00	44.67	44.67	\$44.67	N
L112786	Disk Spring	1.00	52.52	52.52	\$52.52	N
L112787	Ring	1.00	7.31	7.31	\$7.31	N
L115178	O-Ring	1.00	6.07	6.07	\$6.07	N
L158906	Snap Ring	1.00	10.57	10.57	\$10.57	N
L168886	Shim	-3.00	6.71	6.71	(\$20.13)	N
L220965	Spacer	1.00	54.56	54.56	\$54.56	N
R107620	THRUST WASHE	2.00	10.32	10.32	\$20.64	N
R115998	SHIM	4.00	1.61	1.61	\$6.44	N
R115999	SHIM	1.00	1.84	1.84	\$1.84	N
R116000	SHIM	3.00	2.18	2.18	\$6.54	N
R154996	Impeller	2.00	11.32	11.32	\$22.64	N
R154997	Thrust Washer	1.00	25.23	25.23	\$25.23	N
R154998	Thrust Washer	1.00	3.66	3.66	\$3.66	N
R155027	Seal	1.00	5.57	5.57	\$5.57	N
R158123	Helical Gear	1.00	673.79	673.79	\$673.79	N
R271542	DISK	7.00	25.48	25.48	\$178.36	N
R31401	Piston Ring	1.00	26.34	26.34	\$26.34	N
R35365	SHIM	2.00	2.86	2.86	\$5.72	N
R35366	SHIM	3.00	3.33	3.33	\$9.99	N
R35367	SHIM	4.00	4.12	4.12	\$16.48	N
R39283	RING	2.00	8.34	8.34	\$16.68	N
R49002	SHIM	1.00	2.19	2.19	\$2.19	N

CONTINUED ON NEXT PAGE->



**TRUE NORTH EQUIPMENT**  
 5101 Gateway Drive  
 Grand Forks, ND 58203-1109  
 www.truenorthequipment.com

Grafton, ND (701) 352-1401  
 Grand Forks, ND (701) 746-4436  
 Kennedy, MN (218) 674-4111  
 Northwood, ND (701) 587-5050  
 Warren, MN (218) 745-4516  
 Thief River Falls, MN (218) 681-1131  
 Mahnomen, MN (218) 935-2241  
 Baudette, MN (218) 634-2231



**JOHN DEERE**

Invoice To Account No: 53143

Deliver To:

## SERVICE INVOICE

JOHNSON STOCK FARM WAYNE/KEITH JOHNSON 13341 16TH ST NE SHARON ND 58277	JOHNSON STOCK FARM 13341 16TH ST NE SHARON ND 58277	<b>Invoice Number:</b> 10040173
Bus Phone: 701-543-3793	Bus Phone: (701)543-3793	Invoice Date: 11/6/2019
Prv Phone:	Prv Phone:	Location: 02
		Work Order Number: 211915
		Payment Type: Finance
		Page: 6 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 7420	8967	RW7420D004371	RW7420D004371	

### \*\*SEGMENT 9 Retail

R49003	Shim	1.00	2.55	2.55	\$2.55	N
R49004	Shim	1.00	2.84	2.84	\$2.84	N
R51200	LOCK NUT	1.00	20.06	20.06	\$20.06	N
R62673	O-RING	1.00	3.41	3.41	\$3.41	N
RE211156	SOLENOID VALVE	1.00	207.09	207.09	\$207.09	N
RE238208	Housing	1.00	1,994.55	1,994.55	\$1,994.55	N
RE326611	CLUTCH DISK	6.00	34.79	34.79	\$208.74	N
RE46684	FITTING PL	1.00	5.51	5.51	\$5.51	N
RE49486	Tapered Roller Bearing	1.00	314.40	314.40	\$314.40	N
TY26101	BRAKE/CLUTCH SPRAY	1.00	5.22	5.17	\$5.17	Y
U43360	O-RING	1.00	4.26	4.26	\$4.26	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
3750	FREIGHT	2.00	11.75	11.75	\$23.50	N

**Labor: \$3,080.00    Parts: \$4,239.65    OL&M: \$0.00    Misc: \$23.50    Sub-Total: \$7,343.15**

### ###AG-DIAGNOSTICS Retail

COMPLAINT:

10 AG DIAGNOSTICS- AIR SEAT LEAKS DOWN?

CORRECTION:

Aired up the seat and took down the apron. Sprayed soapy water around and could not find anything leaking. Seat aired up fine.

T219

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------

CONTINUED ON NEXT PAGE->





**TRUE NORTH EQUIPMENT**  
5101 Gateway Drive  
Grand Forks, ND 58203-1109  
[www.truenorthequipment.com](http://www.truenorthequipment.com)

Grafton, ND (701) 352-1401  
Grand Forks, ND (701) 746-4436  
Kennedy, MN (218) 674-4111  
Northwood, ND (701) 587-5050  
Warren, MN (218) 745-4516  
Thief River Falls, MN (218) 681-1131  
Mahnomon, MN (218) 935-2241  
Baudette, MN (218) 634-2231



**JOHN DEERE**

Invoice To Account No: 53143

Deliver To:

## SERVICE INVOICE

JOHNSON STOCK FARM WAYNE/KEITH JOHNSON 13341 16TH ST NE SHARON ND 58277	JOHNSON STOCK FARM 13341 16TH ST NE SHARON ND 58277	<b>Invoice Number:</b> 10040173
Bus Phone: 701-543-3793	Bus Phone: (701)543-3793	Invoice Date: 11/6/2019
Prv Phone:	Prv Phone:	Location: 02
		Work Order Number: 211915
		Payment Type: Finance
		Page: 7 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 7420	8967	RW7420D004371	RW7420D004371	

### ###AG-DIAGNOSTICS Retail

L154067	Push Nut	4.00	1.07	1.07	\$4.28	N
<b>Labor: \$56.00</b>	<b>Parts: \$4.28</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$0.00</b>	<b>Sub-Total: \$60.28</b>		

### 7420/3030/IVT/10 Retail

COMPLAINT:

11 TRANSMISSION IVT- REMOVE & INSTALL

REMOVE AND INSTALL REMAN TRANSMISSION, TRANSMISSION WAS TRANSFERRED FROM NWD PARTS

### CORRECTION:

Brought the tractor into the shop. Sucked down the a/c system and also drained the coolant. Drained the transmission and differential case. Disconnected electrical assemblies and hydraulic hoses. Removed the exhaust pipe and the low side hose from the compressor. Removed the battery jumper assembly from the bottom of the cab on the right hand side. Removed the steps from the cab. Disconnected the coolant hoses from the heater core. Steering and brake hoses were disconnected and the loader push pull cables along with the electrical wiring harness. Lifted the cab up a foot and removed all other lines. Removed the park release cable through the floor board of the cab. Removed the cab and set aside. Removed the transmission wiring harness and any hoses connected to the transmission. Removed the filter at the front of the transmission and also the drive shaft between the engine and transmission. Removed the cooler also. Once the cooler was off I removed the bolts holding the transmission to the differential and removed the transmission. Once it was out I set that aside and called the customer. Talked with the customer on a few things that needed to be done along with the transmission. He wanted to replace pretty much everything I said needed to be replaced. Engine dampener, oil cooler and lines, u-joints on the drive shaft between engine and transmission and so on. Ordered all the parts I would think I needed and started to take apart things. Went and took apart the mfwd clutch assembly. Also the u-joints for the drive shaft. Once everything was done I installed the new transmission and a new transmission harness. Installed the new cooler and new drive shaft since it would have cost more to rebuild the drive shaft than to just replace it. Once that was all done I installed a new transmission harness and any lines that I had removed. Torqued everything and verified that it was tight. Went and installed the cab and torqued cab bolts. Connected all the hoses and electrical assembly's that I had removed to take the cab off. Installed and adjusted the push pull cables for the loader. Installed the a/c line and replaced the receiver dryer. Filled with 3.3 pounds of freon. Filled the cooling system with 8 gallons of coolant. Filled the transmission with oil. Ran the tractor around and verified everything ran smooth. Cleaned up the stall and put tools away.

T219

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
11M7021	COTTER PIN	1.00	0.64	0.64	\$0.64	Y
11M7023	COTTER PIN	1.00	0.70	0.70	\$0.70	Y

CONTINUED ON NEXT PAGE->



**TRUE NORTH EQUIPMENT**  
 5101 Gateway Drive  
 Grand Forks, ND 58203-1109  
[www.truenorthequipment.com](http://www.truenorthequipment.com)

Grafton, ND (701) 352-1401  
 Grand Forks, ND (701) 746-4436  
 Kennedy, MN (218) 674-4111  
 Northwood, ND (701) 587-5050  
 Warren, MN (218) 745-4516  
 Thief River Falls, MN (218) 681-1131  
 Mahnomen, MN (218) 935-2241  
 Baudette, MN (218) 634-2231



**JOHN DEERE**

Invoice To Account No: 53143

Deliver To:

## SERVICE INVOICE

JOHNSON STOCK FARM WAYNE/KEITH JOHNSON 13341 16TH ST NE SHARON ND 58277	JOHNSON STOCK FARM 13341 16TH ST NE SHARON ND 58277	<b>Invoice Number:</b> 10040173
Bus Phone: 701-543-3793	Bus Phone: (701)543-3793	Invoice Date: 11/6/2019
Prv Phone:	Prv Phone:	Location: 02
		Work Order Number: 211915
		Payment Type: Finance
		Page: 8 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 7420	8967	RW7420D004371	RW7420D004371	

### 7420/3030/IVT/10 Retail

14M7410	Lock Nut	1.00	3.49	3.49	\$3.49	N
19M7139	CAP SCREW	3.00	0.95	0.95	\$2.85	Y
19M8241	CAP SCREW	2.00	2.58	2.58	\$5.16	Y
24M7051	WASHER	1.00	1.31	1.31	\$1.31	Y
34M7124	Spring Pin	1.00	1.47	1.47	\$1.47	N
51M7043	O-RING	2.00	2.22	2.22	\$4.44	N
A4540R	O-RING	1.00	5.31	5.31	\$5.31	N
AL117414	Universal Driveshaft	1.00	514.17	514.17	\$514.17	N
AL155400	Fitting	4.00	54.54	54.54	\$218.16	N
AL155882	Oil Line	1.00	105.36	105.36	\$105.36	N
AL159249	Oil Cooler	1.00	1,169.00	1,169.00	\$1,169.00	N
AL160012	Hose	1.00	111.30	111.30	\$111.30	N
AL160013	Hose	1.00	148.38	148.38	\$148.38	N
AL160704	Wiring Harness	1.00	539.23	539.23	\$539.23	N
AL172814	MODULE REMAN	1.00	28,911.17	28,911.17	\$28,911.17	N
AL172814-CR	CORE for:Transmission Reman	-1.00	6,000.00	6,000.00	(\$6,000.00)	N
AL203061	Oil Filter	1.00	83.29	83.29	\$83.29	N
AL220792	Receiver-Dryer	1.00	109.11	109.11	\$109.11	N
AL64588	CLAMP	4.00	3.26	3.26	\$13.04	N
AL76568	KNOB	1.00	10.76	10.76	\$10.76	N
HYGARD	HYGARD BULK QTS	98.00	3.55	3.55	\$347.90	N
JD8856	Needle Bearing	1.00	4.31	4.31	\$4.31	N
JD9812	THRUST BEA	2.00	1.27	1.27	\$2.54	N
L114670	O-RING	1.00	1.50	1.50	\$1.50	N

CONTINUED ON NEXT PAGE->





**TRUE NORTH EQUIPMENT**  
 5101 Gateway Drive  
 Grand Forks, ND 58203-1109  
[www.truenorthequipment.com](http://www.truenorthequipment.com)

Grafton, ND (701) 352-1401  
 Grand Forks, ND (701) 746-4436  
 Kennedy, MN (218) 674-4111  
 Northwood, ND (701) 587-5050  
 Warren, MN (218) 745-4516  
 Thief River Falls, MN (218) 681-1131  
 Mahnomen, MN (218) 935-2241  
 Baudette, MN (218) 634-2231



**JOHN DEERE**

Invoice To Account No: 53143

Deliver To:

## SERVICE INVOICE

JOHNSON STOCK FARM WAYNE/KEITH JOHNSON 13341 16TH ST NE SHARON ND 58277	JOHNSON STOCK FARM 13341 16TH ST NE SHARON ND 58277	<b>Invoice Number:</b> 10040173
Bus Phone: 701-543-3793	Bus Phone: (701)543-3793	Invoice Date: 11/6/2019
Prv Phone:	Prv Phone:	Location: 02
		Work Order Number: 211915
		Payment Type: Finance
		Page: 9 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 7420	8967	RW7420D004371	RW7420D004371	

### 7420/3030/IVT/10 Retail

L150601	GASKET	1.00	1.56	1.56	\$1.56	N
L153368	GASKET	1.00	12.00	12.00	\$12.00	N
L153369	Gasket	1.00	7.21	7.21	\$7.21	N
L153592	Cover	1.00	52.90	52.90	\$52.90	N
L154848	Hose	1.00	15.58	15.58	\$15.58	N
L155512	Hose	1.00	18.84	18.84	\$18.84	N
L157400	Washer	4.00	26.88	26.88	\$107.52	N
L157435	Spacer	2.00	55.10	55.10	\$110.20	N
L157513	Clamp	4.00	3.54	3.54	\$14.16	N
L168886	Shim	3.00	6.71	6.71	\$20.13	N
L169406	Grommet	3.00	4.28	4.28	\$12.84	N
L220642	CAM	1.00	264.56	264.56	\$264.56	N
L76782	Sleeve	4.00	15.39	15.39	\$61.56	N
L77173	Cap Screw	4.00	2.05	2.05	\$8.20	N
L80445	Cap Screw	4.00	3.17	3.17	\$12.68	N
PM38657	HI-FLEX FORM A GASKET	1.00	20.07	19.87	\$19.87	Y
R10093	O-RING	2.00	1.19	1.19	\$2.38	N
R111173	ISOLATOR	4.00	24.26	24.26	\$97.04	N
R120901	GASKET	1.00	3.59	3.59	\$3.59	N
R33259	O-RING	1.00	1.62	1.62	\$1.62	N
R66375	Isolator	4.00	24.06	24.06	\$96.24	N
R66670	ROLLER	1.00	12.93	12.93	\$12.93	N
T77613	O-RING	2.00	1.44	1.44	\$2.88	N
T77857	O-RING	5.00	1.48	1.48	\$7.40	N

CONTINUED ON NEXT PAGE->



**TRUE NORTH EQUIPMENT**  
 5101 Gateway Drive  
 Grand Forks, ND 58203-1109  
[www.truenorthequipment.com](http://www.truenorthequipment.com)

Grafton, ND (701) 352-1401  
 Grand Forks, ND (701) 746-4436  
 Kennedy, MN (218) 674-4111  
 Northwood, ND (701) 587-5050  
 Warren, MN (218) 745-4516  
 Thief River Falls, MN (218) 681-1131  
 Mahnomen, MN (218) 935-2241  
 Baudette, MN (218) 634-2231



**JOHN DEERE**

Invoice To Account No: 53143

Deliver To:

## SERVICE INVOICE

JOHNSON STOCK FARM WAYNE/KEITH JOHNSON 13341 16TH ST NE SHARON ND 58277	JOHNSON STOCK FARM 13341 16TH ST NE SHARON ND 58277	<b>Invoice Number:</b> 10040173
Bus Phone: 701-543-3793	Bus Phone: (701)543-3793	Invoice Date: 11/6/2019
Prv Phone:	Prv Phone:	Location: 02
		Work Order Number: 211915
		Payment Type: Finance
		Page: 10 of 11

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 7420	8967	RW7420D004371	RW7420D004371	

### 7420/3030/IVT/10 Retail

TY15951	REFRIGERANT R134	3.30	24.29	24.29	\$80.16	Y
TY22465	HOSE CLAMP	2.00	1.02	1.01	\$2.02	Y
TY26578G	BULK ANTI-FREEZE	8.00	13.49	13.49	\$107.92	N

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
3750	FREIGHT	1.00	16.00	16.00	\$16.00	N

**Labor: \$7,392.00      Parts: \$27,468.58      OL&M: \$0.00      Misc: \$16.00      Sub-Total: \$34,876.58**

### 7420/1401/10 Retail

#### COMPLAINT:

13 BATTERY - REMOVE & INSTALL

#### REMOVE & INSTALL BATTERY

Remove and install battery.

Includes cleaning cables for assembly as required.

#### CORRECTION:

Removed & Installed batteryIncluded cleaning cables for assembly as required

Had to replace the battery since the old one wouldn't keep a charge.

T219

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



CONTINUED ON NEXT PAGE->



**TRUE NORTH EQUIPMENT**  
5101 Gateway Drive  
Grand Forks, ND 58203-1109  
[www.truenorthequipment.com](http://www.truenorthequipment.com)

Grafton, ND (701) 352-1401  
Grand Forks, ND (701) 746-4436  
Kennedy, MN (218) 674-4111  
Northwood, ND (701) 587-5050  
Warren, MN (218) 745-4516  
Thief River Falls, MN (218) 681-1131  
Mahnomen, MN (218) 935-2241  
Baudette, MN (218) 634-2231



**JOHN DEERE**

Invoice To Account No: 53143

Deliver To:

## SERVICE INVOICE

JOHNSON STOCK FARM WAYNE/KEITH JOHNSON 13341 16TH ST NE SHARON ND 58277  Bus Phone: 701-543-3793 Prv Phone:	JOHNSON STOCK FARM 13341 16TH ST NE SHARON ND 58277  Bus Phone: (701)543-3793 Prv Phone:	<b>Invoice Number:</b> 10040173 <b>Invoice Date:</b> 11/6/2019 <b>Location:</b> 02 <b>Work Order Number:</b> 211915 <b>Payment Type:</b> Finance  <b>Page:</b> 11 of 11
---	---	---

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 7420	8967	RW7420D004371	RW7420D004371	

<b>7420/1401/10 Retail</b> TY26782A	Wet Charged Battery	1.00	367.59	367.59	\$367.59	Y
<b>Labor: \$92.40</b>	<b>Parts: \$367.59</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$0.00</b>	<b>Sub-Total: \$459.99</b>		

INVOICE CONTAINS \$0.27 DISCOUNT

### Miscellaneous Charges:

Service Accessories	\$150.00
EPA Disposal Fee	\$5.00

### Finance Information

<b>Customer PO No:</b>	<b>Type:</b> Multi-use Acct US	<b>Auth. No:</b> 630423	<b>Labor:</b> \$11,551.40
<b>Tax Exempt No:</b> CONV	<b>Merchant No:</b> 55000324		<b>Parts:</b> \$33,622.81
<b>Advisor:</b> JOSH BURIANEK	<b>Card No:</b> xxxxxxxxxxx8281		<b>OL&amp;M:</b> \$0.00
	<b>Bill Code:</b> 704 - JD TRACTOR PARTS/SERVICE		<b>Misc:</b> \$215.50
	<b>Credit Plan:</b> 11435 - 365 Days NP/NI (12 Months)		<b>Sales Tax:</b> \$35.86
			<b>Grand Total:</b> \$45,425.57

\*\*\* DOCUMENT COPY \*\*\*

JOHN DEERE

### TERMS AND CONDITIONS

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by: .....Date: .....