

RMACs Truck & Equipment

814 E. Santa Fe Blvd.
 Ellinwood, KS 67526
 Phone 620-564-2643

Invoice

Date	Invoice #
9/22/2025	75608
	S.O. No.
	898

Bill To
Tom Snell Harvesting 509 W. 6th Ellinwood Ks 67526

Rep	Year	Make	Unit #	Mileage	Vin #
	2022	Freightliner 1225D	58	76,229	3AKJGNDV3PDUH7658
Quantity	Item Code	Description	Price Each	Core	Amount
1	Part	A22-66694-104 A/C Line	248.99		248.99
1	Part	CL108825-25 Clutch	1,080.92		1,080.92
1	FLYWHEEL	RESURFACED FLYWHEEL	125.00		125.00
1	306DD-SWTC	Pilot BRG	16.40		16.40
1	SCB200.440-ITP	2" CLUTCH BRAKE	43.46		43.46
1	Part	05-21934-000 Upper Rad Hose	77.71		77.71
1	24010-PERM	Thread Locking Compound	17.86		17.86
1	27010-PERM	Thread Locking Compound	18.65		18.65
1	G218-LIN	Grease Gun Hose	10.75		10.75
1	203200-EDE	Brass Fitting	1.92		1.92
8	16RLA-AUS	Hose HS	0.58		4.64
5	24840-GAT	2-1/2" SILICONE HOSE (BY INCH) HS	4.13		20.65
1	4305294-SWTP	Tower Gasket	10.65		10.65
1	Part	MT1429 Seal Ring	1.00		1.00
1	Part	MT1426 Seal Ring	1.00		1.00
1	Part	MT0395 Seal Ring	1.00		1.00
1	Part	MT1428 Seal Ring	1.00		1.00
1	Part	MT1426 Seal King	1.00		1.00
3	016620-SWTP	5/32 Pushlock Splice	11.66		34.98
4	134A30-NWDT	134A Freon Bulk	11.00		44.00
1	Nitrogen Charge	Accumulator	33.00		33.00
1	AFC11000-NWDT	HD RED ANTIFREEZE	17.02		17.02
1	LABOR/SERVICE	Labor/Service Total	2,558.25		2,558.25

Subtotal
Sales Tax (0.0%)
Total

RMACs Truck & Equipment

814.E. Santa Fe Blvd,
Ellinwood, KS 67526
Phone 620-564-2643

Invoice

Date	Invoice #
9/22/2025	75608
	S.O. No.
	898

Bill To
Tom Snell Harvesting 509 W. 6th Ellinwood Ks 67526

Rep	Year	Make	Unit #	Mileage	Vin #
	2022	Freightliner 122SD	58	76,229	3AKJGNDV3PDUH7658
Quantity	Item Code	Description	Price Each	Core	Amount
		Removed drive shaft, exhaust, shift tower, clutch linkage, cooler lines, wiring, transmission, clutch and flywheel. Sent flywheel out for resurfacing. Reinstalled resurfaced flywheel. Installed new clutch, clutch brake and pilot bearing. Reinstalled transmission, wiring, cooler lines, clutch linkage, shift tower, exhaust and drive shaft. Connected A/C reclaimer to truck. Found A/C system overcharged. Evacuated A/C system. Removed and replaced A/C hose about to have a hole rubbed in it. Expansion valve leaking on evaporator in sleeper. Removed HVAC box in sleeper and replaced o-rings on evaporator. Reinstalled HVAC box. Introduced nitrogen into A/C system to check for leaks. Charged A/C system with freon. Found three coolant hoses leaking. Drained coolant and removed and replaced leaking hoses. Refilled cooling system. Checked operation.			

Thank You for your business!

Limited 90 Day Workmanship Warranty. Parts warranty varies by manufacturer. Ask for details.

RETURN POLICY: All returns must have original invoice. A 10% restocking charge will be deducted from credit on ALL special order parts if not returned within 30 days from invoice date.

A finance charge of 1.5% will be applied to your bill on all remaining balances not paid before the next billing cycle. In the event this and/or other invoices are referred to an attorney or agency for collection, the undersigned agrees to pay all costs of collection, including a reasonable attorney's fee.

Subtotal	\$4,369.85
Sales Tax (0.0%)	\$0.00
Total	\$4,369.85

SIGNATURE _____