



87 Work Orders

DUE	WO #	STATUS	DESCRIPTION	ASSET	LAST UPDATED	CREATED ON	COMPLETED ON	FORM ITEMS	PARTS
	10586	Complete	Trailer dumped but wouldn't come down found broken wire in junction box	SD53	04/20/22	04/07/22	04/20/22 08:17:26 CDT	0 Form Item	0 Part
	15361	Complete	Tarp doesn't work replaced black and orange cable from female plus on trailer to tarp motor adjust front and rear tarp arms	SD53	01/02/24	01/02/24	01/02/24 10:57:08 CST	0 Form Item	1 Part
	15388	Complete	Winterized Spring Rolling Lobe-air bag Amber marker light	SD53	01/05/24	01/05/24	01/05/24 08:44:24 CST	0 Form Item	5 Parts
	11486	Complete	Installed 2 new mud flaps and DOT reflective strips.	SD53	08/27/22	08/27/22	08/27/22 14:52:16 CDT	0 Form Item	2 Parts
	11553	Complete	Replaced mud flap drive side	SD53	09/06/22	09/05/22	09/06/22 06:15:18 CDT	0 Form Item	1 Part
	9465	Complete	Replaced both mudflaps	SD53	10/11/21	10/11/21	10/11/21 07:41:52 CDT	0 Form Item	1 Part
	13360	Complete	service call to the bison truck stop in alexander. air bag had hole in it. change out.	SD53	05/26/23	05/26/23	05/26/23 17:37:08 CDT	0 Form Item	1 Part
	11143	Complete	Service call to IHD. Aired up LF tire. Aired up left tag axle tire.	SD53	07/08/22	07/05/22	07/08/22 09:45:53 CDT	0 Form Item	0 Part
	10623	Complete	Cody weld icc bumper back on. Noah replaced spool valve.	SD53	04/21/22	04/20/22	04/21/22 16:41:40 CDT	0 Form Item	1 Part
	9292	Complete	Flat repair on tag axle driver side.	SD53	09/22/21	09/19/21	09/22/21 16:50:58 CDT	0 Form Item	0 Part
	6944	Complete	Changed air bag on 3rd axle passenger side.	SD53	11/17/20	11/16/20	11/17/20 06:42:23 CST	0 Form Item	1 Part
	8678	Complete	Looked over wiring, traced all over. Found bare wire for license plate light rubbing on lice se bracket. Replicated light issue with bare wire. Fixed wiring. Replaced RF marker light & pigtail.	SD53	07/08/21	06/30/21	07/08/21 05:29:00 CDT	0 Form Item	2 Parts
	11658	Complete	Replaced driver side mud flap	SD53	09/30/22	09/30/22	09/30/22 12:13:23 CDT	0 Form Item	1 Part
	10968	Complete	Plugged driver side 2nd axle tire.	SD53	06/10/22	06/10/22	06/10/22 11:29:13 CDT	0 Form Item	0 Part
	10661	Complete	Plugged tire - third axle back passenger side.	SD53	04/28/22	04/27/22	04/28/22 08:34:21 CDT	0 Form Item	0 Part
	10978	Complete	Replaced middle axle driver side air bag.	SD53	06/11/22	06/11/22	06/11/22 08:37:35 CDT	0 Form Item	1 Part
	10873	Complete	Replaced rear brake valve. Installed new mud flaps.	SD53	05/26/22	05/26/22	05/26/22 17:21:49 CDT	0 Form Item	2 Parts

8601	Complete	Replaced 4 sets of brakes and drums. Replaced #1 axle left tire	SD53	06/23/21	06/23/21	06/23/21 09:00:39 CDT	0 Form Item	3 Parts
9600	Complete	Tag axle won't go down wiring issues air line ani freeze add to trailer.	SD53	12/15/21	12/08/21	12/15/21 12:35:38 CST	0 Form Item	2 Parts
9156	Complete	Replaced tarp and installed used motor assy.	SD53	09/01/21	09/01/21	09/01/21 05:04:30 CDT	0 Form Item	1 Part
10431	Complete	Installed complete tarp system. Had parts that came off of the trailer. Installed front and rear spring and swing poles. Repaired roll tube. Installed new tarp. Installed new motor assembly.	SD53	03/21/22	03/21/22	03/21/22 16:28:40 CDT	0 Form Item	3 Parts
10977	Complete	Fixed tarp wiring.	SD53	06/11/22	06/11/22	06/11/22 08:35:44 CDT	0 Form Item	0 Part
8523	Complete	1 new super single sd53	SD53	06/03/21	06/02/21	06/03/21 06:39:21 CDT	0 Form Item	1 Part
9927	Complete	Middle axle driver side blow up tire. Put new tire on. Super single tire.	SD53	01/20/22	01/11/22	01/20/22 08:09:21 CST	0 Form Item	1 Part
8711	Complete	Passanger side first and second axle brakes drums. Super single tire on passanger side second axle, grease trailer. Adjust brakes.	SD53	07/08/21	07/08/21	07/08/21 06:54:41 CDT	0 Form Item	3 Parts
7026	Complete	Put new dump valve. Don't have part number on it.	SD53	11/23/20	11/22/20	11/23/20 08:48:27 CST	0 Form Item	1 Part
8403	Complete	Flat repair driver side front axle.	SD53	05/13/21	05/08/21	05/13/21 06:20:39 CDT	0 Form Item	0 Part
5596	Complete	Mud on trailer passanger side rear	SD53	06/28/20	06/24/20	06/28/20 11:53:42 CDT	0 Form Item	1 Part
9387	Complete	Driver didn't have enough air in trailer to dump. Also had to rev engine up a little more. Load was heavy.	SD53	09/30/21	09/30/21	09/30/21 07:17:34 CDT	0 Form Item	0 Part
16454	Complete	Replaced 7 way dump socket. Replaced tarp dual pole socket. Cleaned 7 way dump socket on 2032.	SD53	05/22/24	05/22/24	05/22/24 15:16:46 CDT	0 Form Item	2 Parts
13303	Complete	Replaced left front air bag.	SD53	05/18/23	05/18/23	05/18/23 09:04:41 CDT	0 Form Item	1 Part
12970	Complete	Replaced all s-cam bushings. Replaced all slack adjusters. Replaced all wheel seals. Replaced wheel bearings on axle 3. Replaced all brake shoes.	SD53	05/20/23	03/30/23	03/30/23 12:19:57 CDT	0 Form Item	8 Parts
15528	Complete	Replaced 7 way socket for dump/tag. John Johnson done the work.	SD53	01/21/24	01/21/24	01/21/24 11:06:12 CST	0 Form Item	1 Part
15991	Complete	Checked trailer over. Dump not working. Found bad wire on frame. Fixed wire and works as it should. John Johnson done the work.	SD53	03/28/24	03/28/24	03/28/24 06:47:30 CDT	0 Form Item	0 Part

15987	Complete	Tub won't come back over. Found loose wire on 7 way. Replaced quick coupler o-rings.	SD53	03/27/24	03/27/24	03/27/24 11:27:14 CDT	0 Form Item	1 Part
16020	Complete	Grease and checked over.	SD53	04/07/24	04/07/24	04/07/24 12:19:11 CDT	0 Form Item	1 Part
10457	Complete	Grease slacks and scam bushings.	SD53	03/25/22	03/24/22	03/25/22 07:36:15 CDT	0 Form Item	0 Part
15949	Complete	Grease, Checked over. Suspension was riding really high. Adjust leveling valve linkage rod. Adjust brakes. Annual inspection.	SD53	03/21/24	03/21/24	03/21/24 12:37:51 CDT	0 Form Item	0 Part
15727	Complete	Greased, checked tires, hubs, brakes, lights. Replaced mud flap on front passenger side.	SD53	02/21/24	02/21/24	02/21/24 07:47:33 CST	0 Form Item	1 Part
16074	Complete	Inspected trailer John Johnson done the work.	SD53	04/10/24	04/10/24	04/10/24 17:49:25 CDT	0 Form Item	0 Part
15672	Complete	Kobe done the work. Replaced marker light and pigtail on right front.	SD53	02/12/24	02/12/24	02/12/24 17:20:31 CST	0 Form Item	2 Parts
14029	Complete	Took apart Brake can, Slack Adjuster, S-cam on rear axle passenger side. Midknight Welder replaced spider. Cowboy paid for spider. Zack put everything back together. Replaced brake chamber on #2 left axle. Replaced wheel seal on #2 axle right. Replaced wheel seal, s-cam on #4 right axle.	SD53	08/25/23	08/24/23	08/25/23 18:12:21 CDT	0 Form Item	6 Parts
12760	Complete	Replaced tag axle control box. Replaced tarp motor.	SD53	03/02/23	03/02/23	03/02/23 09:12:53 CST	0 Form Item	2 Parts
13240	Complete	Tag axle would not go up. The cause was a corroded line at the trailer plug as well as a corroded plug. Replaced the 7 pin female. Plugged air leak on passenger side tire on tag axle.	SD53	05/07/23	05/05/23	05/07/23 07:22:35 CDT	0 Form Item	1 Part
6858	Complete	Replaced tarp motor and head	SD53	11/08/20	11/08/20	11/08/20 06:16:49 CST	0 Form Item	1 Part
10611	Complete	Front side of big tarp pole ripped off. Repaired tarp pole.	SD53	04/20/22	04/18/22	04/20/22 13:18:53 CDT	0 Form Item	0 Part
12239	Complete	#2 axle driver side tire repair. #3 axle driver side tire repair. Tag axle works as it should.	SD53	01/08/23	01/08/23	01/08/23 09:46:40 CST	0 Form Item	0 Part
9753	Complete	Repaired left 2nd tire. Weld ICC bumper on rear of trailer.	SD53	12/21/21	12/21/21	12/21/21 11:43:03 CST	0 Form Item	0 Part
11759	Complete	Front axle driver side tire changed. Tag axle passenger side tire flat. Flat repair from inside.	SD53	10/25/22	10/20/22	10/25/22 17:46:22 CDT	0 Form Item	1 Part
12230	Complete	Brandon in welding shop welded all 4 corners on tub.	SD53	01/07/23	01/07/23	01/07/23 11:19:11	0 Form Item	2

		King fixed marker lights.				CST		Parts
14116	Complete	Replaced license plate light.	SD53	08/31/23	08/31/23	08/31/23 17:02:29 CDT	0 Form Item	0 Part
7323	Complete	Replaced right rear brake shoe & drum Adjust brake & torque lug nuts	SD53	12/26/20	12/26/20	12/26/20 07:51:17 CST	0 Form Item	2 Parts
4131	Complete	Replaced all brakes except tag axle and did full service and brad welded the old shock bracket back in place on front left shock. New brackets are locked up in Wallys box.	SD53	01/30/20	01/24/20	01/30/20 09:43:53 CST	0 Form Item	1 Part
16265	Complete	Checked lights Tires Hub oil Greased Trailer is good to go Brandon did the work	SD53	05/07/24	05/07/24	05/07/24 14:11:29 CDT	0 Form Item	0 Part
13172	Complete	Repaired corroded line to front and rear running light on driver side. Replaced corroded 2 inch amber light and 2 wire plug. Put new ends on the tarp cable to the plug.	SD53	04/26/23	04/26/23	04/26/23 08:09:44 CDT	0 Form Item	2 Parts
6792	Complete	Changed super single	SD53	11/06/20	10/27/20	11/06/20 12:01:46 CST	0 Form Item	1 Part
5554	Complete	Replaced dual prong tarp plug	SD53	06/18/20	06/18/20	06/18/20 05:51:34 CDT	0 Form Item	1 Part
11703	Complete	Middle Axle driver side tire repair.	SD53	10/07/22	10/07/22	10/07/22 06:49:14 CDT	0 Form Item	1 Part
15792	Complete	Rear Running lights and Wirings Replaced Kobe	SD53	03/02/24	03/02/24	03/02/24 11:00:05 CST	0 Form Item	1 Part
10646	Complete	Replaced tarp motor and drive assembly	SD53	04/25/22	04/25/22	04/25/22 16:57:27 CDT	0 Form Item	1 Part
4568	Complete	Replaced hub cap on RF	SD53	03/03/20	03/03/20	03/03/20 18:22:43 CST	0 Form Item	1 Part
4692	Complete	Replaced RF marker light & pigtail.	SD53	03/12/20	03/12/20	03/12/20 17:36:12 CDT	0 Form Item	2 Parts
10863	Complete	Driver dumped load on tarp. Replaced tarp motor assembly. Replaced tarp roll tube.	SD53	05/25/22	05/25/22	05/25/22 13:19:16 CDT	0 Form Item	2 Parts
11172	Complete	#4 Axle left tire. #3 Axle right tire. #2 Axle left tire. #2 Axle left - Wally fabricated new shock bracket.	SD53	07/10/22	07/10/22	07/10/22 17:27:27 CDT	0 Form Item	1 Part
7014	Complete	Air leak on airbag dump valve Need to oredrer new valve	SD53	11/22/20	11/21/20	11/22/20 05:25:55 CST	0 Form Item	0 Part
6840	Complete	Wield shock mount greased	SD53	11/07/20	11/07/20	11/07/20 05:40:27 CST	0 Form Item	0 Part
7691	Complete	Sd53 tire repair left 3rd axle tire had nail in it	SD53	02/18/21	02/18/21	02/18/21 16:38:11 CST	0 Form Item	0 Part
7876	Complete	Rr 3rd tire goes flatugged tire a Found screw in tire Pond filled with air	SD53	03/04/21	03/04/21	03/04/21 05:19:57 CST	0 Form Item	0 Part
6474	Complete	Welded cracks on trailer	SD53	10/06/20	09/29/20	10/06/20 06:18:43 CDT	0 Form Item	0 Part
		Change driver side front axle brake						

10905	Complete	drum and tire. Change driver side second axle brake. Change passenger side second axle brake and wheel seal. Fix wiring to marker lights.	SD53	06/06/22	06/01/22	06/06/22 08:34:23 CDT	0 Form Item	3 Parts
11389	Complete	New brake wheel seal and a-cam bushings passenger front axle. New brakes, drums, s-cam bushings, abs sensors 3rd axle both sides. New brakes and drums tag axle. New tire passenger side tag axle. New airbag driver side 2nd axle. Grease job.	SD53	08/16/22	08/15/22	08/16/22 15:11:33 CDT	0 Form Item	4 Parts
10352	Complete	Fix wire in junction box for air solenoid. Fix wiring to front corner marker. Fix wiring to passenger middle marker blinker. Brakes froze up with cuttings. Dig cuttings out and clean brakes up. Grease job.	SD53	03/10/22	03/10/22	03/10/22 11:24:16 CST	0 Form Item	1 Part
13176	Complete	Mud flap	SD53	04/26/23	04/26/23	04/26/23 08:11:44 CDT	0 Form Item	2 Parts
12555	Complete	Tarp cord receptacle. Fixed marker light.	SD53	02/15/23	02/09/23	02/15/23 12:15:57 CST	0 Form Item	5 Parts
13093	Complete	Mud flaps	SD53	04/19/23	04/19/23	04/19/23 12:48:16 CDT	0 Form Item	3 Parts
10874	Complete	Service call to pdi. Tarp pole broke and burned motor up. Changed whole motor head assembly. Forced tarp to close. Will need new tarp pole	SD53	05/27/22	05/26/22	05/27/22 06:11:22 CDT	0 Form Item	1 Part
10891	Complete	Service call to pdi. Patch driver side pusher tire. Fix broken wire in junction box for dump air solenoid.	SD53	06/06/22	05/30/22	06/06/22 07:52:30 CDT	0 Form Item	0 Part
11139	Complete	Fix leak on driver side second axle tire. Air up other low tires.	SD53	07/08/22	07/03/22	07/08/22 09:51:23 CDT	0 Form Item	0 Part
7111	Complete	Replaced tarp	SD53	12/01/20	11/30/20	12/01/20 05:27:37 CST	0 Form Item	1 Part
13459	Complete	Tires	SD53	06/18/23	06/09/23	06/18/23 09:52:32 CDT	0 Form Item	1 Part
6699	Complete	New super single	SD53	10/20/20	10/19/20	10/20/20 06:35:53 CDT	0 Form Item	1 Part
14019	Complete	Tarp arms didn't extend completely sprayed down with pb blaster and forced to move a few times and had smooth movement afterwards. Tarp pole was catching on the arm brackets causing it to not roll over into the closed position. Richard ground down the brackets to have more of a bevel for and easier rotation. Had help from Richard and Chris.	SD53	08/23/23	08/23/23	08/23/23 08:35:55 CDT	0 Form Item	0 Part
4303	Complete	Fix wiring on tarp plug. Did an annual.	SD53	02/09/20	02/09/20	02/09/20 08:41:00 CST	0 Form Item	0 Part

4721	Complete	Cleaned air line filters	SD53	03/15/20	03/15/20	03/15/20 08:51:49 CDT	0 Form Item	1 Part
01/24/20 4140	Complete	Replaced tarp pig tail socket Replaced light	SD53	01/31/20	01/24/20	01/31/20 11:51:28 CST	0 Form Item	2 Parts
11/09/21 9582	Complete	Change 7 Way Plug Add Air line antfreeze	SD53	11/30/21	11/30/21	11/30/21 09:34:05 CST	0 Form Item	1 Part
06/11/23 13588	Complete	Removed/replaced shocks removed/replaced wheel seal added hub oil roque tire Mechanic: JB	SD53	07/01/23	06/30/23	07/01/23 13:48:59 CDT	0 Form Item	2 Parts

62 Work Orders assigned to **Automated**
5 Work Orders assigned to **Laura Girolamo**
5 Work Orders assigned to **Chris Helland**
3 Work Orders assigned to **Day Shift**
3 Work Orders assigned to **johnnylangham@rocketmail.com**
6 Work Orders assigned to **Wally Burr**
2 Work Orders assigned to **Richard Burr**
1 Work Orders assigned to **Naqibullah King Azizi**

0 Open Work Orders
0 On Hold Work Orders
0 In Progress Work Orders
87 Closed Work Orders

Total Time: **219** hours **49** minutes
 Total Cost: **\$49288.51**
 Total time to complete: **3297** hours **27** minutes