

TRUCK MAINTENANCE

Unit: 88

Vin: 1XP5DB9X1YD480963
year/truck: 2000 Peterbilt

DATE	MILEAGE	DESCRIPTION	PERFORMED BY
3/1/18		Mechanics sand the truck completed body fill as needed, and taped off and painted the truck. They put all truck exterior and interior back together, made a deck pla with bulk heads for air/electrical hook ups. New tires on on both drive axles, installed an air horn, grounded 2 pins to the ECM, installed CB radio, installed phone charger, new fuel filter and all new fuel lines from tanks to the connectors, and new 1/4 fenders.	Grant/Nick/David
5/3/18		Mechanic completed a DOT inspection.	
5/14/18		Removed and replaced 5/8" air tank fitting. Mechanic removed king pins, bearing and shims on both sides. Richie from truck repair bored out axle and installed sleeves. Mechanics installed new bearings, shims and king pins, drums, brake lines to front axle. Then the truck was sent to Bauer Built to be aligned. The mechanics then installed quad outlet for phone charger, deck plat with bulk header for air/electrical hook up. The mechanic then installed a fitting for passenger side wiper fluid, and new window seals on driver and passenger sides. They also added a fire extinguisher.	Grant
5/15/18		Bauer Built completed an alignment.	Grant/David/Nick
5/21/18	20084795	Mechanic added a new 5 amp fuse to ECM.	Bauer Built
5/25/18		Mechanic removed quarter panels and installed new half fenders, a new radio, and chrome cover for the vent on the driver side, and removed the oil pan.	David/Matt
5/31/18	2015366	Mechanics changed out steer ties on both sides, and torqued to 475. Also-charged the ac.	Grant/Nick
6/9/18	20166902	Mechanic changed out the low pressure hose on power steering and added 1 qt trans fluid. Also- extended power wire to running light on left front.	David/Grant
6/22/18	2021567	Mechanic added 1 gallon of antifreeze, and installed new step grips.	Dave
			Davey

7/24/18	2029649	Mechanics removed and replaced the oil and fuel filter, oil, greased the truck, and added ATF for power steering.	Grant
8/3/18	2033147	Mechanic changed out the cab air bags and right shock.	David
10/9/18	2050996	Mechanic removed rear drive shaft (female end and u-joint), removed the pinion seal, installed new pinion seal and female shaft with u-joint. Mechanic then removed and replaced the rear drive axle gear oil, removed the high pressure fitting on steering box. Then, replaced high pressure fitting on steering box. Mechanic removed and replaced the high pressure fitting on the steering box, as well as the power steering fluid. Mechanic adjusted the 5th wheel plate to do the proper adjustment.	Grant
		Mechanic removed the evaporator and R1-34A from the system.	Dave
		Mechanic then completed a full service on the truck, and then looked over the rest of the truck.	Grant
10/12/18		Mechanic took seat out of 88 and installed in 80.	Grant
11/26/18		Mechanic changed out the low pressure fitting on power steering pump. (Pump from Brozene Hydraulic).	Dave
12/12/18	2069989	Mechanic removed and replaced the oil, oil filter, fuel filter, greased the truck, adjusted the plate, fixed the air leak from the air tank and removed and replaced the high pressure line for power steering.	Grant/Wes
12/17/18		Mechanic removed and replaced the side mud flap holder.	Grant
12/19/18		Mechanic removed and replaced the ac condensor and #3 air bag.	Grant
1/7/19		Mechanic installed a new seat and installed the bed in bunk, the truck was also washed.	Grant
1/7/19		Mechanic changed out the right front drive spider, brakes and drums.	Dave
1/17/2019		Mechanic changed out fire extinguishers.	Dave
2/12/19	2082158	Mechanic rebuilt the 5th wheel plate, and took the drive shaft to Sadler to be rebuilt. New u-joints, carrier bearing and yake installed. Mechanic intalled new clutch adjuster, and then adjusted the clutch. Mechanic installed new LED headlights (low side), fixed fuel leak, plugged the tire, installed new clutch inspection plate, new drain on air dryer, new brake chamber on #2, installed new air line on driver steer chamber, fixed in cab lights, installed new marker lights on	

3/11/19	2088779	bumper passenger side, and greased, as well as lubed clutch linkage. Driver reported a problem with braking so mechanics replaced the spider, drums, scam bushings, shoes, slack adjusters, wheel seals, pro torq axle nut, DOT inspection and serviced the truck. Mechanics followed the wheel seal torque specs, wheel torque spics. They also greased the truck, added washer fluid, ATF fluid, cleaned out the wiper nozzle.	Grant		
3/18/19		Mechanic plugged in buzzer, replaced the relay.	Grant		
4/5/19		Mechanic installed pump, motor, valves (x2), hydraulic lines, pto motor, hydro pack, and installed a buzzer.	Grant/Dave		
4/8/19		Mechanic removed and replaced the relay and blinker switch and tightened the loose hydraulic lines.	Grant		
4/25/19		Mechanic removed and replaced the #1 wheel seal drive, #1 brake shoe, axle housing vent, #1 brake piggy back, patched #6 tire, added oil to axle housing and aired up tires.	Grant/Dave		
5/8/19	2107894	Mechanic completed a full service, greased the truck, removed and replaced the oil pan, oil lines to filter.	Grant/Dave		
5-10-19		Mechanic removed and replaced the oil pan and gasket.	Grant		
6-3-19		Mechanic removed and replaced the steer brake shoes, steer drums, and starter.	Grant		
6-24-19	2118459	Bauer Built completed a 3xle alignment.	Bauer Built		
7-30-19	2126992	Mechanic ran ground wire to bunk lights, changed out the side turn light, and fuel sending unit turned.	Dave		
7-31-19	2131844	Mechanic completed a service, greased, and then changed out the oil pan gasket.	Dave		
9-23-19	2151500	Mechanic removed and replaced the fuel and oil filters, drive steer brake line, and serviced the truck.	Grant		
10-1-19		Mechanic replaced the a/c condensor, replaced a/c low pressure line (from compressor to condensor), recharged a/c system, and replaced the rear mudflaps.	John		
10-21-19		Mechanic replaced the front drive assembly, rf bearings, rf wheel seal, front drive rear output seal, right fuel tank replaced, rear hydraulic valve, moved hydraulix outlets to deck plate.	John/Bryce		

11-18-19		Mechanic replaced fuel lines from junction valve to the tanks on suction and return lines, alternator replaced.	John				
12-11-19	2177712	Mechance greased, serviced, replaced hood bushing.	Grant				
1-14-20	2189194	Mechanic replaced the return fuel hose coolant line to air comp, temp sensor on thermostat housing.	John				
2-5-20	2198203	Mechanic serviced and greased the truck. Also noted that driver window needs new window channel, inside drivers door latch, needs replaced, low air pressure switch is not working correctly. Mechanic found that passenger side fuel tank leaks, re-sealed bottom drain plug and replaced fuel cap.					
2-18-20		Mechanic removed and replaced the #2 steer hub, #2 steer balancers,	John				
2-20-20		both sides, 1/2 qt oil in #2 steer hub. 3 axle alignment, and balanced.	Grant Bauer Built				
3-4-20	2205716	shoes, 1/4 qt of oil in passenger side hub, DOT.	Grant				
	2231000	Mechanic changed out turn switch.	Dave				
		Mechanic removed and replaced the alternator, and belts.					
		Mechanic serviced, replaced 90 degree fuel fitting, re-wired head lights,					
		and now brights work.					
8-4-20		Mechanic replaced alternator pully and 2 worn belts.	Bryce				
8-28-20	2255431	Mechanic serviced truck, greased, noticed irregular wear on passenger side, steer tire, checked king pins, and they need replaced at a later time.	DTS				
10-17-20	2262844	Mechanic did a tear down to replace exhaust manifold gaskets. Inspected turbo, found a bearing out, or very close to being out. Prepped engine parts for installation. Replaced exhaust manifold gaskets, manifold (3 pc), manifold studs, turbo gasket, turbo studs, water pump housing gaskets, block side water jacket gasket. Re-wired temp sensor harness, diagnosed power diver, no problem found. Steer tires replaced, installed mud flaps brackets, and fenders. Hood springs					

10-22-20	2262844	replaced, clutch adjusted. Mechanic changed out king pins, brake shoes, and drums, replaced. Steer tires replaced, right steer brake chamber hose, replaced due to rub marks,	John
11-11-20		Left turn signal not working, right signal hyper flashes, replaced electronic flasher. Mechanic installed new hood springs, put new bolts with lock tite in lower alternator bracket, found abs cable unhooked, put back together and zip tied in better route, also checked air to air clamps so they didn't rub on hood springs.	John
11-19-20	2269795	Mechanic changed out #2 wheel seal as well as the shoes and drums.	Dave
11-30-20	2273240	Mechanic made a diagnosis of no bunk heat, temp fixed with an external ground to bunk blower motor. Cab (front) HVAC control panel needs replaced. Bunk control panel may be bad also.	Dave
12-10-20		Replaced 5/8 x 1/2: NPT, replaced pressure proction valve on passenger side air tank.	John/Grant
12-14-20	2277555	Mechanic removed and replaced oil, greased, fixed bad ECM ground. Checked all fluids, tightened up fenders, replaced fender bolt on fender. Zip tied up some lines under truck, added gear oil to forward drive axle.	John
February 2021		DOT inspection completed.	Grant/Bryce
3-26-21	2296594	Mechanic changed out air window switch fan left side. Old one was leaking at air in fitting.	Dave
5-19-21	2302700	Mechanic completed service and grease. Replaced all drive tires, LF, LR, RR brakes, shoes and drums.	Bryce
5-27-21	2312818	Charged AC system to 5 lbs, and replaced AC fuse. Sprayed lube on brake plunger.	Brian
	2314306	Vent was not switching, so mechanic foudn bad mode switch and missing mode motor. Mechanic changed out with used. Mechanic also found broken wire on right middle turn light.	Dave

6-25-21	2316266	Drained AC system, removed and replaced low side valve core, recharged ac system	Cole
7-30-21	2318070	Mechanic completed a service, and fixed bunk AC.	Brian
8-7-21	2319910	Mechanic removed and replaced brake chamber and air lines to brake chamber.	Cole
8-24-21	2325006	Driver reported a broken u bolt on the passenger side axle. Mechanic removed and replaced the broken u bolt, and then installed new u bolt.	Brian/Jeremiah
9-9-21	2327809	Mechanic removed and replaced height control rod, rubber boot, and front driver side chrome trim piece.	Brian/Jeremiah
10-4-21		Washed and cleaned out side of truck.	Russ
9-24-21	2329641	Removed cell phone holder, reinstalled in truck 93, fab hub replaced, dampener replaced, oil cooler replaced, front main seal replaced, reinstalled front end, driver side driver fenders, removed and installed new fenders.	Brian
10-8-21	2331844	Removed and replaced both front RH drive axle tires.	Brian
10-14-21	2333485	Fixed screws in headlight.	Grant
		Changed filters and filled oil, greased installed air horn, interior/added self tap screws into interior panel in bunk, installed inverter, changed wiper blades.	Brian, Russ
10-18-21	2334538	Chased down air leak, found leak in dash.	Brian
11-1-21		Replaced sleeper shocks	Jeremiah, Russ
11-10-21		Removed and replaced jack shaft, drove to Sperry for service calls.	Russ
11-16-21	2344267	Cab bags, track bar, removed and replaced clutch brake, checked front end.	Brian/Jeff
11-20-21		Removed and replaced u bolt on # 3 drive axle leaf spring, #1 drive shock, rear end torque rod, air leaf bushing, short shaft, front axle out out yoke/nut, tightened up #4 fender.	Grant
11-29-21		Welded front bumper and adjusted fender.	Russ
		Fixed air leaks, replaced lines and fittings, replaced 12" 5/8 air line, replaced 1/4 T fitting.	Grant, Russ
12-14-21	2354559	Serviced, removed and replaced steering shaft, greased truck,	

12-29-21	2358344	Inspected, checked, and aired up tires. Checked for power at the motor then traced the power back to fuse box, replaced fuse and blower, kicked back on.	Brian, Grant, Jeff		
1-11-22		Replaced windshield sprayer on driver side, tightened battery cables, aired tires.	Brian		
1-14-22	2365400	Removed mode door, shut the fresh air flap and ordered the part.	Russ		
1-17-22	2365776	Removed and replaced air governor on compressor. Rotated passenger	Brian		
2-8-22	2371468	steer tire, replaced drive tires, #3 and 4 with the original drive tires. Removed and replaced carrier/wheel seals, serviced.	Brian, Russ, Grant		
2-21-22	2374021	Removed the yokes, air bag, shocks and bracket. Installed both yokes, shocks, and bracket. Removed the fittings and old air bag, when removing air bag, noticed that the frame was bent, needed to reinstall the old air bag and fix the air line for the air bag, tested for leaks, no leaks at this time, the ABS cables are also stripped.	Brian, Grant		
2-25-22		Removed and replaced relay valve and both ABS modulator valves on rear drive axle, straightened frame, installed tires, checked lights.	Integrity Truck & Trailer Marshall, WI		
3-5-22	2392043	Serviced, greased, changed out rear axle breather, changed out left tail light.	Russ, Brian		
4-15-22	2396788	Looked at truck for cruise control issues, found that the micro switch under the cab that operates off of the clutch rod was defective. Replaced switch with a used one from another truck, cruise is working now.	Dave, Asher		
4-18-22	2397687	Changed out male pig tail end on trailer side.	Brian		
4-25-22	2400858	Removed and replaced driver's side mirror rivots, spot mirror, wiper blades.	Dave		
4-27-22		Removed and replaced hydro lines, air leak leveling valve, replaced 1/4" air line for #6 air bag to leveling valve. Replaced foot long flex pipe from turbo to down pipe.	Brian		
5-6-22		Installed under cab and filler panel cover/lights. Installed and wired aux lights and under glow. Cut and made front brakcet for underglow.	Russ		
5-23-22	2412661	Serviced, greased, removed and replaced intake o rings on turbo.	Grant, Brian, Asher, Dave, Russ Cole, Asher, Dave		

6-2-22	2415235	Replaced both rear stop light assemblies, front exhaust leak from flex pipe behind turbo, removed and replaced flex pipe and exhaust clamps from turbo to down pipe.	Asher						
6-20-22		Per Brian, Davey rewired lights to the way that they had worked previously.							
6-23-22	2420658	Removed and replaced turbo	Brian						
6-24-22	2421299	Removed and replaced front steer tires with used ones, removed and replaced passenger side far rear drive axle inside tire with a used one.	Brian						
6-30-22	2423603	Drilled stripped hole to 21/32" then tapped to 3/4"x10	Cole						
7-1-22		Driver replaced wire blades.							
7-11-22	2429497	Serviced oil, oil filters and fuel filters. Greased, checked transmission and differential oil levels, checked brakes and wheel seals. Checked tire pressures and repaired RH front brake line. Topped of coolant and washer fluid.	Asher						
		Diagnosed wiring problem for chicken lights and underglow. Found poor power supply, switched power to key switch power.	Grant						
7-13-22		Removed secondary oil filter and housing, plugged the existing ports. Tightened up the axle drive bolt.	Grant						
7-26-22		Installed new gateway	Asher						
		Installed shoe on left steer	Dave						
		Reconnected power wire behind dash.	Grant						
7-27-22		Reseal the breaker.	Russ						
		Looked over entire truck and made a list of repairs and worn out parts. Installed dash camera, secured coolant lines on RH side of motor. Replaced both steer axle brake lines (built lines), greased truck and checked all fluids. Checked front suspension for play (front tires uneven wear). Replaced leaking coolant line/topped off coolant level, drained power divider differential (seal leaking for diff), cleaned differential mating surfaces, removed and replaced both rear dog bones, torque rods, installed differential/sealed and replaced steer axle tires, drained RH fuel tank. Repaired/built airline for differential. Serviced oil and fuel filters, installed drive shaft, helped install fuel tank strap, filled differential, have to drill and tap bolt hole for differential, reinstalled diff/filled and installed drive shaft. Filled fuel tank with fuel, replaced broked exhaust clamp.	Asher/Cole						

8-26-22	Alignment completed.		
9-1-22	Removed and replaced ground light brackets, made 2 new from SS angle 15" long, 4 holes cut out plasma for light. Driver side bumper bracket, broke on bottom monitor per Grant. Install new air bag drive #1,	2448279	Russ
9-3-22	Replaced worn fuel line and fittings.		Asher
9-9-22	Replaced broken docking/work light (LH) and adjuster mirrors for driver.		Asher
10-10-22	Serviced oil, fuel filters, checked tire pressures, rear end oil levels, tightened front end u bolts, greased truck, replaced door hinge on driver's side.	2462061	Cole, Asher, Wyatt
10-31-22	Checked u bolts, helped clamp, reenforced (LH) sleeper air bag, dog bone, mounting plate to back of sleeper.		Asher, Grant
11-8-22	Replaced dash warning cluster lights and fixed low air warning beeper, tightened dog bone on front drive axle.		Cole
12-21-22	<p>Air leak on the cab in the cab brake valve. Removed and replaced dash valve. Exhaust is hanging on the crossmember and needs moved so it doesn't rub. Rotated clamp at brace to clear cross member, also changed out clamp at flex pipe before Y pipe, rotated down pipe to miss frame member. Rear u bolts on drive axle need checked for tightness, these have been loose. Took apart ubolt and put 2 washers in, loc tighted them and tightened them up. Checked steer ale u bolts for tightness, u bolts checked with torque wrench, set at 250 ft lbs. Washer fluid nozzle needs fixed. Removed and replaced washer fluid nozzles with new ones. Work lamp on the passenger side of the truck. Both passenger and driver's side work lamps replaced with Trux 3in mini. Lights on dash for gauges not working. Repaired and installed dash light bulbs. Driver and passenger side cab air bags are starting to separate from the cab and is going to need further repairs at another time. Wet service completed. ABS wiring on the truck needs replaced. Cut all rear axle ABS wiring and hard wired all the wires together bypassing all the corroded ends and plugs. Will need to test drive to confirm the repair. Repair did not fix the ABS issue-continued to work on the ABS issue and try to find the cause of the wirin issue. Took apart mounts on bunk, cleaned up parts, cut out bad spots of back of cab under mounts, added new painted, added bigger bolts for mounting. Tightened and tank strap bolts. Replaced hood springs and removed old hood cable and replaced it with new one that was made. Left turn signal not working, bulb was out in dash causing break in the circuit, so replaced the bulb to fix circuit. Changed out window and axle air switches with new.</p>		

12-22-22	2484711	Replaced left rear outside due to blowout.	Love, St Joseph MO
12-29-22	2485950	Removed motive ELD and installed samsara eld with camera.	Cole
1-11-23	2485950.9	Loose finder, checked steer u bolts.	Davey
2-3-23	2499813	Replaced fuel filters and tightenend coolant hose clamps.	RR Truck Repair (Albert Lea MN)
2-6-23	2500072	Removed and replaced all filters, oil, checked all fluids, topped off coolant.	DTS
2-9-23	2500072	Put pressure to coolant system found leak on the back right corner of the block going into the cooler, replaced the clamp on the fitting and pressure tested again. Disassembled and found that the bunk latch and handle need replaced. Inspected brakes still have plenty of lift left on shoes, didn't seem to be dragging/hanging up. Pogo stick installed.	DTS
2-15-23	2290517?	Ground wire running into the plug was corroded, went to go wiggle it around and the pin came out of the pug, so made a new plug for just the ground wire.	Grant
3-1-23		Light was starting to pop out of the back of the gauge, popped the light back in.	DTS
3-3-23		pulled about the whole wiring harness because once i fixed the low beam the truck would blow a fuse when brights were flicked on. Found that the high beam was running to a ground on the light causing a fuse to blow. So I wired it back up the correct way and everything works as it should now	DTS
3-7-23	2504886	DOT inspection completed. Checked all wheels, tire pressures (100 psi for drives and 110 psi for steer tires), checked brake drums and linings, checked wheel seals, checked wiper blades and windshields, checked operation of all lights. Removed dash to get to tracker system, removed old tracker, installed new tracker system and had to wait 10 minutes for tracker to boot up. Got the alert from office that tracker was working correctly. Installed dash back in place and secured all interior panels that were removed.	DTS
3-24-23		Removed and replaced CB radio.	DTS

4-7-23		<p>Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection. Removed herd bumper due to deer collision. Removed bumper off of 84 and installed it onto 88. Re tapped license plate bracket holes. Completed service and checked all fluids.</p>	DTS
4-12-23		<p>Oil temp sensor in the oil pan is not hooked up looks like the wires were either cut or ripped off at some point in time. Tested the pyro gauge and the wiring all of it is good wasn't able to test the exhaust probe nstalled used cb (did not tune it) tightened up the locknut on the shift tower. train horn works fine. / greased the entire truck and checked all fluids, and brakes. nspected for fuel leak and found that the fuel line on the back of the block was being rubbed on the block and fuel was seeping out, replaced the line had to brozenes to pick up the right fittings. let truck sit and run for 5 mins and nothing started leaking. Door Trim panels were removed</p>	DTS
4-13-23		<p>-Old handles cut out and replaced with new handles -Door Trim panel reinstalled Drivers Door Latch Striker Replaced, Part Robbed From Truck 94</p>	DTS
5-16-23		<p>removed all loose mounting hardware cleaned up threads and remounted</p>	DTS
5-17-23	2326226	<p>Completed full service and greased truck</p>	DTS
5-23-23	2327975	<p>Removed and replace #8 & #7 drive tires due to amount of wear due to a flat tire replaced with used 11r24.5 drive tires</p>	DTS
6-6-23		<p>Adjust Striker - Adjust Door to help Aline Striker</p>	DTS
6-9-23		<p>Removed dash and inspected the voltage and fuel level gauge bulbs -Replaced burnt out bulbs -</p>	DTS

Unit	Unit Type	Unit Miles	Complaint Description	Service Description	Date Action Completed
88 Peterbilt			Remove and Replace- warning cluster lights	Remove and Replace- warning cluster lights	7:05AM 11/9/2022
88 Peterbilt			Remove and Replace- air dryer filter	Remove and Replace- air dryer filter	7:05AM 11/9/2022
88 Peterbilt			Dog bone repaired	Dog bone repaired	7:05AM 11/9/2022
88 Peterbilt					
88 Peterbilt			REPAIRED SLEEPER AIRBAG/ DOGBONE MOUNTING PLATE	REPAIRED SLEEPER AIRBAG/ DOGBONE MOUNTING PLATE	9:51AM 10/31/2022
88 Peterbilt		2,481,286	air leak on the in cab brake valve	Removed and replaced dash valve	10:35AM 11/30/2022
88 Peterbilt		2,481,286	air leak on the in cab brake valve	Removed and replaced dash valve	10:35AM 11/30/2022
88 Peterbilt		2,481,286	air leak on the in cab brake valve	Removed and replaced dash valve	10:35AM 11/30/2022
88 Peterbilt		2,481,286	exhaust is hanging on the crossmember and needs moved so it doesnt rub	rotated clamp at brace to clear cross member. also c/o clamp at flex pipe before Y pipe. rotated down pipe to miss frame member	10:05AM 12/1/2022
88 Peterbilt		2,481,286	exhaust is hanging on the crossmember and needs moved so it doesnt rub	rotated clamp at brace to clear cross member. also c/o clamp at flex pipe before Y pipe. rotated down pipe to miss frame member	10:05AM 12/1/2022

88 Peterbilt	2,481,286	exhaust is hanging on the crossmember and needs moved so it doesnt rub	rotated clamp at brace to clear cross member. also c/o clamp at flex pipe before Y pipe. rotated down pipe to miss frame member	10:05AM 12/1/2022
88 Peterbilt	2,481,286	rear u bolts on drive axle need checked for tightness. these have been loose	took apart ubolt and put 2 washers in, locitied them and tightened them up	10:33AM 11/30/2022
88 Peterbilt	2,481,286	check steer axle u bolts for tightness	U-bolts checked with torque wrench, set at 250 ft-lbs	9:18AM 12/14/2022
88 Peterbilt	2,481,286	washer fluid nozzle needs fixed	R&R washer fluid nozzles with new ones	10:35AM 11/30/2022
88 Peterbilt	2,481,286	washer fluid nozzle needs fixed	R&R washer fluid nozzles with new ones	10:35AM 11/30/2022
88 Peterbilt	2,481,286	work lamp on the passenger side of the truck	Both Pass and Drivers side work lamps replaced with Trux 3in Mini	10:54AM 12/14/2022
88 Peterbilt	2,481,286	work lamp on the passenger side of the truck	Both Pass and Drivers side work lamps replaced with Trux 3in Mini	10:54AM 12/14/2022
88 Peterbilt	2,481,286	work lamp on the passenger side of the truck	Both Pass and Drivers side work lamps replaced with Trux 3in Mini	10:54AM 12/14/2022
88 Peterbilt	2,481,286	work lamp on the passenger side of the truck	Both Pass and Drivers side work lamps replaced with Trux 3in Mini	10:54AM 12/14/2022
88 Peterbilt	2,481,286	lights on dash for gauges not all working	Repaired and installed dash light bulbs	8:32AM 12/21/2022
88 Peterbilt	2,481,286	adjust the cab mount so that truck sits even	driver and passenger side cab air bags are starting to separate from the cab and is going to need further repairs at another time.	12:25PM 11/30/2022

88 Peterbilt	2,481,286 adjust the cab mount so that truck sits even	driver and passenger side cab air bags are starting to separate from the cab and is going to need further repairs at another time.	12:25PM 11/30/2022
88 Peterbilt	2,481,286 full wet service	full wet service	8:31AM 12/21/2022
88 Peterbilt	2,481,286 full wet service	full wet service	8:31AM 12/21/2022
88 Peterbilt	2,481,286 full wet service	full wet service	8:31AM 12/21/2022
88 Peterbilt	2,481,286 full wet service	full wet service	8:31AM 12/21/2022

88 Peterbilt	2,481,286 abs wiring on the truck needs replaced.	cut all the rear axle abs wiring and hardwired all the wires together bypassing all the corroded ends and plugs. will need to test drive to confirm the repair. repair did not fix the abs issue. countified to work on the abs issue and try to find the cause of the wiring issue.	2:45PM 11/30/2022
--------------	---------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------

88 Peterbilt	2,481,286 abs wiring on the truck needs replaced.	cut all the rear axle abs wiring and hardwired all the wires together bypassing all the corroded ends and plugs. will need to test drive to confirm the repair. repair did not fix the abs issue. countified to work on the abs issue and try to find the cause of the wiring issue.	2:45PM 11/30/2022
--------------	---------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------

cut all the rear axle abs wiring and hardwired all the wires together bypassing all the corroded ends and plugs. will need to test drive to confirm the repair.

88 Peterbilt 2,481,286 abs wiring on the truck needs replaced.

2:45PM 11/30/2022

cut all the rear axle abs wiring and hardwired all the wires together bypassing all the corroded ends and plugs. will need to test drive to confirm the repair.

88 Peterbilt 2,481,286 abs wiring on the truck needs replaced.

2:45PM 11/30/2022

took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.

88 Peterbilt 2,481,286 strengthen it

2:12PM 12/15/2022

took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.

88 Peterbilt 2,481,286 strengthen it

2:12PM 12/15/2022

88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022

88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022

88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022

88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022

88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022

88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	remove the bunk mounts and make a plate to strengthen it	took apart mounts cleaned up parts. cut out bad spots if back of cab under mounts added new painted. added bigger bolts for mounting.	2:12PM 12/15/2022
88 Peterbilt	2,481,286	Passenger full tank straps need tightened	tightened the tank strap bolts	2:31PM 11/30/2022
88 Peterbilt	2,481,286	Broken hood spring and cable	replaced hood spring, and removed old hood cable and replaced it with a new one that I made	2:54PM 11/30/2022
88 Peterbilt	2,481,286	Broken hood spring and cable	replaced hood spring, and removed old hood cable and replaced it with a new one that I made	2:54PM 11/30/2022
88 Peterbilt	2,481,286	left turn signal not working	bulb was out in dash causing break in the circuit so i replaced the bulb to fix circuit	9:50AM 12/1/2022

88 Peterbilt	2,481,286	air leak at right window switch also at axle diff lock switch	c/o window and axle air switches with new	3:24PM 12/16/2022
88 Peterbilt	2,481,286	air leak at right window switch also at axle diff lock	c/o window and axle air switches with new	3:24PM 12/16/2022
88 Peterbilt	2,481,286	air leak at right window switch also at axle diff lock switch	c/o window and axle air switches with new	3:24PM 12/16/2022
88 Peterbilt	2,481,286	remove motive eld and installed samsara eld with camera	remove motive eld and installed samsara eld with camera	10:49AM 12/29/2022
88 Peterbilt	#####	loose finder	loose finder	1:37PM 1/11/2023
88 Peterbilt	#####	loose finder	loose finder	1:37PM 1/11/2023
88 Peterbilt	#####	check steer u bolts	check steer u bolts	1:37PM 1/11/2023
88 Peterbilt	#####			
88 Peterbilt	2,500,072	truck has a water leak on a valve near the steps.	Put pressure to coolant system found leak on the back right corner of the block going into the oil cooler replaced the clamp on the fitting and pressure tested again.	10:07AM 2/9/2023
88 Peterbilt	2,500,072	bunk door latch not working	disassembled and found that bunk latch and handle need replaced.	10:08AM 2/9/2023
88 Peterbilt	2,500,072	bunk door latch not working	disassembled and found that bunk latch and handle need replaced.	10:08AM 2/9/2023
88 Peterbilt	2,500,072	inspect front brakes, driver says they may be hanging up a little bit	Inspected the brakes, still have plenty of life left on shoes, didn't seem to be dragging/hanging up	10:08AM 2/9/2023

[illegible]

88	Peterbilt	2,290,517	front headlight flickering in and out.	Ground wire running into the plug was corroded went to go wiggle it around and the pin came out of the plug, so i made a new plug for just the ground wire	11:26AM 2/15/2023
88	Peterbilt	2,290,517	front headlight flickering in and out.	Ground wire running into the plug was corroded went to go wiggle it around and the pin came out of the plug, so i made a new plug for just the ground wire	11:26AM 2/15/2023
88	Peterbilt	2,290,517	front headlight flickering in and out.	Ground wire running into the plug was corroded went to go wiggle it around and the pin came out of the plug, so i made a new plug for just the ground wire	11:26AM 2/15/2023
88	Peterbilt	2,504,886	Federal Annual DOT Inspection w/ Checklist	3/7/23 Asher * Performed DOT inspection * Checked all wheels, tire pressures (100psi for drives and 110psi for steer tires) * Checked brake drums and linings * Checked wheel seals * Checked wiper blades and windshields * Checked operation of all lights	10:31AM 3/7/2023

			3/7/23 Asher	
			* Brought truck into shop and removed dash to get access to tracker system	
			* Removed old tracker system box (Had to wait for Ashley to get me a new tracker, since they were in a meeting)	
			* Installed new tracker system and had to wait 10 minutes for tracker to boot up	
			* Got the alert from Derek that tracker was working correctly	
			* Installed dash back in place and secured all interior panels that were removed	
			* Let driver know his truck was done	
88 Peterbilt	2,504,886	remove and replace the ELD tracker with a new one.		10:37AM 3/7/2023
88 Peterbilt	2,504,886			
88 Peterbilt	2,302,131	remove and replace CB radio	rr cb radio	3:36PM 3/24/2023
88 Peterbilt	2,302,131			
88 Peterbilt	2,302,131	remove and replace CB radio	rr cb radio	3:36PM 3/24/2023
88 Peterbilt	2,302,131			

Asher 4/7/23

- * Greased truck
- * Checked and adjusted tire pressures
- * Found exhaust leak just before Y pipe for stacks
- * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps
- * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next)
- * Cleaned up from repairs and inspection

Asher & Cole 4/7/23

- * Removed herd bumper due to deer collision

Cole & Russ 4/7/23

Removed bumper off of 84 and installed it onto 88
Re-tapped license plate bracket holes

Cole 4/7/23

Completed service and checked all fluids

9:45AM 4/10/2023

88 Peterbilt 2,308,558 18000 Full Wet Service (Lube, Oil & Filters)

Asher 4/7/23

- * Greased truck
- * Checked and adjusted tire pressures
- * Found exhaust leak just before Y pipe for stacks
- * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps
- * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next)
- * Cleaned up from repairs and inspection

Asher & Cole 4/7/23

- * Removed herd bumper due to deer collision

Cole & Russ 4/7/23

Removed bumper off of 84 and installed it onto 88
Re tapped license plate bracket holes

Cole 4/7/23

Completed service and checked all fluids

9:45AM 4/10/2023

88 Peterbilt 2,308,558 18000 Full Wet Service (Lube, Oil & Filters)

		<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection 	
		<p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision 	
		<p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re-tapped license plate bracket holes</p>	
		<p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p>	
88 Peterbilt	2,308,558 18000 Full Wet Service (Lube, Oil & Filters)		9:45AM 4/10/2023

			Asher 4/7/23
			<ul style="list-style-type: none">* Greased truck* Checked and adjusted tire pressures* Found exhaust leak just before Y pipe for stacks* Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps* Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next)* Cleaned up from repairs and inspection
			Asher & Cole 4/7/23
			<ul style="list-style-type: none">* Removed herd bumper due to deer collision
			Cole & Russ 4/7/23
			Removed bumper off of 84 and installed it onto 88
			Re tapped license plate bracket holes
			Cole 4/7/23
			Completed service and checked all fluids
88 Peterbilt	2,308,558	18000 Full Wet Service (Lube, Oil & Filters)	9:45AM 4/10/2023

		<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection
		<p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision
		<p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re-tapped license plate bracket holes</p>
		<p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p>
88 Peterbilt	2,308,558 18000 Full Wet Service (Lube, Oil & Filters)	9:45AM 4/10/2023

Asher 4/7/23

- * Greased truck
- * Checked and adjusted tire pressures
- * Found exhaust leak just before Y pipe for stacks
- * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps
- * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next)
- * Cleaned up from repairs and inspection

Asher & Cole 4/7/23

- * Removed herd bumper due to deer collision

Cole & Russ 4/7/23

Removed bumper off of 84 and installed it onto 88
Re tapped license plate bracket holes

Cole 4/7/23

Completed service and checked all fluids

9:45AM 4/10/2023

88 Peterbilt 2,308,558 18000 Full Wet Service (Lube, Oil & Filters)

		<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection
		<p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision
		<p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re tapped license plate bracket holes</p>
		<p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p>
88 Peterbilt	2,308,558 18000 Full Wet Service (Lube, Oil & Filters)	9:45AM 4/10/2023

			<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection
			<p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision
			<p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re tapped license plate bracket holes</p>
			<p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p>
88 Peterbilt	2,308,558	18000 Full Wet Service (Lube, Oil & Filters)	9:45AM 4/10/2023

		<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection
		<p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision
		<p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re-tapped license plate bracket holes</p>
		<p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p>
88 Peterbilt	2,308,558 18000 Full Wet Service (Lube, Oil & Filters)	9:45AM 4/10/2023

		<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection 	
		<p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision 	
		<p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re tapped license plate bracket holes</p>	
		<p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p>	
88 Peterbilt	2,308,558 18000 Full Wet Service (Lube, Oil & Filters)		9:45AM 4/10/2023

88 Peterbilt 2,308,558 18000 Full Wet Service (Lube, Oil & Filters)	<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection <p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision <p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re-tapped license plate bracket holes</p> <p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p> <p>9:45AM 4/10/2023</p>
---------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Asher 4/7/23

- * Greased truck
- * Checked and adjusted tire pressures
- * Found exhaust leak just before Y pipe for stacks
- * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps
- * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next)
- * Cleaned up from repairs and inspection

Asher & Cole 4/7/23

- * Removed herd bumper due to deer collision

Cole & Russ 4/7/23

Removed bumper off of 84 and installed it onto 88
Re tapped license plate bracket holes

Cole 4/7/23

Completed service and checked all fluids

9:45AM 4/10/2023

88 Peterbilt 2,308,558 18000 Full Wet Service (Lube, Oil & Filters)

88 Peterbilt 2,308,558 18000 Full Wet Service (Lube, Oil & Filters)	<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection <p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision <p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re tapped license plate bracket holes</p> <p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p> <p>9:45AM 4/10/2023</p>
---------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

			<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection
			<p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision
			<p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re-tapped license plate bracket holes</p>
			<p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p>
88 Peterbilt	2,308,558	18000 Full Wet Service (Lube, Oil & Filters)	9:45AM 4/10/2023

				<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection
				<p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision
				<p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re tapped license plate bracket holes</p>
				<p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p>
88 Peterbilt	2,308,558	18000	Full Wet Service (Lube, Oil & Filters)	9:45AM 4/10/2023

Asher 4/7/23

- * Greased truck
- * Checked and adjusted tire pressures
- * Found exhaust leak just before Y pipe for stacks
- * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps
- * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next)
- * Cleaned up from repairs and inspection

Asher & Cole 4/7/23

- * Removed herd bumper due to deer collision

Cole & Russ 4/7/23

Removed bumper off of 84 and installed it onto 88
Re-tapped license plate bracket holes

Cole 4/7/23

Completed service and checked all fluids

9:45AM 4/10/2023

88 Peterbilt 2,308,558 18000 Full Wet Service (Lube, Oil & Filters)

Asher 4/7/23

- * Greased truck
- * Checked and adjusted tire pressures
- * Found exhaust leak just before Y pipe for stacks
- * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps
- * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next)
- * Cleaned up from repairs and inspection

Asher & Cole 4/7/23

- * Removed herd bumper due to deer collision

Cole & Russ 4/7/23

Removed bumper off of 84 and installed it onto 88
Re tapped license plate bracket holes

Cole 4/7/23

Completed service and checked all fluids

88 Peterbilt 2,308,558 18000 Full Wet Service (Lube, Oil & Filters)

9:45AM 4/10/2023

88 Peterbilt	2,308,558 18000 Full Wet Service (Lube, Oil & Filters)	Asher 4/7/23	
		* Greased truck	
		* Checked and adjusted tire pressures	
		* Found exhaust leak just before Y pipe for stacks	
		* Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps	
		* Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next)	
		* Cleaned up from repairs and inspection	
		Asher & Cole 4/7/23	
		* Removed herd bumper due to deer collision	
		Cole & Russ 4/7/23	
		Removed bumper off of 84 and installed it onto 88	
		Re tapped license plate bracket holes	
		Cole 4/7/23	
		Completed service and checked all fluids	
		9:45AM 4/10/2023	

88 Peterbilt	2,308,558 18000 Full Wet Service (Lube, Oil & Filters)	Asher 4/7/23	
		* Greased truck	
		* Checked and adjusted tire pressures	
		* Found exhaust leak just before Y pipe for stacks	
		* Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps	
		* Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next)	
		* Cleaned up from repairs and inspection	
		Asher & Cole 4/7/23	
		* Removed herd bumper due to deer collision	
		Cole & Russ 4/7/23	
		Removed bumper off of 84 and installed it onto 88	
		Re tapped license plate bracket holes	
		Cole 4/7/23	
		Completed service and checked all fluids	
		9:45AM 4/10/2023	

Asher 4/7/23

- * Greased truck
- * Checked and adjusted tire pressures
- * Found exhaust leak just before Y pipe for stacks
- * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps
- * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next)
- * Cleaned up from repairs and inspection

Asher & Cole 4/7/23

- * Removed herd bumper due to deer collision

Cole & Russ 4/7/23

Removed bumper off of 84 and installed it onto 88
Re tapped license plate bracket holes

Cole 4/7/23

Completed service and checked all fluids

9:45AM 4/10/2023

88 Peterbilt 2,308,558 18000 Full Wet Service (Lube, Oil & Filters)

			<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection
			<p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision
			<p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re-tapped license plate bracket holes</p>
			<p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p>
88 Peterbilt	2,308,558	18000 Full Wet Service (Lube, Oil & Filters)	9:45AM 4/10/2023

88 Peterbilt	2,308,558 18000 Full Wet Service (Lube, Oil & Filters)	Completed service and checked all fluids	9:45AM 4/10/2023
Asher 4/7/23			
* Greased truck			
* Checked and adjusted tire pressures			
* Found exhaust leak just before Y pipe for stacks			
* Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps			
* Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next)			
* Cleaned up from repairs and inspection			
Asher & Cole 4/7/23			
* Removed herd bumper due to deer collision			
Cole & Russ 4/7/23			
Removed bumper off of 84 and installed it onto 88			
Re tapped license plate bracket holes			
Cole 4/7/23			

Asher 4/7/23

- * Greased truck
- * Checked and adjusted tire pressures
- * Found exhaust leak just before Y pipe for stacks
- * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps
- * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next)
- * Cleaned up from repairs and inspection

Asher & Cole 4/7/23

- * Removed herd bumper due to deer collision

Cole & Russ 4/7/23

Removed bumper off of 84 and installed it onto 88
Re tapped license plate bracket holes

Cole 4/7/23

Completed service and checked all fluids

88 Peterbilt 2,308,558 18000 Full Wet Service (Lube, Oil & Filters)

9:45AM 4/10/2023

			<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection
			<p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision
			<p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re tapped license plate bracket holes</p>
			<p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p>
88 Peterbilt	2,308,558	18000 Full Wet Service (Lube, Oil & Filters)	9:45AM 4/10/2023

		<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection
		<p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision
		<p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re-tapped license plate bracket holes</p>
		<p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p>
88 Peterbilt	2,308,558 18000 Full Wet Service (Lube, Oil & Filters)	9:45AM 4/10/2023

		<p>Asher 4/7/23</p> <ul style="list-style-type: none"> * Greased truck * Checked and adjusted tire pressures * Found exhaust leak just before Y pipe for stacks * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next) * Cleaned up from repairs and inspection 	
		<p>Asher & Cole 4/7/23</p> <ul style="list-style-type: none"> * Removed herd bumper due to deer collision 	
		<p>Cole & Russ 4/7/23</p> <p>Removed bumper off of 84 and installed it onto 88</p> <p>Re tapped license plate bracket holes</p>	
		<p>Cole 4/7/23</p> <p>Completed service and checked all fluids</p>	
88 Peterbilt	2,308,558 18000 Full Wet Service (Lube, Oil & Filters)		9:45AM 4/10/2023

Asher 4/7/23

- * Greased truck
- * Checked and adjusted tire pressures
- * Found exhaust leak just before Y pipe for stacks
- * Cut out old flex pipe, cut section of new exhaust pipe, and installed with new exhaust clamps
- * Tried to secure exhaust system, but exhaust bracket half rusted out and brittle (Will need to fully repair when truck is brought into shop next)
- * Cleaned up from repairs and inspection

Asher & Cole 4/7/23

- * Removed herd bumper due to deer collision

Cole & Russ 4/7/23

Removed bumper off of 84 and installed it onto 88

Re-tapped license plate bracket holes

Cole 4/7/23

Completed service and checked all fluids 9:45AM 4/10/2023

88 Peterbilt	2,308,558	18000 Full Wet Service (Lube, Oil & Filters)
88 Peterbilt	2,308,558	

Drivers Door Latch Striker Replaced, Part Robbed
From Truck 94
4:56PM 4/13/2023

88 Peterbilt	2,311,890	Repair passenger door latch
88 Peterbilt	2,311,890	

88 Peterbilt	2,290,517	blue light behind rpm gauge is flickering	light was starting to pop out of the back of the gauge, popped the light back in.	9:23AM 3/1/2023
88 Peterbilt	2,290,517	oil temp gauge not working	Oil temp sensor in the oil pan is not hooked up looks like the wires were either cut or ripped off at some point in time. Tested the pyro gauge and the wiring all of it is good wasnt able to test the exhaust probe	8:49PM 4/12/2023
88 Peterbilt	2,290,517	gear shifter needs secured down	installed used cb (did not tune it) tightened up the locknut on the shift tower	8:50PM 4/12/2023
88 Peterbilt	2,290,517	train horn is very weak, fix or install new horn.	train horn works fine	1:20PM 3/1/2023
88 Peterbilt	2,290,517	give truck a full PM as this will be getting a new driver on Monday.	greased the entire truck and checked all fluids, and brakes.	2:29PM 3/1/2023
88 Peterbilt	2,290,517	give truck a full PM as this will be getting a new driver on Monday.	greased the entire truck and checked all fluids, and brakes.	2:29PM 3/1/2023
88 Peterbilt	2,290,517	truck needs cleaned out and the outside washed. there will be a new driver getting in this truck on Monday.	truck needs cleaned out and the outside washed. there will be a new driver getting in this truck on Monday.	3:15PM 4/17/2023

88 Peterbilt 2,290,517 Fuel leak on the back of the block

cole-Inspected for fuel leak and found that the fuel line on the back of the block was being rubbed on the block and fuel was seeping out, replaced the line had to brozenes to pick up the right fittings. let truck sit and run for 5 mins and nothing started leaking.

4:05PM 4/19/2023

88 Peterbilt 2,290,517 Fuel leak on the back of the block

cole-Inspected for fuel leak and found that the fuel line on the back of the block was being rubbed on the block and fuel was seeping out, replaced the line had to brozenes to pick up the right fittings. let truck sit and run for 5 mins and nothing started leaking.

4:05PM 4/19/2023

88 Peterbilt 2,290,517 Fuel leak on the back of the block
88 Peterbilt 2,290,517 Replace Door Handles
88 Peterbilt 2,290,517 Replace Door Handles
88 Peterbilt 2,290,517 Replace Door Handles
88 Peterbilt 2,290,517 Replace Door Handles
88 Peterbilt 2,290,517 Replace Door Handles

cole-Inspected for fuel leak and found that the fuel line on the back of the block was being rubbed on the block and fuel was seeping out, replaced the line had to brozenes to pick up the right fittings. let truck sit and run for 5 mins and nothing started leaking.

4:05PM 4/19/2023

#NAME?
#NAME?
#NAME?
#NAME?
#NAME?
#NAME?

8:47PM 4/12/2023
8:47PM 4/12/2023
8:47PM 4/12/2023
8:47PM 4/12/2023
8:47PM 4/12/2023
8:47PM 4/12/2023

88 Peterbilt 2,290,517 Drivers side low beam not working

pulled about the whole wiring harness because once i fixed the low beam the truck would blow a fuse when brights were flicked on. Found that the high beam was running to a ground on the light causing a fuse to blow. So I wired it back up the correct way and everything works as it should now 4:50PM 3/3/2023

88 Peterbilt 2,290,517 Drivers side low beam not working
88 Peterbilt 2,290,517

pulled about the whole wiring harness because once i fixed the low beam the truck would blow a fuse when brights were flicked on. Found that the high beam was running to a ground on the light causing a fuse to blow. So I wired it back up the correct way and everything works as it should now 4:50PM 3/3/2023

Asher 5/5/23

- Jacked front end and removed both steer wheels
 - Removed brake drums and shoes
 - Retrieved brake shoes and drums from inventory
 - Cleaned and lubricated wheel studs, lug nut flanges and hub guides
 - Installed new brake shoes and brake drums
 - Installed both steer wheels
 - Torqued lug nuts and installed plastic axle covers 3:23PM 5/11/2023
- 88 Peterbilt 2,322,341 steer axle brake shoes and drums need replaced

Asher 5/5/23

- Jacked front end and removed both steer wheels
 - Removed brake drums and shoes
 - Retrieved brake shoes and drums from inventory
 - Cleaned and lubricated wheel studs, lug nut flanges and hub guides
 - Installed new brake shoes and brake drums
 - Installed both steer wheels
 - Torqued lug nuts and installed plastic axle covers 3:23PM 5/11/2023
- 88 Peterbilt 2,322,341 steer axle brake shoes and drums need replaced

88 Peterbilt 2,322,341 steer axle brake shoes and drums need replaced

Asher 5/5/23

- Jacked front end and removed both steer wheels
- Removed brake drums and shoes
- Retrieved brake shoes and drums from inventory
- Cleaned and lubricated wheel studs, lug nut flanges and hub guides
- Installed new brake shoes and brake drums
- Installed both steer wheels
- Torqued lug nuts and installed plastic axle covers 3:23PM 5/11/2023

88 Peterbilt 2,322,341 steer axle brake shoes and drums need replaced

Asher 5/5/23

- Jacked front end and removed both steer wheels
- Removed brake drums and shoes
- Retrieved brake shoes and drums from inventory
- Cleaned and lubricated wheel studs, lug nut flanges and hub guides
- Installed new brake shoes and brake drums
- Installed both steer wheels
- Torqued lug nuts and installed plastic axle covers 3:23PM 5/11/2023

88 Peterbilt	2,322,341	Truck Fails to turn Over	swapped ignition switch Pulled all battery cables out to check for breaks or rub throughs found loose frame ground contacting the power junction for the alternator fixed frame mount reconnected battery cables and truck started up	9:46PM 5/5/2023
--------------	-----------	--------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------

88 Peterbilt	2,322,341	Truck Fails to turn Over	swapped ignition switch Pulled all battery cables out to check for breaks or rub throughs found loose frame ground contacting the power junction for the alternator fixed frame mount reconnected battery cables and truck started up	9:46PM 5/5/2023
--------------	-----------	--------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------

88 Peterbilt	2,322,341	Truck Fails to turn Over		9:46PM 5/5/2023
--------------	-----------	--------------------------	--	-----------------

88 Peterbilt	2,326,226	18000 Full Wet Service (Lube, Oil & Filters)	completed full wet service greased truck checked all fluid lvs	4:02PM 5/17/2023
--------------	-----------	----------------------------------------------	----------------------------------------------------------------------	------------------

88	Peterbilt	2,326,226	18000 Full Wet Service (Lube, Oil & Filters)	completed full wet service greased truck checked all fluid lvs completed full wet service greased truck	4:02PM 5/17/2023
88	Peterbilt	2,326,226	18000 Full Wet Service (Lube, Oil & Filters)	checked all fluid lvs completed full wet service greased truck	4:02PM 5/17/2023
88	Peterbilt	2,326,226	18000 Full Wet Service (Lube, Oil & Filters)	checked all fluid lvs completed full wet service greased truck	4:02PM 5/17/2023
88	Peterbilt	2,326,226	18000 Full Wet Service (Lube, Oil & Filters)	checked all fluid lvs completed full wet service greased truck	4:02PM 5/17/2023
88	Peterbilt	2,326,226	18000 Full Wet Service (Lube, Oil & Filters)	checked all fluid lvs completed full wet service greased truck	4:02PM 5/17/2023
88	Peterbilt	2,327,975	#8 tire is flat	Removed and replace #8 & #7 drive tires due to amount of wear due to a flat tire replaced with used 11R24.5 drive tires 9/32 8/32	9:42AM 5/23/2023
88	Peterbilt	2,327,975	#8 tire is flat	Removed and replace #8 & #7 drive tires due to amount of wear due to a flat tire replaced with used 11R24.5 drive tires 9/32 8/32	9:42AM 5/23/2023

88 Peterbilt	2,327,975 #8 tire is flat	<p>Removed and replace #8 & #7 drive tires due to amount of wear due to a flat tire replaced with used 11r24.5 drive tires</p> <p>9/32</p> <p>8/32</p>	9:42AM 5/23/2023
88 Peterbilt	2,327,975 #8 tire is flat	<p>Removed and replace #8 & #7 drive tires due to amount of wear due to a flat tire replaced with used 11r24.5 drive tires</p> <p>9/32</p> <p>8/32</p>	9:42AM 5/23/2023
88 Peterbilt	2,326,319 repair voltage and fuel gauge light within dash	<p>Asher 6/7/23</p> <p>-Removed dash and inspected the voltage and fuel level gauge bulbs</p> <p>-Replaced burnt out bulbs</p>	11:11AM 6/9/2023
88 Peterbilt	2,326,319 repair voltage and fuel gauge light within dash	<p>Asher 6/7/23</p> <p>-Removed dash and inspected the voltage and fuel level gauge bulbs</p> <p>-Replaced burnt out bulbs</p>	11:11AM 6/9/2023
88 Peterbilt	2,326,319 repair voltage and fuel gauge light within dash	<p>Asher 6/7/23</p> <p>-Removed dash and inspected the voltage and fuel level gauge bulbs</p> <p>-Replaced burnt out bulbs</p>	11:11AM 6/9/2023

88 Peterbilt 2,326,319 repair voltage and fuel gauge light within dash

88 Peterbilt 2,326,319 Repair driver side door Latch

88 Peterbilt 2,326,319 Repair Fender Bracket

Asher 6/7/23

-Removed dash and inspected the voltage and fuel level gauge bulbs

-Replaced burnt out bulbs

#NAME?

11:11AM 6/9/2023

10:10AM 6/6/2023

removed all loose mounting hardware cleaned up threads and remounted

2:31PM 5/16/2023

88 Peterbilt 2,326,319 ABS light on

-removed lower section of dash to access ABS ECU
-removed old ABS ECU and replaced it with new one
-re-installed lower section of the dash
Grant 5/16/23
inspected abs wiring, control muduals, and ecm codes
removed wiring on the rear abs system
removed the control units and the module
Grant 6/5/23
removed the driver side steer axel abs module
removed fittings and installed onto new
installed new module
test drove truck
Asher 6/6/23
-Hooked up code reader an checked codes of abs light
-Checked connect of all harness in the back of front module recently installed
-Started inspecting data link wires (Will continue in the morning)
Asher 6/7/23
-Inspected wear and condition of data link wires from abs module to firewall
-Dug deep into dash abs harness and checked wire continuties

11:15AM 6/9/2023

88 Peterbilt 2,326,319 ABS light on

-removed lower section of dash to access ABS ECU
-removed old ABS ECU and replaced it with new one
-reinstalled lower section of the dash
Grant 5/16/23
inspected abs wiring, control muduals, and ecm codes
removed wiring on the the rear abs system
removed the control units and the module
Grant 6/5/23
removed the driver side steer axel abs module
removed fittings and installed onto new
installed new module
test drove truck
Asher 6/6/23
-Hooked up code reader an checked codes of abs light
-Checked connect of all harness in the back of front module recently installed
-Started inspecting data link wires (Will continue in the morning)
Asher 6/7/23
-Inspected wear and condition of data link wires from abs module to firewall
-Dug deep into dash abs harness and checked wire continuities

11:15AM 6/9/2023

88 Peterbilt 2,326,319 ABS light on

-removed lower section of dash to access ABS ECU
-removed old ABS ECU and replaced it with new one
-reinstalled lower section of the dash
Grant 5/16/23
inspected abs wiring, control muduals, and ecm codes
removed wiring on the rear abs system
removed the control units and the module
Grant 6/5/23
removed the driver side steer axel abs module
removed fittings and installed onto new
installed new module
test drove truck
Asher 6/6/23
-Hooked up code reader an checked codes of abs light
-Checked connect of all harness in the back of front module recently installed
-Started inspecting data link wires (Will continue in the morning)
Asher 6/7/23
-Inspected wear and condition of data link wires from abs module to firewall
-Dug deep into dash abs harness and checked wire continuties

11:15AM 6/9/2023

88 Peterbilt 2,326,319 ABS light on

-removed lower section of dash to access ABS ECU
-removed old ABS ECU and replaced it with new one
-reinstalled lower section of the dash
Grant 5/16/23
inspected abs wiring, control muduals, and ecm codes
removed wiring on the the rear abs system
removed the control units and the module
Grant 6/5/23
removed the driver side steer axel abs module
removed fittings and installed onto new
installed new module
test drove truck
Asher 6/6/23
-Hooked up code reader an checked codes of abs light
-Checked connect of all harness in the back of front module recently installed
-Started inspecting data link wires (Will continue in the morning)
Asher 6/7/23
-Inspected wear and condition of data link wires from abs module to firewall
-Dug deep into dash abs harness and checked wire continuties

11:15AM 6/9/2023

88 Peterbilt 2,326,319 ABS light on

-removed lower section of dash to access ABS ECU
-removed old ABS ECU and replaced it with new one
-reinstalled lower section of the dash
Grant 5/16/23
inspected abs wiring, control muduals, and ecm codes
removed wiring on the the rear abs system
removed the control units and the module
Grant 6/5/23
removed the driver side steer axel abs module
removed fittings and installed onto new
installed new module
test drove truck
Asher 6/6/23
-Hooked up code reader an checked codes of abs light
-Checked connect of all harness in the back of front module recently installed
-Started inspecting data link wires (Will continue in the morning)
Asher 6/7/23
-Inspected wear and condition of data link wires from abs module to firewall
-Dug deep into dash abs harness and checked wire continuities

11:15AM 6/9/2023

88 Peterbilt 2,326,319 ABS light on

-removed lower section of dash to access ABS ECU
-removed old ABS ECU and replaced it with new one
-reinstalled lower section of the dash
Grant 5/16/23
inspected abs wiring, control muduals, and ecm codes
removed wiring on the the rear abs system
removed the control units and the module
Grant 6/5/23
removed the driver side steer axel abs module
removed fittings and installed onto new
installed new module
test drove truck
Asher 6/6/23
-Hooked up code reader an checked codes of abs light
-Checked connect of all harness in the back of front module recently installed
-Started inspecting data link wires (Will continue in the morning)
Asher 6/7/23
-Inspected wear and condition of data link wires from abs module to firewall
-Dug deep into dash abs harness and checked wire continuties

11:15AM 6/9/2023

88 Peterbilt 2,326,319 ABS light on

-removed lower section of dash to access ABS ECU
-removed old ABS ECU and replaced it with new one
-reinstalled lower section of the dash
Grant 5/16/23
inspected abs wiring, control muduals, and ecm codes
removed wiring on the the rear abs system
removed the control units and the module
Grant 6/5/23
removed the driver side steer axel abs module
removed fittings and installed onto new
installed new module
test drove truck
Asher 6/6/23
-Hooked up code reader an checked codes of abs light
-Checked connect of all harness in the back of front module recently installed
-Started inspecting data link wires (Will continue in the morning)
Asher 6/7/23
-Inspected wear and condition of data link wires from abs module to firewall
-Dug deep into dash abs harness and checked wire continuities

11:15AM 6/9/2023

88 Peterbilt 2,326,319 ABS light on

removed lower section of dash to access ABS ECU
-removed old ABS ECU and replaced it with new one
-reinstalled lower section of the dash
Grant 5/16/23
inspected abs wiring, control muduals, and ecm codes
removed wiring on the the rear abs system
removed the control units and the module
Grant 6/5/23
removed the driver side steer axel abs module
removed fittings and installed onto new installed new module
test drove truck
Asher 6/6/23
-Hooked up code reader an checked codes of abs light
-Checked connect of all harness in the back of front module recently installed
-Started inspecting data link wires (Will continue in the morning)
Asher 6/7/23
-Inspected wear and condition of data link wires from abs module to firewall
-Dug deep into dash abs harness and checked wire continuities
11:15AM 6/9/2023

88 Peterbilt 2,326,319 ABS light on

-removed lower section of dash to access ABS ECU
-removed old ABS ECU and replaced it with new one
-reinstalled lower section of the dash
Grant 5/16/23
inspected abs wiring, control muduals, and ecm codes
removed wiring on the the rear abs system
removed the control units and the module
Grant 6/5/23
removed the driver side steer axel abs module
removed fittings and installed onto new
installed new module
test drove truck
Asher 6/6/23
-Hooked up code reader an checked codes of abs light
-Checked connect of all harness in the back of front module recently installed
-Started inspecting data link wires (Will continue in the morning)
Asher 6/7/23
-Inspected wear and condition of data link wires from abs module to firewall
-Dug deep into dash abs harness and checked wire continuties

11:15AM 6/9/2023

88 Peterbilt 2,326,319 ABS light on

- removed lower section of dash to access ABS ECU
- removed old ABS ECU and replaced it with new one
- reinstalled lower section of the dash
- Grant 5/16/23
- inspected abs wiring, control muduals, and ecm codes
- removed wiring on the rear abs system
- removed the control units and the module
- Grant 6/5/23
- removed the driver side steer axel abs module
- removed fittings and installed onto new installed new module
- test drove truck
- Asher 6/6/23
- Hooked up code reader an checked codes of abs light
- Checked connect of all harness in the back of front module recently installed
- Started inspecting data link wires (Will continue in the morning)
- Asher 6/7/23
- Inspected wear and condition of data link wires from abs module to firewall
- Dug deep into dash abs harness and checked wire continuities

11:15AM 6/9/2023

88 Peterbilt 2,326,319 ABS light on

-removed lower section of dash to access ABS ECU
-removed old ABS ECU and replaced it with new one
-reinstalled lower section of the dash
Grant 5/16/23
inspected abs wiring, control muduals, and ecm codes
removed wiring on the the rear abs system
removed the control units and the module
Grant 6/5/23
removed the driver side steer axel abs module
removed fittings and installed onto new
installed new module
test drove truck
Asher 6/6/23
-Hooked up code reader an checked codes of abs light
-Checked connect of all harness in the back of front module recently installed
-Started inspecting data link wires (Will continue in the morning)
Asher 6/7/23
-Inspected wear and condition of data link wires from abs module to firewall
-Dug deep into dash abs harness and checked wire continuties

11:15AM 6/9/2023

88 Peterbilt 2,326,319 ABS light on

-removed lower section of dash to access ABS ECU
-removed old ABS ECU and replaced it with new one
-reinstalled lower section of the dash
Grant 5/16/23
inspected abs wiring, control muduals, and ecm codes
removed wiring on the the rear abs system
removed the control units and the module
Grant 6/5/23
removed the driver side steer axel abs module
removed fittings and installed onto new
installed new module
test drove truck
Asher 6/6/23
-Hooked up code reader an checked codes of abs light
-Checked connect of all harness in the back of front module recently installed
-Started inspecting data link wires (Will continue in the morning)
Asher 6/7/23
-Inspected wear and condition of data link wires from abs module to firewall
-Dug deep into dash abs harness and checked wire continuities

11:15AM 6/9/2023

88 Peterbilt 2,326,319 ABS light on

-removed lower section of dash to access ABS ECU
-removed old ABS ECU and replaced it with new one
-reinstalled lower section of the dash
Grant 5/16/23
inspected abs wiring, control muduals, and ecm codes
removed wiring on the rear abs system
removed the control units and the module
Grant 6/5/23
removed the driver side steer axel abs module
removed fittings and installed onto new
installed new module
test drove truck
Asher 6/6/23
-Hooked up code reader an checked codes of abs light
-Checked connect of all harness in the back of front module recently installed
-Started inspecting data link wires (Will continue in the morning)
Asher 6/7/23
-Inspected wear and condition of data link wires from abs module to firewall
-Dug deep into dash abs harness and checked wire continuities

11:15AM 6/9/2023

88 Peterbilt 2,326,319 ABS light on

-removed lower section of dash to access ABS ECU
-removed old ABS ECU and replaced it with new one
-reinstalled lower section of the dash
Grant 5/16/23
inspected abs wiring, control muduals, and ecm codes
removed wiring on the the rear abs system
removed the control units and the module
Grant 6/5/23
removed the driver side steer axel abs module
removed fittings and installed onto new
installed new module
test drove truck
Asher 6/6/23
-Hooked up code reader an checked codes of abs light
-Checked connect of all harness in the back of front module recently installed
-Started inspecting data link wires (Will continue in the morning)
Asher 6/7/23
-Inspected wear and condition of data link wires from abs module to firewall
-Dug deep into dash abs harness and checked wire continuities

11:15AM 6/9/2023

		<ul style="list-style-type: none"> -removed lower section of dash to access ABS ECU -removed old ABS ECU and replaced it with new one -reinstalled lower section of the dash 	
		Grant 5/16/23	
		inspected abs wiring, control muduals, and ecm codes	
		removed wiring on the rear abs system	
		removed the control units and the module	
		Grant 6/5/23	
		removed the driver side steer axel abs module	
		removed fittings and installed onto new installed new module	
		test drove truck	
		Asher 6/6/23	
		-Hooked up code reader an checked codes of abs light	
		-Checked connect of all harness in the back of front module recently installed	
		-Started inspecting data link wires (Will continue in the morning)	
		Asher 6/7/23	
		-Inspected wear and condition of data link wires from abs module to firewall	
		-Dug deep into dash abs harness and checked wire continuities	
88 Peterbilt	2,326,319 ABS light on		11:15AM 6/9/2023
88 Peterbilt	2,326,319 air horn does not work, may be a wiring issue	power wire for the horn that runs from battery go switched to a ground post last time we had the battery cables off so i switched the wire back and horn worked perfect	4:38PM 5/17/2023

88 Peterbilt	2,326,319	Inspect fuel leak/ fuel caps	Asher 6/6/23 -Removed and replaced both fuel fill caps	11:12AM 6/9/2023
88 Peterbilt	2,326,319	Inspect fuel leak/ fuel caps	Asher 6/6/23 -Removed and replaced both fuel fill caps	11:12AM 6/9/2023
88 Peterbilt	2,339,963	both steer tires need replaced, balanced and front aligned front steer axle	RR steer tires and and balanced them(had to figure out how to run the balancer again Set up truck for alignment checked the rear and it was in spec	3:44PM 6/26/2023
88 Peterbilt	2,339,963	both steer tires need replaced, balanced and front aligned front steer axle	RR steer tires and and balanced them(had to figure out how to run the balancer again Set up truck for alignment checked the rear and it was in spec	3:44PM 6/26/2023
88 Peterbilt	2,339,963	both steer tires need replaced, balanced and front aligned front steer axle	RR steer tires and and balanced them(had to figure out how to run the balancer again Set up truck for alignment checked the rear and it was in spec	3:44PM 6/26/2023
88 Peterbilt	2,339,963	both steer tires need replaced, balanced and front aligned front steer axle	RR steer tires and and balanced them(had to figure out how to run the balancer again Set up truck for alignment checked the rear and it was in spec	3:44PM 6/26/2023

88 Peterbilt	2,339,963	both steer tires need replaced, balanced and front alignment checked	replace dash lights.	3:44PM 6/26/2023
88 Peterbilt	2,339,963	both steer tires need replaced, balanced and front alignment checked	RR steer tires and and balanced them(had to figure out how to run the balancer again Set up truck for alignment aligned front steer axle checked the rear and it was in spec	3:44PM 6/26/2023
88 Peterbilt	2,339,963	both steer tires need replaced, balanced and front alignment checked	RR steer tires and and balanced them(had to figure out how to run the balancer again Set up truck for alignment aligned front steer axle checked the rear and it was in spec	3:44PM 6/26/2023
88 Peterbilt	2,339,963	both steer tires need replaced, balanced and front alignment checked	replace dash lights.	3:44PM 6/26/2023
88 Peterbilt	2,339,963	both steer tires need replaced, balanced and front alignment checked	replace dash lights.	3:44PM 6/26/2023

88 Peterbilt	2,342,829	Full Wet Service (Truck #88)	Completed full wet service greased truck (had to change out grease fittings) King pin cap's threads stripped out so i replaced the cap Pressure tested coolant system	10:21AM 7/5/2023
88 Peterbilt	2,342,829	Full Wet Service (Truck #88)	Completed full wet service greased truck (had to change out grease fittings) King pin cap's threads stripped out so i replaced the cap Pressure tested coolant system	10:21AM 7/5/2023
88 Peterbilt	2,342,829	Full Wet Service (Truck #88)	Completed full wet service greased truck (had to change out grease fittings) King pin cap's threads stripped out so i replaced the cap Pressure tested coolant system	10:21AM 7/5/2023
88 Peterbilt	2,342,829	Full Wet Service (Truck #88)	Completed full wet service greased truck (had to change out grease fittings) King pin cap's threads stripped out so i replaced the cap Pressure tested coolant system	10:21AM 7/5/2023

88 Peterbilt	RR thermostat	RR thermostat and all components on the way cleaned all surfaces thoroughly installed new thermostats into the housing and reinstalled into the truck pressure tested coolant system filled coolant system back up degreased engine and inspected head gasket	1:53PM 7/18/2023
--------------	---------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------

88 Peterbilt	RR thermostat	RR thermostat and all components on the way cleaned all surfaces thoroughly installed new thermostats into the housing and reinstalled into the truck pressure tested coolant system filled coolant system back up degreased engine and inspected head gasket	1:53PM 7/18/2023
--------------	---------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------

88 Peterbilt	RR thermostat	RR thermostat and all components on the way cleaned all surfaces thoroughly installed new thermostats into the housing and reinstalled into the truck pressure tested coolant system filled coolant system back up degreased engine and inspected head gasket	1:53PM 7/18/2023
--------------	---------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------

88 Peterbilt	RR thermostat	RR thermostat and all components on the way cleaned all surfaces thoroughly installed new thermostats into the housing and reinstalled into the truck pressure tested coolant system filled coolant system back up degreased engine and inspected head gasket	1:53PM 7/18/2023
88 Peterbilt 88 Peterbilt	RR thermostat	RR thermostat and all components on the way cleaned all surfaces thoroughly installed new thermostats into the housing and reinstalled into the truck pressure tested coolant system filled coolant system back up degreased engine and inspected head gasket	1:53PM 7/18/2023
88 Peterbilt	2,346,555 inspect condition of tires	rr number 2 drive due to being past legal limit patched number 6 tire due to hole from screw in tire	9:00AM 8/22/2023
88 Peterbilt	2,346,555 inspect condition of tires	rr number 2 drive due to being past legal limit patched number 6 tire due to hole from screw in tire	9:00AM 8/22/2023
88 Peterbilt	2,346,555 dot tape rear mud flap brackets need to be installed with	removed fenders from truck 85 and installed onto truck 88	8:58AM 8/22/2023
88 Peterbilt	2,346,555 hood cable needs to be installed	installed	8:39AM 8/22/2023

88 Peterbilt	2,346,555 hood cable needs to be installed		installed	8:39AM 8/22/2023
88 Peterbilt	2,346,555 hood cable needs to be installed		installed	8:39AM 8/22/2023
88 Peterbilt	2,346,555 cleaned, door handle lubed up, remove fire hose,	5th wheel greased, hydraulic oil topped off, fittings cleaned, door handle lubed up, remove fire hose,	5th wheel greased, hydraulic oil topped off, fittings cleaned, door handle lubed up, remove fire hose,	8:35AM 8/22/2023
88 Peterbilt	2,346,555 cleaned, door handle lubed up, remove fire hose,	5th wheel greased, hydraulic oil topped off, fittings cleaned, door handle lubed up, remove fire hose,	5th wheel greased, hydraulic oil topped off, fittings cleaned, door handle lubed up, remove fire hose,	8:35AM 8/22/2023
88 Peterbilt	2,346,555 cleaned, door handle lubed up, remove fire hose,	5th wheel greased, hydraulic oil topped off, fittings cleaned, door handle lubed up, remove fire hose,	5th wheel greased, hydraulic oil topped off, fittings cleaned, door handle lubed up, remove fire hose,	8:35AM 8/22/2023
88 Peterbilt	2,352,630 Outside Services and Repairs	outside repair service (WEILER DIESEL)		4:53PM 12/6/2023
88 Peterbilt	2,362,760 Outside Services and Repairs	complaint #1 Tractor/Other- Mechanical/Other-Battery issue		8:48AM 12/28/2023
88 Peterbilt	Federal Annual DOT Inspection w/ Checklist	Asher 11/17/23 -Performed thorough DOT inspection		3:57PM 11/17/2023
88 Peterbilt	2,558,745 Full Wet Service (Lube, Oil & Filters)	performed a pm/ dot on tractor. everything is satisfactory		8:34AM 11/30/2023
88 Peterbilt	2,558,745 Full Wet Service (Lube, Oil & Filters)	performed a pm/ dot on tractor. everything is satisfactory		8:34AM 11/30/2023

88 Peterbilt	2,558,745	18000 Full Wet Service (Lube, Oil & Filters)	performed a pm/ dot on tractor. everything is satisfactory	8:34AM 11/30/2023
88 Peterbilt	2,558,745	18000 Full Wet Service (Lube, Oil & Filters)	performed a pm/ dot on tractor. everything is satisfactory	8:34AM 11/30/2023
88 Peterbilt	2,558,745	18000 Full Wet Service (Lube, Oil & Filters)	performed a pm/ dot on tractor. everything is satisfactory	8:34AM 11/30/2023
88 Peterbilt	2,558,745	18000 Full Wet Service (Lube, Oil & Filters)	performed a pm/ dot on tractor. everything is satisfactory	8:34AM 11/30/2023
88 Peterbilt	2,367,175	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	9:06AM 1/5/2024
88 Peterbilt	2,367,175	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	9:06AM 1/5/2024
88 Peterbilt	2,367,175	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	9:06AM 1/5/2024
88 Peterbilt	2,367,175	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	9:06AM 1/5/2024
88 Peterbilt	2,367,175	needs clutch brake installed	replaced clutch brake with a new one	8:42AM 1/5/2024
88 Peterbilt	2,367,175	needs clutch brake installed	replaced clutch brake with a new one	8:42AM 1/5/2024
88 Peterbilt	2,367,175	replace drive axle brakes	replaced both drive axle brake	9:14AM 1/10/2024

88 Peterbilt	2,367,175	replace drive axle brakes	replaced both drive axle brake	9:14AM 1/10/2024
88 Peterbilt	2,367,175	replace drive axle brakes	replaced both drive axle brake	9:14AM 1/10/2024
88 Peterbilt	2,367,175	replace drive axle brakes	replaced both drive axle brake	9:14AM 1/10/2024
88 Peterbilt	2,367,175	replace front passenger drive axle u bolt	replaced passenger side front axle leaf spring u bolt	8:26AM 1/10/2024
88 Peterbilt	2,367,175	replace front passenger drive axle u bolt	replaced passenger side front axle leaf spring u bolt	8:26AM 1/10/2024
88 Peterbilt	2,367,175	loose drive axle shock	tighted up shock absorber	9:49AM 1/5/2024
88 Peterbilt	2,385,755	Outside Services and Repairs	Replaced Fuel filters w/ truck service 2/7/2024	2:56PM 2/13/2024
88 Peterbilt	2,385,755			
88 Peterbilt	2,382,999	washer fluid leaked inside of dash now	removed broken windshield washer elbow and replaced it with a used one from a truck out back of shop	1:57PM 2/6/2024
88 Peterbilt	2,382,999	speedometer is not functioning correctly		
88 Peterbilt	2,381,031	Remove and Replace cab Air Bag	Remove and Replace cab Air Bag on passenger side.	2:07PM 2/2/2024
88 Peterbilt	2,381,031	Remove and Replace cab Air Bag	Remove and Replace cab Air Bag on passenger side.	2:07PM 2/2/2024
88 Peterbilt	2,381,031	Remove and Replace cab Air Bag	Remove and Replace cab Air Bag on passenger side.	2:07PM 2/2/2024
88 Peterbilt	2,381,031	Remove and Replace cab Air Bag	Remove and Replace cab Air Bag on passenger side.	2:07PM 2/2/2024
88 Peterbilt	2,381,031	Remove and Replace cab Air Bag	removed transmission inspection cover and adjusted the clutch with grants help. then adjusted clutch brake rod for less free play in clutch pedal	3:18PM 2/2/2024
88 Peterbilt	2,381,031	Service: Manual Transmission & Clutch		
88 Peterbilt	2,381,031			

88 Peterbilt 2,379,463 driver's side step came loose

1/31/24 Brian- driver's side step mounting bolts broke on the right and side closest to the exhaust stack. Used an air bottle jack to lift up driver's side step. searched the shop the found a drill and drill bits to drill 3 holes to insert new bolts to the step frame work. Had to sharpen the drill bit several tires to drill through the stainless steel step. Tightened up the 3 new bolts and then released pressure off of jack. step stayed in place and hand the driver stand on it to confirm repair. 10:00AM 1/31/2024

88 Peterbilt 2,379,463 driver's side step came loose

1/31/24 Brian- driver's side step mounting bolts broke on the right and side closest to the exhaust stack. Used an air bottle jack to lift up driver's side step. searched the shop the found a drill and drill bits to drill 3 holes to insert new bolts to the step frame work. Had to sharpen the drill bit several tires to drill through the stainless steel step. Tightened up the 3 new bolts and then released pressure off of jack. step stayed in place and hand the driver stand on it to confirm repair. 10:00AM 1/31/2024

88 Peterbilt 2,379,463 driver's side step came loose

1/31/24 Brian- driver's side step mounting bolts broke on the right and side closest to the exhaust stack. Used an air bottle jack to lift up driver's side step. searched the shop the found a drill and drill bits to drill 3 holes to insert new bolts to the step frame work. Had to sharpen the drill bit several tires to drill through the stainless steel step. Tightened up the 3 new bolts and then released pressure off of jack. step stayed in place and hand the driver stand on it to confirm repair. 10:00AM 1/31/2024

88 Peterbilt 2,379,463 driver's side step came loose

1/31/24 Brian- driver's side step mounting bolts broke on the right and side closest to the exhaust stack. Used an air bottle jack to lift up driver's side step. searched the shop the found a drill and drill bits to drill 3 holes to insert new bolts to the step frame work. Had to sharpen the drill bit several tires to drill through the stainless steel step. Tightened up the 3 new bolts and then released pressure off of jack. step stayed in place and hand the driver stand on it to confirm repair. 10:00AM 1/31/2024

88 Peterbilt 2,379,463 needs new front license plate bracket

1/31/24 Brian removed the two license plate bolts from bumper. notched new license plate bracket reinstalled the two mounting bolts with lock tight on the treads. installed new license plate on bracket.

11:07AM 1/31/2024

88 Peterbilt 2,379,463 needs new front license plate bracket

1/31/24 Brian removed the two license plate bolts from bumper. notched new license plate bracket reinstalled the two mounting bolts with lock tight on the treads. installed new license plate on bracket.

11:07AM 1/31/2024

88 Peterbilt 2,379,463 needs new front license plate bracket

1/31/24 Brian removed the two license plate bolts from bumper. notched new license plate bracket reinstalled the two mounting bolts with lock tight on the treads. installed new license plate on bracket.

11:07AM 1/31/2024

88 Peterbilt 2,379,463 needs new front license plate bracket

1/31/24 Brian removed the two license plate bolts from bumper. notched new license plate bracket reinstalled the two mounting bolts with lock tight on the treads. installed new license plate on bracket.

11:07AM 1/31/2024

88 Peterbilt 2,379,463 needs new front license plate bracket

1/31/24 Brian removed the two license plate bolts from bumper. notched new license plate bracket reinstalled the two mounting bolts with lock tight on the treads. installed new license plate on bracket.

11:07AM 1/31/2024

88 Peterbilt 2,379,463 Repair wiper motor linkage.

1/31/24 Brian removed wiper motor and wiper arms from truck. Removed dash clusters for speedometer and parking and trailer air release buttons. removed dash defrost tube on driver's side. removed wiper arm linkage assembly from the dash through the speedometer dash cluster. reinstalled the wiper arm linkage assembly the same way it was removed. reinstalled dash cluster pieces and air duct tube on the driver's side of the dash. reinstalled the wiper motor and wiper arms on the out of the truck. operated wiper functions to verify correct operation and the issue has been resolved.

2:20PM 1/31/2024

		1/31/24 Brian removed wiper motor and wiper arms from truck. Removed dash clusters for speedometer and parking and trailer air release buttons. removed dash defrost tube on driver's side. removed wiper arm linkage assembly from the dash through the speedometer dash cluster. reinstalled the wiper arm linkage assembly the same way it was removed. reinstalled dash cluster pieces and air duct tube on the driver's side of the dash. reinstalled the wiper motor and wiper arms on the out of the truck. operated wiper functions to verify correct operation and the issue has been resolved.	2:20PM 1/31/2024
88 Peterbilt	2,379,463 Repair wiper motor linkage.	Removed and Replaced cab torsion bar.	4:08PM 1/31/2024
88 Peterbilt	2,379,463 Remove and Replace cab torsion bar.	Removed and Replaced cab torsion bar.	4:08PM 1/31/2024
88 Peterbilt	2,379,463 Remove and Replace cab torsion bar.	removed pit man arm from steering gear box inspected splines on gear box and pit man arm. cleaned both sides up and reinstalled pit man arm on steering gear box and there is no movement in both parts like previously to removing it.	3:08PM 1/31/2024
88 Peterbilt	2,379,463 steering gear pit man arm needs inspected		
88 Peterbilt	2,379,463		

[illegible]

88 Peterbilt	2,384,216	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	4:13PM 2/9/2024
88 Peterbilt	2,384,216	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	4:13PM 2/9/2024
88 Peterbilt	2,384,216	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	4:13PM 2/9/2024
88 Peterbilt	2,384,216	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	4:13PM 2/9/2024
88 Peterbilt	2,384,216	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	4:13PM 2/9/2024
88 Peterbilt	2,384,216	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	4:13PM 2/9/2024
88 Peterbilt	2,402,802	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	10:24AM 3/14/2024
88 Peterbilt	2,402,802	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	10:24AM 3/14/2024
88 Peterbilt	2,402,802	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	10:24AM 3/14/2024

88 Peterbilt	2,402,802	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters worked on service from 9:00 Am - 10:23 Am	10:24AM 3/14/2024
88 Peterbilt	2,402,802	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters worked on service from 9:00 Am - 10:23 Am	10:24AM 3/14/2024
88 Peterbilt	2,409,543	trailer pigtail male end needs replaced that plugs into the trailer	RR male pigtail end going into trailer	2:01PM 4/2/2024
88 Peterbilt	2,409,543	trailer pigtail male end needs replaced that plugs into the trailer	RR male pigtail end going into trailer	2:01PM 4/2/2024
88 Peterbilt	2,402,802	IDR Boost issue, Replace intake piping	replaced piping AKA Intake Horn or intake elbow. -kyle	3:41PM 3/14/2024
88 Peterbilt	2,402,802	IDR Boost issue, Replace intake piping	replaced piping AKA Intake Horn or intake elbow. -kyle	3:41PM 3/14/2024
88 Peterbilt	2,402,802	IDR Boost issue, Replace intake piping	replaced piping AKA Intake Horn or intake elbow. -kyle	3:41PM 3/14/2024
88 Peterbilt	2,402,802	IDR Engine fan switch. Replace solenoid.	replaced fan solenoid.	1:33PM 3/14/2024
88 Peterbilt	2,402,802	IDR Engine fan switch. Replace solenoid.	replaced fan solenoid.	1:33PM 3/14/2024

88 Peterbilt	2,402,802	Repair exhaust clamp under cap	replaced exhaust U-bolt with a used exhaust U-bolt.	11:33AM 3/14/2024
88 Peterbilt	2,402,802	A/C requires charge.	recovered, pulled a vacuum and performed a leak check which it passed the test. when adding freon into the system the high side port leaked a little and will need replaced in the future	2:01PM 3/14/2024
88 Peterbilt	2,402,802	A/C requires charge.	recovered, pulled a vacuum and performed a leak check which it passed the test. when adding freon into the system the high side port leaked a little and will need replaced in the future	2:01PM 3/14/2024
88 Peterbilt	2,402,802	inside.	tech one and shop foreman determined no alignment is needed at this time and front tires are wearing down properly.	1:56PM 3/14/2024
88 Peterbilt	2,412,909	Shaft for PTO needs to be rebuilt.	RR u-joint	1:25PM 4/10/2024
88 Peterbilt	2,412,909	Shaft for PTO needs to be rebuilt.	RR u-joint	1:25PM 4/10/2024
88 Peterbilt	2,419,218	Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	9:51AM 4/26/2024
88 Peterbilt	2,419,218	Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	9:51AM 4/26/2024
88 Peterbilt	2,419,218	Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	9:51AM 4/26/2024

88 Peterbilt	2,419,218	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	9:51AM 4/26/2024
88 Peterbilt	2,419,218	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	9:51AM 4/26/2024
88 Peterbilt	2,419,218	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	9:51AM 4/26/2024
88 Peterbilt	2,419,218	hood hinge replacement	hood hinge replacement	8:46AM 5/13/2024
88 Peterbilt	2,419,218	hood hinge replacement	hood hinge replacement	8:46AM 5/13/2024
88 Peterbilt	2,419,218	hood hinge replacement	hood hinge replacement	8:46AM 5/13/2024
88 Peterbilt	2,419,218	a/c compressor repair or replacement	replaced AC compressor.	3:47PM 4/26/2024
88 Peterbilt	2,419,218	a/c compressor repair or replacement	replaced AC compressor.	3:47PM 4/26/2024
88 Peterbilt	2,419,218	drivers side door latch	replaced AC compressor.	3:47PM 4/26/2024
88 Peterbilt	2,419,218	drivers side door latch	replaced door latch.	8:47AM 5/13/2024
88 Peterbilt	2,419,218	drivers side door latch	replaced door latch.	8:47AM 5/13/2024
88 Peterbilt	2,419,218	drive shock replacement	replaced all four drive shocks.	3:37PM 4/26/2024
88 Peterbilt	2,419,218	drive shock replacement	replaced all four drive shocks.	3:37PM 4/26/2024
88 Peterbilt	2,424,849	a/c line needs replaced	replaced low pressure a/c line charged system but the new a/c compressor clutch was bad. driver had it fixed at truck repair	8:12AM 5/13/2024
88 Peterbilt	2,426,377	Service Call - Tire repair	Service Call - replaced outside passenger front axle tire with spare tire.	8:19AM 5/16/2024

88	Peterbilt	2,426,377	Service Call - Tire repair	Service Call - replaced outside passenger front axle tire with spare tire.	8:19AM 5/16/2024
88	Peterbilt	2,426,377	Remove and replace wheel seal	removed wheel and cleaned all components, replaced wheel seal.	8:23AM 5/16/2024
88	Peterbilt	2,426,377	Remove and replace wheel seal	removed wheel and cleaned all components, replaced wheel seal.	8:23AM 5/16/2024
88	Peterbilt	2,426,377	Drive to unit (Service Call)		4:03PM 5/20/2024
88	Peterbilt	2,426,377	Drive to unit (Service Call)		4:03PM 5/20/2024
88	Peterbilt	2,434,697	IDR turbo oi leak	gaskets replaced	2:34PM 6/24/2024
88	Peterbilt	2,434,697	IDR turbo oi leak	gaskets replaced	2:34PM 6/24/2024
88	Peterbilt	2,434,697	IDR turbo oi leak	gaskets replaced	2:34PM 6/24/2024
88	Peterbilt	2,434,697	IDR turbo oi leak	gaskets replaced	2:34PM 6/24/2024
88	Peterbilt	2,434,697	IDR turbo oi leak	thermostat sensor wire not plugged in all the way, contact cleaned and re plugged in. fan now kicks on automatically	11:41AM 6/3/2024
88	Peterbilt	2,434,697	fender bracket broken	fender mount welded and re installed	9:52AM 6/3/2024
88	Peterbilt	2,434,697	passenger side fuel tank leak	fuel tank patched and reinstalled	11:35AM 6/7/2024
88	Peterbilt	2,434,697	passenger side fuel tank leak	fuel tank patched and reinstalled	11:35AM 6/7/2024
88	Peterbilt	2,434,697	passenger side air window	when adequate air is built up window functions normally, no leaks detected, slider surfaces lubricated and cleaned	10:19AM 6/3/2024

88 Peterbilt	2,434,697	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	10:19AM 6/4/2024
88 Peterbilt	2,434,697	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	10:19AM 6/4/2024
88 Peterbilt	2,434,697	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	10:19AM 6/4/2024
88 Peterbilt	2,434,697	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	10:19AM 6/4/2024
88 Peterbilt	2,434,697	18000 Full Wet Service (Lube, Oil & Filters)	'B' Full Wet Service - Engine Inspection & Service, Lube, Oil & Filters	10:19AM 6/4/2024
88 Peterbilt	2,441,663	no abs power to trailer	Dave found no power coming out of cab to blue wire.ran new power wire off key switch. fixed issue	4:06PM 6/27/2024
88 Peterbilt	2,441,663			
88 Peterbilt	2,441,374	replace #1 & #2 drive tires	replace #1 & #2 drive tires	3:33PM 6/26/2024
88 Peterbilt	2,441,374	replace #1 & #2 drive tires	replace #1 & #2 drive tires	3:33PM 6/26/2024

