

Midwest Machinery Co.

PO Box 197 78412 County Rd. 20 Stewart, MN 55385









Invoice To Account No: 309540

DONN BEMIS 85445 COUNTY ROAD 24 **BUFFALO LAKE MN 55314**

Phone Number:

320-833-2270

SERVICE INVOICE

Invoice Number:

2062818 Invoice Date: 12/23/2019

Location: Work Order Number:

03 345904

Payment Type:

Finance

Page:

1 of 6

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9630	3683	RW9630P013174	DBB9630	

Gen- Retail

COMPLAINT:

01 General Repairs - CHECK FRONT AXLE BEARINGS

CORRECTION:

CONTINUED ON NEXT PAGE->

Midwest Machinery Co. PO Box 197 78412 County Rd. 20 Stewart, MN 55385

Phone: (320) 562-2630





www.midwestmachineryco.com

Invoice To Account No: 309540

SERVICE INVOICE

DONN BEMIS 85445 COUNTY ROAD 24 BUFFALO LAKE MN 55314

Phone Number:

320-833-2270

Invoice Number: Invoice Date: 2062818 12/23/2019 03

Location: Work Order Number: Payment Type:

03 345904 Finance

Page: 2 of 6

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9630	3683	RW9630P013174	DBB9630	

Gen- Retail

drove tractor into shop

axle lube pressure code would come on when driving. also had ccu 524068.01 stored

oil was leaking from front Ih axle seal

jacked up tractor and found axle bearing was bad

drained oil from front axle and it had a lot of fine metal in it

drained transmission and rear axle, did not find any debris in them but oil was dark and could see silver in it

jacked up front of tractor and removed all wheels

removed axle driveshaft and all hoses

removed front axle from tractor

mounted it in stand and removed both final drives

found the inner bearing on LH side was completely destroyed

disassembled final drive, and inspected parts

all gears had some damage from metal going through them, axle shaft was bad from bearing spinning on it, axle housing was also

bad from planetary rubbing on it

looked up parts and made estimate

ordered needed parts after talking with customer

installed new bearings and housing on new axle shaft and adjusted bearings removed all gears from first planetary carrier and installed new gears and needle bearings installed new gears onto new second planetary carrier installed new ring gear in axle housing and reinstalled planetary in housing disassembled RH final drive and inspected parts all gears looked good, just removed and replaced bearings reassembled final drive

disassembled center section of axle and removed differential removed and replaced bearings in differential disassembled pinion shaft and replaced bearings in it adjusted bearings in pinion shaft and reinstalled in center section adjusted differential bearings and checked and adjusted backlash and gear contact pattern on ring gear

reinstalled final drive to center section and reinstalled axle into tractor hooked up drive shaft and all hoses reinstalled all hubs, spacers and wheels

jacked up rear of tractor and removed all rear wheels, spacers and hubs removed rear axle from tractor removed final drives and disassembled center section replaced all bearings and races in differential sealing ring groove in bearing holder for differential broken when pulling old bearing off looked up and ordered new part reassembled and adjusted differential

Midwest Machinery Co. PO Box 197 78412 County Rd. 20 Stewart, MN 55385

Phone: (320) 562-2630

MIDWEST MACHINERY CO



www.midwestmachineryco.com

Invoice To Account No: 309540

DONN BEMIS 85445 COUNTY ROAD 24 BUFFALO LAKE MN 55314

Phone Number:

320-833-2270

SERVICE INVOICE

 Invoice Number:
 2062818

 Invoice Date:
 12/23/2019

 Location:
 03

 Work Order Number:
 345904

Payment Type: Finance

Page: 3 of 6

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 9630	3683	RW9630P013174	DBB9630	

replaced and adjusted bearings and reassembled final drives reinstalled final drives to center section and torqued all bolts reinstalled in tractor reinstalled rear hubs, spacers and wheels

removed sump screen and flushed out transmission case with solvent to try and remove any debris installed new trans and axle filters removed and replaced brake hose from rear axle to brake valve that was damaged while removing axle removed axle scavenge pump from rear of transmission and disassembled inside of pump looked ok so reassembled it and reinstalled on transmission

filled transmission with new oil ran tractor and rechecked level

Dort Manhan

	urt Number BH4219	<u>Description</u> 5/8x 10 1/2	Quantity 2.00	List Price 7.69	Extended Price \$15.38	Taxed Ind N
14	1H1039	5/8 NUT	2.00	1.84	\$3.68	N
19	9H3650	5/8x11	2.00	15.77	\$31.54	· N
19	9H3707	Cap Screw	12.00	5.22	\$62.64	N
F	2380R	WASHER	12.00	1.77	\$21.24	N
R	109867	Pin Fastener	5.00	2.70	\$13.50	N
R	112079	Thrust Washer	20.00	23.67	\$473.40	N
R	135543	WASHER	96.00	1.09	\$104.64	N
R	168163	BUSHING	4.00	99.44	\$397.76	N
R2	207832	CAP SCREW	96.00	11.30	\$1,084.80	N
R:	228931	Spur Gear	5.00	414.82	\$2,074.10	N
R2	228933	Spur Gear	5.00	625.80	\$3,129.00	N
R	228934	Ring Gear	1.00	2,138.37	\$2,138.37	N
R2	242376	Sealing Ring	4.00	34.49	\$137.96	N
R2	244602	O-Ring	6.00	25.97	\$155.82	N
R	249513	Needle Roller	435.00	0.60	\$261.00	N
R2	251685	Sun Gear	1.00	857.81	\$857.81	N

Midwest Machinery Co. PO Box 197 78412 County Rd. 20 Stewart, MN 55385 Phone: (320) 562-2630





www.midwestmachineryco.com

Invoice To Account No: 309540

DONN BEMIS 85445 COUNTY ROAD 24

BUFFALO LAKE MN 55314

Phone Number:

320-833-2270

SERVICE INVOICE

 Invoice Number:
 2062818

 Invoice Date:
 12/23/2019

 Location:
 03

Work Order Number: 345904
Payment Type: Finance

Page: 4 of 6

JOHN DEERE 9630 3683 RW9630P013174 DBB9630 Gen- Retail R257680 Planet Pinion Carrier 1.00 1,267.97 3 R257682 Shaft 5.00 71.27	\$1,267.97 \$356.35 \$1,019.25 \$42.51 \$20.52 \$21.54	N N N N N N N N N N N N N N N N N N N
Gen- Retail R257680 Planet Pinion Carrier 1.00 1,267.97 3 R257682 Shaft 5.00 71.27 R257683 Shaft 5.00 203.85 3 R257819 Ring 13.00 3.27	\$356.35 \$1,019.25 \$42.51 \$20.52	N N N
R257680 Planet Pinion Carrier 1.00 1,267.97 3 R257682 Shaft 5.00 71.27 R257683 Shaft 5.00 203.85 3 R257819 Ring 13.00 3.27	\$356.35 \$1,019.25 \$42.51 \$20.52	N N N
R257680 Planet Pinion Carrier 1.00 1,267.97 3 R257682 Shaft 5.00 71.27 R257683 Shaft 5.00 203.85 3 R257819 Ring 13.00 3.27	\$356.35 \$1,019.25 \$42.51 \$20.52	N N N
R257683 Shaft 5.00 203.85 S R257819 Ring 13.00 3.27	\$1,019.25 \$42.51 \$20.52	N N
R257819 Ring 13.00 3.27	\$42.51 \$20.52	N
•	\$20.52	
R263461 Snap Ring 1.00 20.52	·	N
	\$21.54	
R263462 Thrust Ring 1.00 21.54		N
R271501 Bearing Cup 2.00 44.16	\$88.32	N
R273060 2.00 43.55	\$87.10	N
R273061 Bearing Cone 4.00 81.22	\$324.88	. N
R277669 Washer 5.00 17.49	\$87.45	N
R290351 Spacer 2.00 22.85	\$45.70	N
R300031 Sun Gear 1.00 730.93	\$730.93	N
R304673 Bearing Cup 2.00 25.94	\$51.88	N
R305032 Spacer 2.00 13.78	\$27.56	N
R346226 Shaft 1.00 2,133.46	\$2,133.46	N
R375R PACKING 2.00 1.27	\$2.54	N
R39322 SEAL RING 6.00 20.30	\$121.80	N
R47151 O-RING 1.00 1.71	\$1.71	N
R59439 SHIM 5.00 2.84	\$14.20	N
R59440 SHIM 4.00 4.60	\$18.40	N
R61461 SHIM 2.00 2.23	\$4.46	N
R63237 SHIM 4.00 10.19	\$40.76	N
R69549 PLATE 2.00 21.34	\$42.68	N
R72232 BALL 8.00 0.59	\$4.72	N
R79989 SHIM 6.00 3.52	\$21.12	N
R81162 BOLT 4.00 26.65	\$106.60	N

Midwest Machinery Co.

PO Box 197 78412 County Rd. 20 Stewart, MN 55385 Phone: (320) 562-2630





www.midwestmachineryco.com

Invoice To Account No: 309540

85445 COUNTY ROAD 24 **BUFFALO LAKE MN 55314**

Phone Number:

DONN BEMIS

320-833-2270

SERVICE INVOICE

2062818 Invoice Number: Invoice Date: 12/23/2019 Location: 03 Work Order Number: 345904

> Finance Payment Type:

> > 5 of 6 Page:

320-833-2270				Page:			
Make/Model:	Mete	er:	Serial Number:		Eq ID:	Fleet No	
JOHN DEERE 9630	3683	3	RW9630P013174		DBB9630	•	
Gen- Retail R93623	Thrust Washer			2.00	24.07	#40	NA NI
				2.00	24.97	\$49.5	
RE174130	HYD FILTER			1.00	85.71	\$85.	
RE191816	SEAL			4.00	209.53	\$838.	
RE284771	Bearing Housing W/O Bearing	g	•	1.00	379.04	\$379.	04 N
RE292203	Housing			1.00	5,919.95	\$5,919.	95 N
RE293316	TAPERED RO		:	5.00	254.45	\$1,272.	25 N
RE304674	Bearing Cone		:	2.00	27.22	\$54.·	14 N
RE305950	Shim Kit			1.00	63.62	\$63.	62 N
RE48761	TAPERED RO		:	2.00	607.50	\$1,215.	00 N
RE578425	Bearing Cone			4.00	405.62	\$1,622.	48 N
TY6341	SD POLY GREASE		,	1.00	4.41	\$4.	41 N
U42016	CO-Ring			2.00	6.34	\$12.	58 N
X1J743-6-6	11/16 FFSF E			1.00	20.53	\$20.	53 N
X1JC43-6-6	HOSE FITTI			1.00	8.67	\$8.	67 N
X471TC-6-RL	Bulk Hose		16	1.00	0.54	\$86.	94 N
YZ502166	SEAL			2.00	36.11	\$72.	22 N
YZ502378	OIL FILTER			1.00	83.40	\$83.	40 N
9639	18" Black Zip Tie			8.00	0.23	\$1.	84 N
AR69445	HYGARD SHOP OIL (QT)		10	8.00	3.02	\$326.	16 N
Miscellaneous P3750	<u>Description</u> FREIGHT			antity 2.00	<u>List Price</u> 421.01	Extended Pr \$842.	

Midwest Machinery Co.

PO Box 197 78412 County Rd. 20 Stewart, MN 55385 Phone: (320) 562-2630





www.midwestmachineryco.com

Invoice To Account No: 309540

SERVICE INVOICE

DONN BEMIS 85445 COUNTY ROAD 24

BUFFALO LAKE MN 55314

Number:

Invoice Number: Invoice Date: Location: 2062818 12/23/2019 03

Work Order Number: Payment Type:

345904 Finance

Page:

6 of 6

Make/Model:

Meter:

Serial Number: RW9630P013174 Eq ID: DBB9630

Fleet No:

JOHN DEERE 9630

3683

Gen- Retail

S3773

FILTER DISPOSAL - 2.50

2.00

2.50

\$5.00

Ν

Labor: \$13,482.10

OL&M: \$0.00

320-833-2270

Parts: \$29,764.45

Misc: \$847.02

Sub-Total: \$44,093.57

Miscellaneous Charges:

Shop Supplies **Environmental Fee**

\$75.00

\$25.00

Customer PO No:

Tax Exempt No:

19ST3-LOCM

Advisor:

110

* * * DOCUMENT COPY * * *

Finance Information Type: Multi-use Acct US

Merchant No: 44000168

Card No: xxxxxxxxxxxx6302

Bill Code: 704 - JD TRACTOR PARTS/SERVICE

Auth. No: 661669

Credit Plan: 11438 - DEERE AG 120 DAYS NO

PAYMENTS/NO INTEREST

Labor: Parts:

\$13,482,10 \$29,764.45

OL&M:

\$0.00

\$0.00

Misc: \$947.02 Sales Tax:

Grand Total: \$44,193.57

TERMS AND CONDITIONS

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by: Date: