Company	y# -(Slph	<u>~</u>	202	}	_uk	orica	tion /	Repa	ir Re	cord				
Year - Make - Serial Nu	3.0	. Bd		458	7							ωl		au ;	
Work done by	<u>Date</u>	Check Air Pressure	Lubricate Chassis	Chain & Boomer inspection	Cab hardware & Door latches	Universal Joints	Check: Steering Gear Box	Transmission	Fuel Filter	Differential	Oil filter change & Coolant filter	Service air cleaner & breathers	Drain Transmission differential	Check: 1st Aid kit & Fire extinguisher	Mileage
TO	m			1	:						\leq			· ·	200 HRS 506
-	4	<u> </u>			·	· ·				<u>.</u>					
i			(4)				·	· · · · · · · · · · · · · · · · · · ·	1					Ĭ	
1	• 1	1	i			# #									
<u> </u>		*	3 20	ir	· · · · · ·				i	<u>.</u>	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·			
2		i			1	ī	·		· · · · · · · · · · · · · · · · · · ·	<u>;</u> !		·			
į	!	-	· · ·		· · ·		:	i	!	<u>-</u>	:	i			
	ì	j	į			ı	(4)		İ		!			1	
, <u>I</u>				<u>:</u>	1		i			<u> </u>			1		
	<u>.</u>		- i		<u>t</u>	•		<u>i</u>							
	· · · · · · · · · · · · · · · · · · ·		Y,										9		
	,					-			1		:				
	<u> </u>	<u> </u>					p	ī			:				
	<u> </u>		:		· · · · ·						:		 ;		
<u> </u>	<u> </u>	!		i	ı	i	!	<u>.</u>				!	i		
•									1		i				
	<u>.</u> !	1		T.			ř		i	<u> </u>	<u>.</u>				
				*:						<u>;</u>	!		*		
		-	1						,						



RDO Equipment Co. 14057 49th St NW Williston, ND 58801 701-577-0736 Fax: 701-577-0740

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Ship to:

Branch

WILLISTON, ND

Date 01/24/23 Time 21:25:04 (B) Page

Account No. 2733014

Phone No. 7015722733 Invoice No. W2020317

Ship Via w99/111 **Purchase Order**

Tax Exemption Number

Federal ID Number

Salesperson N15 / N15

SERVICE INVOICE

STK#/FLEET#

Invoice to:

410L BACKHOE LOADE

EVERSON ENTERPRISE, INC

DBA ALPHA ROUSTABOUT

WILLISTON ND 58802

HRS PIN/EIN WARRANTY DATE

HRS

X924174 987794

410L

PO BOX 966

1T0410LXLLF381458 PE4045U109377

02/14/21 02/12/27

4000 X

**Receive your Vermeer equipment inspection for FREE with any parts or labor work over \$1,000. Now through March 31, 2023. Ask us for more information!

SEGMENT# 1 C LF001 RDO-080-DIAG 11/15/22 01/05/23

MISCELLANEOUS DIAGNOSTICS

CONDITION:

.94 HRS

- Customer said the cab does not get warm even when working the unit
- CORRECTION:
- -tested cooling system and found machine would not get to operating temp
- -checked coolant temp in monitor and found low
- -checked fan speed and found actual and desired do not
- -verified wiring to fan and found checks okay
- -unplugged fan and no change
- -fan is failed internally and will need replaced
- -checked coolant temp on thermostat housing and found cold
- -will need to open t-stat housing to confirm t-stat failure
- -found t-stat had broken legs

LABOR

Warranty

SEGMENT TOTAL ==>

Warranty

10401099 10501017

SEGMENT# 2 C LF001 10-030-072

11/15/22 11/15/22

THERMOSTAT, R&R

2.00 HRS

CAUSE:

legs on t-stats cracked causing them to stick open CORRECTION:

CONTINUED ON PAGE 02



RDO Equipment Co. 14057 49th St NW Williston, ND 58801 701-577-0736 Fax: 701-577-0740

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Ship to: N/A

Branch WILLISTON, ND

Date 01/24/23 Time 21:25:04 (B)

Page 02

Account No. 2733014

Phone No. 7015722733

Invoice No. W2020317

Ship Via w99/111

Purchase Order

Tax Exemption Number

Federal ID Number

Salesperson N15 / N15

SERVICE INVOICE

STK#/FLEET#

н

HRS PIN/EIN

WARRANTY DATE

HRS

X924174 410 987794 41

410L BACKHOE LOADE

440

1T0410LXLLF381458 PE4045U109377 02/14/21 02/12/27

4000 X

Lifted boom and installed boom locks

Invoice to: EVERSON ENTERPRISE, INC

PO BOX 966

DBA ALPHA ROUSTABOUT

WILLISTON ND 58802

Raised hood

Removed fan guards on either side of machine

Had coworker hold fan pully in place while I broke the nut

loose

Removed fan assembly

Relieved tension and removed serpentine belt

Turned off battery switch

Removed all electrical connections on alternator

Removed alternator mounting bolts and alternator

Installed coolant barrier tool onto surge tank

Removed upper radiator hose

Removed mounting bolts and thermostat housing cover

Removed damaged thermostats

Installed new thermostats

Reinstalled thermostat housing cover and mounting screws

Reinstalled upper radiator hose

Reinstalled alternator and mounting bolts

Reconnected alternator electrical connections

Reinstalled serpentine belt

Pulled vacuum on cooling system

Topped off with coolant

Test drove machine and ensured proper operation

Washed all coolant residue out of engine bay

Rinsed off entire machine

Tagged and returned all warranty parts

Finished story

ADDITIONAL DESCRIPTION:

Deere Standard (WARR DEERE)

Failed Part #:DZ122884

CONTINUED ON PAGE 03

Thank you for your business



PO BOX 966

EVERSON ENTERPRISE, INC

DBA ALPHA ROUSTABOUT

WILLISTON ND 58802

RDO Equipment Co. 14057 49th St NW Williston, ND 58801 701-577-0736 Fax: 701-577-0740

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Ship to:

Invoice to:

N/A

Branch WILLISTON, ND

Date 01/24/23 Time 21:25:04 (B) Page

Account No. 2733014

Phone No. 7015722733 Invoice No. W2020317

Ship Via w99/111

Purchase Order

Tax Exemption Number

Federal ID Number

Salesperson N15 / N15

202.09

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS 410L BACKHOE LOADE X924174 440 1T0410LXLLF381458 02/14/21 987794 410L PE4045U109377 02/12/27 4000 X Failed/Function Area:2219 Failed Type Code: 3 DTAC Case / Solution #: Diagnostic Hours: .50 If Reman, Failed Serial #: New Serial #: DZ122884 Thermostat 2 Warr/Int Warr/Int FRT SHIP/HANDLING 2 63.26 126.52 TY26576 COOL-GARD TM 2 Warr/Int Warr/Int T428855 V-Belt 1 75.57 75.57 PARTS Warr/Int 202.09 LABOR Warr/Int 10401099 10501017 740T1D17 SEGMENT TOTAL ==> Warr/Int

SEGMENT# 3 C LF001 00510A006

11/15/22 01/05/23

FAN BLADE AND OR VISCOUS FAN DRIVE - REPLACE

CAUSE:

6.00 HRS

fan drive has internal failure and is running at wide open CORRECTION:

removed fan harness

removed fan blade

Removed viscous fan drive from fan and installed new one

Reinstalled fan assembly

Tightened nut

ADDITIONAL DESCRIPTION:

Deere Standard (WARR DEERE)

Failed Part #: AT485838

Failed/Function Area: 0512

Failed Type Code: 28

CONTINUED ON PAGE 04



PO BOX 966

RDO Equipment Co. 14057 49th St NW Williston, ND 58801 701-577-0736 Fax: 701-577-0740

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Ship to:

Branch WILLISTON, ND

Date 01/24/23

Time 21:25:04 (B) Page 04

Account No. 2733014

Phone No. 7015722733

Invoice No. W2020317

Ship Via

Purchase Order

w99/111

Tax Exemption Number

Federal ID Number

Salesperson N15 / N15

SERVICE INVOICE

PIN/EIN

440 1T0410LXLLF381458

PE4045U109377

STK#/FLEET#

Invoice to:

410L BACKHOE LOADE

EVERSON ENTERPRISE, INC

DBA ALPHA ROUSTABOUT

WILLISTON ND 58802

X924174 987794

410L

DTAC Case / Solution #: Diagnostic Hours: .44

-----If Reman, Failed Serial #:

New Serial #:

AT485838

Viscous Fan Dri

HRS

1 N Warranty

WARRANTY DATE

02/14/21

02/12/27

Warranty

HRS

4000 X

Viscous Fan Drive

PARTS

Warranty

LABOR

Warranty

10501017

SEGMENT TOTAL ==>

Warranty

***** WORK ORDER TOTALS ***** INTERNAL CUSTOMER PARTS Warr/Int 202.09 LABOR Warr/Int SUB TOTAL ==> Warr/Int 202.09 ND COUNTY TAX 2.02 ND STATE TAX 10.11 INTERNAL TOTAL Warr/Int TOTAL DUE RDO 214.22

Payments are due on your RDO account 30 days from the invoice date

PLEASE REMIT TO: RDO EQUIPMENT CO.

P.O. BOX 7160

CONTINUED ON PAGE 05



RDO Equipment Co. 14057 49th St NW Williston, ND 58801 701-577-0736 Fax: 701-577-0740

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

N/A Ship to:

Branch WILLISTON, ND

Date 01/24/23 Time 21:25:04 (B) Page

Account No. 2733014

Phone No. 7015722733

Invoice No. W2020317

Ship Via

Purchase Order

w99/111

Tax Exemption Number

Federal ID Number

Salesperson N15 / N15

SERVICE INVOICE

STK#/FLEET#

X924174 987794

410L BACKHOE LOADE

410L

Invoice to: EVERSON ENTERPRISE, INC

PO BOX 966

DBA ALPHA ROUSTABOUT

WILLISTON ND 58802

HRS PIN/EIN

440 1T0410LXLLF381458

PE4045U109377

WARRANTY DATE

02/14/21

02/12/27

4000 X

HRS

FARGO, ND 58106-7160

'ear 1ake	2025 Lubrication / Repair Record Company # - 'ear - 200 Take - JD BH erial Number - 1458																					
Work done by	Da		Check Air Pressure	X Lubricate Chassis	9	Chain & Boomer inspection	X Cab hardware & Door latches	>	Universal Joints		Check: Steering Gear Box	Transmission		X Fuel Filter	Differential	× 100	Oil filter change & Coolant filter	Service air cleaner & breathers	Drain Transmission differential	Check: 1st Aid kit & Fire extinguisher	Mileage 506	
<u>-D</u>	80		<i>SO</i> (X.		: /								<u>:</u> :				1			~	747	-
			·		•								Ť			:			:	1	<i>V-1-f</i>	
		·			i			3						·		!	;		/A			
					•								!			:	1					
													<u>:</u>			<u> </u>	<u> </u>					_
						:																-
														1		!	· 					-
<u>i</u> ;		<u> </u>	<u>:</u>			· ·			1		- I	i			i		-	ř				-
		·	<u>:</u>	. i					:					- <u>-</u>			1					-
						÷	-								<u>.</u> 		<u>.</u>					
		<u>.</u>	<u>-</u> -										*******		!		†		ì	:		1
·		:	10			•	•							•	:		;					
		:		# 200										!				*				
-,		,													383		<u>. </u>					
		!	· 											. <u>.</u>	; 	 						
		!	<u> </u>			: 	-27-							+	-			<u>.</u>		· · · · · · · · · · · · · · · · · · ·		
1		: 	· ī						; ;		ia	- 1		-	- <u>i</u> -				- -			
:			· · · · · ·		-									1	<u> </u>			-;				
			· · · · · ·								·				<u>:</u> !							
	<u>.</u>		·	71										!	:							
-	<u>:</u>		1									•		<u>I</u>	<u> </u>				*)			