

PREVIEW RO# I 55982 CUST# 10000 C J W FARMS 7088 COMBINE TRAD
UNIT# 46415 2011 CASE-IH 7088 COMBI

***** REPAIR ORDER SUMMARY DATA *****
C J W FARMS 7088 COMBINE TRADE CUST# 10000 RO# I55982
START 9/09/15 11:34
BILLED 12/28/15 13:52
PILOT GROVE IA 52648-0000 PO#
WRITER 050
PHONE: HOME 319 469-4461 PHC 06 PBC 02 APPROVAL 050 /050

***** REPAIR ORDER TOTALS BY PAY TYPE *****
C PRB 0 I PRB 11 W PRB 0
BILLED 12/28/15 13:52 050 BILLED
LABOR 0.00 1,218.65 0.00
PARTS 0.00 131.78 0.00
SUBLET 0.00 0.00 0.00
OTHER 0.00 0.00 0.00
MISC EXP 0.00 0.00 0.00
MISC CHARGES 0.00 8.91 0.00
DEDUCTIBLE 0.00 0.00 0.00
TAX 0.00 0.00 0.00
TOTAL DUE 0.00 1,359.34 0.00

***** SERVICE UNIT INFORMATION *****
OWNER 10000 UNIT# 46415 2011 CASE-IH 7088 COMBI CURR HRS 1,068.0
DELIVERED: 9/15/15
VIN: YBG006367 ENGINE: 73265782
TIRE SIZE: 20.8X42 DUALS AXLE SN: 600-28 REAR
FEEDER LENGTH: BEACON CUT TYPE: AM/FM
ROTOR HRS: 789 HR 9-9-15
WARRANTY EFF: 9/01/11 EXT: N UNIT: YBG006367 EXP: 8/31/12
ENG: 73265782 EXP: 8/31/13

***** PROBLEM # 01 DETAILS *****
PRB# 1 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: INT. COMBINE (MID-RANGE)-RECONDITIONING INSPECTION
PERFORM THE STEPS OUTLINED ON THE FORM TITLED "MID-RANGE &
VINTAGE COMBINE - INTERNAL INSPECTION FORM"
HOLD STATUS: F FINISHED
OPR# 1 I.COMINMIRIC00 ----- FLAT RATE SKILL LEVEL:
INT. COMBINE (MID-RANGE)-RECONDITIONING INS
TECH #: 041
041 1.68 0.00
041 2.58 0.00
041 .95 0.00
174 1.40 0.00
LABOR: 4.00 82.00 328.00
1 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
328.00 0.00 0.00 0.00 0.00 328.00

***** PROBLEM # 02 DETAILS *****
PRB# 2 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: CHUCK DROVE COMBINE INTO THE SHOP 9-9-15
HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:
TECH #: 000
2 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
0.00 0.00 0.00 0.00 0.00 0.00

***** PROBLEM # 04 DETAILS *****
PRB# 4 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: CLEAN UP
TAKE PICTURES FOR TRACTOR HOUSE
HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:
TECH #: 149
149 1.43 51.75 74.00

	149			1.07	51.75	55.37
	149			4.67	51.75	241.67
	149			.58	51.75	30.02
	149			1.02	51.75	52.79
	163			1.14	51.75	59.00
	163			1.25	51.75	64.69
	163			.92	51.75	47.61
	163			.48	51.75	24.84
	163			.50	51.75	25.88
	163			.62	51.75	32.09
	163			.62	51.75	32.09
PARTS:	B17566N		SPRAY PAIN	2.00	9.95	19.90
	990121N		SPRAY PAIN	2.00	9.95	19.90
4	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	740.05	39.80	0.00	0.00	0.00	779.85

***** PROBLEM # 05 DETAILS *****
 PRB# 5 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: REPLACE REAR SHOE SIEVE SEAL
 HOLD STATUS: F FINISHED
 OPR# 1 SKILL LEVEL:

TECH #:	163					
	221			1.18	51.75	61.07
	221			1.73	51.75	89.53
PARTS:	87732448		CANVAS, CH	1.00	91.50	91.50
	87299393		1/8" HAIR	2.00	.24	0.48
5	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	150.60	91.98	0.00	0.00	0.00	242.58

***** PROBLEM # 06 DETAILS *****
 PRB# 6 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: SYSTEM OPERATIONS - THE SEPARATOR DOES NOT RUN, REAR BEACON
 MISSING, SIDE COURTESY LIGHT DOES TO OPERATE, THE CAB HEATER
 DOES NOT OPERATE.
 CORRECTION: NOT DONE AT THIS TIME
 HOLD STATUS: F FINISHED
 OPR# 1 SKILL LEVEL:

TECH #:	221					
6	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	0.00	0.00	0.00	0.00	0.00

***** PROBLEM # 07 DETAILS *****
 PRB# 7 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: FEEDER HOUSING - TIGHTEN THE FEEDER TILT BOLTS, CLIP CLUTCH
 CATCH FINGER SPRINGS OVER STRETCHED
 AUGER BED-AUGER TROUGH BENT
 CORRECTION: NOT DONE AT THIS TIME
 HOLD STATUS: F FINISHED
 OPR# 1 SKILL LEVEL:

TECH #:	221					
7	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	0.00	0.00	0.00	0.00	0.00

***** PROBLEM # 08 DETAILS *****
 PRB# 8 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: CLEANING FAN- SLOP BETWEEN THE VARIABLE SPEED PULLEYS,
 REPLACE THE THRUST BEARINGS.
 STRAW CHOPPER-FLIP ONE SET OF KNIFES (ONE SET IS CHEWED UP)
 CORRECTION: NOT DONE AT THIS TIME
 HOLD STATUS: F FINISHED
 OPR# 1 SKILL LEVEL:

TECH #:	221					
8	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	0.00	0.00	0.00	0.00	0.00

***** PROBLEM # 09 DETAILS *****
 PRB# 9 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: STRAW SPREADER- REPLACE THE MISSING BAT BOLTS, REPLACE THE

LEFT HAND SIDE CONE, STRAIGHTEN THE BENT TRANSITION PAN.

CORRECTION: NOT DONE AT THIS TIME

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 221

9	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	0.00	0.00	0.00	0.00	0.00

***** PROBLEM # 10 DETAILS *****

PRB# 10 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: CLEAN GRAIN ELEVATOR - ELEVATOR SLIP CLUTCH SLIPS, TIGHTEN THE LOOSE DRIVE CHAIN, REPLACE THE UPPER SPROCKET. TAILING ELEVATOR - AUGER DRIVE CHAIN IS ABOUT TO FALL OFF.

CORRECTION: NOT DONE AT THIS TIME

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 221

10	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	0.00	0.00	0.00	0.00	0.00

***** PROBLEM # 11 DETAILS *****

PRB# 11 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: GRAIN TANK-LOWER TEEPEES IN GRAIN TANK, UNLOAD AUGER HOOD NEEDS PATCHED

CORRECTION: NOT DONE AT THIS TIME

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 221

11	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	0.00	0.00	0.00	0.00	0.00

***** PROBLEM # 12 DETAILS *****

PRB# 12 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: ENGINE - THE MUFFLER RAIN FLAP IS MISSING, MOWER BLADE IS BENT AND WON'T TURN

CORRECTION: NOT DONE AT THIS TIME

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 221

12	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	0.00	0.00	0.00	0.00	0.00

***** REPAIR ORDER TOTALS *****

LABOR SALE	1,218.65
PARTS SALE	131.78
REPAIR ORDER SUBTOTAL	1,350.43
TOTAL MISC. SHOP SUPPLIES	8.91
TOTAL DUE	1,359.34

PREVIEW RO# I 58569 CUST# 10000 CRAIG HUNZIKER 7088 COMBINE T
UNIT# 46425 2011 CASE-IH 7088 COMBI

***** REPAIR ORDER SUMMARY DATA *****

CRAIG HUNZIKER 7088 COMBINE TR CUST# 10000 RO# I58569
START 5/09/16 15:33
BILLED 5/18/16 12:12
PILOT GROVE IA 52648-0000 PO#
WRITER 050
PHONE: HOME 319 469-4461 PHC 04 PBC 01 APPROVAL 050 /050

***** REPAIR ORDER TOTALS BY PAY TYPE *****

	C PRB 0	I PRB 3	W PRB 0
BILLED	BILLED	5/18/16 12:12 050	BILLED
LABOR	0.00	1,035.37	0.00
PARTS	0.00	746.12	0.00
SUBLET	0.00	0.00	0.00
OTHER	0.00	0.00	0.00
MISC EXP	0.00	0.00	0.00
MISC CHARGES	0.00	5.43	0.00
DEDUCTIBLE	0.00	0.00	0.00
TAX	0.00	0.00	0.00
TOTAL DUE	0.00	1,786.92	0.00

***** SERVICE UNIT INFORMATION *****

OWNER 10000 UNIT# 46425 2011 CASE-IH 7088 COMBI CURR HRS 987.0
DELIVERED: 9/28/15
VIN: YAG004859 ENGINE: 73151791
TIRE SIZE: 900X60R32 FST AXLE SN: 600/60/28 REAR
FEEDER LENGTH: 54.5SR CUT TYPE: CRSFLW
ROTOR HRS: 712 HRS 7-27-15
WARRANTY EFF: EXT: N UNIT: YAG004859 EXP: 9/14/12
ENG: 73151791 EXP: 9/14/13

***** PROBLEM # 01 DETAILS *****

PRB# 1 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: INT. COMBINE (MID-RANGE)-RECONDITIONING SERVICE
*987 ENG HRS 5-11-16
PERFORM THE STEPS OUTLINED ON THE FORM TITLED "COMBINE
SERVICING CHECK LIST FOR MID-RANGE COMBINES"
CORRECTION: HAD TO JUMP START COMBINE, MOVE OUT OF COLD STORAGE INTO
SHOP.
HOLD STATUS: F FINISHED
OPR# 1 I.COMSEMIRSC00 ----- FLAT RATE SKILL LEVEL:
INT. COMBINE (MID-RANGE)-RECONDITIONING SER
TECH #: 000

	026		1.50		0.00
	026		.76		0.00
	026		1.26		0.00
	026		2.08		0.00
	026		.52		0.00
	026		.80		0.00
LABOR:			6.00	82.00	492.00
PARTS:	73341702	5 GALLON /	1.00	76.00	76.00
	73341701	2-1/2 GALL	1.00	41.45	41.45
	84485647	FILTER, OI	1.00	58.00	58.00
	86998333	FILTER, AI	1.00	106.00	106.00
	86998332	FILTER, AI	1.00	80.50	80.50
	84605017	WATER FILT	1.00	18.50	18.50
	84217229	FILTER / C	1.00	51.00	51.00
	84477358	FILTER - S	1.00	27.50	27.50
	87307432	FILTER - P	1.00	43.00	43.00
	HYTRANC	1 GAL / HY	2.00	14.89	29.78
	HYTRANC	(CORE CHA	2.00	.20	0.40
	HYTRANC	(CORE CRE	2.00-	.20	0.40-
1	LABOR				
	492.00	PARTS			
		531.73	SUBLET		
			0.00	OTHER	
				0.00	
				MISC	
				0.00	
				PROB	
					1023.73

***** PROBLEM # 02 DETAILS *****

PRB# 2 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: CLEAN AND DETAIL

HOLD STATUS: F FINISHED
OPR# 1

SKILL LEVEL:

TECH #: 026

149				.93	51.75	48.13
149				1.55	51.75	80.21
149				2.07	51.75	107.12
149				1.05	51.75	54.34
149				2.67	51.75	138.17
149				1.63	51.75	84.35
149				.60	51.75	31.05
PARTS:	LU10513		SHINE, TIR	1.00	7.62	7.62
2	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	543.37	7.62	0.00	0.00	0.00	550.99

***** PROBLEM # 03 DETAILS *****
PRB# 3 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: INSTALL SPREADER SHIELD THAT WAS MISSING
HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:

TECH #: 149

PARTS:	87655293		PANEL ASSY	1.00	185.92	185.92
	132657A2		CABLE / SH	1.00	20.55	20.55
	P2705-029		1/4 WHIZ N	2.00	.15	0.30
3	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	206.77	0.00	0.00	0.00	206.77

***** REPAIR ORDER TOTALS *****
LABOR SALE 1,035.37
PARTS SALE 746.12
REPAIR ORDER SUBTOTAL 1,781.49
TOTAL MISC. SHOP SUPPLIES 5.43
TOTAL DUE 1,786.92

PREVIEW RO# R 56638 CUST# 10000 CRAIG HUNZIKER 7088 TRADE
UNIT# 46425 2011 CASE-IH 7088 COMBI

***** REPAIR ORDER SUMMARY DATA *****
CRAIG HUNZIKER 7088 TRADE CUST# 10000 RO# R56638
START 10/13/15 15:06
PILOT GROVE IA 52648-0000 BILLED 11/30/15 14:37
PO#
PHONE: HOME 319 469-4461 PHC 02 PBC 01 WRITER 061
APPROVAL 061 /050

***** REPAIR ORDER TOTALS BY PAY TYPE *****
C PRB 0 I PRB 2 W PRB 0
BILLED 11/30/15 14:37 050 BILLED
LABOR 0.00 159.80 0.00
PARTS 0.00 54.55 0.00
SUBLET 0.00 0.00 0.00
OTHER 0.00 0.00 0.00
MISC EXP 0.00 0.00 0.00
MISC CHARGES 0.00 1.60 0.00
DEDUCTIBLE 0.00 0.00 0.00
TAX 0.00 0.00 0.00
TOTAL DUE 0.00 215.95 0.00

***** SERVICE UNIT INFORMATION *****
OWNER 10000 UNIT# 46425 2011 CASE-IH 7088 COMBI CURR HRS 953.0
DELIVERED: 9/28/15
VIN: YAG004859 ENGINE: 73151791
TIRE SIZE: 900X60R32 FST AXLE SN: 600/60/28 REAR
FEEDER LENGTH: 54.5SR CUT TYPE: CRSFLW
ROTOR HRS: 712 HRS 7-27-15
WARRANTY EFF: EXT: N UNIT: YAG004859 EXP: 9/14/12
ENG: 73151791 EXP: 9/14/13

***** PROBLEM # 01 DETAILS *****
PRB# 1 LABOR TYPE 1IR REWORK ** BILLED **
COMPLAINT: HYDRO OIL LEAK BETWEEN THE MOTORS **REWORK--WO 56133**
MIKE W AND CALEB
CORRECTION: CUSTOMER HAD TO PAY FOR HYDROS AND PUMP, WHEN THEY WERE
INSTALLED, FORGOT TO PLACE THE ORING BETWEEN THE HYDRO MOTOR
AND THE TRANSMISSION. HAD TO TAKE APART AND REDO.

HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:
TECH #: 139
139 .50 20.00 10.00
139 .25 20.00 5.00
139 1.10 20.00 22.00
139 1.53 20.00 30.60
139 .75 20.00 15.00
139 1.68 20.00 33.60
139 .56 20.00 11.20
PARTS: 87319344 SEAL 2.00 26.75 53.50
86511479 BOLT, 8X20 1.00 1.05 1.05
1 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
127.40 54.55 0.00 0.00 0.00 181.95

***** PROBLEM # 02 DETAILS *****
PRB# 2 LABOR TYPE 1IR REWORK ** BILLED **
COMPLAINT: REPAIR THE LADDER THAT WAS DAMAGED WHILE LOADING THE
COMBINE ***REWORK***CODI
CORRECTION: CODI WAS NOT WATCHING CLOSE ENOUGH WHEN CHARLIE LOADED
COMBINE AND THE LADDER CAUGHT ON THE TRAILER. HAD TO
STRAIGHTEN AND BEND LADDER BACK INTO PLACE.
HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:
TECH #: 139
139 1.62 20.00 32.40
PARTS: B93228N SPRAY PAIN 9.95 0.00
2 LABOR PARTS SUBLET OTHER MISC PROB TOTAL

32.40

0.00

0.00

0.00

0.00

32.40

REPAIR ORDER TOTALS

LABOR SALE	159.80
PARTS SALE	54.55
REPAIR ORDER SUBTOTAL	214.35
TOTAL MISC. SHOP SUPPLIES	1.60
TOTAL DUE	215.95