WILLMAR FORKLIFT, INC. 320-235-9224 2480 E HWY 12 WILLMAR, MN 56201

Date	Invoice
9/8/2015	39992

GARY MALLIK		

P.O. Number	Terms	Rep	Ship Date	Ship Via	F.O.B.		Project
	NET 10	JR	JR 9/4/2015 W		WO 24998		
Quantity	Item Code		Descript	ion	Pric	e Each	Amount
1 1 1 1 1 4 2 4 2 1 5 1 4 1 1 1 1 6 1 1 2 2 2 4 2 1 1 1 1 1 1 1 1 1 1 1 1 1	LABOR05 4769099 DOT3 BRAKE FL. SHOP SUPPLIES PART 731-1108 #6 RUBBER HYD. #6 JIC COUPLER #8 HYD HOSE CL. 9220-0606 1069 OIL 2222 T14PR-U HYSTER HYSTER HYD OIL BRAKE CLEANER 650-10 TUBE 650-10AIRTIRE SMH FRT	DOT3 BRAK SHOP SUPP CABLE ENI CHOKE CAI #6 HOSE PE #6 JIC FEMA #8 HOSE PE ADAPTOR OIL FILTER QTS SYNTH AIR FILTER SPARK PLU VALVE COV STARTER 13 FREIGHT QTS HYD OI BRAKE CLE 6.50-10 TUB 650-10 AIR T RIM BEAD FREIGHT	YL OLD CAST 1" EE FLUID PER PIN LIES BLE R FOOT RUBBER ALE COUPLER R FOOT REUSABI CHEV SHORT ETIC 10W30 OIL G 3.0GM YER GASKET 183240 L ANER E	1 WIRE Æ	2 1 1 3 2 2 3 1 1 1 2 3 1	95.00 31.84 3.37 5.00 4.55 28.82 7.14 12.64 9.35 14.56 8.24 4.49 18.78 3.16 5.66 94.84 11.80 4.06 5.23 9.03 14.22 9.22 8.00	665.00 81.84T 3.37T 5.00T 4.55T 28.82T 28.56T 25.28T 37.40T 29.12T 8.24T 22.45T 28.78T 12.64T 15.66T 394.84T 21.80T 24.36T 5.23T 38.06T 288.44T 78.44T 18.00T
Thank you f	or using Willm	nar Forklif	t, Inc.			TOTAL:	\$1,948.44

WILLMAR FORKLIFT, INC.

	WILLMAR, MN 56201
CUSTOMER	SERVICES PERFORMED
STREET Mallale	1) vero steer tives
CITY STATE ZIP	
MAKE UNIT HR'S HUST MODEL HISOH ECCIONING P.O.#	Had to make Inhage Time up Aservice
	W Brakes - master ey/
PARTS	5/ starter Century at clotely
1 4769099	1) Owner and willing
1 Dots Ruid	O Valve (over gashe)
1 03338 Ceble Stop 1 731-1108 Push Pull for Chalce	Deplace tokes in mast
2 #6 Coupler	Steach Engine Comportunt
2 #6 Coupler 4Pt #8 hose 2 #10-8 Coupler 7 Cut Drives	
2 # 10-8 Coupler	•
n Cut Drives	
1 6069 0:1 Filher	-
5abs 10cv 30cil 1 2222 xx Riller 4 Spork pluss	I hereby certify the listed repair work was done along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to vehicles
U Spork plugs	placed with them for storage, repair or while road testing.
*	SignedDate

WILLMAR FORKLIFT, INC.

	WILLMAR, MN 56201
CUSTOMER	SERVICES PERFORMED
STREET	
CITY STATE ZIP	
MAKE UNIT HR'S	
MODEL S/N	
DATE 9-3-15 P.O.#	
PARTS	-
1 0388313 Volve Cavorzesta 1 1383740 Storter	
1 1385240 Starter	
1.5 gil hyd oil	
1 Brokleen	
2 6.50-10 AIN TIMES 2 6.50-10 Bead rings	_
	-
	-
	-
	I hereby certify the listed repair work was done along with necessary materials. You and your employ ees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is under stood that this company assumes no responsibility for loss or damage by theft or fire to vehicles placed with them for storage, repair or while road testing.
	SignedDate



Date	Invoice
9/9/2015	40013

GARY MALLIK
20897 KALE DR
SILVER LAKE MN 55381

¥.	

P.O. Numbe	r Terms	Rep	Ship Date	Ship Via	F	F.O.B.		Project
	NET 10	MN	9/8/2015		MN	126629		
Quantity	Item Code		Descrip	tion		Price Ea	ıch	Amount
0.5 1 4	LABOR17 MODEL100 WASHER	REPAIR MECHANICAL SEAT FLIP/TILT ADJUSTABLE SY1862-PRO WASHER				95.00 103.47 0.61		47.50 103.47T 2.44T
		WO MN26629 HYSTER H50H Sales Tax		6.875%	,	7.28		
					2:			
Thank you	Thank you for using Willmar Forklift, Inc.				то	TAL:	\$160.69	

WILLMAR FORKLIFT, INC.

CUSTOMER	SERVICES PERFORMED
STREET Mallik	Tustall new seal
CITY STATE ZIP	Justall alw seax
MAKE UNIT HR'S	
MODEL S/N	Removed old seat drilled 4 new hotes,
DATE 9/3/15 P.O.#	and Puton larger washer work gold
PARTS	
1 model 100	
4 washer's	
	A) 47
·	
	I hereby certify the listed repair work was done along with necessary materials. You and your employ ees may operate above vehicle for purposes of testing, inspection or delivery at my risk. An expres mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is unde stood that this company assumes no responsibility for loss or damage by theft or fire to vehicle placed with them for storage, repair or while road testing.
	SignedDate