

Arnold's of Glencoe 655 Lindbergh Trail Glencoe, MN 55336 320-864-5531 952-442-5908

SOLD TO
GMA120 GARY MALLAK
20897 KALE DR
SILVER LAKE, MN 55381

SHIP TO CELL # 320-224-5641

IH 5/ Sold By: JM/ Ship By:	74 SN:6804 J PO #: 574 JB Tax #: FP	HR 93 Date 7/17/ #12196-55208	338.0 W:(/15 REPA 10:0	00 C: IR ORDER 7:13 PRT:	GR23090 2
Tax D Qty	Description			Price	Amount
COMMENT 1. Had ne spark Was wo	ew cyl. head instal plugs, switched to orking good, then g	led last year. Runs D21 hotter plug, st radually got worse.	rough, s	smokes blacks them.	ck, fouled
LABOR CUS	STOMER	** T∩TN	AT INDOD	CUSTOMER	1277 50
000000 1 000000 1 06875 1 00000 1 00000 1 00000 1 00000 1 06875 1 00000 1	CAS 405925R1 CAS 405924R91 CAS 311608 CAS ZRG017CRBC CAS 531456R1 CAS A48371 CAS A44429 CAS A44430 CAS ZRG017BRC CAS 404769R91	VENTURI KIT FLOAT CARB.CLEANE DI SET E6 CONDENSOR E6 CAP E6 ROTOR E6 BRAKE CLEAN DI FUEL PUMP 5 E3	SPLAY 501 502 502 501 SPLAY	33.75 184.00 40.50 4.70 24.50 26.00 31.75 12.50	33.75 184.00
SHOP SUPP	USED DISTRIBUTOR PLY SHOP SUPPLIES & FP	A CHARGES		175.00	175.00 75.00
PICKUP/DE 00000 00000	TRUCKING \$5.00 A LO TRUCKING \$5.00 A LO	DADED MILE 14M DADED MILE 14M ** TOTA	I. PTCKIII	Ургі /натії.	70.00 70.00 140.00
.5 hrs. 1.0 hrs. 1.0 hrs. .6 hrs. 1.0 hrs. .5 hrs. 2.0 hrs. .5 hrs.	Engine miss firing. Shaft & housing wor Searched for new di found used distribu	running. needs overhaul. t in solvent. Cleane thaul kit. ljusted. Found distributor te. stributor, no longe ntor. s, condensor, cap & timing to spec.	ed. bad. er avail.	J. DELIJ HAOD	140.00
				# # # # # # # # # # # # # # # # # # #	

PAY THIS



Arnold's of Glencoe 655 Lindbergh Trail Glencoe, MN 55336 320-864-5531 952-442-5908

SOLD TO
GMA120 GARY MALLAK
20897 KALE DR
SILVER LAKE, MN 55381

SHIP TO CELL # 320-224-5641

Tax D Qty Descriptio	n		*	Price	Amoun
1.3 hrs. Removed va	lve cover.	70301 Jellin ell			
1.3 hrs. Removed va .5 hrs. Checked va Very littl 2.0 hrs. Adjusted v 1.0 hrs. Started & .5 hrs. Timing flu Need to re pump drive	lve adjustment. e_valve lash.	. Valves out of	adjustm	ent.	
2.0 hrs. Adjusted v 1.0 hrs. Started &	alves to spec. readjusted timi	ing & carb.			
.5 hrs. Timing flu Need to re	ctuates 10-15°, move oil pan &	, possible il p oil pump to ch	oump gear	on on	
pump drive	shaft. Custome	er opted not to	o do it.		
and and a sound on					
	A TOTAL AND ADMINISTRATION OF THE PARTY OF T			West William	
	A STATE OF THE PROPERTY OF THE			WEI VIE	
	A THE STATE OF THE				
				WELL WITH	
	The state of the s				
	And the state of t				
agree to pay the total	al amount of th	nis invoice	** SU	BTOTAL	2304.7
agree to pay the total accordance with the	al amount of the	nis invoice reement.			
agree to pay the total accordance with the	al amount of the Cardholder Agr	nis invoice reement.	** SA	BTOTAL LES TAX	2304.7 .6 2305.3



Arnold's of Glencoe 655 Lindbergh Trail Glencoe, MN 55336 320-864-5531 952-442-5908

SOLD TO GMA120

GARY MALLAK 20897 KALE DR SILVER LAKE, MN 55381 SHIP TO

Tax D Otv Description	* Price	Amoun
Tax D Qty Description COMMENT		Timo arr
	t just quit. Turns over and will not	fire.
LABOR CUSTOMER	** TOTAL LABOR CUSTOMER	348.0
PARTS SHOP 00000 1 CAS A44429 00000 1 CAS A44430 00000 1 CAS A48371 00000 1 CAS 531456R1 00000 4 CAS RD18Y	CAP E602 32.00 ROTOR E601 13.00 CONDENSOR E602 26.00 SET E601 25.00 SPARK PLUG E603 8.85 ** TOTAL PARTS SHOP	32.0 13.0 26.0 25.0 35.4 131.4
SERVICE CALL 00000 SERVICE CALL		100.0
SHOP SUPPLY 00000 SHOP SUPPLIES & EPA	A CHARGES	20.8
Reinstalled & set of the wants a tune up 1.6 hrs. Was in the area. In cap, rotor & plugs	park when grounded points with points out & filed them clean. gap. Then it would have spark. when we are back in the area. istalled new points, condensor,	
	A 48 U V 20 OV 4 40 OV OV O U U U O A	
		y x
I agree to pay the total amount in accordance with the Cardholo	of this invoice ** SUBTOTAL der Agreement.	600.28