

Hofmann ransmission

48395 State Highway 55, Brooten, MI

Phone: 320-346-2251

Mailing address: PO Box 373

Email: hoftrans@tds.net

2006 Dodge Pickup

Rebuilt Transmission
In August, 2018

\$4,420.19

1012582 08/08/2018

rage: 1

Customer:

Heller Farms Blake Schroeder

Pn: (320) 522-1038

Vehicle:

2006 Dodge Ram 2500 Pickup 4WD Eng: L6-359 5.9L OHV Tran: 48RE

VIN: 3D7KS26CX6G137442 Mileage In: 178401 Out: 178440

P Date: Cir:

Lic: 029WAN St: MN

Repair Order:

Service Writer: S Voss

PO Number:

Date In: 08/02/2018 Date Out: 08/08/2018

Driver:

Automatic Trans: Rebuild

Customer Concern:

Slips

Diagnosis:

Internal failure. Cooler and cooler lines leaking. Water lines too cooler rubbed thu and

leaking as well.

Recommendation:

Rebuild trans using HD/updated parts. Replace cooler, lines, and coolant pipes.

Labor:

Description

Remove trans from vehicle. Tear down, clean, and inspect. Assemble, replacing parts listed. Hot Flush cooler. Replace cooler lines. Replace cooler. Replace

lines to water cooler. Road test.

Labor Sub Total: 1300.00

20.00

Hours Extended

1300.00

Price Ea. Qty Extended Description Part Num Parts: 356.09 M. W/S, 48RE 03-UP BONDED 356.09 1.00 22006HW FILTER, A500/518/618 98-UP (METAL & PLASTIC) 14.74 1.00 14.74 12010J SURE CURE KIT, 46/47RH/RE 90- UP (SONNAX) 162.13 1.00 162.13 S22174 SENSOR, GOV. PRESS. 4 PIN RECT A500/518/618 (2000 61.29 1.00 61.29 12415C SOME, 01-UP SOLENOID, A500/A518 GOVERNOR PRESSURE 93-UP(BW) 78.43 1.00 78.43 12432A SOLENOID, A500/518/618 OD/TCC DUAL (2000 SOME, 119.88 119.88 1.00 12420C 01-UP ALL) BAND, 727/518/618 KICKDOWN HI- PERF 62-UP RAY 44.83 1.00 44.83 N22022C in. PRO SERIES in. 33.23 SPRAG,727/518 REAR SPR & ROLLE R KIT(14 ROLLER 33.23 1.00 A22654A TYPE) 1988-UP 80.79 BRG KIT, A518/A618 80.79 1.00 22201A SWITCH, A500/518/618 NEUTRAL SAFETY AND BACK UP 68.38 1.00 68.38 D12410D LITE 5 BUSHING, A727/A518 PUMP (W/BAL L INDENTED OIL 7.25 1.00 7.25 22034B PACKETS) 1993-U 2.00 32.58 16.29 Lubequard ATF +4 friction modifier 100 20.00 80.00 4.00 100 19.66 SENSOR, A604/A606 VSS OUTPUT 89-UP (OEM) 19.66 1.00 D92436 675.00 675.00 TORQUE CONVERTER-BILLET COVER HD 1.00 C50HD 6.75 SNAP RG, A518/A618 O. DR. DIR CLU (FRT) 6.75 1.00 D12864 50.40 SPRAG, A500/A518/A618 OVERDRIVE CLUTCH, 1988-UP 50.40 1.00 A12650

By signing this final invoice, I have authorized the repair work listed hereon, including any sublet work, to be done along with necessary materials. I have also authorized any increase in price and repairs over the original estimate that may be noted elsewhere on this invoice. Fees may have been charged for hazardous waste disposal. Specific part(s) may have longer warranty period and may be noted elsewhere on this invoice. In the event a warranty issue occurs, the vehicle must be returned to Hofmann Transmission for repairs. Hofmann Transmission cannot be held liable for any additional costs outside of the original repairs. In the event it is necessary to retain an attorney to collect for the services and goods shown on this invoice, the repair facility will be entitled to a reasonable attorney fee in addition to its court cost. I acknowledge receipt of the vehicle in good condition and a copy of this Repair Order. I have read and understand the conditions of the warranty issued for this repair.

Subtotal: Sales Tax:

Parts:

Labor:

Misc:

Sublets:

4212.66 207.53

2912.66

1300.00

0.00

0.00

TOTAL: Balance:

4420.19 4420.19

Customer Signature

Date

			MC 200	-C-JUWAL-HUMINIA HARTH VANDENA PERSAN
No messa	ges logged.		-	
Contact Log		As of 08/08/2018 a	As of 08/08/2018 at 3:24 pm	
			Job Sub Tota	4212.66
			Misc Sub Tota	0.00
	aftermarket modifi	or 24000 miles. Any failure due to abuse cations, or external factors (ie. cooler cor) may void warranty.	/misuse, 0.00 1.0 lines,	0.00
Misc:	Description		Sold Price Qty	Extended
			Parts Sub Tota	l: 2912.66
	68004319AA 5175552AC	HOSE HOSE	62.47 1.0	
	5179086AA	ELBOWS	43.41 2.0 108.23 1.0	
	52028915AE 22500	EXTERNAL COOLER PRESSURE PALTES	15.00 2.0	
	52028920AI	COOLER LINE	90.35 1.0 245.30 1.0	
	52028922AL 52028918AI	LINE COOLER LINE	184.20 1.0 110.77 1.0	
AND THE PROPERTY OF THE PROPER	A22024C	BAND, A618 REV (6 1/4 in.ID, DOUB LE WE ROLLER SPRAG #65	RAP, W/14 103.09 1.0	0 103.09
jii Tra	ansmission	ct: Heller Farms	r #: 1012582	Page: 2

No payments received.

Transactions: