

Year Make Model 10 DODGE RAM 3500 R.O. Date 06/18/20 R.O. # 290093 Miles In 15
 Color VIN 3D73Y4CL9 AG179306 Miles Out 239279

Customer Kevin Hamborg

P.O. Box 747
 34650 225th Avenue
 Albany, MN 56307
 Phone: (320) 845-6723
 Phone: (800) 392-3426

Address 9111 225Th Ave Nw
 City Sunburg, MN 56288

Res. Phone 320 894-9294 Bus. Phone - Ext. - Cell Phone -

Email Address kevinhamborg@yahoo.com

Time Rec Promised Labor Rate AD Cust # Delivery Date Stock # Plate In-Service
 152 *10513 00-00-0000

PARTS

A. JOINT KITNONE
 1 2AMGR428.AC 58.35
 A. BALLJOINTLOWER
 2 5086674.AC 276.00
 A. BALLJOINTUPPER
 2 68214646.AA 120.00
 LINE A TOTAL: \$454.35

C. BRACKET STEERING COLUMN G
 1 CSZHT791.AC N/C
 LINE C TOTAL: \$ 0.00

D. WIRING KIFUEL/WATER SEPARA
 1 CBUMP651.AA N/C
 LINE D TOTAL: \$ 0.00

E. STRAP NONE
 2 56001144. 0.70

OTHER

Shop Supplies 15.00

LABOR

A 01 REPLACE UPPER AND LOWER BALLS JOINTS ON BOTH SIDES
 REQUESTED
 REMOVED FRONT TIRES HUB BEARINGS AND EXTENSION AXLE
 SHAFT AND REMOVED CONTROL ARMS. PRESSED OUT BALL
 JOINTS AND PRESSED IN NEW JOINTS. REPLACED THE AXLE
 U-JOINT, JOINT WAS LOOSE. REASSEMBLED AND TEST DROVE
 GOOD.

Parts: 454.35 Labor: 704.18 Total: 1158.53
 B 01 RADIO SCREEN IS CRACKED AND WANT TO KNOW HOW MUCH TO
 FIX THAT
 SCREEN CRACKED
 TEST DROVE AND FOUND RADIO SCREEN CRACKED REMOVED
 TRIM PANEL REMOVED AND REPLACED RADIO INSTALLED PANEL
 TESTED AND RADIO WORKS BACK UP CAMERA INOP
 Labor: 67.70 Total: 67.70

C RE T79 RECALL
 REQUIRED
 REPLACE GEARSHIFT BRACKET, GOOD.

D RE P65 RECALL
 REQUIRED
 INSPECT DIESEL FUEL FILTER HEATER ELECTRICAL
 CONNECTOR AREA FOR FUEL LEAKS AND REPLACE FUEL FILTER
 HEATER ELECTRICAL CONNECTOR.

E 01 CHECK EVERYTHING OVER AND ADVISE INSTALL RUNNING
 BOARDS

REPLACE UPPER BALL JOINTS
 A -C-R- 40 Labor \$323.85
 REPLACE LOWER BALL JOINTS.
 A -C-R- 40 Labor \$323.85
 REPLACE AXLE U-JOINT
 A -C-R- 40 Labor \$ 56.48
 -A- Labor Total: \$ 704.18

B -C-R- 40 Labor \$ 67.70
 -B- Labor Total: \$ 67.70

19T79185
 C -W-R- 40 Labor \$N/C
 -C- Labor Total: \$N/C
 08P65182
 D -W-R- 40 Labor \$N/C
 -D- Labor Total: \$N/C

REMOVED RUNNING BOARDS.
 E -C-R- 40 Labor \$ 32.50

IMPORTANT

You may receive a survey from your vehicles manufacturer in the near future. If for any reason you cannot recommend us or are not completely satisfied (9's & 10's), please call Bruce Gerads at 320-845-6723

THANK YOU!

mechanics lien is hereby acknowledged on the vehicle to secure the amount of repairs therein.
 If charges are not paid upon delivery of the goods and/or services payment is due within 30 days of the billing date. a 1% per month (12% per annum) late payment penalty will be assessed on any unpaid balance remaining after 30 days.

CASH PAYMENTS MADE.

with the necessary material and agree that in vehicles in case of fire, theft or any liability of parts or delays in shipments permission to operate the vehicle of testing and inspection. An expressed

Parts: 1552.81
 Labor: 1100.83
 Other: 15.00
 Discount: 0.00
 Warranty: 0.00
 Internal: 0.00
 Sub-total: 2668.64
 Tax: 110.64
 Total Due: 2779.28

Key Tag:

0

Please feel free to utilize our Service Drive.

Year Make Model R.O. Date R.O. # Miles In
 10 DODGE RAM 3500 06/18/20 290093 15
 Color VIN Miles Out
 3D73Y4CL9 AG179306 239279

Customer
 Kevin Hamburg
 Address
 9111 225Th Ave Nw
 City
 Sunburg, MN 56288

Res. Phone Bus. Phone Ext. Cell Phone
 320 894-9294 - - -

Email Address kevinhamborg@yahoo.com

Time Rec	Promised	Labor Rate	AD	Cust #	Delivery Date	Stock #	Plate	In-Service
		152		*10513				00-00-0000

PARTS

LINE E TOTAL: \$ 0.70

N. TIRE LT235/80R17 R120
 6 Y7426356.81 1097.76
 LINE N TOTAL: \$1097.76

REQUESTED
 REMOVED OLD RUNNING BOARDS AND INSTALLED NEW, GOOD.
 Parts: 0.70 Labor: 97.50 Total: 98.20
F GN THERE IS A CODE COMING UP FOR THE REAR PARK SENSORS
 AND THE BACK UP CAMERA IS FUZZY.
 TEST DROVE AND PARK LIGHT ON
 CHECKED CODES FOUND B1296-12 CLEANED SENSOR CLEARED
 CODE AND LIGHT CAME BACK ON CHECKED WIRING AT PARK
 SENSOR # 9 AND FOUND BROKEN CONNECTOR AND SENSOR
 CORRODED. RECOMMEND NEW SENSOR AND WIRING, ESTIMATE
 \$425.00
 Labor: 112.95 Total: 112.95
M 45 16PT INSPECTION
 TOTAL: N/C
N 11 MOUNT & BALANCE TIRES
 Parts: 1097.76 Labor: 118.50 Total: 1216.26

LABOR

INSTALLED RUNNING BOARDS.
 E -C-R- 40 Labor \$ 65.00
 -E- Labor Total: \$ 97.50
 F -C-R- 40 Labor \$112.95
 -F- Labor Total: \$ 112.95
 16PT INSPECTION
 M -C- - 40 Labor \$N/C
 -M- Labor Total: \$N/C
 MOUNT & BALANCE TIRES
 N -C-R- 40 Labor \$118.50
 -N- Labor Total: \$ 118.50

OTHER

Payment Method?
 Cash Credit Card

**TERMS: STRICTLY CASH
 UNLESS ARRANGEMENTS MADE.**

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in shipments by a supplier or transporter. I hereby grant you and your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and inspection. An expressed mechanics lien is hereby acknowledged on the vehicle to secure the amount of repairs therein.

If charges are not paid upon delivery of the goods and/or services payment is due within 30 days of the billing date. a 1% per month (12% per annum) late payment penalty will be assessed on any unpaid balance remaining after 30 days.

Key Tag:

0

Parts:
 Labor:
 Other:
 Discount:
 Warrantv:
 Internal:
 Sub-total:
 Tax:
 Total Due:



P.O. Box 747
 34650 225th Avenue
 Albany, MN 56307
 Phone: (320) 845-6723
 Phone: (800) 392-3426

Customer
 Kevin Hamborg

Address
 9111 225th Ave Nw

City
 Sunburg, MN 56288

Year Make Model
 10 DODGE RAM 3500

R.O. Date
 06/25/20

R.O. #
 290304

Miles In
 240212

Color
 VIN 3D73Y4CL9 AG179306

Miles Out
 240213

Res. Phone
 320 894-9294

Bus. Phone
 -

Ext.
 -

Cell Phone
 -

Email Address kevinhamborg@yahoo.com

Time Rec	Promised	Labor Rate	AD	Cust #	Delivery Date	Stock #	Plate	In-Service
			045	*10513				00-00-0000

PARTS

A. SENSOR PARK ASSIST
 1 1EW63TZZ.AA 210.00

A. WIRING JUMPER
 1 68031820.AA 98.50

LINE A TOTAL: \$308.50

B. SPOILER TAILGATE
 1 55372052.AH 85.00

B. RIVET PLASTIC
 6 6502632. 22.50

LINE B TOTAL: \$107.50

LABOR

A -C-R- 40 Labor \$ 79.07
 -A- Labor Total: \$ 79.07

B -C-R- 40 Labor \$ 25.50
 -B- Labor Total: \$ 25.50

A GN C/S TO REPAIR THE #9 PARK SENSOR WIRING AND CONNECTOR.
 REQ
 REMOVED PARK SENSOR #9 AND INSTALLED NEW SENSOR.
 REMOVED PARK SENSORS WIRING AND INSTALLED NEW WIRING.
 CLEARED CODES, TEST DROVE AND WORKING GOOD AT THIS TIME.
 Parts: 308.50 Labor: 79.07 Total: 387.57

B GN REPLACE TAILGATE COVER
 REQUESTED
 REMOVED TAILGATE COVER AND REMOVED ALL CLIPS.
 INSTALLED NEW TAILGATE COVER. WORKS GOOD AT THIS TIME.
 Parts: 107.50 Labor: 25.50 Total: 133.00

OTHER

Shop Supplies 15.00

Payment Method?

Cash Credit Card

**TERMS: STRICTLY CASH
 UNLESS ARRANGEMENTS MADE.**

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in shipments by a supplier or transporter. I hereby grant you and your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and inspection. An expressed mechanics lien is hereby acknowledged on the vehicle to secure the amount of repairs therein.

If charges are not paid upon delivery of the goods and/or services payment is due within 30 days of the billing date. a 1% per month (12% per annum) late payment penalty will be assessed on any unpaid balance remaining after 30 days.

Parts: 416.00
 Labor: 104.57
 Other: 15.00
 Discount: 0.00
 Warrantv: 0.00
 Internal: 0.00
 Sub-total: 535.57
 Tax: 29.64
 Total Due: 565.21

Key Tag:

0

X