FLORIDA SHORES

TRUCK CENTER

FL REGISTRATION: MV 1508

3220 W STATE RD. 442 EDGEWATER, FL 32141 P.O. BOX 880 • EDGEWATER, FL 32132 OFFICE (386) 428-0841 • FAX (386) 428-0338 FLORIDASHORESTRUCKCENTER.COM

Bill To

LAPLANT PROPERTIES

ANNANDALE, MN 55302-3222

STEVE LAPLANT

943 JESKE AVE NW



Fall

Invoice

	Date	Invoice #	
ľ	2/27/2019	9066411	

CASH___ CHECK___ VISA___ MC___ AMX___ DISC_ PROPOSED COMPLETION DATE: SAVE OLD PARTS___ YES___ NO___

LABOR CHARGES BASED ON FLAT RATE____ BO

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN: I UNDERSTAND THAT UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE, IF MY

FINAL BILL WILL EXCEED \$100.

I REQUEST A WRITTEN ESTIMATE.

☐ I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED \$______. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.

☐ 1 DO NOT REQUEST A WRITTEN ESTIMATE.

SIGNED X DATE DATE

DATE

On the State of Electric requires a S1 00 fee to be collected for each new tire sold in the state (s 403 718) and a S1 50 fee to be

[E.g.,the State of Florida requires a \$1.00 fee to be collected for each new tire sold in the state [s.403.718],and a \$1.50 fee to be collected for each now or remanufactured battery sold in the state [s.403.7185]). This charge represents costs and profits to the motor vehicle repair lacility for miscellaneous shop supplies or waste disposal.

Serial No.		P.O. No.	Rep	Truck/Trailer No.	Odometer	
078880		·	רא			
Qty	ltem	Description			Rate	Amount
1 1 9 2 3 2 2 2	DOT TRAILER DOT LABOR MRK4515QH23V UB66864B20 ST373-0143 SET414 SET413	DOT TRAILER INSPECTION TRUCK REMOVE DRUMS AND BRAKES ON REAR AXLE. FOUND S-CAMS HAD EXCESSIVE END PLAY. SLACK ADJBUSTER PIN WAS SIZED IN CLEVIS. HEAT CLEVIS AND DRIVE PIN OUT. REMOVE SLACK ADJUSTER. REMOVE S-CAM SLEEVE. REMOVE S-CAMS. INSTALL NEW S-CAM BUSHINGS. INSTALL S-CAM INSTALL SLACK ADJUSTER. INSPECTED WHEEL SEAL. BOTH WHEEL SEALS ON REAR AXLE WERE STARTING TO LEAK. REMOVE HUBS. CLEAN AND INSPECT BEARINGS. BEARINGS WERE SHOT. DRIVE OUT RACES. INSTALL NEW RACES. INSTALL WHEEL SEALS AND NEW BEARINGS. INSTALL HUBS. INSTALL BRAKE SHOES. INSTALL NEW DRUMS. REMOVE AND REPLACE RIGHT FRONT BRAKE DRUM SHOES, BRAKE 16.5X7 STANDARD BRAKE DRUM SEAL VOYAGER 46305 BEARING HM21848-HM218210				50.00T 90.00T 900.00T 900.00T 360.00T 97.70T 140.04T 89.10T
2 2 3 1 1	E11897 330-3067 10088 GREASE MISC.FEE CAMSHAFT REPAIR KIT GASKET, 6 HOLE HUB OIL LUCAS CHASSIS GREASE MISC. SHOP AND MATERIAL \$50.00	FEE. 4% OF SUB-TOTAL, NOT TO EXCEED	44.55 36.95 0.98 10.00 6.00 50.00	73.90T 1.96T 30.00T 6.00T		

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection.

 Subtotal
 \$2,009.58

 Sales Tax
 \$130.62

 Total
 \$2,140.20

T Pyt about 3000 miles on the Trailer following Repairs

and DOT inspection