BODENSTEINER IMPLEMENT COMPANY

1965 290th Street • Rowley, IA 52329 (319) 938-2222 Fax: (319) 938-2243 BODENSTEINER

ELKADER • CLERMONT
CRESCO • DECORAH • DYERSVILLE
MONTICELLO • NEW HAMPTON
OELWEIN • ROWLEY • WAUKON

www.bodimp.com

| Ship To: | Merlon Graham 4440 |
|-------------|---|
| Invoice To: | MERLON GRAHAM 3024 BRANDON DIAG. BLVD BRANDON IA 52210-9798 |

| Branch | | | | | |
|-------------|-----------|----------|-------|--------|---------|
| ROWLEY, IA | *REPRINT* | | | | |
| Date | Time | | | | Page |
| 04/07/14 | 21: | 36:16 | (B) | | 01 |
| Account No. | Phone No | | | Invoi | ice No. |
| GRAHA008 | 319 | 47425 | 64 | W03 | 3036 |
| Ship Via | | Purchase | Order | | |
| | | 4440 | | | |
| | | | | | |
| | | | | | |
| | | | Sale | sperso | n |
| | | | | 735 | |

SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

C010357

Tractor 4440 4995 RW4440H016751

04/01/14 04/01/14

Customer Haul - Hydraulic oil leak at pump

COMPLAINT:

OIL LEAK

CAUSE:

HYD PUMP LEAKING

REPAIR# 1 C ARNOD NA

CORRECTION:

4/1/14

REMOVED HOOD DRAINED COOLANT REMOVED OIL COOLER REMOVED RADIATOR REMOVED PLATES AROUND PUMP REMOVED LINES FROM PUMP REMOVED PUMP COUPLER REMOVED PUMP SHAFT REMOVED PUMP TOOK APART NEEDS REBUILT LOOKED UP PARTS

4/2/14

CLEANED UP PARTS PUT OLD PUMP BACK TOGETHER TO SEND BACK AS A CORE REMOVED WATER PUMP REMOVED THERMOSTATS CLEANED UP HOUSING CLEANED UP BLOCK FOR WATER PUMP PUT A REMAN WATER PUMP ON PAINTED PUT NEW THERMOSTATS IN GOT A NEW HYD PUMP PUT ON SUPPORT CHECKED THE PISTON PLUGS THEY ARE TIGHT CHANGED 2 FITTINGS CHANGED THE SEAL DRAIN LINE FOR THE STEERING. CHANGED THE ENGINE DAMPER CHANGED THE FRONT ENGINE SEAL PUT THE HYD PUMP IN PUT NEW HYD PUMP COUPLER IN WASHED OUT RADIATOR PUT IN PUT NEW SEALS AROUND RADIATOR PUT NEW COOLANT IN CHANGED HYD OIL AND FILTER STARTED CHECKED PUMP FLOW ANS PRESSURE THEY ARE OK TOOK OUTSIDE WASHED OUT OIL COOLER AND CLEANED OFF THE OIL FROM UP FRONT PUT HOOD ON TOPPED OF HYD OIL AND COOLANT ADDITIONAL DESCRIPTION:

Get Hrs.

AR39795 TEE FITTING 1 17.37 17.37 AR48675 THERMOSTAT 2 9.72 19.44

CONTINUED ON PAGE 02



BODENSTEINER IMPLEMENT COMPANY

1965 290th Street • Rowley, IA 52329 (319) 938-2222 Fax: (319) 938-2243



ELKADER • CLERMONT CRESCO • DECORAH • DYERSVILLE MONTICELLO • NEW HAMPTON OELWEIN • ROWLEY • WAUKON

www.bodimp.com

| Ship To: | Merlon Graham 4440 |
|-------------|---|
| Invoice To: | MERLON GRAHAM 3024 BRANDON DIAG. BLVD BRANDON IA 52210-9798 |

| Branch | | | | | |
|-------------|----------|----------|-------|--------|---------|
| ROWLEY, IA | | | | | |
| Date | Time | | | | Page |
| 04/07/14 | 21: | 36:16 | (B) | | 02 |
| Account No. | Phone No | | | Invo | ice No. |
| GRAHA008 | 319 | 47425 | 64 | W03 | 3036 |
| Ship Via | | Purchase | Order | | |
| | | 4440 | | | |
| | | | | | |
| | | | | | |
| | | | Sale | sperso | on |
| | | | | 735 | |

SERVICE INVOICE

| STK#/FLEET# | | | PIN/EI | N | WARRANTY DATE | HRS |
|-------------|--------------|------|--------|----------|---------------|----------|
| C010357 | Tractor | 4995 | RW4440 | н016751 | | |
| | 4440 | | | | | |
| AR49025 | SEAL | | 1 | 23.43 | | 23.43 |
| AR56065 | HYDRAULIC | | 1 | 9.37 | | 9.37 |
| AR57241 | PULLEY, WI | | 1 | 224.06 | | 224.06 |
| AR91035 | FOAM KIT | | 1 | 52.13 | | 52.13 |
| AR94510 | FILTER ELE | | 1 | 34.59 | | 34.59 |
| AR94660 | HYDRAULIC PU | | 1 | 2227.88 | | 2227.88 |
| CRAR94660 | LESS CORE | | | 300.00 | | 300.00 |
| CRAR94660 | LESS CORE | | 1- | 300.00 | | 300.00CR |
| F3171R | O-RING | | 1 | 2.31 | | 2.31 |
| RE11864 | FITTING | | 1 | 64.91 | | 64.91 |
| R124607 | GASKET | | 1 | 7.10 | | 7.10 |
| R26287 | O-RING | | 1 | 1.04 | | 1.04 |
| R27928 | O-RING | | 2 | 1.34 | | 2.68 |
| R34362 | EXTERNAL H | | 2 | 23.90 | | 47.80 |
| R34733 | WASHER | | 1 | 2.11 | | 2.11 |
| R45822 | BUSHING | | 4 | 2.27 | | 9.08 |
| TY22028 | HY-GARD OIL | | 60 | 3.50 | | 210.00 |
| TY26576 | COOL-GARD TM | | 3 | 36.57 | | 109.71 |
| TY6758 | WATER PUMP | | 1 | 157.14 | | 157.14 |
| T11234 | LOCK NUT | | 2 | .94 | | 1.88 |
| 19H2116 | CAP SCREW | | 2 | 1.24 | | 2.48 |
| 19Н3131 | CAP SCREW | | 1 | .92 | | .92 |
| | | | | PARTS | | 3227.43 |
| | | | | LABOR | | 1136.03 |
| 10600013 | | | REPAIR | TOTAL==> | | 4363.46 |
| | | | | | | |

***** WORK ORDER TOTALS *****
PARTS 3227.43
LABOR 1136.03
HAZ MTL 20.00

CONTINUED ON PAGE 03



BODENSTEINER IMPLEMENT COMPANY

1965 290th Street • Rowley, IA 52329 (319) 938-2222 Fax: (319) 938-2243



ELKADER • CLERMONT
CRESCO • DECORAH • DYERSVILLE
MONTICELLO • NEW HAMPTON
OELWEIN • ROWLEY • WAUKON

www.bodimp.com

| Ship To: | Merlon Graham 4440 |
|-------------|---|
| Invoice To: | MERLON GRAHAM 3024 BRANDON DIAG. BLVD BRANDON IA 52210-9798 |

| Branch | | | | | |
|-------------|------|------------|-------------|-------|------|
| ROWLEY, IA | T | | | | - |
| Date | Time | | | | Page |
| 04/07/14 | 21: | 36:16 (| в) | | 03 |
| Account No. |). | | Invoice No. | | |
| GRAHA008 | 319 | 474256 | 4 | W03 | 3036 |
| Ship Via | | Purchase O | rder | | |
| | | 4440 | | | |
| | | | | | |
| | | | | | |
| | · | | Sales | perso | n |
| | | | 7 | 735 | |

SERVICE INVOICE STK#/FLEET# HRS PIN/EIN WARRANTY DATE ${\tt HRS}$ C010357 Tractor 4995 RW4440H016751 4440 SRVC ACCESSORY 25.00 SUB TOTAL ==> 4408.46 103.65 7% IOWA TAX- TAX 1 926307 3610066850 TOTAL FARMPLAN 4512.11

