

Curry's Truck and Trailer Repair

P.O. Box 232
Muscatine, IA 52761
Phone # 563-263-4100
Fax # 563-263-4101

Invoice

| Date | Invoice # |
|-----------|-----------|
| 7/12/2017 | 79045 |

Bill To

Curry's Transportation Service Inc.
9914 County Road G44X
Muscatine, IA 52761



| P.O. No. | Terms | Project |
|----------|-------|---------|
| Trk 53 | | |

| Quantity | Description | Rate | Amount |
|----------|---|----------|----------|
| 1 | Annual Inspection | 50.00 | 50.00 |
| 2 | Changed oil, oil filter and fuel filter. Greased chassis. Checked transmission, rear ends, brakes, lights and tires. -Mileage # 887432 | 50.00 | 100.00 |
| 0.75 | Replaced exhaust clamps | 50.00 | 37.50 |
| 1.5 | Replaced fuel line and fitting on the back of the head. | 50.00 | 75.00 |
| 2 | Replaced wheel seal, bearing and races and left steer axle hub | 50.00 | 100.00 |
| 30 | Inframe rebuild. Replaced pistons, liners, oilers, rod and main bearings. Checked crank end play .003. All rod side to side within spec. Torqued rods and main to spec. Installed head and gasket along with injectors and torqued to specs. Replaced oil pump and relief valves and torqued to specs. Checked backlash it was good. Timed engine and installed cam with new bearings and torqued to spec. Set overhead. Filled with coolant. | 50.00 | 1,500.00 |
| 1 | Checked surface head for cracks. Pressure tested and cleaned | 298.69 | 298.69 |
| 1 | Overhaul Kit DDER23538418 | 4,197.93 | 4,197.93 |
| 1 | Valve Assembly DDE23512901 | 59.64 | 59.64 |
| 1 | Elbow Assembly DDE23528691 | 108.18 | 108.18 |
| 1 | Gasket DDE23539104 | 81.75 | 81.75 |
| 1 | Gasket DDE23539103 | 59.39 | 59.39 |
| 1 | Bearing and Gasket Kit DDE23533692 | 411.72 | 411.72 |
| 1 | Oil Pump DDER23527448 | 441.74 | 441.74 |
| 1 | Injector Harness DDE23536019 | 162.30 | 162.30 |
| 1 | Ring Set DDE23537529 | 64.94 | 64.94 |
| 1 | Injector 6 Pack DDER4147030035 | 3,240.12 | 3,240.12 |
| 1 | Fuel Tube Assembly 23532308 | 25.16 | 25.16 |
| 1 | Fitting 23531275 | 19.89 | 19.89 |
| 1 | 3/8" Bolt | 0.39 | 0.39 |
| 2 | 3/8" Flat Washer | 0.12 | 0.24 |
| 1 | 3/8" Loc Nut | 0.21 | 0.21 |
| 1 | Exhaust Band 20A500 | 9.59 | 9.59 |
| 3 | Exhaust Bank 205500 | 11.10 | 33.30 |
| 3 | Pints Synthetic 75-90 gear lube | 5.25 | 15.75 |
| 1 | Bearing ASET049011 | 33.45 | 33.45 |
| 1 | Bearing ASET378220 | 29.17 | 29.17 |

FINANCE CHARGES will apply if the new balance is unpaid one month from the closing date of the statement. The FINANCE CHARGES are computed by a periodic rate of 2% per month which is an ANNUAL PERCENTAGE RATE of 24% to the unpaid balance.

Total

Curry's Truck and Trailer Repair

P.O. Box 232
Muscatine, IA 52761
Phone # 563-263-4100
Fax # 563-263-4101

Invoice

| Date | Invoice # |
|-----------|-----------|
| 7/12/2017 | 79045 |

| |
|---|
| Bill To |
| Curry's Transportation Service Inc. 9914 County Road G44X Muscatine, IA 52761 |



| P.O. No. | Terms | Project |
|----------|-------|---------|
| Trk 53 | | |

| Quantity | Description | Rate | Amount |
|----------|---|--------|----------|
| 1 | Wheel Seal | 58.84 | 58.84 |
| 1 | Pints 80-90 Gear Lube | 5.25 | 5.25 |
| 1 | Hub Gasket 3303024 | 2.09 | 2.09 |
| 1 | Hub Gasket Seal 3595990 | 4.31 | 4.31 |
| 8 | Cap Tires | 269.49 | 2,155.92 |
| 9 | Tire Mount | 12.50 | 112.50 |
| 9 | Tire Dismount | 12.50 | 112.50 |
| 9 | Tire Disposal | 12.50 | 112.50 |
| 9 | Valve Core | 1.65 | 14.85 |
| 1 | Bridgestone R283 | 556.00 | 556.00 |
| 9 | Valve Cap | 0.24 | 2.16 |
| 1 | Misc Shop Supplies | 10.00 | 10.00 |
| | Changed oil, oil filter and fuel filter. Greased chassis. Checked transmission, rear ends, brakes, lights and tires. -Mileage # 887432 Replaced exhaust clamps Replaced fuel line and fitting on the back of the head. Replaced wheel seal, bearing and races and left steer axle hub Inframe rebuild. Replaced pistons, liners, oilers, rod and main bearings. Checked crank end play .003. All rod side to side within spec. Torqued rods and main to spec. Installed head and gasket along with injectors and torqued to specs. Replaced oil pump and relief valves and torqued to specs. Checked backlash it was good. Timed engine and installed cam with new bearings and torqued to spec. Set overhead. Filled with coolant. Replaced drive tires and left steer tire Trk 53 Date Completed 7/6/17 RD,EM,LS-BW Check wheels and torque after first 20-25 miles of service Re-torque lug nuts after first 50 miles of service | | |

FINANCE CHARGES will apply if the new balance is unpaid one month from the closing date of the statement. The FINANCE CHARGES are computed by a periodic rate of 2% per month which is an ANNUAL PERCENTAGE RATE of 24% to the unpaid balance.

Total

\$14,302.97