

Invoice

Invoice #: 00055912

Bill To:

Ship To:

Precision Manure Application  
511 Washington Av  
Iowa Falls, Ia 50126

Precision Manure Application  
511 Washington Av  
Iowa Falls, Ia 50126

Rhonda Bice		8300	Net 15 after EOM	10/5/2020	1	
6		Outside Labor to magna flux, recondition, center, balance, and install bushings in rods. 4	\$179.01	1	\$1,074.06	X
1		Outside Labor to rebuild head and all head parts. 4	\$1,929.23	1	\$1,929.23	X
1	s	RP1300 Overhaul Kit 12	\$2,752.31	1	\$2,752.31	
6	s	NR74008S Pin Bushing 12	\$24.30	1	\$145.80	
6	s	JD386 Injector Nozzle 45	\$107.04	1	\$642.24	
2	s	F3171R O-ring 11	\$2.69	1	\$5.38	
10	s	R51936 Packing 11	\$1.44	1	\$14.40	
6	s	R67092 Seal 11	\$4.30	1	\$25.80	
2	s	R72328 O-Ring 11	\$1.42	1	\$2.84	
6	s	R79605 Washer 11	\$2.44	1	\$14.64	
1	s	R79846 Cap screw 11	\$3.00	1	\$3.00	
4	s	19M7775 6x16 GRD8 FLT 11	\$0.87	1	\$3.48	
1	s	51M7044 O-Ring 11	\$2.39	1	\$2.39	
2	s	AR48675 Thermostat 11	\$11.34	1	\$22.68	
1	s	R111932 Hose 11	\$5.69	1	\$5.69	
1	s	R120138 Sleeve 11	\$4.84	1	\$4.84	
1	s	R122290 Hose 11	\$19.43	1	\$19.43	
1	s	R125166 Hose 11	\$18.93	1	\$18.93	
1	s	R125359 Radiator Hose 11	\$46.33	1	\$46.33	
1	s	R125635 Hose 11	\$8.69	1	\$8.69	
1	s	R131646 Radiator Hose 11	\$29.69	1	\$29.69	
4	s	R151387 Nut 11	\$1.41	1	\$5.64	
2	s	R164193 Hose 11	\$69.82	1	\$139.64	
1	s	R189038 Radiator Hose 11	\$13.65	1	\$13.65	
1	s	RE57603 Torsion 11	\$346.84	1	\$346.84	
1	s	RE58412 Fitting 11	\$112.70	1	\$112.70	
1	s	RE66000 Fuel Line 11	\$48.99	1	\$48.99	
1	s	RE502650 Fitting 11	\$7.38	1	\$7.38	
1	s	RE519144 Sensor 11	\$38.19	1	\$38.19	

8300 vin 22201 hrs 5212

Invoice #: 00055912

Bill To:

Ship To:

Precision Manure Application  
511 Washington Av  
Iowa Falls, Ia 50126

Precision Manure Application  
511 Washington Av  
Iowa Falls, Ia 50126

Rhonda Bice                      8300    Net 15 after EOM                      10/5/2020                      2

4 s	7051509 Clamp 21	\$9.31	1		\$37.24	
1 s	RE166242 Clamp 11	\$43.58	1		\$43.58	
1 s	RE520036 Seal 11	\$55.01	1		\$55.01	
1 s	R119384 Gasket 11	\$18.18	1		\$18.18	
1 s	R125855 Gasket 11	\$64.20	1		\$64.20	
8 s	R523525 Bolt 11	\$12.77	1		\$102.16	
1 s	RE54368 Gasket 11	\$59.60	1		\$59.60	
1 s	A-RE521503 Water Pump 1	\$351.47	1		\$351.47	
1 s	A-R119383 Gasket 1	\$11.31	1		\$11.31	
1 s	NRG24026 Head Bolt Kit 12	\$219.80	1		\$219.80	
1 s	R109625 Gasket 11	\$7.44	1		\$7.44	
4 s	R71732 O-Ring 11	\$2.40	1		\$9.60	
1 s	RE57190 Seal 11	\$10.03	1		\$10.03	
1 s	R10093 O-Ring 11	\$1.26	1		\$1.26	
1 s	R27564 O-Ring 11	\$1.07	1		\$1.07	
2 s	19M7702 Screw 11	\$1.11	1		\$2.22	
2 s	R166485 Cam 11	\$14.49	1		\$28.98	
3	08880 brake clean	\$5.99	1		\$17.97	
1	P558329 Lube Filter Spin-On*	\$16.29	1		\$16.29	
4	SS3/8X2CARR Stainless Steel 3/8	\$0.75	1		\$3.00	
3	032 hose clamp	\$2.13	1		\$6.39	
5	040 #40 Hose Clamp 2 1/16	\$1.26	1		\$6.30	
6	CHD40015w40-B Delo MG 15w40-Bulk	\$12.10	1 gal		\$72.60	X
7.5	CH9058B FC 50/50 Purple-Bulk	\$7.80	1 Gal		\$58.50	X
1	Misc Shop Supplies	\$50.00	1		\$50.00	
1	Service Call	\$55.00	0	100%		
1	Labor #1 Engine noise. Checked for miss on engine. found loosened injector lines. found #1 cylinder missing. checked exhaust manifold and found #1 cold.	\$80.00	1 hr		\$80.00	X

8300 vin 22201 hrs 5212

Invoice

Invoice #: 00055912

Bill To:

Precision Manure Application  
 511 Washington Av  
 Iowa Falls, Ia 50126

Ship To:

Precision Manure Application  
 511 Washington Av  
 Iowa Falls, Ia 50126

Rhonda Bice	8300		Net 15 after EOM	10/5/2020	3
1.25		Labor #2 Picked up tractor on site and hauled back to shop	\$80.00	1 hr	\$100.00 X
1		Labor #2 Tech help	\$80.00	1 hr	\$80.00 X
13.5		Labor #3 Tear down Engine.	\$80.00	1 hr	\$1,080.00 X
38.25		Labor #4 Rebuild engine. Cleaned block. Installed sleeves, pistons, main bearings & rod bearings, torque mains & rods, installed cylinder head. Torque head bolts. Installed rocker arm assembly. Adjusted valves. Installed injector fuel lines. assembled components on engine. Ran engine to test.	\$80.00	1 hr	\$3,060.00 X
4.25		Labor #4 Tech help	\$80.00	1 hr	\$340.00 X
1		Labor #4 Tech help	\$80.00	1 hr	\$80.00 X
1.25		Labor #5 Service. Removed couplers. Replaced plates on lever. Replaced o-rings on lever. Reinstalled couplers.	\$80.00	1 hr	\$100.00 X
2		Labor #6 Put trimmings, hood, tin work, fender flares and wheels.	\$80.00	1 hr	\$160.00 X
1.5		Labor #6 Tech help..	\$80.00	1 hr	\$120.00 X

8300 vin 22201 hrs 5212

\$13,939.08  
 \$33.00  
 \$583.41  
 \$14,555.49  
 \$14,555.49

\$0.00