

Anderson Repair
 22302 Kandi-Meeker Rd
 Atwater, MN 56209

Phone 320-220-2164

Date	Invoice #
7/3/2017	312

Bill To
Tyler Slinden 17100 Lake Elizabeth Pass Atwater, MN 56209

Work to be done
Replace deck plates Check for other needed repairs

Model	Serial Number	Hours	Terms	
643	338264		Due on receipt	
Quantity	Item	Description	Price Each	Amount
6	A-N102068	Deck plate	22.49	134.94
6	A-N102069	Deck plate	22.49	134.94
11	A-H118945	Gathering chain guide	17.56	193.16
12	A*H84479	Tensioner support	22.26	267.12
2	E42803	Spacer	1.02	2.04
1	W23122	Snap ring	3.19	3.19
8	AN102562	Corn head grease (used 1.5 tubes kept 2 for Anderson Repair)	3.81	30.48
1	Miscellaneous	Metal for covering hole in bottom of corn head	1.00	1.00
1	081115	3M Panel Bond	10.00	10.00
4	03H1558	3/8 X 1 1/2 Carriage bolt	1.05	4.20
9	12H301	Lock Washer	0.44	3.96
4	12H304	3/8 Lock Washer	0.30	1.20
4	14H812	3/8 nut	0.44	1.76
2	24H1305	3/8 Washer	0.38	0.76
10.94	Labor	Labor	80.00	875.20
1	Shop Supplies	Shop supplies used for repair	12.00	12.00
24	Milage	Return trip mileage	1.00	24.00
1	Shipping	Shipping on Parts	23.73	23.73
		Removed all snoots. Disassembled top half of all row units. Replaced all deck plates and tensioner supports. Replaced 11 of 12 gathering chain guides. Reassembled upper part of row units. Set deck plate spacing and adjusted gathering chains. Tensioned row unit and auger drive chains. Greased row units and PTO shafts. Installed snoots. Patched hole in right hand auger trough with flashing and panel bond adhesive. Lubed all drive chains. Ran and checked operation.		
			Total	\$1,723.68