

739 - 2003 Sterling

Maintenance Log

Date	Maintenance /Shop Time	Current Mileage / Hours	Annual Hours Used	Tech (Initial)	Vendor
6/1/2009	new brakes and seals				
6/8/2010	new bed liner from (Warner Plastic & Liners) 1/2' thick	198200			Warner
6/14/2010	changed engine oil and filter 15/40 gold, fuel filter, hyd. Filter, water filter new oil pan gasket, new solenoid for the vibrator on box, new front left leaf spring, new fuse box cover, greased, adjusted brakes, checked all the lights, and inspected.put on new used front bumper	198300		cookie,phil	
9/1/2010	lubed up brake pedal			rick	
2/10/2011	Full inspection of truck. Changed power steering fluid greased entire truck changed air dryer filter filter #TLA109994 installed step and shovel holder on box	199774		rick	
5/25/2011	checked all fluids ok, engine oil needed 1gal, new rear strobe light on right side new air conditioner line, iowa tire charged system needs new wheel seals and water pump	200830		rick	
7/18/2011	new water pump, and new fan clutch			phil	
1/26/2012	checked miles, checked fluids, blow out air filter, anti-freeze tested -15, new braker for running lights, front right tire is bad, new wheel seals on rear axle both sides, and on front drive axle left side	202918	4718	rick,cory	total
8/3/2012	new wheel seal on front right drive axle, old seal # CR 47697 - replaced with National #370003A greased entire truck, checked rear end oil, cleaned air filter			jacob,dan cory	Arnolds
1/1/2013	checked miles,	205092	2174		total
5/10/2013	complete check over of truck. Replaced steer tires Double Coin 315/80/22.5 took oil sample it came back normal	205092		Jon W iowa Tire	iowa Tire
12/13/2013	checked over blew out air cleaner greased replaced coolant tank# 103F/A05-23573-000 \$ 217.08 and replace vibrator motor #3-296			Rick	Arnolds / truck country
12/31/2013	two new air compressor coolantsteel lines # 3944498, #3944496, orings # 3046201			rick	
1/1/2014	checked miles,	207143	2051		total
3/4/2014	new bottom bushings on lift cylinder, turned top bushings on cylinder # 76397G	207678		rick	Cortez Truck Equip.

	tighten tail gate latch, new o-ring on air - compressor coolant line, cleaned cab, new mirror on drivers side				5950 6th street SW
	new engine brake, checked over, and inspected, greased front end				Cedar Rapids 52404
3/18/2014	Painted truck, 4 new wheel studs and nuts; M22x1.5			phil	Altorfer paint \$686.00 319-366-8184
4/2/2015	new DMS SA23251240 POD				truck country, \$51.23
9/19/2014	tire repair				truck repair Davis county tire
10/14/2014	new fan blower #103F/F3UH 19846 AA , welded cage around rear brake lights			jacob	truck country,
	new blower motor resistor #103F/4C4H 19A706 AA, Heater control 103/SOG 896H1CR1U0312S \$10.69				truck country
10/29/2014	installed push button and light for engine intake heater, new air filter, new talegate air solenoid valve	209635			Myer's Repair
1/1/2015	checked miles,	209838	2695		total
2/11/2015	inspected truck, adjusted the brakes, phil welded three wheel studs to hub, filled front right steer hub with 80-90, added 2Qt	209838		travis/phil	rear main seal is leaking
	to engine, 1 gal. to reservoir of anti-freeze, greased, and cleaned cab, built new pull hitch on front				
3/5/2015	took truck to meyer welding for new main bearing seals \$1412.33, new driver seat bottom seat cover from Dent Master \$125.00			lonnie meyer, steve speees	
4/3/2015	new controller for air ride seat #DMS SA23251240 \$83.18			travis	
7/8/2015	new wheel stud on back left tandem				lowa tire
8/17/2015	replaced three tires \$150.00 each used and 1 rim \$100.00 and three studs \$10.00each, labor \$50.00				lowa tire
9/2/2015	worked on			dan	
11/13/2015	tire repair				lowa tire
12/22/2015	changed engine oil and filter 15/40 gold, fuel filter, new outer air filter, all other oil's OK, anti-freeze tested -34	213839		dan	
12/23/2015	bought used tire 11R-22.5				lowa tire
1/1/2016	checked miles,	213936	4098		total
1/15/2016	new governor assy. On air-conditioner pump #KN18530, new air dryer filter #TUFTLA 109994	213936		dan	Arnolds
2/24/2016	ordered new front fender supports #103F/F8HZ 16E013AA \$181.15, #103F/F8HZ 16E012 \$172.75, Nuts M8x1.25 \$3.50 each			dan	truck country
2/26/2016	screws and washers			dan	truck country
3/8/2016	bolts and nuts			dan	arnolds
9/9/2016	added new apron on back of tail gate	217040		tristen/jerry	
9/13/2016	used tire \$40.00				lowa tire

9/23/2016	install spare tire right steer	217130		jerry	
9/26/2016	two new steer tires #315 80 22.5 \$510.43 each	21735			lowa tire
9/27/2016	weld tabs on tailgate pins, new bolts on drivers step	217138		jerry	
10/5/2016	used tire \$150.00			jerry	lowa tire
11/3/2016	rear drive tires OK				
11/11/2016	bought new recap tire to match 3 other recap tires #11R-22.5 \$200.00				lowa tire
1/1/2017	checked miles,	219000	5064		total
1/31/2017	resealed and rebushing walking beams, new rear springs, welded sides on, raised tailgate hinges, relocated chain locks			jerry/ tristen	truck repair
2/2/2017	new bolts for suspension			jerry	sinclair
2/9/2017	new cotter pins			jerry	orchelen's
2/13/2017	new lights			jerry	NAPA
2/14/2017	2 new rear strobe lights #PMM 420SA-1 \$93.99 each			tristen	arnolds
2/17/2017	checked all oil's the engine needed 3 qts of 5-40 gold, the rest was Ok , added 1/2 gal of anti-freeze, did annual inspection greased drive line and front end	219252		jerry/tristen	
3/10/2017	new intake heater button #5512Pt \$6.29, ground down tail gate latch to lock	219274		tristen	arnolds
3/30/2017	new starter # SE 10479036 \$588.65	219280		jerry	Sadler's
6/28/2017	ck. Miles	223480			
8/1/2017	2 - used tires \$150.00 each, disposal fee \$12.50 eachd			dave	lowa tire
8/3/2017	changed tires on right rear driver with used tires, replaced crossfire hose on right rear inside, removed plow lights	23605		jerry / jerrett	lowa tire
8/15/2017	new clearance light				arnolds
8/22/2017	2 new stop/turn lights				arnolds
8/29/2017	new radiator hose and anti-freeze			Ron	arnolds
9/22/2017	new heater control unit # 103F/A22-57400-004 \$264.40			jerry / jerrett	truck country
10/2/2017	replaced viberator solinoid, wiring, and charged A.C.	227021		jerry	
10/3/2017	new brake shoe linings #103F/TDA XK2124707QP \$43.99 each				truck country
10/18/2017	new head light, relay #RY612 \$8.35			travis	arnolds
1/1/2018	checked miles,	227866	8866		total
1/25/2018	new Henderson Box : 14' Mark E TI-Dump body, powdercoated Terra Brown code Ral 8024 \$17901.00 S/N MKE-713047				Henderson Products Inc
2/5/2018	2 - new rear end stablizer bars # 103F/HDR 62001 520 \$77.89, # 103F/HDR 62001 665 \$ 80.02, 3/4" mini clr lights \$3.79 (4)			jerry	truck country
2/19/2018	new air line brass fittings \$132.08 for new bed, new lights, viberator, mud flaps, cylinder bushings, new lift cylinder hose				Henderson Products Inc
					winn's

2/22/2018	new air line tee \$22.90, new bed liner plastic			rick	Napa/ truck country
	changed engine oil and filter 5-40 gold, cleaned air filters, new hyd. Filter, changed both diff. oil's 80-90				
	coolant tested -34, greased and inspected, new 3/8" tube \$5.50 per ft (3)	227866		rick	centre state international
	new rear tail lights # 103F/SIG 6050 \$15.45 each (2), rear axle wheel seal #103F/CHR 47697 \$29.95 (for stock)				truck country
	alternator plug \$6.49 each, tail light mounting brackets # PMM 421-09 \$7.06 each, grommet # PMM421-18 \$3.02 each, oil filter				arnolds
3/3/2018	new bed ground strap				arnolds
3/13/2018	new intake glow plug temperature sensor \$70.42, computer hookup \$75.00, labor \$487.50	227950			McDowell truck & repair inc
5/31/2018	tire repair and tire change				lowa tire
6/11/2018	new hub cap on right front steer axle #343-4046 \$48.67, replaced A.C. condenser and charged system 3lbs, repaired power wire to gauges,horn, A/C, new recap tires on rear drivers, adjusted tailgate latch, new ground wire from frame to box, added 5 gal uni-fluid and 1 gal washer fluid	228419		jerry	arnolds
6/11/2018	3 new recap tires \$250.00 each				lowa tire
	new A.C. condenser #103F/VAL 1210364 \$319.96, rubber flap #103x/ROC-R24x30 \$6.65, flex tube \$22.95, clamp \$7.93, rubber flaps \$7.93 (2), resister - blower motor A.C. \$21.92, TX valve switch \$11.65	228537		jerry	truck country
6/20/2018	replaced condensor, new condensor rubbed a hole in it, charged A.C.	228770		jerry	Oreilly
6/28/2018	new mirror #PMM 617X \$33.32				arnolds
7/5/2018	ck. miles	228773		jerry	
7/20/2018	new brake shoe linings #103F/TDA XK2124707QP \$43.99 each on all drivers, greased truck, replaced 2 mudd flaps	229153		jerry	truck country
	new park brake assy #103F/BW 800620 \$128.03				truck country
8/28/2018	new turbo flange and clamp	229163		jerry	truck repair
8/29/2018	welded flange on exhaust pipe \$20.00, new exhaust clamp #3905216 \$44.38 each				palmer muffler/ truck repair
8/30/2018	new exhaust gasket # 103C/3870865 \$ 31.16				truck country
9/12/2018	ordered new exhaust pipe off turbo # 103F/A04-19836.000 \$340.45			jerry	truck country
10/4/2018	new fuses			rick	swailes
11/5/2018	2- new battery's # 24 stud 31MHD 950 CC			jerrett	interstate
11/7/2018	miles	230853			
11/27/2018	new fuel filter # BF1272SP \$ 20.11, new fuel pump # 4076442RX \$ 4468.38, new front tire # 315/22.5 \$ 525.00, tow from Mt. P.	230983			Bill& ray's
	to osky. \$ 285.00, new surge suppressor \$ 113.55, labor for testing \$ 2280.00				
12/19/2018	replaced 2 new front headlights # PHLH6024CI \$ 8.88 each			jerry	arnolds

1/1/2019	checked miles,	231427	3561	total
1/22/2019	inspected truck , fix head lights, replaced right rear tail light, cleaned cab straightened out front box step, fixed front headlight wiring, cleaned cab and engine air filters	231697		Tyler/rick
1/26/2019		231697		rick
2/6/2019	new Drish stickers, new radio \$ 41.56			travis
2/8/2019	new air tank bracket # 103F/RAY 002454 180 \$ 9.41			walmart
3/1/2019	new antenna # NM0150C \$ 32.00			truck country
6/25/2019	supply's to fix hood \$ 105.59, \$ 200.48			jerry
6/26/2019	new headlight # MTM 42187 \$ 12.69, repaired cracked hood, added 1/2 gal. anti- freeze, 1 gal. 5-30 gold, 1 gal. washer fluid	232417		Arcadian Inc
7/22/2019	new mirror # 610278 \$ 9.45, added Freon 5 oz, blew out evaperator, brace dash, replaced air filter	232781		Arnolds
7/31/2019	repaired front left turn light			jerry/Dylan
8/15/2019	tire repair \$ 44.00			jerry
9/11/2019	replaced tire with used tire \$ 175.00, mount tire \$ 45.00, disposal \$ 11.00, shop supply \$ 10.00			jerry
9/12/2019	tire repair \$ 17.50			gatr
9/24/2019	air hose and gauges			jerry
12/9/2019	new reacap tire 11R-22.5 \$ 250.00			Blacks tire
1/3/2020	ck miles	235580	4153	jerry
1/10/2020	ck miles, straightened right rear door latch ron bent buy pushing with dozer, shop supplies \$ 29.50, replaced heater door accuator # 604-225 \$ 52.99	235664		CFI
1/22/2020	repair windsheild crack \$ 35.00, new brkt - sensor bolt \$ 9.06, new leftside door handle on outside # 103F/A18-51913-008 \$ 73.68, new right rear wheel sensor # 103F/TDA R955342 \$ 45.52, new wheel seal, new ABS sensor housing, new right rear tire	235664		Black's tire
1/24/2020	new park brake valve # 065303 \$ 101.55, 2 fittings \$.86 each (oil has 7730 miles.)	235671		Phil
4/15/2020	bought used rim 22.5x9" \$ 50.00			TSC
6/30/2020	took to Bill&Ray's	235781		iowa tire
7/13/2020	replaced surge suppressor # 3944110 \$ 121.69, new belts # 4080725 \$ 62.75, # 17461 \$ 18.77, AC compressor # 5771 \$ 379.80, Freon \$ 25.13, ignition switch # D8TZ11572A \$ 94.12, labor \$ 851.75	237396		jerry
9/25/2020	new front left rim # 103F/ACC 29039PKGGRY21 \$ 187.60			jarrett
9/28/2020	replaced air supply junction block # 103F/A12-17564-001 \$ 54.78			jarrett
9/30/2020	welded crack in fuel tank, painted tank with bed liner spry, new left steer tire and rim, replaced backup alarm, replaced air manifold in dash, checked engine oil OK	238835		Jarrett
10/5/2020	tire changed \$ 37.45, tire repair \$ 42.80, new backup alarm # 16M530 \$ 39.99			jerry

11/2/2020	replaced dash instrument panel # 103F/A22-53572-101 4 239.46, center air brake panel # 103F/A22-65848-000 \$ 101.08			jerry	truck country
11/5/2020	washed, replaced dash support and dash cover, replaced washer fluid hose, added 2 qt engine oil,	239900		Jarrett/jerry	
11/9/2020	replaced windshield washer surge tank # 103FA05-23573-000 \$ 138.96			jerry	truck country
12/22/2020	8 new rear tires still in shed \$ 235.00 each				iowa tire
1/1/2021	checked miles,	240478	4898		
2/10/2021	service; changed engine oil and filter 5-30 gold, replaced flex tube on exhaust \$ 25.50, 2 exhaust bands 4" \$ 10.82 each, new power steering reservoir filter # T1808G \$ 10.43, new reman steering box \$, new reman brake air dryer \$ 98.29 sample iron high, cleaned air filter, cab filter, welded safety chain on vibrator, added 2 gal coolant, checked both diff. oil OK, replaced passenger side windshield wiper, greased, checked hub oil, new engine oil filter # wix51748 \$ 39.74, 2 exhaust clamps \$ 13.78 each	240771		scott	truck country/Arnolds/amazon
3/4/2021	replaced radiator with new # 238669 \$ 692.12, new power steering fluid \$ 19.16, new overflow hose \$ 4.16	240975		Jarrett	advanced radiator/Arnolds
3/10/2021	bought new replacement seal for front axle # 103F/CHR 43761 \$ 34.84, and belt # 103F/GT 4080730DF \$ 31.25				truck country
4/8/2021	replaced ignition lock cylinder # LC14020 \$ 10.99 901 on oil	241379		jerry	Oreilly's
6/3/2021	removed ignition switch tightened crimp on wires switch# D8TZ11572A tumbler set SMP-US23L summit racing	243178		jerry/Jarrett	
6/7/2021	replaced both batteries # 31- MHD stud \$ 120.95	243287		Jarrett	interstate
6/14/2021	did testing on dash \$ 150.00				iowa repair
6/28/2021	replaced controller for heater/ air- conditioner # 101F/A22-57400-004 \$ 313.55, added dye to A.C,	243487		jerry	truck country
7/5/2021	replaced front left inside tire with used tire			jerry	
7/6/2021	replaced blower motor # 103F/GNR 700087DL \$ 69.51, resistor # 103F/4C4H 19A706AA \$ 25.48			jerry	truck country
7/8/2021	replaced alternator # 860-0310 \$ 250.00			jerry	southern Diesel
7/9/2021	bought new ignition lock cylinder # STIUS-23L \$ 18.11, ignition starter switch # STIUS-115 \$ 28.66			jerry	Arnolds
7/12/2021	replaced 2 LED lights # G6002 \$ 37.04 each			jerry	Napa
7/15/2021	tire repair \$ 40.13, lamp kit # 53122 \$ 58.29 each			rick/ jerry	Lappin tire/ Napa
7/28/2021	tire repair \$ 40.00, replaced rear tire with used tire \$ 170.00, Tyler hit rerod by concrete to blow it			tyler	Lappin tire
8/26/2021	replaced ignition switch and tumbler			jerry	
9/7/2021	replaced 8 1/2" mirror \$ 10.17			phil	truck country
1/1/2022	checked miles				

1/6/2022	bought 5 recaps \$ 300.00 each, desposal 12 x 12.50 each			jerry	lowa tire
1/25/2022	replaced front right leaf spring # 43-686 \$ 537.79, new u-bolts # 7828 \$ 23.79 each, spring pin # B1498-43 \$ 19.14 each (3), new spring hanger # E858-43 \$ 77.08, replaced right shackle # E827-43 \$ 55.48, and 7 wheel studs \$ 6.50 each			jerry	sadler's
1/31/2021	tire repair \$ 40.00			jerry	lowa tire
2/3/2022	bought 2 muffler brackets # 103F/A04-17379-000 \$ 83.26 ea., replaced front diff. input seal # 103F/TDAA1 1205x2728 \$ 58.17, replaced front diff. input shaft u-joint # 103F/SP 5 280x \$ 39.99			jerry	truck country
2/3/2022	bought 2 new oil filters # 21075041 \$ 29.97 each, new dip stick # 25101289 \$ 116.33, replaced air filter cover # 2191-P600116 \$ 17.96			jerry	H&L
2/4/2022	SERVICE: changed engine oil and filter 5-30 gold , greased, checked gear boxes, replaced left steering shackel, and pins , replaced muffler brackets, removed shim from power divider input bearing, replaced power divider seal and u-joint, replaced drivers wiper, filters \$ 69.03			jerry	Arnolds
2/10/2022	inspected truck, cleaned , exhaust parts \$ 55.30			kevin	Arnolds
2/11/2022	replaced engine oil filler cap # 103F/6HZ 6766 AA \$ 37.52			jerry	truck country
2/17/2022	replaced 2 mud flaps \$ 15.50 each				truck country
2/24/2022	replaced blower motor # TCY-GNR-7000 87 DL, resistor # RD-5 10191-OM, replaced 40 amp fuse # nap- 782-2102, \$ 2.99 eachput 2 used tires on right side, put on 1 crossfire			kevin	Napa

