

RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch

HAZEN, ND

\*REPRINT\*

Date

01/19/22

Time 21:16:00 (B) Page

Account No. 6300068

Phone No. 7017486300 Invoice No. W1676959

Ship Via

**Purchase Order** 

**Tax Exemption Number** 

Federal ID Number

Salesperson CF4

# SERVICE INVOICE

STK#/FLEET#

Invoice to:

X746012

COMBINES

WAYNE CLARK

1270 50TH AVE SW

HAZEN ND 58545-9697

9770 STS

HRS PIN/EIN

1H09770SLB0741978 2481 RG6090L101593

06/01/12

WARRANTY DATE

HRS

07/18/15 1531 P

\* We're offering parts, services & sales during restrictions. Learn more at RDOequipment.com/COVID-19

\*\* Buy parts online and view your invoices at RDOequipment.com/account Create your FREE RDO Account today!

3435

SEGMENT# 1 C DGE01 STT-15

12/10/21 12/15/21

TRAVEL, ROUND TRIP

CONDITION:

-drive to Wayne's to do a inspection on his combine.

CAUSE:

-That's where Wayne wants the inspection done.

CORRECTION:

10404099

-Drove to and from Wayne's farm.

LABOR

SEGMENT TOTAL ==>

117.25 117.25

SEGMENT# 2 C DGE01 RDO-900-173 12/10/21 12/15/21

STS COMBINE INSPECTION

CONDITION:

-Combine inspection.

-Inspected combine to look for problems that may occur during harvest.

CORRECTION:

-Inspected combine.

-Made up a estimate.

-Went over estimate with Wayne.

PROMOAG

labor discount

541.00

541.00-

CONTINUED ON PAGE 02



RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch

HAZEN, ND

Date 01/19/22 Time 21:16:00 (B)

Page 02

Account No. 6300068

Phone No. 7017486300

Invoice No. W1676959

Ship Via

**Purchase Order** 

**Tax Exemption Number** 

Federal ID Number

Salesperson CF4

## SERVICE INVOICE

STK#/FLEET#

10404099

Invoice to:

X746012

9770 STS

WAYNE CLARK

1270 50TH AVE SW

HAZEN ND 58545-9697

COMBINES

HRS PIN/EIN 3435

1H09770SLB0741978

2481 RG6090L101593

WARRANTY DATE 06/01/12

07/18/15

HRS 1531 P

PARTS LABOR

541.00-1240.00

SEGMENT TOTAL ==>

699.00

SEGMENT# 3 C DGE01 RDO-001-032 12/10/21 01/06/22

OIL SAMPLE, EACH WHEN MACHINE IS WARM

CONDITION:

-Fluid sampling.

CORRECTION:

-Took samples.

-Filled out paperwork.

TY26859

10404099

SCAN TEST KIT

1

Internal Internal

> PARTS Internal

LABOR

Internal

SEGMENT TOTAL==>

Internal

SEGMENT# 4 C DGE01 RDO-171-141 12/29/21 12/29/21 12/31/21

FEEDERHOUSE FRONT FLOOR, REPLACE

CONDITION:

-Front feederhouse floors are getting thin.

740T1D59

CAUSE:

-Natural wear.

CORRECTION:

-Removed front shields.

-Removed feeder house front tilt I beam.

-Removed floors.

-Installed new floors.

-Installed I beam.

-Installed shield.

ADDITIONAL DESCRIPTION:



1270 50TH AVE SW

HAZEN ND 58545-9697

N/A Ship to:

Invoice to:

RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch

HAZEN, ND

Date 01/19/22 Time 21:16:00 (B) Page 03

Account No. 6300068

Phone No. 7017486300 Invoice No. W1676959

Ship Via

**Purchase Order** 

**Tax Exemption Number** 

**Federal ID Number** 

Salesperson CF4

# SERVICE INVOICE

	HRS	RANTY DATE	WARR	PIN/EIN	HRS	#	STK#/FLEET
		06/01/12	0741978	1H09770SLB0	3435	COMBINES	X746012
	1531 P	07/18/15	593	RG6090L1015	2481	9770 STS	
						GE01 120 minutes	+Assist:D
121.63		121.63	1 M		PLATE		H219091
246.40		246.40	1 M		PLATE		H219180
10.14		1.69	6	NUT	FLANGE		14M7296
378.17		PARTS					
837.00		LABOR					
1215.17		Γ TOTAL==>	SEGMENT				10404099
			12/31/21	1 12/29/21 1	12/29/2	C DGE01 MISC	SEGMENT# 5
				1 12/29/21 1	12/29/2	C DGE01 MISC	

Feeder house main floor.

CONDITION:

-Feeder house floor has holes in it.

CAUSE:

-Natural wear.

CORRECTION:

-Removed main floor.

-Installed a new floor.

AXE24554	Floor	1	1301
H173904	SEAL	1	71
H174755	BOLT	4	2
			PA
			т 70

1	1301.64
1	71.24
4	2.31

SEGMENT TOTAL ==>

9.24 PARTS 1382.12 LABOR 375.10

1301.64 71.24

1757.22

12/29/21 12/29/21 12/31/21

Feeder house drive idler. Replace.

SEGMENT# 6 C DGE01 MISC

CONDITION:

10404099

-Drive idler is rough when spun.

CAUSE:

-Bearing is failing.



**RDO Equipment Co.** PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch

HAZEN, ND

Date 01/19/22 Time 21:16:00 (B)

Page 04

Account No. 6300068

Phone No.

7017486300

Invoice No. W1676959

Ship Via

**Purchase Order** 

Tax Exemption Number

**Federal ID Number** 

Salesperson CF4

# SERVICE INVOICE

STK#/FLEET#

Invoice to:

X746012

COMBINES

WAYNE CLARK

1270 50TH AVE SW

HAZEN ND 58545-9697

9770 STS

HRS PIN/EIN 3435

1H09770SLB0741978 2481 RG6090L101593

06/01/12 07/18/15

WARRANTY DATE

HRS

1531 P

CORRECTION:

-Replaced idler.

ADDITIONAL DESCRIPTION:

-Feeder house drive idler. Replace.

AH204389

10404099

IDLER

80.78 PARTS

80.78 3.10

LABOR

SEGMENT TOTAL ==>

83.88

80.78

SEGMENT# 7 C DGE01 10-171-070 12/29/21 12/29/21 12/31/21

CONVEYOR SHAFT SPROCKETS, REAR, REPLACE

CONDITION:

-Upper feeder house shaft sprockets are cupped.

CAUSE:

-Natural wear.

CORRECTION:

- -Removed feeder house.
- -Removed shaft from feeder house.
- -Removed sprockets and sprockets from shaft.
- -Installed new sprockets.
- -Installed new shaft bearings in pillow blocks.
- -Installed shaft back on feeder house.
- -Removed wear strips and installed new wear strips.

-Installed feeder house back on combine.

AH206701 HXE123463 H171960 H201727 JD10020 JD9373

LINK CHAIN Chain Sprocket STRIP RETAINER BALL BEARI BALL BEARI

1 165.27 3 109.78 3 18.70 2 60.34 1 36.57 1 38.27

165.27 329.34 56.10 120.68 36.57

38.27



1270 50TH AVE SW

HAZEN ND 58545-9697

N/A Ship to:

Invoice to:

RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch

Date

HAZEN, ND

01/19/22

Time 21:16:00 (B) Page

Account No. 6300068

Phone No. 7017486300 Invoice No. W1676959

Ship Via

**Purchase Order** 

**Tax Exemption Number** 

Federal ID Number

Salesperson CF4

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN WARR	ANTY DATE	HRS	
X746012	COMBINES	3435	1H09770SLB0741978	06/01/12		
	9770 STS	2481	RG6090L101593	07/18/15	1531 P	
PM37421		SEALANT	1	8.17		8.17
R38371		WASHER	1 N	4.67		4.67
21M7584		SCREW	1 M	2.89		2.89
				PARTS		761.96
				LABOR		1302.00
10404099			SEGMENT	TOTAL==>		2063.96

SEGMENT# 8 C DGE01 RDO-080-001 12/29/21 12/29/21 12/31/21

TAILINGS DRIVE CHAIN REPLACE

# CONDITION:

-Tailings drive chain is wore out.

# CAUSE:

-Natural wear.

### CORRECTION:

- -Removed drive belt.
- -Removed drive chain.
- -Installed a new drive chain.
- -Adjusted chain tension.
- -Installed drive belt.

SEGMENT# 9 C DGE01 MISC

AE23539

10404099

#50 CHAIN

1 39.36

SEGMENT TOTAL ==>

39.36 39.36

PARTS LABOR

77.50 116.86

12/29/21 01/06/22 12/31/21

Pivot pin for she drive belt is stiff.

-Pivot pin is froze in shoe belt adjusting arm.

#### CAUSE:

-Moisture got into pin a nd arm.

CONTINUED ON PAGE 06



RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch

HAZEN, ND

Date 01/19/22 Time 21:16:00 (B) Page 06

Account No.

Phone No.

Invoice No.

6300068

7017486300

W1676959

Ship Via

**Purchase Order** 

**Tax Exemption Number** 

Federal ID Number

Salesperson CF4

# SERVICE INVOICE

STK#/FLEET#

Invoice to:

X746012

COMBINES

WAYNE CLARK

1270 50TH AVE SW

HAZEN ND 58545-9697

9770 STS

HRS PIN/EIN

3435 1H09770SLB0741978 2481 RG6090L101593

WARRANTY DATE 06/01/12

HRS

07/18/15 1531 P

-Rusted pin in pivot arm.

## CORRECTION:

- -Removed pulley from arm.
- -Removed pivot pin and arm assembly from combine.
- -Pressed pin out of arm.
- -Cleaned rust from pin and arm.
- -Assembled arm and pin.
- -Installed arm and pin back on combine.
- -Installed belt and pulley.
- -Installed belt and adjusted belt tension.

ADDITIONAL DESCRIPTION:

Pivot pin for she drive belt is stiff.

LABOR

217.00

SEGMENT TOTAL ==>

217.00

SEGMENT#10 C DGE01 MISC

12/29/21 12/29/21 12/31/21

LOADING AUGER TUBE, AUGER, END BEARING, REMOVE AND REPLACE CONDITION:

10404099

-Loading auger tube is thin.

#### CAUSE:

-Natural wear.

### CORRECTION:

- -Removed clean grain loading auger from tube.
- -Removed tube from transition housing.
- -Removed hard ware from old tube and installed it on the new tube.
- -Installed tube on transition housing.
- -Installed loading auger in tube.

ADDITIONAL DESCRIPTION:

LOADING AUGER TUBE, AUGER, END BEARING, REMOVE AND REPLACE

CONTINUED ON PAGE 07



1270 50TH AVE SW

HAZEN ND 58545-9697

Ship to: N/A

Invoice to:

RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718 For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch

HAZEN, ND

**Date** 01/19/22

Time 21:16:00 (B)

Page 07

**Account No.** 630068

Phone No. 7017486300

Invoice No. W1676959

Ship Via

**Purchase Order** 

**Tax Exemption Number** 

**Federal ID Number** 

Salesperson CF4

## SERVICE INVOICE

STK#/FLEET# X746012	COMBINES	HRS 3435	PIN/EIN 1H09770SLB074		ANTY DATE 06/01/12	HRS	
	9770 STS	2481	RG6090L101593	3	07/18/15	1531 P	
AMAH217983		AH21798	3	1 N	699.00		699.00
FRT		SHIP/HA	NDLING	1	79.53		79.53
03M7194		BOLT		3	1.86		5.58
14M7296		FLANGE	NUT	3	1.69		5.07
					PARTS		789.18
					LABOR		344.10
10404099				SEGMENT	TOTAL==>		1133.28

SEGMENT#11 C DGE01 RDO-171-011 12/29/21 12/29/21 12/31/21

FEED ACCELERATOR WEAR STRIPS, REPLACE

# CONDITION:

-Feeder house wear strips are wore out.

### CAUSE:

-Natural wear.

## CORRECTION:

-Removed wear strips from feed accelerator.

-Installed new wear strips.

H165407

PLATE

30 O 18.19 PARTS

545.70 545.70

LABOR

558.00 1103.70

10404099

SEGMENT TOTAL==>

SEGMENT#12 C DGE01 RDO-001-040 12/29/21 12/29/21 12/31/21

RDO COMBINE MAINTENANCE PACKAGE, GOLD

## CONDITION:

-Maintenance package.

#### CAUSE

-Customer wants one performed.

## CORRECTION:

-Performed a maintenance package.



1270 50TH AVE SW

HAZEN ND 58545-9697

Ship to: N/A

Invoice to:

RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718 For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch HAZEN, ND

**Date** 01/19/22

Time 21:16:00 (B) Page 08

Account No. 6300068

Phone No. 7017486300

Invoice No. W1676959

Ship Via

**Purchase Order** 

Tax Exemption Number

Federal ID Number

Salesperson CF4

# SERVICE INVOICE

STK#/FLEET	#	HRS	PIN/EIN	WAR	RANTY DATE	HRS	
X746012	COMBINES	3435	1H09770SLB	0741978	06/01/12		
	9770 STS	2481	RG6090L101	593	07/18/15	1531 P	
AH128449		HYDRAUI	LIC	3	58.85		176.55
	Hydraulic Fil	ter					
AH168783		AIR FII	LTER	1	64.19		64.19
AH212295		FILTER	ELEMENT	1	100.99		100.99
AH222225		FILTER	ELEMENT	1	140.41		140.41
H135891		LOCK NU	JT	6	1.82		10.92
H220870		AIR FII	TER	1	43.71		43.71
RE509672		FILTER	ELE	1	21.39		21.39
RE525523		FILTER	ELEMENT	1	88.68		88.68
TY26101		BRAK&PA	ARTS	1	6.56		6.56
	Cleaning Solv	ent					
TY26408		HD460 Q	ΤQ	5	39.07		195.35
19M7786		SCREW		3	1.79		5.37
					PARTS		854.12
					LABOR		775.00
10404099				SEGMEN'	TOTAL==>		1629.12

SEGMENT#13 C DGE01 MISC

12/29/21 12/29/21 12/31/21

discharge beater idler pulley.

# CONDITION:

-Discharge beater idler bearing is rough.

#### CAUSE:

-Dirt and moisture got into bearing.

#### CORRECTION:

- -Loosened belt.
- -Removed belt and idler.
- -Installed a new idler pulley.
- -Installed belt.

AH97031 14M7275

IDLER NUT 1 40.35 1 1.58 40.35



**RDO Equipment Co.** PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch

HAZEN, ND

Date 01/19/22 Time 21:16:00 (B)

Page 09

Account No. 6300068

Phone No. 7017486300 Invoice No. W1676959

Ship Via

**Purchase Order** 

**Tax Exemption Number** 

Federal ID Number

Salesperson CF4

# SERVICE INVOICE

STK#/FLEET#

Invoice to:

X746012

COMBINES

WAYNE CLARK

1270 50TH AVE SW

HAZEN ND 58545-9697

9770 STS

HRS 3435

PIN/EIN

12/29/21 12/29/21 12/31/21

1H09770SLB0741978 2481 RG6090L101593

06/01/12

WARRANTY DATE

HRS

07/18/15 1531 P PARTS

LABOR

41.93 65.10

SEGMENT TOTAL ==>

107.03

SEGMENT#14 C DGE01 10-171-130

FEEDER HOUSE CONVEYOR CHAIN, R&R

CONDITION:

10404099

-Feeder house conveyor chain is wore out.

CAUSE:

-Natural wear.

CORRECTION:

-Removed conveyor chain from feeder house.

-Installed a new chain .

AH220541

AXE24307

10404099

CHAIN LINK

FDR CHN S670-90

10.60 1 1688.99

PARTS

1720.79 372.00

LABOR

SEGMENT TOTAL ==>

2092.79

31.80

1688.99

SEGMENT#15 C DGE01 MISC ALTERNATOR, REPLACE

12/29/21 12/29/21 12/31/21

CONDITION:

-Alternator is not working.

CAUSE:

-Broken exciter wire.

CORRECTION:

- -Started removing alternator.
- -Found exciter wire was broke.
- -Removed exciter wire.
- -Installed a new wire.

CONTINUED ON PAGE 10



RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch

HAZEN, ND

Date

01/19/22

Time 21:16:00 (B)

Page 10

Account No. 6300068

Phone No. 7017486300

HRS

1531 P

Invoice No. W1676959

Ship Via

**Purchase Order** 

**Tax Exemption Number** 

WARRANTY DATE

06/01/12

07/18/15

Federal ID Number

Salesperson CF4

# SERVICE INVOICE

1H09770SLB0741978

STK#/FLEET#

Invoice to:

X746012

COMBINES

WAYNE CLARK

1270 50TH AVE SW

HAZEN ND 58545-9697

9770 STS

-Bolted alternator back on.

-Installed belt.

-Put shields back on AXE17012

10404099

WIRING HARNESS

HRS

3435

1 N

53.00

53.00 53.00

PARTS LABOR

SEGMENT TOTAL ==>

269.70 322.70

SEGMENT#16 C DGE01 MISC

12/29/21 12/29/21 12/31/21

PIN/EIN

2481 RG6090L101593

Cleaning system relief valve.

CONDITION:

-Pressure relief valve or union boss is leaking.

CAUSE:

-Cracked union block.

CORRECTION:

Replaced union block and pressure relief valve assembly.

OUTPT

DSH Engineering

157.14 PARTS 157.14 157.14

LABOR

210.80

10404099

SEGMENT TOTAL ==>

367.94

SEGMENT#17 C DGE01 MISC

12/29/21 12/29/21 12/31/21

Tailings elevator replace.

CONDITION:

-Tailings elevator is wore thin.

CAUSE:

-Conveyor chain was loose and rubbing on housing.

-Also some natural wear.

CORRECTION:

-Removed housing.



Invoice to:

**RDO Equipment Co.** PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch HAZEN, ND

Date 01/19/22 Time 21:16:00 (B) Page 11

Account No. 6300068

Phone No. 7017486300 Invoice No. W1676959

Ship Via

Purchase Order

**Tax Exemption Number** 

**Federal ID Number** 

Salesperson CF4

WAYNE CLARK 1270 50TH AVE SW HAZEN ND 58545-9697

# SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS X746012 COMBINES 3435 1H09770SLB0741978 06/01/12 9770 STS 2481 RG6090L101593 07/18/15 1531 P -Removed chain from housing. -Removed upper shaft from housing. -Installed a new tailings housing. -Installed upper shaft assembly and conveyor chain. -Installed belt tightener assembly. Installed drive chain and drive belt. -Tightened belt and chain to specifications. A-H133143 Chain Sprocket 1 M 36.09 36.09 AMAXE14891 AXE14891 1 N 1311.25 1311.25 FRT SHIP/HANDLING 1 265.81 265.81 H177988 SPROCKET S 1 52.06 52.06 Sprocket Segments H206587 JD9002LABEL 1 N 16.78 16.78 JD10384 BEARING 1 43.46 43.46 19M8241 CAP SCREW 1 3.84 3.84 49M4111 SHAFT KEY 1 4.79 4.79 49M6480 SHAFT KEY 7 3.14 3.14

> \*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\* INTERNAL CUSTOMER PARTS Internal 8000.47 LABOR Internal 8611.25 SUB TOTAL ==> Internal 16611.72 10.50

ND STATE TAX INTERNAL TOTAL

SEGMENT TOTAL ==>

TOTAL MULTI-USE CHG

Internal

16622.22

1737.22

1847.60

3584.82

921254

10404099

1240538142

This purchase(s) is subject to the terms of the Multi-Use Account, a CONTINUED ON PAGE 12

PARTS

LABOR



RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch

HAZEN, ND

Date 01/19/22 Time 21:16:00 (B) Page

Account No.

Phone No.

Invoice No.

6300068

7017486300

W1676959

Ship Via

**Purchase Order** 

**Tax Exemption Number** 

Federal ID Number

Salesperson CF4

## SERVICE INVOICE

STK#/FLEET#

Invoice to:

COMBINES

WAYNE CLARK

1270 50TH AVE SW

HAZEN ND 58545-9697

HRS PIN/EIN

WARRANTY DATE

HRS

X746012

9770 STS

3435 1H09770SLB0741978 2481 RG6090L101593

06/01/12 07/18/15

1531 P

service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

PLEASE REMIT TO: JOHN DEERE FINANCIAL

P.O. BOX 4450

CAROL STREAM, IL 60197-4450