



Estimate Expires 22-Dec-2022

Service Estimate

Customer Roger Custer 1115 Mcduffie Dr Jefferson, IA 50129 PHONE: (515)386-8494 EMAIL: custer@netins.net

Est Labor \$93.80

Equipment John Deere 9570S Serial# H09570S730721 Estimate Details
Estimate# 65931
Created Date: 22-Nov-2022
Created By: Keith Bohan

Cab Fı	resh Air Filte	er, Standard, Remov	e and Replace		Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	AH115833	Air Filter		1.00 EACH	
	Е	Est Labor \$35.00	Parts \$79.47	Recommended \$114.47	
Cab R	ecirculation	Air Filter, Later Vers	sion, Remove and Re	place	Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	H220870	Air Filter		1.00 EACH	
	Е	Est Labor \$35.00	Parts \$49.56	Recommended \$84.56	
Winds	hield (Wash	er) Wiper Fluid, Fill o	or Top Off		Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	WF	Washer Fluid		1.00 GAL	
	Е	Est Labor \$35.00	Parts \$4.09	Recommended \$39.09	
Contro	oller Softwar	e, Update			Customer Response : Declined
	Е	Est Labor \$35.00	Parts \$0.00	Recommended \$35.00	
Eacds	rhouge Drive	Chain 102 Links C	NH High Canadity D	omeye and	
reede Replac		; Chain, 192 Links bi	0H, High Capacity, Re	anove and	Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	

Parts \$161.65

Recommended \$255.45





Estimate Expires 22-Dec-2022

Service Estimate

Customer Response: Declined

Customer Response: Declined

Customer Response: Declined

Customer Response: Declined

Customer **Roger Custer** 1115 Mcduffie Dr Jefferson, IA 50129 PHONE: (515)386-8494 EMAIL: custer@netins.net

Equipment John Deere 9570S Serial# H09570S730721

Estimate Details Estimate# 65931 Created Date: 22-Nov-2022 Created By: Keith Bohan

Feederhouse Conveyor Chain, Remove and Replace

Parts Part # **Part Name**

> AH231006 Roller Chain AH220541

> > Est Labor \$280.00

Chain Link

Parts \$1,262.97

Recommended \$1,542.97

Quantity Units

1.00 EACH

3.00 EACH

Feederhouse Frame Floor Plate, Remove and Replace

Parts Part #

Part Name

H219745 Plate

Est Labor \$700.00

Parts \$325.87

Recommended \$1,025.87

Quantity Units

1.00 EACH

Reverser Gearcase Oil, Change

Parts TY26408

Part #

Part Name

Est Labor \$140.00

Oil

Parts \$150.48

Recommended \$290.48

Quantity Units

4.00 EACH

Feed Accelerator, Standard Serrated (Notched) Wear Plate, Complete Set,

Remove and Replace

Parts Part # **Part Name**

> 14M7296 Flange Nut H165407 Plate 03M7375 Bolt

> > Est Labor \$420.00

Quantity Units

Parts \$666.75

50.00 EACH 25.00 EACH

50.00 EACH

Recommended \$1,086.75





Estimate Expires 22-Dec-2022

Service Estimate

Customer Response: Declined

Customer Roger Custer 1115 Mcduffie Dr Jefferson, IA 50129 PHONE: (515)386-8494 EMAIL: custer@netins.net Equipment
John Deere 9570S
Serial# H09570S730721

Estimate Details
Estimate# 65931
Created Date: 22-Nov-2022
Created By: Keith Bohan

Chaffer, Sieve, and Grain Pan, Swinger Arms, ALL, Remove and Replace	

Parts	Part #	Part Name		Quantity U	Jnits
	14M7299	Flange Nut		12.00 E	EACH
	14M7291	Flange Nut		6.00 E	EACH
	19M7829	Screw		2.00 E	EACH
	19M7830	Screw		2.00 E	EACH
	AH222366	Arm		2.00 E	EACH
	19M7820	Screw		6.00 E	EACH
	AH219844	Arm		1.00 E	EACH
	AH219846	Arm		1.00 E	EACH
	AH220398	Arm		6.00 E	EACH
	H227582	Bolt		2.00 E	EACH
	H154928	Bolt		8.00 E	EACH
	19M8486	Cap Screw		2.00 E	EACH
	H231095	Bolt		2.00 E	EACH
	ı	Est Labor \$2,280.00	Parts \$1,687.76	Recommended \$	3,967.76

Chaffer Frame Seals, Remove and Replace Customer Response : Declined

		Est Labor \$560.00	Parts \$65.74	Recommended \$625.74	
	H222901	Seal		1.00 EACH	
	M64720	Rivet		10.00 EACH	
Parts	Part #	Part Name		Quantity Units	





Estimate Expires 22-Dec-2022

Service Estimate

Customer
Roger Custer
1115 Mcduffie Dr
Jefferson, IA 50129
PHONE: (515)386-8494
EMAIL: custer@netins.net

Equipment John Deere 9570S Serial# H09570S730721 Estimate Details
Estimate# 65931
Created Date: 22-Nov-2022
Created By: Keith Bohan

Prima	Primary (Outer) Engine Air Filter, Remove and Replace				Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	AH222225	Filter Element		1.00 EACH	
	Е	Est Labor \$35.00	Parts \$161.80	Recommended \$196.80	
Secon	dary (Inner)	Engine Air Filter, Re	move and Replace		Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	AH212295	Filter Element		1.00 EACH	
	E	Est Labor \$35.00	Parts \$131.96	Recommended \$166.96	
Engine	e Oil and Filt	ter, Change			Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	RE504836	Oil Filter		1.00 EACH	
	R502513	Seal		1.00 EACH	
	TY26682B	Bulk- Plus-50 II		34.00 QUARTS	8
	E	Est Labor \$210.00	Parts \$256.71	Recommended \$466.71	
Prima	ry and Final	Fuel Filter, Change			Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	RE522878	Filter Element		1.00 EACH	
	RE541922	Filter Element		1.00 EACH	
	Е	Est Labor \$70.00	Parts \$71.97	Recommended \$141.97	





Estimate Expires 22-Dec-2022

Service Estimate

Customer Roger Custer 1115 Mcduffie Dr Jefferson, IA 50129 PHONE: (515)386-8494 EMAIL: custer@netins.net Equipment
John Deere 9570S
Serial# H09570S730721

Estimate Details
Estimate# 65931
Created Date: 22-Nov-2022
Created By: Keith Bohan

Discha	arge Beater	Customer Response : Declined			
Parts	Part #	Part Name		Quantity Units	
	H135891	Lock Nut		4.00 EACH	
	19M7804	Screw		4.00 EACH	
	H202562	Finger		1.00 EACH	
	Е	Est Labor \$420.00	Parts \$180.31	Recommended \$600.31	
Discha	arge Beater	Grate Frame, Remov	e and Replace		Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	14M7299	Flange Nut		4.00 EACH	
	H228984	Vane		2.00 EACH	
	H135891	Lock Nut		12.00 EACH	
	H162227	Strap		2.00 EACH	
	14M7296	Flange Nut		6.00 EACH	
	19M7789	Screw		4.00 EACH	
	19M7786	Screw		12.00 EACH	
	AH213595	Grate		1.00 EACH	
	03M7191	Bolt		6.00 EACH	
	E	Est Labor \$700.00	Parts \$896.84	Recommended \$1,596.84	
Beater	top sheet				Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	AH209003	Cover		1.00 EACH	
	E	Est Labor \$450.00	Parts \$510.06	Recommended \$960.06	





Estimate Expires 22-Dec-2022

Service Estimate

Customer Response: Declined

Customer Roger Custer 1115 Mcduffie Dr Jefferson, IA 50129 PHONE: (515)386-8494 EMAIL: custer@netins.net Equipment John Deere 9570S Serial# H09570S730721 Estimate Details
Estimate# 65931
Created Date: 22-Nov-2022
Created By: Keith Bohan

Upper Feederhouse (Poly) Wear Strips	(3).	Remove and	i Rebiace
--------------------------------------	------	------------	-----------

Parts Part # Part Name Quantity Units

H171960 Strip 3.00 EACH

Est Labor \$280.00 Parts \$64.26 Recommended \$344.26

Agreement:

I hereby authorize the repair work to be done as described above on the machine(s) named here on. All repair parts are to be billed at regular prices. I agree to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full, any such unpaid balance shall contribute a lien on this machinery. I further agree that you will not be responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Signed:	Date:	
•		

Price Type	Declined Total
Est Labor	\$6,813.80
Parts	\$6,728.25
Total	\$13 5 <i>42</i> 05

NOTE: ALL PRICES EXCLUDE SERVICE CHARGES AND SALES TAX





Estimate Expires 22-Dec-2022

Service Estimate

Customer
Roger Custer
1115 Mcduffie Dr
Jefferson, IA 50129
PHONE: (515)386-8494
EMAIL: custer@netins.net

Equipment John Deere 9570S Serial# H09570S730721 Estimate Details
Estimate# 65931
Created Date: 22-Nov-2022
Created By: Keith Bohan

Estimate Summary:

Price Type	Recommended	Accepted	Declined	Undecided
Est Labor	\$6,813.80	\$0.00	\$6,813.80	\$0.00
Parts	\$6,728.25	\$0.00	\$6,728.25	\$0.00
Total	\$13,542.05	\$0.00	\$13,542.05	\$0.00





Estimate Expires 22-Dec-2022

Service Estimate

Customer Roger Custer 1115 Mcduffie Dr Jefferson, IA 50129 PHONE: (515)386-8494 EMAIL: custer@netins.net

Equipment John Deere 9570S Serial# H09570S730721

Estimate Details
Estimate# 65931
Created Date: 22-Nov-2022
Created By: Keith Bohan

Appendix: