SERVICE ESTIMATE

Date

11/28/22

Technician

Keith Bohan

Customer

Make & Model

Contact Info

ROGER CUSTER

H09570S730721

Repair Order #

Due date

930877

Description

cab filters, feederhouse drive chain, fh conveyor chain, fh wear strips, fh pivoting floor, reverser oil, engine air filters, engine oil, fuel filters, beater grate, beater frame, beater top sheet,

chaffer frame curtian seal, seperator arms, feed accelerator wings, washer fluid top off, software update.

		Estimate
Inspection		\$0.00
Wash		\$0.00
Labor		\$6,814.00
Parts		\$6,750.00
Transportation		\$0.00
Freight		\$0.00
Outside Labor/Material		\$0.00
	misc	
	Subtotal	\$13,564.00
	Misc	\$354.33
	Tax	\$949.48
	Total Estimate	\$14,867.81





Estimate Expires 22-Dec-2022

Service Estimate

Customer Roger Custer 1115 Mcduffie Dr Jefferson, IA 50129 PHONE: (515)386-8494 EMAIL: custer@netins.net Equipment John Deere 9570S Serial# H09570S730721

Cab Fı	resh Air Filte	er, Standard, Remov	and Replace		Customer Response : Declined
Parts	Part#	Part Name		Quantity Units	
	AH115833	Air Filter		1.00 EACH	
ik u katalanga - v vika kesi kitak isak isi milik.	en processa de la composición de la co En processa de la composición del composición de la composición de la composición del composición del composición de la composición del composición del composición del composición del composición del composición del composici	Est Labor \$35.00	Parts \$79.47	Recommended \$114.47	
Cab R	ecirculation	Air Filter, Later Vers	ion, Remove and Rep	lace	Customer Response : Declined
Parts	Part#	Part Name		Quantity Units	
	H220870	Air Filter		1.00 EACH	
egend filozof selve dervikel so velegocik Transport	ert eiden herte deutsche zur dem zu zu einem der	Est Labor \$35.00	Parts \$49.56	Recommended \$84.56	
Winds	hield (Wash	er) Wiper Fluid, Fill o	or Top Off		Customer Response : Declined
Parts	Part#	Part Name		Quantity Units	
	WF	Washer Fluid		1.00 GAL	
ikadan (s. 1944) ikan kan kan Pinatan (s. 1944) ikan kan kan ban kan ban ban ban ban ban ban ban ban ban b	in die vorwegelein der ser sich der ser ser ser ser ser ser ser ser ser s	Est Labor \$35.00	Parts \$4.09	Recommended \$39.09	
	oller Softwa	re, Update			Customer Response : Declined
elgentere ditter spesje flesse gleise seisse in der spesje flesse steller spesje flesse steller steller stelle Steller steller stelle	के बहुत होता है . जो के पहल के किए कहा के किए के किए के किए के किए के किए	Est Labor \$35.00	Parts \$0.00	Recommended \$35.00	
Feede	rhouse Driv	e Chain, 192 Links 6	0H, High Capacity, Re	move and	
Repla	ce				Customer Response : Declined
Parts	Part#	Part Name		Quantity Units	
				4.00 =4.011	
	AH206701	Link Chain		1.00 EACH	





Estimate Expires 22-Dec-2022

Service Estimate

Customer Roger Custer 1115 Mcduffie Dr Jefferson, IA 50129 PHONE: (515)386-8494 EMAIL: custer@netins.net

Equipment John Deere 9570S Serial# H09570S730721 Estimate Details Estimate# 65931 Created Date: 22-Nov-2022 Created By: Keith Bohan

Feederhouse Conveyor Chain, Remove and Replace

Customer Response: Declined

Parts Part #

Part Name

Quantity Units

AH231006

Roller Chain

1.00 EACH

AH220541 Chain Link

3.00 EACH

Est Labor \$280.00

Parts \$1,262.97

Recommended \$1,542.97

Feederhouse Frame Floor Plate, Remove and Replace

Customer Response: Declined

Parts

Part#

Part Name

Quantity Units

H219745

Plate

1.00 EACH

Est Labor \$700.00

Parts \$325.87

Recommended \$1,025.87

Reverser Gearcase Oil, Change

Customer Response : Declined

Parts

Part #

Part Name

Quantity Units

TY26408

Oil

4.00 EACH

Est Labor \$140.00

Parts \$150.48

Recommended \$290.48

Feed Accelerator, Standard Serrated (Notched) Wear Plate, Complete Set, Remove and Replace

Customer Response: Declined

Parts

Part #

Part Name

Quantity Units

14M7296

Flange Nut

50.00 EACH

H165407 03M7375 Plate Bolt

25.00 EACH 50.00 EACH

Est Labor \$420.00

Parts \$666.75

Recommended \$1,086.75





Estimate Expires 22-Dec-2022

Service Estimate

Customer
Roger Custer
1115 Mcduffie Dr
Jefferson, IA 50129
PHONE: (515)386-8494
EMAIL: custer@netins.net

Equipment
John Deere 9570S
Serial# H09570S730721

Chaffe	er, Sieve, an	d Grain Pan, Swinger	Arms, ALL, Remove	and Replace	Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	14M7299	Flange Nut		12.00 EACH	
	14M7291	Flange Nut		6.00 EACH	
	19M7829	Screw		2.00 EACH	
	19M7830	Screw		2.00 EACH	
	AH222366	Arm		2.00 EACH	
	19M7820	Screw		6.00 EACH	
	AH219844	Arm		1.00 EACH	
	AH219846	Arm		1.00 EACH	
	AH220398	Arm		6.00 EACH	
	H227582	Bolt		2.00 EACH	
	H154928	Bolt		8.00 EACH	
	19M8486	Cap Screw		2.00 EACH	
	H231095	Bolt		2.00 EACH	
den de service es sergionogée service de ser	i anno considerati di materia di proteccio di materia di materia di materia di materia di materia di materia d	Est Labor \$2,280.00	Parts \$1,687.76	Recommended \$3,967.7	Control of the Contro
Chaffe	r Frame Sea	als, Remove and Repla	ace		Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	M64720	Rivet		10.00 EACH	
	H222901	Seal		1.00 EACH	
		Est Labor \$560.00	Parts \$65.74	Recommended \$625.74	managaman mana managanan nyaétatan'i 1960 ta 1966 ta 1968 ta 1968 ta 1988 ta 1988 ta 1988 ta 1969 ta 1





Estimate Expires 22-Dec-2022

Service Estimate

Customer
Roger Custer
1115 Mcduffie Dr
Jefferson, IA 50129
PHONE: (515)386-8494
EMAIL: custer@netins.net

Equipment John Deere 9570S Serial# H09570S730721

Part#	ngine Air Filter, Rem	ove and Replace		Customer Response : Decline
	Cont Man			
	Part Name		Quantity Units	
H222225	Filter Element		1.00 EACH	
THE CONTRACTOR OF THE CONTRACT	Est Labor \$35.00	Parts \$161.80	Recommended \$196.80	en e
ry (Inner)	Engine Air Filter, Re	emove and Replace		Customer Response : Decline
art#	Part Name		Quantity Units	
H212295	Filter Element		1.00 EACH	
	st Labor \$35.00	Parts \$131.96	Recommended \$166.96	
il and Filt	er, Change			Customer Response : Decline
art#	Part Name		Quantity Units	
E504836	Oil Filter		1.00 EACH	
502513	Seal		1.00 EACH	
Y26682B	Bulk- Plus-50 II		34.00 QUARTS	
	st Labor \$210.00	Parts \$256.71	Recommended \$466.71	
ınd Final I	Fuel Filter, Change			Customer Response : Declined
art#	Part Name		Quantity Units	
E522878	Filter Element		1.00 EACH	
E541922	Filter Element		1.00 EACH	
E	st Labor \$70.00	Parts \$71.97	Recommended \$141.97	And and the controlled and the controlled and the first and the controlled and the contro
	y (Inner) art # H212295 E Il and Filt art # E504836 502513 /26682B E art # E522878 E5522878	Part Name H212295 Filter Element Est Labor \$35.00 Il and Filter, Change art # Part Name E504836 Oil Filter 502513 Seal (26682B Bulk- Plus-50 II Est Labor \$210.00 and Final Fuel Filter, Change art # Part Name E522878 Filter Element	y (Inner) Engine Air Filter, Remove and Replace art # Part Name H212295 Filter Element Est Labor \$35.00 Parts \$131.96 Il and Filter, Change art # Part Name E504836 Oil Filter 502513 Seal //26682B Bulk- Plus-50 II Est Labor \$210.00 Parts \$256.71 and Final Fuel Filter, Change art # Part Name E522878 Filter Element E541922 Filter Element	Est Labor \$35.00 Parts \$161.80 Recommended \$196.80





Estimate Expires 22-Dec-2022

Service Estimate

Customer
Roger Custer
1115 Mcduffie Dr
Jefferson, IA 50129
PHONE: (515)386-8494
EMAIL: custer@netins.net

Equipment John Deere 9570S Serial# H09570S730721

Discharge Beater Grate, Finger (Narrow of Three) Remove and Replace					Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	H135891	Lock Nut		4.00 EACH	
	19M7804	Screw		4.00 EACH	
	H202562	Finger		1.00 EACH	
in de de verse en en el de provincia de la companya de la companya de la companya de la companya de la company La companya de la co	antino de maio de comença de constante de constante de comença de comença de comença de comença de comença de La comença de maio de comença de	Est Labor \$420.00	Parts \$180.31	Recommended \$600.31	
Discha	arge Beater	Grate Frame, Remove	e and Replace		Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	14M7299	Flange Nut		4.00 EACH	
	H228984	Vane		2.00 EACH	
	H135891	Lock Nut		12.00 EACH	
	H162227	Strap		2.00 EACH	
	14M7296	Flange Nut		6.00 EACH	
	19M7789	Screw		4.00 EACH	
	19M7786	Screw		12.00 EACH	
	AH213595	Grate		1.00 EACH	
	03M7191	Bolt		6.00 EACH	
gerthein-delighed goodener voor passage	er - yan salapan demokrati emi emi emi emi emi emi emi emi emi em	Est Labor \$700.00	Parts \$896.84	Recommended \$1,596.84	
Beater	top sheet				Customer Response : Declined
Parts	Part #	Part Name		Quantity Units	
	AH209003	Cover		1.00 EACH	
antiner innerpetado, tipo Madagin	kaja ligikas masamu v. mast u v. vede kombe indes albem kridja bitan kridja bitan sala	Est Labor \$450.00	Parts \$510.06	Recommended \$960.06	





Estimate Expires 22-Dec-2022

Service Estimate

Customer
Roger Custer
1115 Mcduffie Dr
Jefferson, IA 50129
PHONE: (515)386-8494
EMAIL: custer@netins.net

Equipment John Deere 9570S Serial# H09570S730721

Estimate Details
Estimate# 65931
Created Date: 22-Nov-2022
Created By: Keith Bohan

Upper Feederhouse (Poly) Wear	Strips (3), Remove and Replace
-------------------------------	--------------------------------

Customer Response: Declined

Parts

Part # H171960 Part Name

Strip

Quantity Units

3.00 EACH

Est Labor \$280.00

Parts \$64.26

Recommended \$344.26

Agreement	:
-----------	---

I hereby authorize the repair work to be done as described above on the machine(s) named here on. All repair parts are to be billed at regular prices. I agree to pay cash for such repair parts and labor on delivery of machine(s) or on terms satisfactory to you and until paid in full, any such unpaid balance shall contribute a lien on this machinery. I further agree that you will not be responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Of some of a		
Signed:	Date:	-

Price Type	Declined Total			
Est Labor	\$6,813.80			
Parts	\$6,728.25			
Total	\$13,542.05			
NOTE: ALL PRICES EXCLUDE SERVICE				
CHARGES AND SALES TAX				





Estimate Expires 22-Dec-2022

Service Estimate

Customer
Roger Custer
1115 Mcduffie Dr
Jefferson, IA 50129
PHONE: (515)386-8494
EMAIL: custer@netins.net

Equipment
John Deere 9570S
Serial# H09570S730721

Estimate Details
Estimate# 65931
Created Date: 22-Nov-2022
Created By: Keith Bohan

Estimate Summary:

Price Type	Recommended	Accepted	Declined	Undecided
Est Labor	\$6,813.80	\$0.00	\$6,813.80	\$0.00
Parts	\$6,728,25	\$0.00	\$6,728.25	\$0.00
Total	\$13,542.05	\$0.00	\$13,542.05	\$0.00





Estimate Expires 22-Dec-2022

Service Estimate

Customer
Roger Custer
1115 Mcduffie Dr
Jefferson, IA 50129
PHONE: (515)386-8494
EMAIL: custer@netins.net

Equipment John Deere 9570S Serial# H09570S730721 Estimate Details
Estimate# 65931
Created Date: 22-Nov-2022
Created By: Keith Bohan

Appendix: