

RMACs Truck & Equipment

814 E. Santa Fe Blvd.  
 Ellinwood, KS 67526  
 Phone 620-564-2643

# Invoice

Date	Invoice #
9/22/2025	75616
	S.O. No.
	887

Bill To
Tom Snell Harvesting 509 W. 6th Ellinwood Ks 67526

Rep	Year	Make	Unit #	Mileage	Vin #
	4-2015	Freightliner	93	442,756	3AKJGEBG0GSHE4693
Quantity	Item Code	Description	Price Each	Core	Amount
1	Part	MT0369 Seal Ring	3.99		3.99
1	Part	MT1428 Seal Ring	1.79		1.79
1	ATM30-BUSS	Fuse KIT	1.73		1.73
1	129-SWTP	Relay	19.15		19.15
1	Part	22-75836-000 A/C Compressor	662.08		662.08
1	Part	A22-77123-003 Receiver Drier	152.55		152.55
1	Part	VCC T1000898P Expansion Valve	64.04		64.04
1	Part	A22-72459-000 Condenser	561.32		561.32
2	69994-FS	AC FLUSH	16.69		33.38
3	134A30-NWDT	134A Freon Bulk	11.00		33.00
2	Nitrogen Charge	Accumulator	33.00		66.00
1	LABOR/SERVICE	Labor/Service Total	1,533.00		1,533.00

*3 new batteries  
 Jim Pahlmeyer  
 6/17/2025*

Subtotal
Sales Tax (0.0%)
Total

RMACs Truck & Equipment

814 E. Santa Fe Blvd.  
 Ellinwood, KS 67526  
 Phone 620-564-2643

# Invoice

Date	Invoice #
9/22/2025	75616
	S.O. No.
	887

Bill To
Tom Snell Harvesting 509 W. 6th Ellinwood Ks 67526

Rep	Year	Make	Unit #	Mileage	Vin #
	4-2015	Freightliner	93	442,756	3AKJGEBG0GSHE4693
Quantity	Item Code	Description	Price Each	Core	Amount
		Removed left steer tire. Found air leaking from the valve stem. Removed and replaced Schrader valve. Reinstalled tire and torqued to 500 ft lbs. Connected A/C reclaimer to truck. Found pressures low. Introduced nitrogen into A/C system to check for leaks. Found leak on suction side of A/C system. Replaced o-rings. Charged A/C system with freon. A/C compressor would not run. Inspected wiring, relays and fuses. Found A/C compressor needing replacement. Flushed A/C lines. Removed and replaced compressor, dryer, expansion valve and condensor using all new o-rings. Charged A/C system with freon. Checked operation.			

Thank You for your business!

Limited 90 Day Workmanship Warranty. Parts warranty varies by manufacturer. Ask for details.

RETURN POLICY: All returns must have original invoice. A 10% restocking charge will be deducted from credit on ALL special order parts if not returned within 30 days from invoice date.

A finance charge of 1.5% will be applied to your bill on all remaining balances not paid before the next billing cycle. In the event this and/or other invoices are referred to an attorney or agency for collection, the undersigned agrees to pay all costs of collection, including a reasonable attorney's fee.

Subtotal	\$3,132.03
Sales Tax (0.0%)	\$0.00
<b>Total</b>	<b>\$3,132.03</b>

*ok*  
*acs*

SIGNATURE \_\_\_\_\_