



MASSEY FERGUSON

CLAAS

MONDOVI, WI  
715-946-3168



www.lindstromequipment.com

WATERTOWN, WI  
920-765-9532



MENOMONIE, WI  
715-231-3168



SOLD TO \*\*\* emailed \*\*\*  
LEVE04 LEVENDOSKI DAIRY  
TOM LEVENDOSKI  
966 3RD ST SW  
CLEAR LAKE, WI 54005

SHIP TO  
LEVENDOSKI DAIRY  
TOM LEVENDOSKI  
966 3RD ST SW  
CLEAR LAKE, WI 54005

FENDT 819 12 SN: 832/22/1056 HR 10151.0 W:00  
Sold By: BARRY PO #: 819 ENG OIL PSI Date 7/15/25 WORK ORDER WB13916  
Ship By: Tax #: 8:41:44 PRT: 8

Tax D Qty Description -----\* Price Amount

Group: 01

Customer states engine oil pressure warning is always alerting  
Customer replaced sensor and problem persists

SHOP LABOR

\*\* TOTAL SHOP LABOR 1689.60

brock did call me on 6-25 and did say that parts did get out a engine oil pressure sensor for him to try on his machine that did have and still does have engine oil pressure error. 1D101 not for sure if the new sensor is any good and will order another and take with. and there is another error code 0515D and this is for brake pressure which not for sure if they want replaced. take with and see what happens. and the back rest for his 930 take with and finally got that also. going up the week of 30th. did not have time to get to this but the turbo did make it for there other machine which I have been working on. thinking about this issue will order a connector for the oil pressure sensor and the sensor i do have just thinking we could have wiring issue also not just the sensor.

7-9 i did run to the machine and did ask and call brock and make sure it is okay to come up which it was and bring brock back with me and he can drive the 822 home because it is done. i did deliver the seat back rest cushion for there 930 which they will change themselves. get the whole story from the operator when the machine is cold in the morning the engine oil pressure error code does not occur until the machine is warmed up the the error comes up quite often. the customer did just replace the oil pressure sensor thinking it could be the sensor. which it was not. when i got to the machine i did briefly look at the wiring from the connector up the harness 10 inches and seen no bad spots in the wiring and the connector looks fine. so the next thing i did was get out the a pressure guage smaller 200 pound guage and find a adaptor fitting after removing the replaced sensor and get the guage connected.

and at a idle no oil pressure and at 1400 rpms 2 bar and full throttle 3 bar. but for now will talk to agco and see what they think about the situation. i did start a case with agco and see what there thoughts are on this issue. the only to remove oil pan is to remove the engine to acess

The undersigned hereby claims exempt on purchase, lease, rental of tangible personal property or taxable services based upon purchaser's proposed exclusive use of items purchased in farming, dairying, ag., horticulture, floriculture engaged in as a business enterprise. Tractors and farm machines, including parts, fuel, repair service thereof. Feed, seeds for planting, plants, fertilizer, soil conditioners, sprays, pesticides, fungicides. Baling twine and baling wire. A finance charge shall be calculated at 1 1/2% per month with a minimum service charge of \$1.00. By doing business with Lindstrom Equipment ("LEI"), you consent to receiving promotional emails and/or text messages from LEI. In spite of the fact that your mobile phone number(s) may otherwise be on the federal, or a state's Do Not Call List, you agree that, to the maximum extent permitted by law, your consent overrides any prior Do Not Call request. You may opt out of receiving promotional emails or text messages from LEI by following the instructions in those emails or text messages. If you opt out, we may still send you non-promotional emails, such as those about your account or our ongoing business relations.



MASSEY FERGUSON

CLAAS

MONDOVI, WI  
715-946-3168

**LINDSTROM**  
EQUIPMENT, INC.

www.lindstromequipment.com

WATERTOWN, WI  
920-765-9532



MENOMONIE, WI  
715-231-3168



SOLD TO \*\*\* emailed \*\*\*  
LEVE04 LEVENDOSKI DAIRY  
TOM LEVENDOSKI  
966 3RD ST SW  
CLEAR LAKE, WI 54005

SHIP TO  
LEVENDOSKI DAIRY  
TOM LEVENDOSKI  
966 3RD ST SW  
CLEAR LAKE, WI 54005

FENDT 819 12 SN: 832/22/1056 HR 10151.0 W:00  
Sold By: BARRY PO #: 819 ENG OIL PSI Date 7/15/25 WORK ORDER WB13916  
Ship By: Tax #: 8:41:44 PRT: 8

Tax D Qty Description -----\* Price Amount

the oil pump not for sure if that makes any sense.7-14 after agco getting back to me and he did just hopefully the oil control valve will help the situation. agco did say that at a idle the min oil pressure should be around 7 psi which when warm at a idle was zero. so any improvement would be a plus and the only option. 7-14 just talked to brock and he did say that for now this machine will not be repaired at this time. and might not be repaired. and will be sold.

Type of Sale: Purchase  
Descriptive Billing Code: 00103 SHOP WORK TRACTOR  
This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

The undersigned hereby claims exempt on purchase, lease, rental of tangible personal property or taxable services based upon purchaser's proposed exclusive use of items purchased in farming, dairying, ag., horticulture, floriculture engaged in as a business enterprise. Tractors and farm machines, including parts, fuel, repair service thereof. Feed, seeds for planting, plants, fertilizer, soil conditioners, sprays, pesticides, fungicides. Baling twine and baling wire. A finance charge shall be calculated at 1 1/2% per month with a minimum service charge of \$1.00. By doing business with Lindstrom Equipment ("LEI"), you consent to receiving promotional emails and/or text messages from LEI. In spite of the fact that your mobile phone number(s) may otherwise be on the federal, or a state's Do Not Call List, you agree that, to the maximum extent permitted by law, your consent overrides any prior Do Not Call request. You may opt out of receiving promotional emails or text messages from LEI by following the instructions in those emails or text messages. If you opt out, we may still send you non-promotional emails, such as those about your account or our ongoing business relations.

I agree to pay the total amount of this invoice in accordance with the Cardholder Agreement. \*\* SUBTOTAL 1689.60

X \_\_\_\_\_ \*FP XXXXXX8020 \*\* TOTAL \*\* 1689.60  
AUTH# 508459 1689.60

Page 2 Last Page PAY THIS AMOUNT \$0.00

SEE US FOR ALL YOUR HYDRAULIC HOSE & FITTING NEEDS



CLAAS

LINDSTROM EQUIPMENT, INC. www.lindstromequipment.com



MASSEY FERGUSON

MONDOVI, WI 715-946-3168

WATERTOWN, WI 920-765-9532

MENOMONIE, WI 715-231-3168

SOLD TO \*\*\* emailed \*\*\*
LEVE04 LEVENDOSKI DAIRY
TOM LEVENDOSKI
966 3RD ST SW
CLEAR LAKE, WI 54005

SHIP TO
LEVENDOSKI DAIRY
TOM LEVENDOSKI
966 3RD ST SW
CLEAR LAKE, WI 54005

FENDT 819 12 SN: 832/22/1056 HR 9700.0 W:00
Sold By: BARRY PO #: FENDT 819 ELECT Date 5/23/25 WORK ORDER WB13653
Ship By: Tax #: 8:43:43 PRT: 7

Table with columns: Tax, D, Qty, Description, Price, Amount. Includes rows for PARTS SERVICE, SHOP LABOR, MISC.SHOP SUPPLY, and TRUCK/HAULING.

Brock did call me and did have some error codes. which are 1d.2.DE, 1D.1.12, 1D.1.30, 04.1.3E and 1D.1.13. which these errors are mostly all to do with emissions. Brock did tell me that they were having trouble and could not shut machine down by removing the key and then by disconnecting the battery still was running and then they had pulled some fuses from the fuse panel for engine not for sure. and then it did shut down. i did start a case on with agco and told them of what is going on. They did reply back and wanted the kwp which is added to the error code but the only way to get that is we need to connect to the machine to get these. so either we will have visit machine or the machine comes to shop. i will call brock again.

5-1-25 after going back and forth with agco on the case for this they want the fmi spn and kwp which the only way to see is connect laptop to the machine and take pictures before and after. there were 3 errors in the stored error in the engine section that were associated with the def pump.

The undersigned hereby claims exempt on purchase, lease, rental of tangible personal property or taxable services based upon purchaser's proposed exclusive use of items purchased in farming, dairying, ag., horticulture, floriculture engaged in as a business enterprise. Tractors and farm machines, including parts, fuel, repair service thereof. Feed, seeds for planting, plants, fertilizer, soil conditioners, sprays, pesticides, fungicides. Baling twine and baling wire. A finance charge shall be calculated at 1 1/2% per month with a minimum service charge of \$1.00. By doing business with Lindstrom Equipment ("LEI"), you consent to receiving promotional emails and/or text messages from LEI. In spite of the fact that your mobile phone number(s) may otherwise be on the federal, or a state's Do Not Call List, you agree that, to the maximum extent permitted by law, your consent overrides any prior Do Not Call request. You may opt out of receiving promotional emails or text messages from LEI by following the instructions in those emails or text messages. If you opt out, we may still send you non-promotional emails, such as those about your account or our ongoing business relations.



CLAAS

LINDSTROM EQUIPMENT, INC. www.lindstromequipment.com



MASSEY FERGUSON

MONDOVI, WI 715-946-3168

WATERTOWN, WI 920-765-9532

MENOMONIE, WI 715-231-3168

SOLD TO \*\*\* emailed \*\*\*
LEVE04 LEVENDOSKI DAIRY
TOM LEVENDOSKI
966 3RD ST SW
CLEAR LAKE, WI 54005

SHIP TO
LEVENDOSKI DAIRY
TOM LEVENDOSKI
966 3RD ST SW
CLEAR LAKE, WI 54005

FENDT 819 12 SN: 832/22/1056 HR 9700.0 W:00
Sold By: BARRY PO #: FENDT 819 ELECT Date 5/23/25 WORK ORDER WB13653
Ship By: Tax #: 8:43:43 PRT: 7

Tax D Qty Description -----\* Price Amount

first try to find the key and i did find in the manual area by the radio.
but this key will not work something wrong with the key tractor will
not start with it. so found tom's son and he went and got the key. in the
meantime removed the cover over the def supply module and unplugged the
connector and def just poured from it. started cleaning and dry out and
key back on and all of the errors went away except for the supply module
error was still on but was unplugged. so get I called parts and they
do have one. at this point just go home and stop by the shop and pickup
the new part and run back up to the machine and replace the unit and could
not get one line off so i unscrew the old fitting from the old unit and
remove fitting from the new unit and install the old fitting and hose
into the new unit. unbolt the old unit and bolt the new unit back in place
and do some more cleaning on the connector first use the battery terminal
cleaner and then terminal cleaner a couple times. and finally terminal
grease connect the connector and start tractor and no
errors and then clear errors and let machine run for 10 min and then put
paneling back.and go back to shop.and put in the error codes that i seen
for agco to the case.

TID: 001 TransactionType: CreditSale TransactionResult: Approved
Ref: 0510202E-CC62-1AD8-8140-0004AC1EA28B CardScheme: VISA
AuthDateTime: 2025-05-23-08.31.24.701000 TransactionSource: Token

The undersigned hereby claims exempt on purchase, lease, rental of tangible personal property or taxable services based upon purchaser's proposed exclusive use of items purchased in farming, dairying, ag., horticulture, floriculture engaged in as a business enterprise. Tractors and farm machines, including parts, fuel, repair service thereof. Feed, seeds for planting, plants, fertilizer, soil conditioners, sprays, pesticides, fungicides. Baling twine and baling wire. A finance charge shall be calculated at 1 1/2% per month with a minimum service charge of \$1.00. By doing business with Lindstrom Equipment ("LEI"), you consent to receiving promotional emails and/or text messages from LEI. In spite of the fact that your mobile phone number(s) may otherwise be on the federal, or a state's Do Not Call List, you agree that, to the maximum extent permitted by law, your consent overrides any prior Do Not Call request. You may opt out of receiving promotional emails or text messages from LEI by following the instructions in those emails or text messages. If you opt out, we may still send you non-promotional emails, such as those about your account or our ongoing business relations.

I agree to pay the total amount of this invoice \*\* SUBTOTAL 3827.79
in accordance with the Cardholder Agreement.

X \_\_\_\_\_ \*GP XXXXXXXXXXXXX8210 \*\* TOTAL \*\* 3827.79
AUTH# 03732G 3827.79



SEE US FOR ALL YOUR HYDRAULIC HOSE & FITTING NEEDS