



www.midwestmachinervco.com

Invoice To Account No: 812893

KENNETH ERICKSON 2081 357TH AVE NW

CAMBRIDGE MN 55008

Phone Number:

763-689-4770

SERVICE INVOICE

Invoice Number: Invoice Date:

cation:

Location: Work Order Number: Payment Type:

187888 Finance

1128137

8/25/2015

09

Page:

1 of 2

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 468S	3559	1E00468SEBB372473	E372473	

Gen- Retail

COMPLAINT:

REPAIR SPROCKET DAMAGE ON LEFT HAND SIDE. CHECK OVER TO SEE WHY THIS IS HAPPENING.

CORRECTION:

LOOKING AT THE BALER AND HOW MANY TIMES THIS HAS HAPPENED I DECIDED IT WAS BEST TO ELIMINATE THE ROOT OF THE CAUSE. THE CAUSE OF ALL THESE ISSUES IS THE CROSS AUGER ON TOP OF THE FRONT IDLER. I OPENED THE BALER UP AND REMOVED THE SPROCKET FOR THIS AUGER. REMOVED THE SHAFTS OFF OF BOTH SIDES AND REMOVED THE AUGER. ORDERED THE PART I NEEDED TO PUT THE WELD ON BRACKET BACK ON, WENT INTO TOWN AND GOT SOME 7 GAUGE STEEL PLATE AND WELDED A PLATE OVER THE HOLES IN THE SIDE OF THE BALER WHERE THE AUGER WAS. WELDED ON A NEW BRACKET FOR THE CHAIN TIGHTENER. SHORTENED THE OLD CHAIN AND INSTALLED IT BACK ON THE BALER. INSTALLED THE IDLER SPROCKET AND RAN THE BALER TO CHECK FOR ANY OTHER ISSUES. EVERYTHING CHECKED OUT FINE AND IT IS READY TO GO NOW.

Part Number 03M7212	<u>Description</u> BOLT	Quantity 1.00	<u>List Price</u> 2.92	Extended Price \$2.92	Taxed Ind N
AE74659	BRACKET-IDLER SPROCKET	1.00	51.60	\$51.60	N
AXE15284	IDLER SPRO	1.00	87.72	\$87.72	N
Miscellaneous	<u>Description</u>	Quantity	List Price	Extended Price	Taxed Ind





Grand Total:

www.midwestmachineryco.com

SERVICE INVOICE Invoice To Account No: 812893 Invoice Number: 1128137 KENNETH ERICKSON 2081 357TH AVE NW 8/25/2015 Invoice Date: CAMBRIDGE MN 55008 09 Location: Phone 187888 Work Order Number: Number: Finance Payment Type: 2 of 2 Page: 763-689-4770 Fleet No: Serial Number: Eq ID: Make/Model: Meter: 1E00468SEBB372473 E372473 JOHN DEERE 468S 3559 Gen- Retail 0.00 \$0.00 Ν 20.00 **FREIGHT** P3750 Sub-Total: \$659.99 Parts: \$142.24 OL&M: \$0.00 Misc: \$0.00 Labor: \$517.75 Miscellaneous Charges: \$1.42 **Environmental Fee** \$7.77 **Shop Supplies Finance Information** Labor: \$517.75 Parts: \$142.24 Type: Multi-use Acct US Auth. No: **Customer PO No:** OL&M: \$0.00 Tax Exempt No: 13ST3-LOCM Merchant No: Misc: \$9.19 Card No: Advisor: 915 Sales Tax: \$0.63 - JD HAY PARTS/SERVICE **Bill Code:** 120 DAYS NO PAYMENTS/NO Credit Plan: 1 \$669.81

INTEREST

TERMS AND CONDITIONS

*** DOCUMENT COPY * * *

Repayment Terms: Customer Disclosure - This form must be signed by the customer to process the multi-use account transaction. The following special terms, as described in the multi-use account credit agreement, apply to the attached invoice. Up to 120 Days No Payments / No Interest Financing followed by the ANNUAL PERCENTAGE RATE (APR) applicable to your Account.

This purchase(s) is subject to the terms of the multi-use account, a service of John Deere Financial, f.s.b. 1 grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.





www.midwestmachineryco.com

Invoice To Account No: 812893

SERVICE INVOICE

KENNETH ERICKSON 2081 357TH AVE NW CAMBRIDGE MN 55008

Phone Number:

763-689-4770

Invoice Number: 920436
Invoice Date: 8/26/2014
Location: 09
Work Order Number: 157101
Payment Type: Finance

Page: 1 of 2

 Make/Model:
 Meter:
 Serial Number:
 Eq ID:
 Fleet No:

 JOHN DEERE 468S
 3492
 1E00468SEBB372473
 E372473

Gen- Retail

COMPLAINT:

REPLACE IDLER SPROCKET, ALSO NEEDS A NEW ROLLER CHAIN. CHECK OVER BALER

CORRECTION:

Found that all the chains were bad replaced all the chains, replaced idler sprocket, the bracket that the idler sprocket sits on is bent bad, tried to get it bent back in to place as best i could. That did not work out, talked with customer told him i would have to cut out the support and make a new one, turned out that there was a support not being used, so I cut the bad one off and cut the good one off and welded the good one in place of the bad one, put the chains back on and ever thing worked out good, installed new bearings

Part Number 03M7212	<u>Description</u> BOLT	Quantity 2.00	<u>List Price</u> 2.92	Extended Price \$5.84	<u>Taxed Ind</u> N
14M7291	FLANGE NUT	1.00	2.29	\$2.29	N
AE74238	ROLLER CHA	1.00	46.09	\$46.09	N
AE74423	Roller Chain	1.00	101.06	\$96.25	N
AE74659	BRACKET-IDLER SPROCKET	1.00	51.60	\$50.09	N
AFH206114	ROLLER CHA	1.00	277.46	\$252.24	N
AXE15284	IDLER SPRO	2.00	87.72	\$170.32	N
JD9313	BALL BEARI	1.00	18.70	\$17.00	N
JD9338	BALL BEARI	1.00	39.13	\$36.58	N
SW80COUS	CHAIN LINK	2.00	3.48	\$6.96	N
SW80OLUS	CHAIN LINK	2.00	8.08	\$16.16	N
SW80X10US	ROLLER CHA	69.00	1.13	\$77.97	N
Miscellaneous	<u>Description</u>	Quantity	<u>List Price</u>	Extended Price	Taxed Ind





www.midwestmachineryco.com

SERVICE INVOICE Invoice To Account No: 812893 KENNETH ERICKSON Invoice Number: 920436 2081 357TH AVE NW Invoice Date: 8/26/2014 CAMBRIDGE MN 55008 Location: 09 Phone Work Order Number: 157101 Number: Finance Payment Type: 2 of 2 Page: 763-689-4770 Eq ID: Fleet No: Make/Model: Meter: Serial Number: **JOHN DEERE 468S** 1E00468SEBB372473 E372473 3492 Gen- Retail 0.00 (\$700.00)Ν S3970 LABOR DISCOUNT 1.00 Sub-Total: \$1,197.03 Labor: \$1,119.22 Parts: \$777.79 OL&M: \$0.00 Misc: (\$699.98) **INVOICE CONTAINS \$40.91 DISCOUNT** Miscellaneous Charges: \$1.00 **Environmental Fee** \$16.79 **Shop Supplies** Finance Information Labor: \$1,119.22 \$777.79 Parts: **Customer PO No:** Type: Multi-use Acct US Auth. No: \$0.00 OL&M: Tax Exempt No: 13ST3-LOCM Merchant No: 4 (\$682.19)Misc: 912 Card No: Advisor: \$0.00 - JD HAY PARTS/SERVICE Sales Tax: Bill Code: 150 DAYS NO PAYMENTS/NO Credit Plan: \$1,214.82 Grand Total:

INTEREST

TERMS AND CONDITIONS

* * * DOCUMENT COPY * * *

Repayment Terms: Customer Disclosure - This form must be signed by the customer to process the multi-use account transaction. The following special terms, as described in the multi-use account credit agreement, apply to the attached invoice.

150 Days No Payments and No Interest. Following the deferral period, the ANNUAL PERCENTAGE RATE (APR) applicable to your Account will apply to this purchase.

This purchase(s) is subject to the terms of the multi-use account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

ceived by: Date:
