

**The Shop**  
 2362 hancock Ave  
 Eagle grove, IA 50533  
 theshop\_2019@yahoo.com  
 5158510917

**Invoice: 1120**  
**Date: 11/6/2019**

**Bill To**  
**KEITH BARKEMA**

**Remit Payment To**  
**Primary**  
 2362 hancock Ave  
 Eagle grove, IA 50533

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
1032	COD	11/6/2019	KEITH BARKEMA	1120	B1

Item	Description	Quantity	Rate	Amount
<b>Complaint: LOW OIL PRESSURE</b>				
<b>Cause: LOW OIL PRESSURE</b>				
Labor	<b>Correction:</b> Engine / Bearings / PUT RODS AND BEARINGS IN CLEANED ALL PIPING FOR NEW OIL PUMP, PUT OIL PUMP IN AND TWO RELIVES, CLEANED OIL PAN, PUT TOP END OF ENGINE TOGETHER, REPLACED O-RINGS FOR CAM PLATE, REPLACED BEARINGS FOR CAM, RAN OVER HEAD RE-SET EVERYTHING, GOT RUNNING AND CLEARED ALL CODES, REPLACED LOW OIL SENSOR, TORQUED EVERYTHING DOWN PUT PAN ON, CHANGED OIL FILTERS 40QT ENGINE OIL IN,REPLACED VALVE COVER GASKET PUT ON - 11/8/2019	24.00000	\$80.00	\$1,920.00
Parts	FUEL FILTER	1.00000	\$18.06000	\$18.06
Parts	AIR ELEMENT	1.00000	\$62.77000	\$62.77
Parts	OIL FILTER	2.00000	\$15.78000	\$31.56
Parts	SENSOR	1.00000	\$278.15000	\$278.15
Parts	15/40 OIL	10.00000	\$20.58000	\$205.80
Parts	L/END BRG KT	1.00000	\$488.76000	\$488.76
Parts	O/PUMP ASSY	1.00000	\$815.99000	\$815.99
Parts	M-SEAL RING	1.00000	\$21.86000	\$21.86
Parts	14 L PAN GASKET	1.00000	\$88.20000	\$88.20
Parts	SEAL	1.00000	\$17.15000	\$17.15
Parts	GASKET	1.00000	\$64.08000	\$64.08
Parts	CAM BEARING SET	1.00000	\$192.17000	\$192.17
Parts	SEAL	1.00000	\$17.15000	\$17.15
Parts	VALVE ASSEMBLY	1.00000	\$64.34000	\$64.34
Parts	ELBOW ASSEMBLY	1.00000	\$116.71000	\$116.71
<b>Sub Total</b>				<b>\$4,402.75</b>

**Unit: B1 VIN: 1FUJAHCG31LH70486**  
**2001 Freightliner FLD120**  
**Chassis: 754,738 Miles**

**Labor \$1,920.00**

**Parts \$2,482.75**

**Pre Tax Total \$4,402.75**

**Eagle Grove Sales Tax (7.0000% of \$4,402.75) \$308.19**

**Total \$4,710.94**

**Payments & Credits \$0.00**

**Balance Due \$4,710.94**