

PREVIEW RO# I 55758 CUST# 10000 MIKE WALKER 7088 COMBINE TRAD
UNIT# 46161 2009 CASE-IH 7088 COMBI

***** REPAIR ORDER SUMMARY DATA *****
MIKE WALKER 7088 COMBINE TRADE CUST# 10000 RO# I55758
START 8/21/15 12:58
BILLED 12/28/15 13:55
PILOT GROVE IA 52648-0000 PO#
WRITER 061
PHONE: HOME 319 469-4461 PHC 08 PBC 03 APPROVAL 061 /050

***** REPAIR ORDER TOTALS BY PAY TYPE *****
C PRB 0 I PRB 13 W PRB 0
BILLED BILLED 12/28/15 13:55 050 BILLED
LABOR 0.00 1,423.44 0.00
PARTS 0.00 344.88 0.00
SUBLET 0.00 0.00 0.00
OTHER 0.00 0.00 0.00
MISC EXP 0.00 0.00 0.00
MISC CHARGES 0.00 6.03 0.00
DEDUCTIBLE 0.00 0.00 0.00
TAX 0.00 0.00 0.00
TOTAL DUE 0.00 1,774.35 0.00

***** SERVICE UNIT INFORMATION *****
OWNER 10000 UNIT# 46161 2009 CASE-IH 7088 COMBI CURR HRS 1,020.0
DELIVERED: 5/20/13
VIN: Y8G000204 ENGINE: 46957661
TIRE SIZE: 20.8R42/18.4X26 AXLE SN: PLATFORM EXT 20
FEEDER LENGTH: 54"SR CUT TYPE: 2SPHY
ROTOR HRS: 795 HR 11-1-13
WARRANTY EFF: 9/01/09 EXT: N UNIT: Y8G000204 EXP: 8/31/10
ENG: 46957661 EXP: 8/31/11

***** PROBLEM # 01 DETAILS *****
PRB# 1 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: CLEAN UP FOR CHRIS B TO SHOW KEN MEEKER
LOCATE AND GET STARTED--DRAG OUT OF THE BARN, THERE WERE TWO
COMBINES BEHIND IT
CUSTOMER ENDED UP PURCHASING A DIFFERENT COMBINE
HOLD STATUS: F FINISHED
OPR# 1 SKILL LEVEL:
TECH #: 221
221 2.40 51.75 124.20
221 .12 51.75 6.21
221 .48 51.75 24.84
221 .82 51.75 42.44
221 .57 51.75 29.50
1 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
227.19 0.00 0.00 0.00 0.00 227.19

***** PROBLEM # 02 DETAILS *****
PRB# 2 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: INT. COMBINE (MID-RANGE)-RECONDITIONING INSPECTION
CORRECTION: PERFORM THE STEPS OUTLINED ON THE FORM TITLED "MID-RANGE &
VINTAGE COMBINE - INTERNAL INSPECTION FORM"
PUT SHIELDS ON CALEB 11-9-15
HOLD STATUS: F FINISHED
OPR# 1 I.COMINMIRIC00 ----- FLAT RATE SKILL LEVEL:
INT. COMBINE (MID-RANGE)-RECONDITIONING INS
TECH #: 221
221 .70 0.00
LABOR: 4.00 82.00 328.00
2 LABOR PARTS SUBLET OTHER MISC PROB TOTAL
328.00 0.00 0.00 0.00 0.00 328.00

***** PROBLEM # 03 DETAILS *****
PRB# 3 LABOR TYPE 1I INTERNAL WORK ** BILLED **
COMPLAINT: INT. COMBINE (MID-RANGE)-RECONDITIONING SERVICE
CORRECTION: PERFORM THE STEPS OUTLINED ON THE FORM TITLED "COMBINE

SERVICING CHECK LIST FOR MID-RANGE COMBINES"

HOLD STATUS: F FINISHED

OPR# 1 I.COMSEMIRSC00 ----- FLAT RATE SKILL LEVEL:
 INT. COMBINE (MID-RANGE)-RECONDITIONING SER

TECH #: 221

LABOR:					6.00	82.00	492.00
3	LABOR	PARTS	SUBLET	OTHER		MISC	PROB TOTAL
	492.00	0.00	0.00	0.00		0.00	492.00

***** PROBLEM # 04 DETAILS *****

PRB# 4 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: WON'T START CALEB 8-22-15
 WON'T START SAM D 10-20-15

CAUSE: BATTERY
 HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 221

	041				1.05	51.75	54.34
4	LABOR	PARTS	SUBLET	OTHER		MISC	PROB TOTAL
	54.34	0.00	0.00	0.00		0.00	54.34

***** PROBLEM # 05 DETAILS *****

PRB# 5 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: REPLACE REAR SHOE SIEVE SEAL

HOLD STATUS: F FINISHED
 OPR# 1

SKILL LEVEL:

TECH #: 221

	221				.07	51.75	3.62
	221				.24	51.75	12.42
	221				1.02	51.75	52.79
	221				.65	51.75	33.64
PARTS:	87732448		CANVAS, CH		1.00	91.50	91.50
	16044331		SCREW, 8MM		1.00	1.70	1.70
	87656137		BOLT 8X20		1.00	1.36	1.36
	86507066		NUT, 8MM F		1.00	.32	0.32
5	LABOR	PARTS	SUBLET	OTHER		MISC	PROB TOTAL
	102.47	94.88	0.00	0.00		0.00	197.35

***** PROBLEM # 06 DETAILS *****

PRB# 6 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: CLEAN UP AND DETAIL

HOLD STATUS: F FINISHED
 OPR# 1

SKILL LEVEL:

TECH #: 221

	163				.210	51.75	108.68
	163				.32	51.75	16.56
	163				1.44	51.75	74.52
6	LABOR	PARTS	SUBLET	OTHER		MISC	PROB TOTAL
	199.76	0.00	0.00	0.00		0.00	199.76

***** PROBLEM # 07 DETAILS *****

PRB# 7 LABOR TYPE 1I INTERNAL WORK ** BILLED **
 COMPLAINT: SYSTEM OPERATION - CHARGE AND LOAD TEST THE BATTERIES - IF
 THEY FAIL PLEASE REVIEW WITH PAT TO CONFIRM HE WANTS THEM
 REPLACED AT THIS TIME.

CORRECTION: REPLACED BATTERIES
 HOLD STATUS: F FINISHED

OPR# 1 SKILL LEVEL:

TECH #: 221

	138				.32	61.50	19.68
PARTS:	BMF31GW		BATTERY		2.00	125.00	250.00
	BMF31GW		(CORE CHA		2.00	22.50	45.00
	BMF31GW		(CORE CRE		2.00-	22.50	45.00-
7	LABOR	PARTS	SUBLET	OTHER		MISC	PROB TOTAL
	19.68	250.00	0.00	0.00		0.00	269.68

***** PROBLEM # 08 DETAILS *****

PRB# 8 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: FEEDER HOUSING - CUT THE TABS OFF THE FRONT FEEDER PLATE,
ADD SPACERS TO THE ROCK TRAP SPROCKET

CORRECTION: NOT DONE AT THIS TIME

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 221

8	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	0.00	0.00	0.00	0.00	0.00

***** PROBLEM # 09 DETAILS *****

PRB# 9 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: STRAW CHOPPER - FREE UP THE STATIONARY KNIFE SO IT WILL SWING UP

CORRECTION: NOT DONE AT THIS TIME

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 221

9	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	0.00	0.00	0.00	0.00	0.00

***** PROBLEM # 10 DETAILS *****

PRB# 10 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: CLEAN GRAIN ELEVATOR - REPLACE INSIDE TENSIONER BEARING

CORRECTION: NOT DONE AT THIS TIME

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 221

10	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	0.00	0.00	0.00	0.00	0.00

***** PROBLEM # 11 DETAILS *****

PRB# 11 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: TAILING ELEVATOR - REPAIR THE SLIDE SPROCKET TENSIONER

CORRECTION: NOT DONE AT THIS TIME

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 221

11	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	0.00	0.00	0.00	0.00	0.00

***** PROBLEM # 12 DETAILS *****

PRB# 12 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: UNLOADING SYSTEM - REPLACE THE LOWER AUGER

CORRECTION: NOT DONE AT THIS TIME

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 221

12	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	0.00	0.00	0.00	0.00	0.00

***** PROBLEM # 13 DETAILS *****

PRB# 13 LABOR TYPE 1I INTERNAL WORK ** BILLED **

COMPLAINT: ENGINE - STRAIGHTEN OR REPLACE THE LAWN MOWER BLADE IN THE RADIATOR COMPARTMENT

CORRECTION: NOT DONE AT THIS TIME

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 221

13	LABOR	PARTS	SUBLET	OTHER	MISC	PROB TOTAL
	0.00	0.00	0.00	0.00	0.00	0.00

***** REPAIR ORDER TOTALS *****

LABOR SALE	1,423.44
PARTS SALE	344.88
REPAIR ORDER SUBTOTAL	1,768.32
TOTAL MISC. SHOP SUPPLIES	6.03

TOTAL DUE

1,774.35