

SEND REMITTANCE TO:

1342 Pilot Grove Rd.
Pilot Grove, IA 52648
Phone: 319-469-4461
Fax: 319-469-4703

J.J. NICHTING COMPANY

FARMALL COUNTRY SINCE 1920



www.jjnichting.com

SHIP TO

REPAIR ORDER

707 East Winfield Ave.
Mt. Pleasant, IA 52641
Phone: 319-385-3314
Fax: 319-385-2710

21582 HWY 92 East
Sigourney, IA 52591-0225
Phone: 641-622-3440
Fax: 641-622-1050

SOLD TO

46174 JIM L STAFFORD
17803 40TH AVE
BURLINGTON, IA 52601

CIH 1640 SN: JJC0034911 HR 4053.0 W:01
Sold By: 50 PO #: 1640 17-18 CMI Date 7/09/18 WORK ORDER WP05638
Ship By: Tax #: 2018 8:47:37 PRT: 13

Work Order Summary

01 2017-2018 1640 Combine CMI Inspection **\$350.00 flat rate** Free*	
02 Trucking Ron picked up 6-13-18 **Free Trucking**	
03 Head-injection pump? Randy needs to look at this.	965.83
04 Left mirror broke during transport of combine--no charge to	
05 Repair the right tail light that is out.	214.70
06 Adjust the feeder chain tension.	2.85
07 Replace the torn shift linkage grommet.	18.65
08 Clean grain pan is almost worn through. Need to weld a patch	545.30
09 Tighten all belts and chains not being replaced.	2292.80
10 Check into why the coolant light and alarm keeps going off.	186.70
11 Grease the axle couplers.	1715.35
12 Customer will take care of the following repairs.	
13 Fix lights.	431.58
** SALES TAX	300.81
** TOTAL	6674.57

Tax	D	Qty	Description	Price	Amount
-----	---	-----	-------------	-------	--------

Group: 01

01 2017-2018 1640 Combine CMI Inspection **\$350.00 flat rate** Free*

XL Black Coat is in the cab of the combine
4053 engine hours

SHOP LABOR

Total Hours:

** TOTAL SHOP LABOR

* SEGMENT SUBTOTAL

No returns without this invoice. No returns after 30 days. No returns on special orders, No returns on parts not in original package. 20% Handling charge on returned parts after 14 days. The selling dealer makes no warranty of any kind whatsoever as the merchantability of the products listed heron or as to their fitness for any particular purpose any warranty which may exist is an agreement solely between the manufacturer and the purchaser. ALL PURCHASES MADE DURING THE MONTH ARE DUE ON THE 30th OF THE MONTH FOLLOWING RECEIPT OF YOUR STATEMENT. If not paid by the 30th of the month, a finance charge of 1.75% which is an annual percentage rate of 21%, or a minimum charge of \$1.00 will be added to the unpaid balance at that time.



SEND REMITTANCE TO:

J.J. NICHTING COMPANY

REPAIR ORDER

1342 Pilot Grove Rd.
Pilot Grove, IA 52648
Phone: 319-469-4461
Fax: 319-469-4703

FARMALL COUNTRY SINCE 1920



www.jjnichting.com

SHIP TO

707 East Winfield Ave.
Mt. Pleasant, IA 52641
Phone: 319-385-3314
Fax: 319-385-2710

21582 HWY 92 East
Sigourney, IA 52591-0225
Phone: 641-622-3440
Fax: 641-622-1050

SOLD TO
46174 JIM L STAFFORD
17803 40TH AVE
BURLINGTON, IA 52601

CIH 1640 SN: JJC0034911 HR 4053.0 W:01
Sold By: 50 PO #: 1640 17-18 CMI Date 7/09/18 WORK ORDER WP05638
Ship By: Tax #: 2018 8:47:37 PRT: 13

Tax	D	Qty	Description	Price	Amount
02 Trucking Ron picked up 6-13-18 **Free Trucking***					
			Trucking Charlie delivered 7-6-18 **Free Trucking***		
			TRUCKING Total Hours: ** TOTAL TRUCKING		
					* SEGMENT SUBTOTAL

03 Head-injection pump? Randy needs to look at this.					
CORRECTION Injection pump leaking fuel. Cleaned off the engine and checked-ran it. Checked the injection pump for leaks. Found it leaking around the head off it. Had Randy look at it and we decided to replace/rebuild the head. Got new parts and removed the head/top of the pump. Cleaned up the gasket surface and swapped everything over from the old cap to the new cap. Installed the new cap and new gasket and adjusted the throttle cable. Ran the combine to check for leaks. All ok.					
			SHOP LABOR Total Hours: 8.56		
					** TOTAL SHOP LABOR 813.20
			PARTS SHOP		
		00000	1 SPN CAV7180-872N-RB TOP COVER X	126.38	126.38
			FREIGHT		
		00000*	FRGT IN		26.25
					* SEGMENT SUBTOTAL 965.83

No returns without this invoice. No returns after 30 days. No returns on special orders, No returns on parts not in original package. 20% Handling charge on returned parts after 14 days. The selling dealer makes no warranty of any kind whatsoever as the merchantability of the products listed heron or as to their fitness for any particular purpose any warranty which may exist is an agreement solely between the manufacturer and the purchaser. ALL PURCHASES MADE DURING THE MONTH ARE DUE ON THE 30th OF THE MONTH FOLLOWING RECEIPT OF YOUR STATEMENT. If not paid by the 30th of the month, a finance charge of 1.75% which is an annual percentage rate of 21%, or a minimum charge of \$1.00 will be added to the unpaid balance at that time.

SEND REMITTANCE TO:

J.J. NICHTING COMPANY

REPAIR ORDER

1342 Pilot Grove Rd.
Pilot Grove, IA 52648
Phone: 319-469-4461
Fax: 319-469-4703

FARMALL COUNTRY SINCE 1920



www.jjnichting.com

SHIP TO

707 East Winfield Ave.
Mt. Pleasant, IA 52641
Phone: 319-385-3314
Fax: 319-385-2710

21582 HWY 92 East
Sigourney, IA 52591-0225
Phone: 641-622-3440
Fax: 641-622-1050

SOLD TO
46174 JIM L STAFFORD
17803 40TH AVE
BURLINGTON, IA 52601

CIH 1640 SN: JJC0034911 HR 4053 0 W:01
Sold By: 50 PO #: 1640 17-18 CMI Date 7/09/18 WORK ORDER WP05638
Ship By: Tax #: 2018 8:47:37 PRT: 13

Tax	D	Qty	Description	Price	Amount
-----	---	-----	-------------	-------	--------

04 Left mirror broke during transport of combine--no charge to

customer for the replacement. **Rework**

CORRECTION
Took the nut off the mirror, removed old mirror and put the new mirror on the combine.

SHOP LABOR Total Hours: ** TOTAL SHOP LABOR

00000		1	CAS 1283403C1	MIRROR	X	N/C
-------	--	---	---------------	--------	---	-----

* SEGMENT SUBTOTAL

Repair the right tail light that is out.

CORRECTION
Found bare wires and a ground that was not hooked up. Cut the bare spot out of the wires and soldered them back together and connected the ground back to the light.

SHOP LABOR Total Hours: 2.26 ** TOTAL SHOP LABOR 214.70

* SEGMENT SUBTOTAL 214.70

No returns without this invoice. No returns after 30 days. No returns on special orders, No returns on parts not in original package. 20% Handling charge on returned parts after 14 days. The selling dealer makes no warranty of any kind whatsoever as the merchantability of the products listed hereon or as to their fitness for any particular purpose any warranty which may exist is an agreement solely between the manufacturer and the purchaser. ALL PURCHASES MADE DURING THE MONTH ARE DUE ON THE 30th OF THE MONTH FOLLOWING RECEIPT OF YOUR STATEMENT. If not paid by the 30th of the month, a finance charge of 1.75% which is an annual percentage rate of 21%, or a minimum charge of \$1.00 will be added to the unpaid balance at that time.

SEND REMITTANCE TO:

J.J. NICHTING COMPANY

REPAIR ORDER

1342 Pilot Grove Rd.
Pilot Grove, IA 52648
Phone: 319-469-4461
Fax: 319-469-4703

FARMALL COUNTRY SINCE 1920



www.jjnichting.com

SHIP TO

707 East Winfield Ave.
Mt. Pleasant, IA 52641
Phone: 319-385-3314
Fax: 319-385-2710

21582 HWY 92 East
Sigourney, IA 52591-0225
Phone: 641-622-3440
Fax: 641-622-1050

SOLD TO
46174 JIM L STAFFORD
17803 40TH AVE
BURLINGTON, IA 52601

CIH 1640 SN: JJC0034911 HR 4053.0 W:01
Sold By: 50 PO #: 1640 17-18 CMI Date 7/09/18 WORK ORDER WP05638
Ship By: Tax #: 2018 8:47:37 PRT: 13

Tax	D	Qty	Description	Price	Amount
06 Adjust the feeder chain tension.					
Replace the left feeder chain stripper. Adjust the feeder chain tension.					
CORRECTION Replaced the left feeder chain stripper. Loosened up the feeder chain and removed the old stripper. Installed the new stripper with new hardware. Adjusted the feeder chain. All ok.					
SHOP LABOR		Total Hours:		.03	
				** TOTAL SHOP LABOR	2.85
				* SEGMENT SUBTOTAL	2.85

07 Replace the torn shift linkage grommet.					
CORRECTION Ordered a new grommet and installed it. All ok.					
SHOP LABOR		Total Hours:		.16	
				** TOTAL SHOP LABOR	15.20
PARTS SHOP		GROMMET #		C09-2E	3.45
00000	1	CAS 87107420			3.45
				* SEGMENT SUBTOTAL	18.65

No returns without this invoice. No returns after 30 days. No returns on special orders, No returns on parts not in original package.
20% Handling charge on returned parts after 14 days. The selling dealer makes no warranty of any kind whatsoever as the merchantability
of the products listed heron or as to their fitness for any particular purpose any warranty which may exist is an agreement solely between
the manufacturer and the purchaser. ALL PURCHASES MADE DURING THE MONTH ARE DUE ON THE 30th OF THE MONTH
FOLLOWING RECEIPT OF YOUR STATEMENT. If not paid by the 30th of the month, a finance charge of 1.75% which is an annual
percentage rate of 21%, or a minimum charge of \$1.00 will be added to the unpaid balance at that time.

SEND REMITTANCE TO:

J.J. NICHTING COMPANY

REPAIR ORDER

1342 Pilot Grove Rd.
Pilot Grove, IA 52648
Phone: 319-469-4461
Fax: 319-469-4703

FARMALL COUNTRY SINCE 1920

707 East Winfield Ave.
Mt. Pleasant, IA 52641
Phone: 319-385-3314
Fax: 319-385-2710



www.jjnichting.com

SHIP TO

21582 HWY 92 East
Sigourney, IA 52591-0225
Phone: 641-622-3440
Fax: 641-622-1050

SOLD TO
46174 JIM L STAFFORD
17803 40TH AVE
BURLINGTON, IA 52601

CIH 1640 SN: JJC0034911 HR 4053.0 W:01
Sold By: 50 PO #: 1640 17-18 CMI Date 7/09/18 WORK ORDER WP05638
Ship By: Tax #: 2018 8:47:37 PRT: 13

Tax	D	Qty	Description	Price	Amount
-----	---	-----	-------------	-------	--------

08 Clean grain pan is almost worn through. Need to weld a patch

on it.

CORRECTION

Clean grain pan is almost worn through.
Made a patch and cleaned up the area. Welded the new patch on
and painted the area. All ok.

SHOP LABOR

Total Hours:	5.74	
** TOTAL SHOP LABOR		545.30
* SEGMENT SUBTOTAL		545.30

No returns without this invoice. No returns after 30 days. No returns on special orders, No returns on parts not in original package.
20% Handling charge on returned parts after 14 days. The selling dealer makes no warranty of any kind whatsoever as the merchantability
of the products listed heron or as to their fitness for any particular purpose any warranty which may exist is an agreement solely between
the manufacturer and the purchaser. ALL PURCHASES MADE DURING THE MONTH ARE DUE ON THE 30th OF THE MONTH
FOLLOWING RECEIPT OF YOUR STATEMENT. If not paid by the 30th of the month, a finance charge of 1.75% which is an annual
percentage rate of 21%, or a minimum charge of \$1.00 will be added to the unpaid balance at that time.

SEND REMITTANCE TO:

J.J. NICHTING COMPANY

REPAIR ORDER

1342 Pilot Grove Rd.
Pilot Grove, IA 52648
Phone: 319-469-4461
Fax: 319-469-4703

FARMALL COUNTRY SINCE 1920

707 East Winfield Ave.
Mt. Pleasant, IA 52641
Phone: 319-385-3314
Fax: 319-385-2710



www.jjnichting.com

SHIP TO

21582 HWY 92 East
Sigourney, IA 52591-0225
Phone: 641-622-3440
Fax: 641-622-1050

SOLD TO

46174 JIM L STAFFORD
17803 40TH AVE
BURLINGTON, IA 52601

CIH 1640 SN: JJC0034911 HR 4053 0 W:01
Sold By: 50 PO #: 1640 17-18 CMI Date 7/09/18 WORK ORDER WP05638
Ship By: Tax #: 2018 8:47:37 PRT: 13

Tax	D	Qty	Description	Price	Amount
-----	---	-----	-------------	-------	--------

09 Tighten all belts and chains not being replaced.

Replace the 6 sided belt.
Replace the cleaning fan jackshaft belt.
Replace the feeder drive belt.
Replace the feeder jackshaft belt.
Install new cleaning fan belt.

CORRECTION

Removed and replaced the 6 sided belt.
Removed and replaced the cleaning fan jackshaft belt.
Removed and replaced the feeder drive belt.
Removed and replaced the feeder jackshaft belt.
Also had to remove the feeder jackshaft pulley and cleaned up the pivot point to get the belt to tighten up

SHOP LABOR

Total Hours: 14.24
** TOTAL SHOP LABOR 1352.80

PARTS SHOP

00000	1	CAS 84462590	BELT / FAN	BELT8	78.00	78.00
00000	1	CAS 87476487	BELT / ELE	BELT10	282.00	282.00
00000	1	CAS 192738C1	BELT / UPP	BELT3	225.00	225.00
00000	1	CAS 87629602	V-BELT FEE	BELT11	288.00	288.00
00000	1	CAS 195396C2	BELT / CLE	BELT3	67.00	67.00
					** TOTAL PARTS SHOP	940.00

* SEGMENT SUBTOTAL 2292.80

No returns without this invoice. No returns after 30 days. No returns on special orders, No returns on parts not in original package. 20% Handling charge on returned parts after 14 days. The selling dealer makes no warranty of any kind whatsoever as the merchantability of the products listed heron or as to their fitness for any particular purpose any warranty which may exist is an agreement solely between the manufacturer and the purchaser. ALL PURCHASES MADE DURING THE MONTH ARE DUE ON THE 30th OF THE MONTH FOLLOWING RECEIPT OF YOUR STATEMENT. If not paid by the 30th of the month, a finance charge of 1.75% which is an annual percentage rate of 21%, or a minimum charge of \$1.00 will be added to the unpaid balance at that time.

SEND REMITTANCE TO:

J.J. NICHTING COMPANY

REPAIR ORDER

1342 Pilot Grove Rd.
Pilot Grove, IA 52648
Phone: 319-469-4461
Fax: 319-469-4703

FARMALL COUNTRY SINCE 1920



www.jjnichting.com

SHIP TO

707 East Winfield Ave.
Mt. Pleasant, IA 52641
Phone: 319-385-3314
Fax: 319-385-2710

21582 HWY 92 East
Sigourney, IA 52591-0225
Phone: 641-622-3440
Fax: 641-622-1050

SOLD TO
46174 JIM L STAFFORD
17803 40TH AVE
BURLINGTON, IA 52601

CIH 1640 SN: JJC0034911 HR 4053.0 W:01
Sold By: 50 PO #: 1640 17-18 CMI Date 7/09/18 WORK ORDER WP05638
Ship By: Tax #: 2018 8:47:37 PRT: 13

Tax	D	Qty	Description	Price	Amount
10 Check into why the coolant light and alarm keeps going off.					
Customer says he already has a new sensor.					
CORRECTION					
Checked into why the coolant light keeps coming on. Found the coolant slightly low. Couldn't find any external leaks so I pressure tested the system. System holds pressure. Topped off with anti-freeze and ran the combine. All ok.					
SHOP LABOR		Total Hours:		1.81	
		** TOTAL SHOP LABOR			171.95
PARTS SHOP		ANTIFREEZE B03-END		14.75	14.75
07000		1	CAS B30204		
				* SEGMENT SUBTOTAL	186.70

No returns without this invoice. No returns after 30 days. No returns on special orders, No returns on parts not in original package. 20% Handling charge on returned parts after 14 days. The selling dealer makes no warranty of any kind whatsoever as the merchantability of the products listed heron or as to their fitness for any particular purpose any warranty which may exist is an agreement solely between the manufacturer and the purchaser. ALL PURCHASES MADE DURING THE MONTH ARE DUE ON THE 30th OF THE MONTH FOLLOWING RECEIPT OF YOUR STATEMENT. If not paid by the 30th of the month, a finance charge of 1.75% which is an annual percentage rate of 21%, or a minimum charge of \$1.00 will be added to the unpaid balance at that time.

SEND REMITTANCE TO:

J.J. NICHTING COMPANY

REPAIR ORDER

1342 Pilot Grove Rd.
Pilot Grove, IA 52648
Phone: 319-469-4461
Fax: 319-469-4703

FARMALL COUNTRY SINCE 1920

707 East Winfield Ave.
Mt. Pleasant, IA 52641
Phone: 319-385-3314
Fax: 319-385-2710



www.jjnichting.com

SHIP TO

21582 HWY 92 East
Sigourney, IA 52591-0225
Phone: 641-622-3440
Fax: 641-622-1050

SOLD TO
46174 JIM L STAFFORD
17803 40TH AVE
BURLINGTON, IA 52601

CIH 1640 SN: JJC0034911 HR 4053.0 W:01
Sold By: 50 PO #: 1640 17-18 CMI Date 7/09/18 WORK ORDER WP05638
Ship By: Tax #: 2018 8:47:37 PRT: 13

Tax	D	Qty	Description	Price	Amount
-----	---	-----	-------------	-------	--------

11 Grease the axle couplers.

Repair the leaking hydraulic hose going through the t-axle.
Repair the leak on the bottom of the hydro pump.
Repair the leaking hose going to the Vittitoe spreader.
Repair the leak on the hydraulic reservoir hoses.
Repair the leak on the auxiliary pump. Call customer with a price on a Reman/New pump.

CORRECTION

Repair the leaking hydraulic hose through the T-Axle.
Split the hoses where they connect and checked the flair sealing surfaces. They look fine. Cleaned the surfaces and put it back together. cleaned it up and ran it. No leaks.
Repair leak on bottom of hydro pump.
Cleaned off the pump and ran the combine. Found the o-ring on the fitting was deteriorated. Replaced the o-ring and installed the fitting. Filled with hytran and ran. All ok.
Repair the leak going to the Vittitoe spreader.
Found the hoses were deteriorated and leaking. Removed the hoses and had new ones made. Installed new hoses and ran the combine. All ok.
Repair the leak on the hydraulic reservoir.
Cleaned off the reservoir and tightened the hose clamps. All ok.
Repair the leak on the auxiliary hydraulic pump.
Cleaned off the pump and ran the combine. Found the seal on the pump was leaking. Checked to see if we could replace the seal. The pump is non-serviceable. Got a new pump and installed it. Filled with hytran and ran the combine. All ok.

SHOP LABOR	Total Hours:	9.87		
	** TOTAL SHOP LABOR			937.65
PARTS SHOP				
07000	1 CAS 132096A1	GREASE TUB	A04-END	4.30 4.30
00000	1 CAS 1272258C92R	REMAN-HYD	X	535.00 535.00
00000	1 CAS 1272258C92C	CORE		100.00 100.00
00000	1 CAS 185818C1	PIVOT/LH #	C06-4G	15.00 15.00
00000	2 TRN 247780	3/8" NC WH	C18-7A	.30 .60

No returns without this invoice. No returns after 30 days. No returns on special orders, No returns on parts not in original package. 20% Handling charge on returned parts after 14 days. The selling dealer makes no warranty of any kind whatsoever as the merchantability of the products listed hereon or as to their fitness for any particular purpose any warranty which may exist is an agreement solely between the manufacturer and the purchaser. ALL PURCHASES MADE DURING THE MONTH ARE DUE ON THE 30th OF THE MONTH FOLLOWING RECEIPT OF YOUR STATEMENT. If not paid by the 30th of the month, a finance charge of 1.75% which is an annual percentage rate of 21%, or a minimum charge of \$1.00 will be added to the unpaid balance at that time.

PAY THIS AMOUNT



SEND REMITTANCE TO:

J.J. NICHTING COMPANY

REPAIR ORDER

1342 Pilot Grove Rd.
Pilot Grove, IA 52648
Phone: 319-469-4461
Fax: 319-469-4703

FARMALL COUNTRY SINCE 1920

707 East Winfield Ave.
Mt. Pleasant, IA 52641
Phone: 319-385-3314
Fax: 319-385-2710



www.jjnichting.com

SHIP TO

21582 HWY 92 East
Sigourney, IA 52591-0225
Phone: 641-622-3440
Fax: 641-622-1050

SOLD TO
46174 JIM L STAFFORD
17803 40TH AVE
BURLINGTON, IA 52601

CIH 1640 SN: JJC0034911 HR 4053 0 W:01
Sold By: 50 PO #: 1640 17-18 CMI Date 7/09/18 WORK ORDER WP05638
Ship By: Tax #: 2018 8:47:37 PRT: 13

Tax	D	Qty	Description		Price	Amount
00000		2	CAS 139727A1	3/8 X 1" W C18-9A	6.00	12.00
00000		1	PED 08U-M08	FITTING D18-8F	23.24	23.24
00000		1	PED 08U-M08	FITTING D18-8F	23.24	23.24
00000		1	CAS WH08U108	FITTING - D18-2G	8.74	8.74
00000		7	CAS B94996	1/2" 2 WIR D18	5.78	40.46
00000		1	CAS 167268	O-RING C17S-15F	1.20	1.20
00000		8	CAS B94996	1/2" 2 WIR D18	5.78	46.24
07000		16	CAS HYTRAN	OIL / QUAR SHOP	3.76	60.16
07000		2	CAS HYTRAN	OIL / QUAR SHOP	3.76	7.52
00000		1	CAS 1272258C92C	PUMP CORE X	100.00	-100.00
** TOTAL PARTS SHOP						777.70
* SEGMENT SUBTOTAL						1715.35

12 Customer will take care of the following repairs.

- Cab filters need to be replaced.
- Concave Adjuster is free spinning.
- Service the engine.
- Change inner and outer air filters.
- Missing tail pipe rain cap.
- Replace coolant filter.
- Brake fluid is low.
- Needs engine oil changed.

* SEGMENT SUBTOTAL

No returns without this invoice. No returns after 30 days. No returns on special orders, No returns on parts not in original package. 20% Handling charge on returned parts after 14 days. The selling dealer makes no warranty of any kind whatsoever as the merchantability of the products listed hereon or as to their fitness for any particular purpose any warranty which may exist is an agreement solely between the manufacturer and the purchaser. ALL PURCHASES MADE DURING THE MONTH ARE DUE ON THE 30th OF THE MONTH FOLLOWING RECEIPT OF YOUR STATEMENT. If not paid by the 30th of the month, a finance charge of 1.75% which is an annual percentage rate of 21%, or a minimum charge of \$1.00 will be added to the unpaid balance at that time.

SEND REMITTANCE TO:

J.J. NICHTING COMPANY

REPAIR ORDER

1342 Pilot Grove Rd.
Pilot Grove, IA 52648
Phone: 319-469-4461
Fax: 319-469-4703

FARMALL COUNTRY SINCE 1920



www.jjnichting.com

SHIP TO

707 East Winfield Ave.
Mt. Pleasant, IA 52641
Phone: 319-385-3314
Fax: 319-385-2710

21582 HWY 92 East
Sigourney, IA 52591-0225
Phone: 641-622-3440
Fax: 641-622-1050

SOLD TO
46174 JIM L STAFFORD
17803 40TH AVE
BURLINGTON, IA 52601

CIH 1640 SN: JJC0034911 HR 4053.0 W:01
Sold By: 50 PO #: 1640 17-18 CMI Date 7/09/18 WORK ORDER WP05638
Ship By: Tax #: 2018 8:47:37 PRT: 13

Tax	D	Qty	Description	Price	Amount	
13 Fix lights.						
Install two new batteries.						
SHOP LABOR		Total Hours: 1.14				
				** TOTAL SHOP LABOR	108.30	
PARTS SHOP						
00000	2	CAS	BMF31GSW	BATTERY RACK-1D	133.00 266.00	
00000	2	CAS	SCR3	CORE	27.00 54.00	
00000	2	CAS	SCR3	CORE CORES	27.00 -54.00	
07000	2	PRM	W10077	11OZ CLEAN C02-NORT	3.46 6.92	
00000	1	CAS	WH08U108	FITTING - D18-2G	8.74 8.74	
				** TOTAL PARTS SHOP	281.66	
SHOP SUPPLIES						
07000*	SHOP SUPPLIES					41.62
				* SEGMENT SUBTOTAL	431.58	

No returns without this invoice. No returns after 30 days. No returns on special orders, No returns on parts not in original package. 20% Handling charge on returned parts after 14 days. The selling dealer makes no warranty of any kind whatsoever as the merchantability of the products listed heron or as to their fitness for any particular purpose any warranty which may exist is an agreement solely between the manufacturer and the purchaser. ALL PURCHASES MADE DURING THE MONTH ARE DUE ON THE 30th OF THE MONTH FOLLOWING RECEIPT OF YOUR STATEMENT. If not paid by the 30th of the month, a finance charge of 1.75% which is an annual percentage rate of 21%, or a minimum charge of \$1.00 will be added to the unpaid balance at that time.

** SUBTOTAL 6373.76
** SALES TAX 300.81

Charge Sale

Phone: (319) 750-1950
Page 10 Last Page

PAY THIS AMOUNT

\$6674.57