

WELLMAN AUTOMOTIVE

207 7th Ave PO Box 436

Wellman, IA 52356

Phone: 319-646-8860 Fax: 319-646-8860

YOUR FULL SERVICE CENTER
INVOICE
22561

Org. Est # 035020

INVOICE

Print Date: 09/14/2015

PSI Precision Structures Inc. - Chris Harmsen

PO Box 29

Wellman, IA 52356

Office : 319-646-2430 Cellular : 319-530-2718 Chris

Cust ID : 6

2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (442

Lic # : 40 - IA

Odometer In : 220734

VIN # : 1FDWX37F3 1ED61014

| Part Description / Number | Qty | Sale | Ext | Labor Description | Extended |
|-------------------------------------|-------|----------|----------|--|----------|
| OIL 15w40 | 16.00 | 3.12 | 49.92 | - | 0.00 |
| OIL FILTER | 1.00 | 26.15 | 26.15 | **** Symptoms: **** CHECK NO START SERVICED VEHICLE | 32.63 |
| Fuel Tank F84A | 1.00 | 1,046.22 | 1,046.22 | - | |
| FUEL SENDING UNIT XC3Z9275AC | 1.00 | 595.07 | 595.07 | FUEL TANK - Remove & Replace - Rear,Mount - [Includes: Drain and refill] replaced fuel lifter assembly | 195.75 |
| FUEL LIFTER ASSEMBLY F81Z9C407AC | 1.00 | 622.03 | 622.03 | | |
| Fuel Filter (Gold) 3818 | 1.00 | 55.31 | 55.31 | | |
| Air Filter (Gold) 6728 | 1.00 | 49.58 | 49.58 | | |
| Shop Supplies | | | 39.73 | | |

Org. Estimate 2,902.26 Revisions 0.00 Current Estimate 2,902.26

| | |
|----------|------------|
| Labor: | 228.38 |
| Parts: | 2,484.01 |
| Sub: | 2,712.39 |
| Tax: | 189.87 |
| Total: | 2,902.26 |
| Bal Due: | \$2,902.26 |

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____

Date _____ Time _____

Written By: Slaubaugh, Scott - Technicians : Please Select, Technician, Staley, Lawre

WELLMAN AUTOMOTIVE

207 7th Ave PO Box 436

Wellman, IA. 52356

Phone: 319-646-8860 Fax: 319-646-8860

YOUR FULL SERVICE CENTER

INVOICE

22855

Org. Est. # 035297

INVOICE

Print Date: 10/05/2015

PSI Precision Structures Inc. - Chris Hammen

PO Box 29

Wellman, IA 52356

Office : 319-646-2430 Cellular : 319-530-2718 Chris

Cust ID : 6

2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (44

Lic #: 40 - IA

Odometer In : 221054

VIN #: 1FDWX37F3 1E:D61014

| Part Description / Number | Qty | Sale | Ext | Labor Description | Extended |
|--|------|--------|--------|---|----------|
| Brake Rotor Only - Rear - Premium 4886824 | 2.00 | 76.67 | 153.34 | REPLACED RIGHT REAR AXLE SEAL AND HAD TO INSTALL AXLE SLEEVE BECAUSE THE AXLE HAD BEEN FIXED PREVIOUSLY; REPLACED REAR PADS AND ROTORS AND RIGHT REAR CALIPER; FIXED MARKER LAMPS AND TAIL LIGHTS | 358.88 |
| Brake Caliper w/ Hardware - Right Rear (Eclipse Semi-Loaded) - Remfd SE53034 | 1.00 | 111.10 | 111.10 | | |
| Brake Pads - Rear, Ultra Premium - OE Semi-Metallic UP7626M | 1.00 | 95.13 | 95.13 | | |
| REAR AXLE SEALS BRS179 | 2.00 | 21.56 | 43.12 | | |
| RIGHT REAR AXLE SLEEVES 99287 | 2.00 | 58.16 | 116.32 | | |
| MARKER LAMPS 6050 | 2.00 | 24.32 | 48.64 | | |
| LED TAIL LIGHTS 6060C | 2.00 | 53.53 | 107.06 | | |
| Shop Supplies | | | 39.73 | | |

Org. Estimate 1 148.45 Revisions 0 00 Current Estimate 1,148.45

| | |
|----------|------------|
| Labor: | 358.88 |
| Parts: | 714.44 |
| Sub: | 1,073.32 |
| Tax: | 75.13 |
| Total: | 1,148.45 |
| Bal Due: | \$1,148.45 |

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____ Time _____

Written By: Slaubaugh, Scott - Technicians Please Select Technician: Staley, Lawrence

Page 1 of 1

Copyright (c) 2015 Mitchell Repair Information Company, LLC invhrs 08.21.14JD

WELLMAN AUTOMOTIVE

207 7th Ave PO Box 436

Wellman, IA 52356

Phone: 319-646-8860 Fax: 319-646-8860

YOUR FULL SERVICE CENTER**INVOICE****23332**

Org. Est. # 035434

INVOICE

Print Date: 12/03/2015

PSI Precision Structures Inc. - Chris Harmsen

PO Box 29

Wellman, IA 52356

Office : 319-646-2430 Cellular : 319-530-2718 Chris

Cust ID : 6

2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (444

Lic # : 40 - IA

Odometer In : 222116

VIN # : 1FDWX37F3 1ED61014

| Part Description / Number | Qty | Sale | Ext | Labor Description | Extended |
|---|-------|---------|----------|---|----------|
| FAN CLUTCH AU2Z8A616L | 1.00 | 353.07 | 353.07 | ORDER; FAN CLUTCH; SWAY BAR BUSHINGS AND LINKS; ACCELERATOR PEDAL | |
| SWAY BAR BUSHINGS 2C3Z5484AA | 2.00 | 20.32 | 40.64 | FAN CLUTCH - Remove & Replace - Diesel, 7.3L Eng | 64.60 |
| SWAY BAR LINK 1C2Z5K483BB | 1.00 | 113.35 | 113.35 | STABILIZER BAR CONTROL LINK - Remove & Replace - Both | 65.25 |
| SWAY BAR LINK 1C3Z5K483BA | 1.00 | 117.52 | 117.52 | REPLACED BATTERIES | |
| MAP SENSOR F8UZ9F479BA | 1.00 | 130.16 | 130.16 | ADJUSTABLE ACCELERATOR PEDAL ASSEMBLY - Remove & Replace - F350 Super Duty | 32.63 |
| TRAILER PLUG IN FOR ENCLOSED TRAILER--ONE OF THE GUYS STOPPED IN ON 11-2-15 755-1760 | 1.00 | 25.32 | 25.32 | REPLACED INJECTORS | 352.35 |
| Battery 7565 | 1.00 | 110.28 | 110.28 | | |
| BRACKET FOR ACCEL PEDAL 5c3z9c803aa | 1.00 | 50.61 | 50.61 | | |
| ACCELERATOR PEDAL EC3Z9F836A | 1.00 | 265.23 | 265.23 | | |
| INJECTORS 5C3Z9VE527BRM 5C3Z9VE527ARM | 8.00 | 379.673 | 3,037.36 | | |
| BBB Industries / New Starter N6669 | 1.00 | 255.98 | 255.98 | | |
| BATTERY 8465 | 1.00 | 102.09 | 102.09 | | |
| Valve Cover Gasket w/ Harness 6003500 | 1.00 | 116.16 | 116.16 | | |
| OIL 15W/40 | 16.00 | 3.12 | 49.92 | | |
| OIL FILTER | 1.00 | 26.15 | 26.15 | | |
| Shop Supplies | | | 39.73 | | |

PSI Precision Structures Inc. - Chris Harmsen

PO Box 29

Wellman, IA 52356

Office : 319-646-2430 Cellular : 319-530-2718 Chris

Cust ID : 6

2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (442

Lic # : 40 - IA

Odometer In : 222116

VIN # : 1FDWX37F3 1ED61014

| Part Description / Number | Qty | Sale | Ext | Labor Description | Extended |
|---------------------------|-----|------|-----|-------------------|----------|
|---------------------------|-----|------|-----|-------------------|----------|

| | | | |
|--|--------------------|---------------------------|---------------------|
| Org. Estimate 1,306.27 | Revisions 3,976.03 | Current Estimate 5,282.30 | Labor: 514.83 |
| Revision # 1 Previous Estimate Amount: 1306.27, Additional Cost: 306.53, Revised Estimate: 1612.80, Parts: \$265.23 Labor: \$0.00 Sublet: \$0.00 Taxes & Fees: \$413.000 Authorized by - Harmsen, Chris, Date - 1/11/2015, Time - 11:24 AM, Initiated By - Shop, Phone Number - Cellular: 319-530-2718xChris | | | Parts: 4,833.57 |
| Revision # 2 Previous Estimate Amount: 1624.97, Additional Cost: 3669.50, Revised Estimate: 5294.47, Parts: \$3037.36 Labor: \$352.35 Sublet: \$0.00 Taxes & Fees: \$275.7900 Authorized by - Harmsen, Chris, Date - 1/23/2015, Time - 12:49 PM, Initiated By - Shop, Phone Number - Cellular: 319-530-2718xChris | | | Sub: 5,348.40 |
| | | | Tax: 374.39 |
| | | | Total: 5,722.79 |
| | | | Bal Due: \$5,722.79 |

Payments - 1

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____

Date _____

Time _____

Written By: Siaubaugh, Scott - Technicians : Please Select, Technician: Staley, Lawrence

WELLMAN AUTOMOTIVE

207 7th Ave PO Box 436
 Wellman, IA. 52356
 Phone: 319-646-8860 Fax: 319-646-8860
 YOUR FULL SERVICE CENTER

INVOICE**25065**

Org. Est. # 037509

INVOICEVehicle Received: **09/12/2016**Invoice Date: **09/12/2016****PSI Precision Structures Inc. - Chris Harmsen**

PO Box 29

Wellman, IA 52356

Office : 319-646-2430 Cellular : 319-530-2718 Chris

Cust ID : 6

2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (442

Lic # : 40 - IA

Odometer In : 230067

VIN # : 1FDWX37F3 1ED61014

| Part Description / Number | Qty | Sale | Ext | Labor Description | Extended |
|--|------|--------|--------|--|----------|
| Radiator 2768 | 1.00 | 250.47 | 250.47 | RADIATOR - Remove & Replace - Diesel, 7.3L Eng | 208.80 |
| Hose - Radiator Upper 9175 | 1.00 | 23.11 | 23.11 | REPLACED WATER PUMP AND TEMPATURE SENDING UNIT | |
| Water Pump - New 43546 | 1.00 | 190.32 | 190.32 | | |
| TOWING FROM WASHINGTON; (MOORES BP) TOWING | 1.00 | 225.00 | 225.00 | | |
| Coolant Temp Sensor F65Z10884AA | 1.00 | 84.50 | 84.50 | | |
| Water Outlet / Engine Coolant Water Outlet 85190 | 1.00 | 43.86 | 43.86 | | |
| Shop Supplies | | | 39.73 | | |

Org. Estimate 1,140.40 Revisions 0.00 Current Estimate 1,140.40

| | |
|------------------|-------------------|
| Labor: | 208.80 |
| Parts: | 856.99 |
| SubTotal: | 1,065.79 |
| Tax: | 74.61 |
| Total: | 1,140.40 |
| Bal Due: | \$1,140.40 |

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on public street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____

Date _____

Time _____

Written By: Slaubaugh, Scott - Technicians : Please Select, Technician, Lana, Cody

Page 1 of 1

Copyright (c) 2016 Mitchell Repair Information Company, LLC invtrs 7 2 15d

WELLMAN AUTOMOTIVE

207 7th Ave PO Box 436

Wellman, IA. 52356

Phone: 319-646-8860 Fax: 319-646-8860

YOUR FULL SERVICE CENTER

INVOICE**25260**

Org. Est. # 037713

INVOICEVehicle Received: **10/13/2016**Invoice Date: **10/13/2016****PSI Precision Structures Inc. - Chris Harmsen**

PO Box 29

Wellman, IA 52356

Office : 319-646-2430 Cellular : 319-530-2718 Chris

Cust ID : 6

2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (442

Lic # : 40 - IA

Odometer In : 231696

VIN # : 1FDWX37F3 1ED61014

| Part Description / Number | Qty | Sale | Ext | Labor Description | Extended |
|--|-------|--------|--------|---|----------|
| Shock - Gas Grande Fleet - Front 76686 | 2.00 | 82.04 | 164.08 | - | n/c |
| DYNA PRO HANKOOK HT RH12 Size: 235/85R16 235/85r16 | 2.00 | 141.74 | 283.48 | **** Symptoms: **** front end wobble MOUNT AND BALANCE | 30.00 |
| VALVE STEMS - | 2.00 | 2.35 | 4.70 | RIGHT FRONT AXLE UJOINT - Remove & Install or Remove & Replace - One Side - [DOES NOT include alignment.] | 195.75 |
| TIRE DISPOSAL FEE - | 2.00 | 2.00 | 4.00 | REPLACED RIGHT FRONT HUB LOCKOUT (Combination) - UNIVERSAL JOINT - Remove & Replace Each | 28.71 |
| Axle Shaft Seal - Outer - Front Axle 28603 | 1.00 | 90.52 | 90.52 | REPLACE ENGINE OIL AND FILTER, PERFORM COURTESY CHECKS AND FILL WINDSHEILD WASHEF TANK | 32.63 |
| U-Joint - Front Axle Shaft - Right Outer UJ374 | 1.00 | 57.33 | 57.33 | LABOR TO PERFORM 7.5K SERVICE ALIGNMENT | 40.00 |
| LEFT FRONT HUB/LOCKOUT 1C3Z3B396CB | 1.00 | 315.25 | 315.25 | - | |
| PREMIUM OIL FILTER 84312 | 1.00 | 26.15 | 26.15 | - | |
| 15W40 CHEVRON ENGINE OIL 15W40 | 16.00 | 3.15 | 50.40 | - | |
| Air Filter (Gold) 6728 | 1.00 | 34.27 | 34.27 | - | |
| Shop Supplies | | | 39.73 | - | |

Org. Estimate 1,494.79 Revisions 0.00 Current Estimate 1,494.79

| | |
|------------------|-------------------|
| Labor: | 327.09 |
| Parts: | 1,069.91 |
| SubTotal: | 1,397.00 |
| Tax: | 97.79 |
| Total: | 1,494.79 |
| Bal Due: | \$1,494.79 |

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____ Time _____

Written By: Slaubaugh, Scott - Technicians : Please Select, Technician; Tourres, Tim

Page 1 of 1

Copyright (c) 2016 Mitchell Repair Information Company, LLC invhrs 7.2.15d

WELLMAN AUTOMOTIVE

207 7th Ave PO Box 436

Wellman, IA. 52356

Phone: 319-646-8860 Fax: 319-646-8860

YOUR FULL SERVICE CENTER

INVOICE

25817

Ord Est #

INVOICE

 Vehicle Received: **01/19/2017**

 Invoice Date **01/19/2017**

PSI Precision Structures Inc. - Chris Harmsen

PO Box 29

Wellman IA 52356

Office 319 646 2430 Cellular 319-530-2718 Chris

Card ID 6

2001 Ford - Cab & Chassis F350 Super Duty 7.3L V8

Lic #: 40 - IA

Odometer In

VIN #: 1FDWX37F3 1ED61014

233648

| Part Description / Number | Qty | Sale | Ext | Labor Description | Extend. |
|--|------|--------|--------|--|---------|
| GASKET OIL LEAK F1T76A636A | 1.00 | 20.46 | 20.46 | OIL LEAK CHECK FOR OTHER FLUID LEAKS **** Symptoms: **** | |
| GASKET OIL LEAK F1T76A636AAA | 1.00 | 30.88 | 30.88 | NEED TO DO D.O.T. INSPECTION!! | |
| WATER PUMP OIL LEAK 1C3Z6C610BA | 2.00 | 5.58 | 11.16 | D.O.T. INSPECTED | |
| WATER PUMP OIL LEAK 1C3Z6K649BA | 2.00 | 12.66 | 25.32 | REPLACED MARKER LIGHT; ADJUSTED PARKING BRAKE CABLES | |
| VALVE ASSEMBLY F81Z9A153AA | 1.00 | 63.26 | 63.26 | NEEDS LEFT SIDE EXHAUST MANIFOLD AND GASKET AND BOLTS AND BOLTS FROM THE MANIFOLD TO THE PIPE coolant leak | |
| Heater Hose Connector - Universal 6601673 | 1.00 | 6.31 | 6.31 | replaced heater hose T fuel leak | |
| Oil Filter (Gold) 1734 | 1.00 | 25.96 | 25.96 | replaced fuel filter housing drain | |
| FLAREANCE LIGHT 1211AD | 1.00 | 6.08 | 6.08 | ENGINE OIL COOLER - Remove & Replace - Diesel | |
| GR 15W40 | 3.00 | 3.12 | 9.36 | replaced the gaskets for the oil cooler EXHAUST MANIFOLD - Remove & Replace - Diesel 7.3L V8 Eng Left | |
| COOLANT | 5.00 | 10.00 | 50.00 | had to replace broken bolts to replace the exhaust manifold | |
| Brake Hose - Right Front 381187 | 1.00 | 39.37 | 39.37 | | |
| LEFT EXHAUST MANIFOLD F81Z9431AA | 1.00 | 284.32 | 284.32 | | |
| EXHAUST MANIFOLD BOLTS F4TZ9S425A | 8.00 | 3.83 | 30.64 | | |
| NUTS AND BOLTS W300013&W300050 | 4.00 | 6.00 | 24.00 | | |
| Shop Supplies | | | 39.73 | | |

WELLMAN AUTOMOTIVE

207 7th Ave PO Box 436

Wellman, IA. 52356

Phone: 319-646-8860 Fax: 319-646-8860

YOUR FULL SERVICE CENTER

INVOICE

25817

Ord Est #00000

INVOICEVehicle Received: **01/19/2017**Invoice Date **01/19/2017****PSI Precision Structures Inc. - Chris Harmsen**

PO Box 29

Wellman IA 52356

Office 319-646-2430 Cellular 319-530-2718 Chris

Cust ID : 6

2001 Ford - Cab & Chassis F350 Super Duty / 3L V8

Lic #: 40 - IA

Odometer in 10000

VIN #: 1FDWX37F3 1ED61014

| Part Description / Number | Qty | Sale | Ext | Labor Description | Extended |
|---------------------------|-----|------|-----|-------------------|----------|
|---------------------------|-----|------|-----|-------------------|----------|

Org Estimate 1,421.48 Revisions 0.00 Current Estimate 1,421.48

Labor: 661.80

Parts: 666.80

SubTotal: 1,328.40

Tax: 92.97

Total: 1,421.48

Bal Due: \$1,421.48

Payments - 1

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____

Date _____

Time _____

WELLMAN AUTOMOTIVE

207 7th Ave PO Box 436

Wellman, IA. 52356

Phone: 319-646-8860 Fax: 319-646-8860

YOUR FULL SERVICE CENTER

INVOICE**26556**

Org. Est. # 039086

INVOICE

Date: 07/13/2017

PSI PRECISION STRUCTURES INC - CHRIS HARMSSEN #6 2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (444CI)
 PO BOX 29 Lic # :40 - IA Odometer In : 236869
 Wellman, IA 52356
 Office : 319-646-2430 Cellular : 319-530-2718 Chris VIN# : 1FDWX37F3 1ED61014

| Part Description / Number | Qty | Sale | Ext | Labor Description | Ex |
|------------------------------------|-------|--------|--------|--|-------|
| Towing Mileage TM | 52.00 | 4.00 | 208.00 | Hook up | 75.00 |
| BACK PRESSURE SENSOR 4C3Z9J460A | 1.00 | 113.68 | 113.68 | REPLACED FUEL FILTER | 65.25 |
| BATTERIES 65CP | 2.00 | 130.32 | 260.64 | Diagnose No Start/Hard Start Symptoms: Engines Crank OK but either is hard to start or will not start | 65.25 |
| Air Filter (Gold) 6728 | 1.00 | 35.00 | 35.00 | FIXED LEFT REAR TIRE ON TRUCK #24 ON 7/3/2017 | 15.00 |
| Fuel Filter (Gold) 3818 | 1.00 | 50.37 | 50.37 | REPLACE ENGINE OIL AND FILTER, PERFORM COURTESY CHECKS AND FILL WINDSHEILD WASHER TANK | 32.63 |
| PREMIUM OIL FILTER 84312 | 1.00 | 26.15 | 26.15 | LABOR TO PERFORM 7.5K SERVICE | |
| 15W40 CHEVRON ENGINE OIL 15W40 | 16.00 | 3.15 | 50.40 | BATTERY - Remove & Replace - Both - [Includes: Test.] | 52.20 |
| Shop Supplies | | | 39.73 | | |

Org. Estimate 357.11 Revisions 0.00 Current Estimate 357.11

Labor: 305.33

Parts: 783.97

SubTotal: 1,089.30

Tax: 76.25

Total: 1,165.55

Bal Due: \$1,165.55

[Payments -]

Vehicle Received: 6/24/2017

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____ Date _____ Time _____

WELLMAN AUTOMOTIVE

207 7th Ave PO Box 436

Wellman, IA. 52356

Phone: 319-646-8860 Fax: 319-646-8860

YOUR FULL SERVICE CENTER

INVOICE**26994****INVOICE**

Date: 09/15/2017

PSI PRECISION STRUCTURES INC - CHRIS HARMSSEN #6

PO BOX 29

Wellman, IA 52356

Office : 319-646-2430 Cellular : 319-530-2718 Chris

2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (444CI)

Lic # :40 - IA

Odometer In : 239076

VIN # :1FDWX37F3 1ED61014

| Part Description / Number | Qty | Sale | Ext | Labor Description | Ex |
|---|------|--------|--------|--|--------|
| STEERING GEAR STG60RM | 1.00 | 365.32 | 365.32 | TOWED FROM CASEYS | 25.00 |
| P/S HOSE / Power Steering Pressure Line Hose Assembly 80241 | 1.00 | 39.29 | 39.29 | STEERING GEAR - Remove, Install, and Overhaul - All Applicable Models - [Includes: Adjust toe-in on Rack and Pinion type Steering Gears. NOTE: Deduct .4 if alignment is also performed.] | 215.33 |
| Shop Supplies | | | 39.73 | | |

Org. Estimate 732.60 Revisions 0.00 Current Estimate 732.60

Labor: 240.33

Parts: 444.34

SubTotal: 684.67

Tax: 47.93

Total: 732.60

Bal Due: \$732.60

[Payments -]

Vehicle Received: 9/15/2017

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____

Date _____

Time _____

WELLMAN AUTOMOTIVE

207 7th Ave PO Box 436

Wellman, IA. 52356

Phone: 319-646-8860 Fax: 319-646-8860

YOUR FULL SERVICE CENTER

INVOICE**27836****INVOICE**

Date: 03/08/2018

PSI PRECISION STRUCTURES INC - CHRIS HARMSEN

PO BOX 29

Wellman, IA 52356

Office 319-646-2430 -- Cellular 319-530-2718 Chris

2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (444CI)

Lic #: 40

Odometer In : 242238

VIN#: 1FDWX37F3 1ED61014

| Part Description / Number | Qty | Sale | Ext | Labor Description | Ext |
|-----------------------------------|-------|--------|--------|---|--------|
| PREMIUM OIL FILTER 1734mp | 1.00 | 26.15 | 26.15 | DOT INSPECTION | 32.63 |
| Oil Filter - NAPA Gold 1734 | 0.00 | 20.75 | n/c | Fluid Capacity: Engine Oil - Volume: 17.00 QTS. (16.1L) - SAE 15W-40 Super Duty, 10W-30 Super Duty; Diesel - w/Filter - (Note: Use oil that has been certified by the American Petroleum Institute.) | |
| 15W40 CHEVRON ENGINE OIL 15W40 | 17.00 | 3.15 | 53.55 | REPLACE ENGINE OIL AND FILTER, PERFORM COURTESY CHECKS AND FILL WINDSHEILD WASHER TANK | 32.63 |
| Air Filter - NAPA Gold 6728 | 1.00 | 36.76 | 36.76 | LABOR TO PERFORM 7.5K SERVICE | |
| Ball Joint K80026 | 1.00 | 85.84 | 85.84 | TOE-IN - Adjustment - All Applicable Models | 43.07 |
| Ball Joint K8607T | 1.00 | 123.34 | 123.34 | BALL JOINT - Remove & Replace - 4WD One Side, Both - [DOES NOT include alignment.] | 193.79 |
| Tie Rod ES3427T | 1.00 | 102.90 | 102.90 | TIE ROD &/OR ENDS - Remove & Replace - Each Additional - [Includes: Adjust toe-in only. NOTE: Deduct .4 if alignment is also performed. | 21.53 |
| LAMP 60202R1 | 1.00 | 14.17 | 14.17 | NOTE: Manufacturer recommends removal of Rack and Pinion Steering Gear when replacing Inner Tie Rod End(s) on some mode | |
| Shop Supplies | | | 39.73 | | |

Org. Estimate 632.12 Revisions 0.00 Current Estimate 632.12

| | |
|-----------|----------|
| Labor: | 323.65 |
| Parts: | 482.44 |
| SubTotal: | 806.09 |
| Tax: | 56.43 |
| Total: | 862.52 |
| Bal Due: | \$862.52 |

[Payments -]

Vehicle Received: 3/8/2018

Customer Number : 6

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____

Date _____

Our Email Address: sschneider243@hotmail.com

WELLMAN AUTOMOTIVE

207 7th Ave PO Box 436

Wellman, IA. 52356

Phone: 319-646-8860 Fax: 319-646-8860

YOUR FULL SERVICE CENTER

INVOICE**28539****INVOICE**

Work Completed : 08/16/2018 Date: 08/16/2018

PSI PRECISION STRUCTURES INC - CHRIS HARMSSEN

PO BOX 29

Wellman, IA 52356

Office 319-646-2430 -- Cellular 319-530-2718 Chris

2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (444CI)

Lic # : 40

Odometer In : 247414

VIN# : 1FDWX37F3 1ED61014

| Part Description / Number | Qty | Sale | Ext | Labor Description | Ext |
|---|-------|--------|--------|---|--------|
| PREMIUM OIL FILTER 1734mp | 1.00 | 26.15 | 26.15 | CHECK BRAKES GRINDING | n/c |
| 15W40 CHEVRON ENGINE OIL 15W40 | 17.00 | 3.15 | 53.55 | DIAG AND REPAIR ACCELERATOR PEDAL ISSUE | n/c |
| Air Filter - NAPA Gold 6728 | 1.00 | 39.03 | 39.03 | Fluid Capacity: Engine Oil - Volume: 17.00 QTS. (16.1L) - SAE 15W-40 Super Duty, 10W-30 Super Duty; Diesel - w/Filter - (Note: Use oil that has been certified by the American Petroleum Institute.) | |
| Brake Pads - Rear - Fleet FT7626 | 1.00 | 80.52 | 80.52 | REPLACE ENGINE OIL AND FILTER, PERFORM COURTESY CHECKS AND FILL WINDSHIELD WASHER TANK | 32.63 |
| Brake Rotor (Rotor Only) - Rear - Premium 4886824 | 2.00 | 64.62 | 129.24 | LABOR TO PERFORM 7.5K SERVICE | |
| Brake Caliper with Hardware - Rear Left - (Eclipse Semi-Loaded) - Remanufactured SE5304A | 1.00 | 85.34 | 85.34 | PADS & DISC ROTOR - Remove & Replace - Rear,Both,Full Floating Axle,Inboard Mounted Rotor,Seperable,w/Dual Rear Wheels - [Includes: Repack Wheel Bearings (where applicable) and replace Pads (if necessary). DOES NOT include refinishing.] | 236.86 |
| Brake Pads - Front - Fleet FT7625 | 1.00 | 93.26 | 93.26 | CALIPER - Remove & Replace - Rear,One Side - [Includes: Bleed System and replace Pads (if necessary).] | 71.78 |
| Brake Rotor (Rotor Only) - Front - Premium 4886914 | 2.00 | 64.09 | 128.18 | PADS & DISC ROTOR - Remove & Replace - 4WD Front,Both - [Includes: Repack Wheel Bearings (where applicable) and replace Pads (if necessary). DOES NOT include refinishing.] | 143.55 |
| Brake Caliper Bracket - Front Left - Remanufactured N141580 | 1.00 | 37.60 | 37.60 | PARKING BRAKE CABLE - Remove & Replace - Rear,Both | 129.20 |
| PARKING BRAKE CABLE RR YC3Z2A635CA | 1.00 | 136.08 | 136.08 | PARKING BRAKE SHOE & LINING - Remove & Replace - Rear,Both Sides,Full Floating Axle,Inboard Mounted Rotor,w/Dual Rear Wheels - [Includes: Repack Wheel Bearings.] | 65.25 |
| PARKING BRAKE CABLE LR YC3Z2A635FA | 1.00 | 133.89 | 133.89 | ADJUSTABLE ACCELERATOR PEDAL ASSEMBLY - Remove & Replace - F350 Super Duty | 35.89 |
| Brake Backing Plate - Rear - Disc Brakes 8272435 | 1.00 | 163.00 | 163.00 | | |
| Parking Brake Shoes - Fleet FT10771PB | 1.00 | 119.12 | 119.12 | | |
| Parking Brake Shoe Hardware Kit 3034 | 1.00 | 27.29 | 27.29 | | |
| REAR AXLE SEALS 27SS3307 | 2.00 | 13.03 | 26.06 | | |
| ACC PEDAL EC3Z9F836A | 1.00 | 305.80 | 305.80 | | |
| ACC PEDAL BRACKET 5C3Z9C803AA | 1.00 | 64.85 | 64.85 | | |

[Recommendations]

RR spindle has been replaced (welded on) at some point. It was put on with the measurements wrong and now the rotor sits out too far causing the caliper mount to need spacers to clear the rotor. Is all working fine at this time. cl

Our Email Address: sschneider243@hotmail.com

WELLMAN AUTOMOTIVE

207 7th Ave PO Box 436

Wellman, IA. 52356

Phone: 319-646-8860 Fax: 319-646-8860

YOUR FULL SERVICE CENTER

INVOICE**28539****INVOICE**

Work Completed : 08/16/2018

Date: 08/16/2018

PSI PRECISION STRUCTURES INC - CHRIS HARMSSEN

PO BOX 29

Wellman, IA 52356

Office 319-646-2430 -- Cellular 319-530-2718 Chris

2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (444CI)

Lic # : 40

Odometer In : 247414

VIN# : 1FDWX37F3 1ED61014

| Part Description / Number | Qty | Sale | Ext | Labor Description | Ext |
|---------------------------|-----|------|-----|-------------------|-----|
|---------------------------|-----|------|-----|-------------------|-----|

*Logged by Marcus
on 8/23/2018*

Org. Estimate 129.81 Revisions 678.33 Current Estimate 808.14

Revision # 1, Previous Estimate Amount: 129.81, Additional Cost: 678.33, Revised Estimate: 808.14, Parts: \$594.22 Labor: \$0.00 Sublet: \$0.00 Taxes & Fees: \$84.11 Authorized by - HARMSSEN, CHRIS, Date - 8/2/2018, Time - 6:32 AM, Initiated By - Shop, Written By - Lana, Cody, Phone Number - Office: 319-646-2430

| | |
|-----------|------------|
| Labor: | 715.16 |
| Parts: | 1,648.96 |
| SubTotal: | 2,364.12 |
| Tax: | 165.49 |
| Total: | 2,529.61 |
| Bal Due: | \$2,529.61 |

[Payments -]

Vehicle Received: 8/16/2018

Customer Number : 6

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____

Date _____

Our Email Address: sschneider243@hotmail.com

WELLMAN AUTOMOTIVE

207 7th Ave PO Box 436

Wellman, IA. 52356

Phone: 319-646-8860 Fax: 319-646-8860

YOUR FULL SERVICE CENTER

INVOICE**29597**

Org. Est. # 042191

INVOICE

Date: 03/22/2019

PSI PRECISION STRUCTURES INC - CHRIS HARMSSEN

PO BOX 29

Wellman, IA 52356

Office 319-646-2430 -- Cellular 319-530-2718 Chris

2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (444CI)

Lic # : 40

Odometer In : 250116

VIN # : 1FDWX37F3 1ED61014

| Part Description / Number | Qty | Sale | Ext | Labor Description | Ext |
|---|-------|--------|--------|---|-------|
| TOW - FROM AINSWORTH TO WELLMAN TOW | 1.00 | 380.00 | 380.00 | CRANK NO START | 65.25 |
| Battery - NAPA Legend Professional 7565 | 2.00 | 137.95 | 275.90 | DOT INSPECTION | 32.63 |
| Fuel Injection Control Pressure Sensor Connector EC89 | 1.00 | 29.33 | 29.33 | BATTERY - Remove & Replace - Both - [Includes: Test.] | 52.20 |
| FUEL INJECTION CONTROL PRESSURE SENSOR SHOTT | 1.00 | 222.03 | 222.03 | INJECTION CONTROL PRESSURE SENSOR - Remove & Replace - All Applicable Models | 35.89 |
| FIX WINDSHIELD CHIP/CRACK SAFELIGHT | 1.00 | 78.44 | 78.44 | Fluid Capacity: Engine Oil - Volume: 17.00 QTS. (16.1L) - SAE 15W-40 Super Duty, 10W-30 Super Duty; Diesel - w/Filter - (Note: Use oil that has been certified by the American Petroleum Institute.) | |
| Wiper Blade - Exact Fit - Front 60201 | 2.00 | 9.99 | 19.98 | REPLACE ENGINE OIL AND FILTER, PERFORM COURTESY CHECKS AND FILL WINDSHEILD | 32.63 |
| PREMIUM OIL FILTER 1734mp | 1.00 | 29.01 | 29.01 | WASHER TANK | |
| 15W40 CHEVRON ENGINE OIL 15W40 | 17.00 | 4.04 | 68.68 | LABOR TO PERFORM 7.5K SERVICE | |
| | | | | OIL LEAK AT LEFT VALVE COVER AREA. MINOR SEEPAGE AROUND REAR PINION NUT | |

Logged by Marcus
on 4/9/19

[Recommendations]

RR spindle has been replaced (welded on) at some point. It was put on with the measurements wrong and now the rotor sits out too far causing the caliper mount to need spacers to clear the rotor. Is all working fine at this time. cl

Org. Estimate 1,415.92 Revisions 0.00 Current Estimate 1,415.92

| | |
|-----------|------------|
| Labor: | 218.60 |
| Parts: | 1,103.37 |
| SubTotal: | 1,321.97 |
| Tax: | 92.54 |
| Total: | 1,414.51 |
| Bal Due: | \$1,414.51 |

Customer Number : 6

[Payments -]

Vehicle Received: 3/20/2019

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____

Date _____

Our Email Address: sschneider243@hotmail.com