## **WELLMAN AUTOMOTIVE**

207 7th Ave PO Box 436

Wellman, IA, 52356

Phone: 319-646-8860 Fax: 319-646-5101

Lic#: 40

YOUR FULL SERVICE CENTER

INVOICE

32257

Org. Est. # 045082

## Invoice from History

Work Completed:

09/16/2020

Date: 09/22/2020

PSI PRECISION STRUCTURES INC - CHRIS HARMSEN **PO BOX 29** 

2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (444Cl) Odometer In: 253562

Wellman, IA 52356

Office 319-646-2430 -- 319-325-2431 MARCU

VIN # - 1FDWX37F3 1FD61044

0.0 020 240 1 M/4//OO				VIN #: 1FDWX37F3 1ED61014		
Part Description / Number	Qty	Sale	Ext	Labor Description	Ext	
Tow from Ainsworth location X	1.00	335.71	335.71	EXI		
Water Pump - New 43546	1.00	183.43	183.43	Check Engine Cooling System - Customer said coolant leak	23.89	
Air Filter - NAPA Gold 6728	1.00	29.90	29.90	Pressure test cooling system for leaks Pressure tested and found water pump leaking. CL		
Battery - NAPA Legend Professional 7565	2.00	153.53	307.06	WATER PUMP - Remove & Replace - Diesel DOT INSPECTION	165.17 34.13	
RR rear facing bed marker light (small round) 10202R	1.00	3.00	3.00	BATTERY - Remove & Replace - Both - [Includes: Test.]  Batteries were both completely discharged when truck arrived.  Bulging of batteries indicates that they have frozen at some poin appears that this vehicle has been sitting undriven for quite a whole		
ΓΙRE DISPOSAL <i>DISP</i>	4.00	2.50	10.00			
Hankook Dynapro AT2 235/85/16	4.00	158.00	632.00	MOUNT AND BALANCE	62.00	
Shop Supplies			39.73			

## [ Recommendations ]

RR spindle has been replaced (welded on) at some point. It was put on with the measurements wrong and now the rotor sits out too far causing the caliper mount to need spacers to clear the rotor. Is all working fine at this time. cl

AIR FILTER - 247414 CABIN AIR FILTER -FUEL FILTER - 236869 TRAN SERVICE -FRONT DIFF SERVICE - 231696 REAR DIFF SERVICE - 247414 TRANSFER CASE SERVICE -SPARK PLUGS -COOLANT SERVICE - 233648 DOT - 3/8/19

## **WELLMAN AUTOMOTIVE**

207 7th Ave PO Box 436

Wellman, IA. 52356

Phone: 319-646-8860 Fax: 319-646-5101

YOUR FULL SERVICE CENTER

INVOICE

32257 Org. Est. # 045082

Invoice from History

Work Completed:

09/16/2020

Date: 09/22/2020

**PO BOX 29** 

PSI PRECISION STRUCTURES INC - CHRIS HARMSEN

Lic#:40

2001 Ford - Cab & Chassis F350 Super Duty - 7.3L, V8 (444Cl) Odometer In: 253562

Wellman, IA 52356

Office 319-646-2430 - 319-325-2431 MARCU

VIN #: 1FDWX37F3 1ED61014

Part Description / Number

Qty

Sale

**Ext Labor Description** 

Ext

Org. Estimate 2,018.11 Revisions 0.00 Current Estimate 2.018.11		
Org. Estimate 2,018.11 Revisions 0.00 Current Estimate 2,018.11	Labor:	345.25
	Parts:	1,540.83
	SubTotal:	1,886.08
	Tax:	132.03
Payments - 1	Total:	2,018.11
Vehicle Received: 9/16/2020	Bal Due:	\$2,018.11
I hereby authorize the above repair work to be done along with the passages and bring the	Cust	omer Number : 6
I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged amount of repairs thereto. Warranty on new parts and labor is one years or 12,000 miles whichever comes first. There is no warranty on used gwarranty work has to be performed in our shop & cannot exceed the original cost of repair.	to operate the car or tru on above car or truck to earts or customer provid	uck herein secure the ed parts.

Email Address: wellmanauto@hotmail.com

Date

Signature