



455 West Broad Street | Story City, IA 50248 | 515-733-4921 | vanwall.com

Remittance Address:
PO Box 575
Perry, IA 50220

*** PROFORMA INVOICE ***

Deliver To:

SERVICE INVOICE

| | | |
|--|------------------------|------------|
| | Invoice Number: | |
| | Invoice Date | 02/10/2021 |
| | Location: | 11 |
| | Work Order Number: | 771347 |
| | Payment Type: | Account |
| | Page: | 1 of 5 |

| | | | | |
|-----------------|-------|----------------|---------|-----------|
| Make/Model: | Meter | Serial Number: | EQ Id: | Fleet No: |
| JOHN DEERE 6400 | 4927 | L06400M107156 | 207872W | |

/DYNO-T Retail

COMPLAINT:

01 TRACTOR IN FOR SERVICE SPECIAL --

CORRECTION:

CHECKED OPERATIONS OF TRANSMISSION, REAR AXLE BEARINGS, AND OPERATION OF BRAKES & STEERING. CHECKED FOR LEAKS. CHECKED ENGINE SPEEDS. CHECKED ENGINE OIL PRESSURE. CHECKED AIR INTAKE SYSTEM. TOOK OIL SAMPLE & SENT IN FOR RESULTS. SET ALL BELT TENSIONS. CHECKED WATER PUMP END PLAY. TESTED ANTI-FREEZE. CHECKED ALL LIGHTS AND ELECTRICAL FUNCTIONS IN THE CAB. CHECKED ALTERNATOR OUTPUT. CHECKED HYDRAULIC PRESSURE AT REAR OUTLETS PSI. CHECKED AIR CONDITIONING SYSTEM FOR COOLING.

| PartNumber | Description | Quantity | Net Price | Extended Price | Taxed Ind |
|-------------------------|-------------|----------|-------------------|-----------------|-----------|
| IPSKIT2 | SCAN TEST | 1.00 | 13.64 | \$13.64 | Y |
| Labor: \$285.60 | | | | | |
| Parts: \$13.64 | | | | | |
| OL&M: \$0.00 | | | | | |
| Misc: \$0.00 | | | | | |
| | | | Sub-Total: | \$299.24 | |

EXPERT-100000029520 Retail

COMPLAINT:

02 Engine Oil and Filter, Remove and Replace

CORRECTION:

Drain Engine Oil
Remove engine oil filter, clean filter base surface.
Pre-fill engine oil filter and install filter.
Install and Tighten Drain Plug
Fill with Approved Oil per OM
Operate engine then recheck oil level, top off as needed.

| PartNumber | Description | Quantity | Net Price | Extended Price | Taxed Ind |
|-------------------------|-------------|----------|-------------------|-----------------|-----------|
| T19044 | OIL FILTER | 1.00 | 6.59 | \$6.59 | Y |
| TY26682B | PLUS-50 II | 13.00 | 4.00 | \$52.00 | Y |
| Labor: \$210.00 | | | | | |
| Parts: \$58.59 | | | | | |
| OL&M: \$0.00 | | | | | |
| Misc: \$0.00 | | | | | |
| | | | Sub-Total: | \$268.59 | |

EXPERT-100000050907 Retail

COMPLAINT:

03 Starter Motor, Remove and Replace

CONTINUED ON NEXT PAGE->



455 West Broad Street | Story City, IA 50248 | 515-733-4921 | vanwall.com

Remittance Address:
PO Box 575
Perry, IA 50220

*** PROFORMA INVOICE ***

Deliver To:

SERVICE INVOICE

| | | | | | |
|-----------------|-------|----------------|---------|--|--|
| | | | | Invoice Number: Invoice Date: 02/10/2021 Location: 11 Work Order Number: 771347 Payment Type: Account Page: 3 of 5 | |
| Make/Model: | Meter | Serial Number: | EQ Id: | Fleet No: | |
| JOHN DEERE 6400 | 4927 | L06400M107156 | 207872W | | |

Loosen return line hose clamps, loosen and remove fitting from the cylinder block.
 Remove the hose and clamps, install new hose on the return line, slide on the new clamps.
 Install the fitting in the cylinder block and tighten, tighten the hose clamps once positioned.
 Start tractor and check for leaks

Labor: \$240.00 Parts: \$0.00 OL&M: \$0.00 Misc: \$0.00 Sub-Total: \$240.00

EXPERT-100000025891 Retail

COMPLAINT:

06 Fuel Filter Housing Line Leaking

CORRECTION:

Removed fuel filter housing to find the fuel line rubbed against the hood support causing a hole in the line, Removed muffler, removed fuel filter bracket and found a bolt broken off in the engine head, welded a nut onto the broken off bolt and removed bolt, installed new hard fuel line. reinstalled parts in reverse order and installed new bolt in the fuel filter bracket

| PartNumber | Description | Quantity | Net Price | Extended Price | Taxed Ind |
|--|----------------|----------|---------------------|----------------|-----------|
| 19H2284 | 3/8 X 7/8 BOLT | 1.00 | 0.76 | \$0.76 | Y |
| RE57269 | FUEL LINE | 1.00 | 78.99 | \$78.99 | Y |
| RE62419 | FUEL FILTE | 1.00 | 21.31 | \$21.31 | Y |
| Labor: \$360.00 Parts: \$101.06 OL&M: \$0.00 Misc: \$0.00 | | | Sub-Total: \$461.06 | | |

EXPERT-100000026431 Retail

COMPLAINT:

07 Warning lights

CORRECTION:

Replaced left front warning light and right rear light, diagnosed flasher issue to the relay and replaced the relay

| PartNumber | Description | Quantity | Net Price | Extended Price | Taxed Ind |
|------------|-------------------------|----------|-----------|----------------|-----------|
| AD2062R | BULB | 1.00 | 3.00 | \$3.00 | Y |
| AL76702 | RELAY | 1.00 | 12.00 | \$12.00 | Y |
| H133384 | BULB | 1.00 | 2.93 | \$2.93 | Y |
| TY22465 | HOSE CLAMP | 2.00 | 0.99 | \$1.98 | Y |
| TY22563 | 3/4" OIL RESISTANT HOSE | 1.00 | 0.43 | \$0.43 | Y |

CONTINUED ON NEXT PAGE->



455 West Broad Street | Story City, IA 50248 | 515-733-4921 | vanwall.com

Remittance Address:
PO Box 575
Perry, IA 50220

*** PROFORMA INVOICE ***

SERVICE INVOICE

| | | | |
|--|--|------------------------|------------|
| | | Invoice Number: | |
| | | Invoice Date | 02/10/2021 |
| | | Location: | 11 |
| | | Work Order Number: | 771347 |
| | | Payment Type: | Account |
| | | Page: | 5 of 5 |

| Make/Model: | Meter | Serial Number: | EQ Id: | Fleet No: |
|-----------------|-------|----------------|---------|-----------|
| JOHN DEERE 6400 | 4927 | L06400M107156 | 207872W | |

| | |
|-----------------|--------------|
| Customer PO No: | |
| Tax Exempt No: | |
| Advisor: | AARON BURREN |

| | |
|-------------------|-------------------|
| Labor: | \$1,983.60 |
| Parts: | \$774.73 |
| OL&M: | \$0.00 |
| Misc: | \$113.15 |
| Sales Tax: | \$201.01 |
| Total: | \$3,072.49 |

TERMS AND CONDITIONS

Van Wall Equipment assumes no responsibility for loss or damage by theft or fire to machines placed with us for storage, sale, repair, or while field testing.

Received by:

Date: