



1611 Highway 65 | Hampton, IA 50441 | 641-456-2534 | vanwall.com

Remittance Address:  
PO Box 575  
Perry, IA 50220

Invoice To Account No: 4

Deliver To:

## SERVICE INVOICE

<b>WARRANTY CUSTOMER</b> 22728 141ST DRIVE PERRY IA 50220  Bus Phone: 515-465-5681 Prv Phone:	Precision Manure Application Inc. 511 WASHINGTON AVE IOWA FALLS IA 50126  Bus Phone: (641)373-2886 Prv Phone:	<b>Invoice Number: 10288062</b> Invoice Date: 11/14/2020 Location: 30 Work Order Number: 538795 Payment Type: Account  Page: 1 of 2		
Make/Model: JOHN DEERE 8370R	Meter: 4072	Serial Number: 1RW8370RVFD105635	Eq ID: FD105635	Fleet No:

### Wty1 Warranty

#### COMPLAINT:

01 Complaint: 1. Transmission defaults to neutral and does not sound right.  
 Codes that occurred: TII 000581.07 PTI 190.02  
 Failed part number: RE584713  
 Cause: Major internal failure of transmission.  
 DTAC Case #:  
 DTAC Solutions:

#### CAUSE:

Some major components came apart internally in the transmission, causing the failure.

#### CORRECTION:

Diagnostics Performed: Drive tractor and check transmission operation. Transmission will speed up and slow down like it is not staying in gear. Tractor will also default to neutral and is throwing codes for ring gear speed mismatch PTI 190.02. Run pressure checks and found pressures were ok. Drain oil from transmission and remove sump screen. Found metal and chunks of gear teeth in the screen.

Repairs Performed: Run pressure checks and found pressures were ok. Drain oil from transmission and remove sump screen. Found metal and chunks of gear teeth in the screen. As tractor has powergard on it, talk with our TCSM (David Moline) and he said to order a reman for it. Order transmission. Drain all contaminated hydraulic oil from the tractor. Remove and replace transmission per book procedure. Install new wiring harness that came with transmission. Fill tractor with new hydraulic oil and replace filter. Run tractor to check transmission operation. Perform calibrations as needed and check for leaks - ok. Wash off machine where repairs were made.

Tech XID: X719995

#### Labor Breakdown:

Diagnostic: 1.25  
 Repair: 26.25  
 Clean up: 0.5  
 Clean work area.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7785	10 X 25 GRD8 FLT	1.00	1.10	1.10	\$1.10	N
F3171R	O-RING	2.00	2.42	2.42	\$4.84	N
P50631	O-RING	1.00	3.81	3.81	\$3.81	N
R122886	O-RING	1.00	4.69	4.69	\$4.69	N
R183409	O-RING	3.00	1.13	1.13	\$3.39	N



1611 Highway 65 | Hampton, IA 50441 | 641-456-2534 | vanwall.com

Remittance Address:  
PO Box 575  
Perry, IA 50220

Invoice To Account No: 4

Deliver To:

### SERVICE INVOICE

WARRANTY CUSTOMER 22728 141ST DRIVE PERRY IA 50220  Bus Phone: 515-465-5681 Prv Phone:	Precision Manure Application Inc. 511 WASHINGTON AVE IOWA FALLS IA 50126  Bus Phone: (641)373-2886 Prv Phone:	Invoice Number: <b>10288062</b> Invoice Date: 11/14/2020 Location: 30 Work Order Number: 538795 Payment Type: Account  Page: 2 of 2
---	--	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 8370R	4072	1RW8370RVFD105635	FD105635	

**Wty1 Warranty**

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
R183412	O-RING	1.00	1.72	1.72	\$1.72	N
R228278	GASKET	1.00	171.12	171.12	\$171.12	N
R529510	GASKET	2.00	22.01	22.01	\$44.02	N
R56465	O-RING	2.00	1.46	1.46	\$2.92	N
R61015	O-RING	1.00	3.03	3.03	\$3.03	N
RE573817	Filter Element	1.00	143.45	143.45	\$143.45	N
RE576834	RECEIVER-D	1.00	46.51	46.51	\$46.51	N
RM100075	Transmission Reman	1.00	39,026.90	39,026.90	\$39,026.90	N
RM100075-CR	CORE for:Transmission Reman	-1.00	3,000.00	3,000.00	(\$3,000.00)	N
TY22028B	HY-GARD	156.00	3.41	3.41	\$531.96	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
FREIGHT30	FREIGHT-LOC 30	1.00	35.00	35.00	\$35.00	N
WARRDEDU30	WARRANTY DEDUCTIBLE-LOC 30	1.00	0.00	-500.00	(\$500.00)	N

<b>Labor:</b> \$3,641.99	<b>Parts:</b> \$36,989.46	<b>OL&amp;M:</b> \$0.00	<b>Misc:</b> (\$465.00)	<b>Sub-Total:</b> \$40,166.45
--------------------------	---------------------------	-------------------------	-------------------------	-------------------------------

<b>Customer PO No:</b>	
<b>Tax Exempt No:</b>	ONFILE
<b>Advisor:</b>	KEN PUTZ

<b>Labor:</b>	\$3,641.99
<b>Parts:</b>	\$36,989.46
<b>OL&amp;M:</b>	\$0.00
<b>Misc:</b>	(\$465.00)
<b>Sales Tax:</b>	\$0.00
<b>Grand Total:</b>	<u>\$40,166.45</u>

\*\*\* DOCUMENT COPY \*\*\*

**TERMS AND CONDITIONS**

Van Wall Equipment assumes no responsibility for loss or damage by theft or fire to machines placed with us for storage, sale, repair, or while field testing.

Received by: ..... Date: .....