



Time of Transfer Inspection Report (DNR Form 542-0191)

Property information

Current owner MaryLyn Fincher
 Buyer _____ Realtor _____
 Mailing address 2771 210th St Fort Madison Ia
 Site Address/County 2771 210th St Fort Madison Ia
 Legal Description _____
 No. of bedrooms 3 Last occupied? Still Records available yes
 Permit/installation date Sept 14-1979 Separation distances ok/no? _____

Septic system information

Septic tank(s): size 2-600 material concrete condition decent
 Tank pumped? yes date Sept 13, 2021 licensed pumper ST-99
 Septic/trash/processing tank: size na material na condition na
 Tank pumped? no date na licensed pumper na
 Aerobic treatment unit (ATU) mfg none size na
 Tank pumped? no date na licensed pumper na
 Maintenance contract? no expiration date na service provider na
 Condition na
 Pump tanks/vaults: type na size na condition na
 Distribution system: distribution box no outlets used na condition na
 Header pipe(s) yes # of lines ? Pressure dosed? no

Secondary treatment:

length of absorption fields na determined by Report
 condition of fields na determined by Report
 type of trench material na
 Size of sand filter 2-12 x 30 determined by Report
 Vent pipes above grade? na discharge pipe located? yes
 Effluent sample taken? no Results na

Media filters: type na
 Maintenance contract? no expiration date na service provider na
 Condition na

NPDES General Permit No. 4: required? no permitted? yes NOI provided na



Time of Transfer Inspection Report

Other components:

Alarms no Working? no disinfection no working? no

Control box no Timers no inspection ports no

Other components none

Overall condition of the private sewage disposal system

Report system status is in working order to date!

Explain (attach additional pages as needed): _____

Comments: System checked out Fine to DATE!

Site status at conclusion of Time of Transfer inspection:

- Verify that controls are set on the appropriate mode.
- Power is on to all components.
- Revisit all components to verify lids are secure.
- Gather all tools for removal from the site.
- Verify that no sewage is on the ground surface.

Using this worksheet, write a narrative report of the inspection results and attach a site sketch.

This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.

Signature of Certified inspector: [Signature] Date: 9-14-2021
 Name (print): GLEN A MAYORS Certificate #: 8928
 Address: P.O. Box 488 Keokuk IA 52632
 Phone #: 319 524 7329

Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person ordering the inspection, the county sanitarian/environmental health office, and to;

Iowa DNR
 Private Sewage Disposal Program
 502 E. 9th St.
 Des Moines, IA 50319

Subject: Report
From: Glen Meyers <gl drivesetank@qwestoffice.net>
Date: 9/14/2021, 12:50 PM
To: Glen Meyers <gl drivesetank@qwestoffice.net>

9-14-2021

Meyers Septic Service

P.O. Box 488

Keokuk Iowa 52632

Septic Report: 2771 210 st Fort Madison Iowa

At time of inspection this system was put in per DNR codes per year installed. These type of dual stage sand filters are not used anymore but this system still working. Also tried to get a effluent sample but was not able to. We let water run for 1 hour and nothing came out the discharge pipe. Which in some cases this will happen. Due to soil absorbing around the sand filter!! This system had some repair work done in 1993.

Nothing major. Home owner has had no issues since!!

Thank You



Owner

1-319-524-7329



—20210913_131439.jpg—



—20210913_131350.jpg—





—20210913_131519.jpg—



—20210913_131443.jpg—



—20210913_131530.jpg—



---20210913_131512.jpg---



---20210913_131344.jpg---

