



# INVOICE

Invoice Date	Cust No.	Order No	Page	Invoice No.
09/24/2021	71115	10 - 127386	1 / 1	10 - 124025
License:		Mileage: 0	Time in 9:06 AM	

O.K. Tire Store-Minot  
 504 9th St SE  
 Minot, ND 58701  
 Phone: (701) 839-2686

**Sold To:** RUACH RESOURCES LLC  
 1027 S WELO ST  
 TIOGA, ND 58852

**Ship To:** RUACH RESOURCES LLC  
 1027 S WELO ST  
 TIOGA, ND 58852

Purchase Ord. No.	Sales Person	Main Phone	Other Phone	Ship Via	Terms: NET 10TH Entered: 004 Finalized: T		
SAM 9RX SCRAF	074	(701) 664-3500					
Item No.	Description	Qty Ordered	Qty Shipped	F.E.T.	Price	Net Extension	
303054	30" 9RX SCRAPER CAMSO 6500	2	2		8,753.00	17,506.00	
5W-0391PJD	HD CAMSO NEW REAR IDLER JD 9RX	4	4		1,082.00	4,328.00	
4W-5056	8RT/9RX 9.3" BOLT ON REMAN POLY	8	8		424.00	3,392.00	
4W-0155C	8RT/9RX CORE *TRACKS ON A TRANSFER AS WELL AS *BOGIES, IDLERS WILL BE COMING BY *FREIGHT.	8	8		200.00	1,600.00	

Lug nuts must be re-torqued within 50 to 100 miles of initial tightening.  
 Tires should be rotated every 5,000 to 6,000 miles.  
 All returned product is subject to inspection prior to credit being issued. Any product returned after 30 days from invoice date is subject to a 15% restocking fee. Discontinued or special order product is not eligible for return.

**Sub-Total Parts: 26,826.00**  
**Non-Taxable Amount: 0.00**  
**Taxable Amount: 26,826.00**  
**Tax 7.500%: 2,011.95**  
**Total: 28,837.95**

X

Customer Authorization for Total

Home Product Tracking 1RW9570RAGE801035

# 1RW9570RAGE801035

Model 9570RX	Days Rented 449
Base Machine 09Z0RW	Maintenance Plans No
Built 1.3.2016	Amount of Use 3931 Hour (9.11.2020)
Delivered 29.6.2020	Status Used machine <a href="#">More</a>

[Open PIPs](#)

## Customer

RUACH RESOURCES, LLC  
 1027 S WELO ST  
 TIOGA, ND 588527310  
 US  
 (701) 6643500  
[MALLORYE@RUACHRESOURCES.COM](mailto:MALLORYE@RUACHRESOURCES.COM)

## Warranty Coverage

[Parts Coverage Search](#)

Basic Warranty Expired

Starts 6.8.2016	Expires 7.8.2018	Time Limit 2000 Hour
-----------------	------------------	----------------------

Default Warranty Expired

Starts 10.3.2016	Expires 5.8.2016
------------------	------------------

Emissions Warranty Expired

Starts 6.8.2016	Expires 7.8.2021	Time Limit 3000 Hour
-----------------	------------------	----------------------

Extended Warranty (Powertrain) Expired

Plan Name Extended (C&F)	Contract Purchased 17.10.2019	Contract Type NEW	Start Amount of Use 3600 Hour	Time Limit 6000 Hour	Deductible 750 USD
Starts 6.8.2016	Expires 5.8.2020				

Diagnostics Covered

## Purchase Information

Purchaser Type  
OTHER COMMERCIAL  
 End Use Code  
STONE & AGGREGATE QUARRYING  
 Operator's Manual Number  
 License Plate Number  
 Delivered 29.6.2020  
 Registered 13.7.2020  
 Expected First Use 29.6.2020

Responsible Dealer  
 RDO CONSTRUCTION EQ  
 CO MW  
 178738 (C&F)  
 Williston, ND

Invoice Number	17866329
Invoiced	10.3.2016
Settled	15.3.2019

Invoice Dealer  
 RDO Construction  
 Equipment Co.  
 178711 (C&F)  
 Burnsville, MN

[Expand All](#) [Collapse All](#)

Amount of Use History (68)

Components (72)

Option Codes (645)

Maintenance Plans (0)

24 Month Claim History (20)

PIP History (19)

16RW697 - 9RX STEERING LINE CRIMP Fully Completed  
 IMPROVEMENT - SAFETY MAND

PIP # 16RW697	Type Mandatory Safety	Participant Dealer	Expires 1.11.2017
---------------	-----------------------	--------------------	-------------------

16RW667A-L - 6R-9R HITCH/SCV LEVER Fully Completed  
 IMPROVEMENT - MANDATORY

PIP # 16RW667B	Type Mandatory	Participant Dealer	Expires 1.12.2017
----------------	----------------	--------------------	-------------------

16RW709A-J - MY16 - 9RX 4-TRACK STEERING LINE IMPROVEMENT - **Fully Completed**

PIP # 16RW709A    Type Mandatory Safety    Participant Dealer    Expires 1.5.2018

16RW716 - 9R / 9RX TRANSMISSION OUTPUT SHAFT OVER SPEED ALER **Fully Completed**

PIP # 16RW716    Type Mandatory    Participant Dealer    Expires 1.5.2018

17PC076 - DUAL DISPLAY PERFORMANCE MONITOR IMPROVEMENT - FIX **Terminated**

PIP # 17PC076    Type Fix-as-fail    Participant Dealer    Expires 1.4.2018

17RW762D - 9000, 9020, 9030, 9R AND 9RX FRONT DRIVESHAFT IMP **Fully Completed**

PIP # 17RW762D    Type Mandatory    Participant Dealer    Expires 1.10.2020

16RW722A - 9R WITH DOUBLE REDUCTION AXLE AND 9RX REAR DRIVE **Fully Completed**

PIP # 16RW722A    Type Mandatory    Participant Dealer    Expires 1.8.2019

18RW792A - 9R, 9RT, & 9RX QSX15 ECM SOFTWARE IMPROVEMENT - **Fully Completed**

PIP # 18RW792A    Type Mandatory    Participant Customer    Expires 1.6.2019

17RW782A - 9R & 9RX SCRAPER SPECIAL CASE DRAIN IMPROVEMENT - **Fully Completed**

PIP # 17RW782A    Type Mandatory    Participant Dealer    Expires 1.8.2019

17RW756B - 9R, 9RT, AND 9RX QSX15 STARTER IMPROVEMENT -MANDA **Fully Completed**

PIP # 17RW756B    Type Mandatory    Participant Dealer    Expires 1.9.2019

17RW760A - AG AND SCRAPER SPECIAL TRACTOR E18 TRANSMISSION **Fully Completed**

PIP # 17RW760A    Type Mandatory    Participant Dealer    Expires 1.10.2020

18RW815B - 9R CHARGE DERATE IMPROVEMENT - FIX AS FAIL **Terminated**

PIP # 18RW815B    Type Fix-as-fail    Participant Dealer    Expires 1.1.2020

17RW773A - 9RX CAB NOISE IMPROVEMENT - **Fully Completed**  
 MANDATORY

PIP # 17RW773A    Type Mandatory    Participant Dealer    Expires 1.10.2020

17RW761 - 9R&9RX MY2015—2017.5 SCRAPER **Fully Completed**  
 SPECIAL GUDGEON IMPRO

PIP # 17RW761    Type Mandatory    Participant Dealer    Expires 1.3.2021

17RW757B - 9R, 9RT, 9RX QSX15 ALTERNATOR **Terminated**  
 IMPROVEMENT - FASF

PIP # 17RW757B    Type Fix-as-fail    Participant Dealer    Expires 27.2.2020

18RW816A - 9R & 9RX SIDE SHIELDS **Fully Completed**  
 ENHANCEMENT - PEP

PIP # 18RW816A    Type Product Enhancement Program    Participant Dealer    Expires 1.2.2022

19RW830 - 9R AND 9RX FDH UPPER RETAINER **Fully Completed**  
 IMPROVEMENT - MANDAT

PIP # 19RW830    Type Mandatory    Participant Dealer    Expires 1.10.2020

18RW819A - 9R, 9RT AND 9RX IN-LINE DEF FILTER **62 Days Left**  
 IMPROVEMENT

PIP # 18RW819A    Type Mandatory    Participant Dealer    Expires 1.1.2022

21RW938 - 9R 15L EGR SCR SOFTWARE UPDATE - **335 Days Left**  
 MANDATORY

PIP # 21RW938    Type Mandatory    Participant Dealer    Expires 1.10.2022

Registration History (5)

Ship To  
N/A

Location

WILLISTON, ND

Date	Time	Page
07/07/20	21:03:51 (B)	01

Account Number	Phone Number	Invoice Number
3500116	7016643500	W1766617

Sold To  
RUACH RESOURCES, LLC  
1027 S WELO ST  
TIOGA ND 58852

Ship Via	Purchase Order

Tax Exemption Number	Federal ID Number

Salesperson
N15

Description

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
X956904	4WD TRACTOR (WHEEL 3726	1RW9570RAGE801035	08/07/18	2000
	9570RX	E CONSIGNMENT	08/05/20	6000 P
SEGMENT# 1 C AHV01 PM20-0500	06/29/20	06/29/20	06/29/20	
500 HOUR SERVICE				
CONDITION:				
machine needs 500 service				
1RW9570RAGE801035				
3726 hours				
CAUSE:				
500 hour service needed due to normal operations				
CORRECTION:				
drained and refilled engine oil				
changed engine oil filter				
changed fuel filter				
changed water separator				
checked wheels and weight bolts				
lubricated hitch				
lubricated drive line				
N378887	FUEL FILTER	1 N	25.46	25.46
POLICYADJ	SERVICE	1-	602.75	602.75-
RE561968	Filter Element	1 N	75.39	75.39
RE574467	Filter Element	1 N	141.93	141.93
RE574468	oil Filter	1 N	52.72	52.72
RE594852	Air Filter	2 N	141.85	283.70
RE594853	Filter Element	2 N	43.88	87.76
TY26673	15W40 +50II GAL	1	16.11	16.11
TY26679	PLUS-50 II OIL 15W40 CK4/SN	2	76.26	152.52
TY6341	PLUS-50 II OIL 15W40 CK4/SN	1	3.18	3.18
	GREASE			236.02

CONTINUED ON PAGE 02

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
X956904	4WD TRACTOR (WHEEL 3726	1RW9570RAGE801035	08/07/18	2000
	9570RX	E CONSIGNMENT	08/05/20	6000 P
10401099			LABOR	273.00
			SEGMENT TOTAL==>	509.02

SEGMENT# 2 C AHV01 RDO-900-080 06/29/20 06/29/20 06/29/20  
CUSTOMER MACHINE INSPECTION, CONSTRUCTION/FORESTRY/VERMEER  
CONDITION:

hydraulic motor leaking  
tracks are worn but one severely damaged

10401099	740T1D17	LABOR	Internal
		SEGMENT TOTAL==>	Internal

SEGMENT# 3 C PEND MISC 06/29/20 06/29/20 06/29/20  
\*\*\*AVAILABLE REPAIR\*\*\*  
CONDITION:

	sales portion of PM service		
POLICYADJ	SERVICE	1	Internal Internal

Invoice Detail

10401099	24001017	SEGMENT	PARTS TOTAL==>	Internal Internal
				***** WORK ORDER TOTALS *****
				INTERNAL CUSTOMER
PARTS				Internal 236.02
LABOR				Internal 273.00
HAZARDOUS MTL				13.65
SRV ACCESSORIES				27.30
SUB TOTAL==>				Internal 549.97
ND WILLIAMS COUNTY 6%				52.78
INTERNAL TOTAL				Internal
TOTAL DUE RDO				602.75

-----+-----+  
CONTINUED ON PAGE 03  
STK#/FLEET#                  HRS    PIN/EIN                  WARRANTY DATE          HRS  
X956904            4WD TRACTOR (WHEEL    3726   1RW9570RAGE801035    08/07/18          2000  
                          9570RX                                  E CONSIGNMENT          08/05/20          6000 P  
|    Payments are due on your RDO account 30 days from the invoice date    |  
-----+-----+

\*\*\*\*\*  
PLEASE REMIT TO: RDO EQUIPMENT CO.  
                  P.O. BOX 7160  
                  FARGO, ND 58106-7160  
\*\*\*\*\*

Ship To  
N/A

Location

WILLISTON, ND

Date	Time	Page
09/29/20	21:07:08 (B)	01

Account Number	Phone Number	Invoice Number
3500116	7016643500	W1785217

Sold To  
RUACH RESOURCES, LLC  
1027 S WELO ST  
TIOGA ND 58852

Ship Via	Purchase Order
	PREPAIDNOTRAVEL

Tax Exemption Number	Federal ID Number

Salesperson
RAF

Description

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X956904	4WD TRACTOR (TRACK 9570RX S	3940	1RW9570RAGE801035 CONSIGNMENT	08/07/18 08/05/20	2000 6000 P
SEGMENT# 1	C AR501 PM20-1000 1000 HOUR SERVICE CORRECTION:	08/11/20	09/16/20	08/11/20	

Ordered parts and loaded truck.  
Performed 1000 hour service as outlined.  
Cleaned up mess from service and loaded onto truck.  
Cleaned out truck once returned.  
Wrote up story.  
ADDITIONAL DESCRIPTION:

\*\*\*TRAVEL NOT PREPAID, MUST OPEN SEPARATE W/O FOR TRAVEL\*\*\*  
Back flush fuel water separator (if equipped).  
Change cab air and recirculation filters.  
Change engine air filters.  
Change engine oil and filter (9470RX and 9520RX only).  
Change fuel filters(9470RX and 9520RX only).  
Check air intake system hoses and hose clamps for tightness.  
Check drawbar mounting bolts torque.  
Check drive wheel scraper clearance.  
Check drive, mid-rollers, and idler wheels.  
Check for track wear and trash build-up.  
Check manual brakes.  
Check neutral start system.  
Check scraper hydraulic accumulator.  
Check track alignment.  
Check transmission PARK function.  
Check transmission, hydraulic, and axle oil level(s).  
Check undercarriage articulation bumper stops.  
Clean dual beam radar sensor.  
Lubricate gudgeon bearings.

CONTINUED ON PAGE 02

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X956904	4WD TRACTOR (TRACK 9570RX S	3940	1RW9570RAGE801035 CONSIGNMENT	08/07/18 08/05/20	2000 6000 P

Lubricate hinge pin(s).  
Lubricate hydraulic hose support bracket.  
Lubricate lower drive line bearings.  
Lubricate PTO drive shaft(s).  
Lubricate steering pin(s).  
Lubricate telescoping drive shafts.  
Lubricate tension cylinder.  
Lubricate VARI-COOL fan drive (9470RX and 9520RX) only.  
Service water separator filter element (if equipped).  
Test coolant and add conditioner or extender.  
Tighten bolts on drive and idler wheels, mid-rollers, and weights.

FRT	SHIP/HANDLING	4
GALFOX	WASHER FLUID	1 M
JD7759	LUBRICATIO	3 O
	Lubrication Fitting	
RE284091	AIR FILTER	1 N
RE291412	AIR FILTER	1 N
RE561968	Filter Element	1 M

RE574467	Filter Element	1	M
RE574468	Oil Filter	1	N
RE594852	Air Filter	2	N
RE594853	Filter Element	2	N
TY26682	PLUS-50 TM ENGI	39	O

PLUS-50 II OIL 15W40 CK4/SN

PARTS	1186.68
LABOR	585.00
SEGMENT TOTAL==>	1771.68

24102017

SEGMENT# 2 C AR501 RDO-900-080 08/11/20 09/28/20 08/11/20

CONTINUED ON PAGE 03

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
X956904	4WD TRACTOR (TRACK	3940	1RW9570RAGE801035	08/07/18
	9570RX S		CONSIGNMENT	08/05/20
				2000
				6000 P

CUSTOMER MACHINE INSPECTION, CONSTRUCTION/FORESTRY/VERMEER  
CONDITION:

Right rear track is falling apart.  
Signal arm are damaged.  
Grille, hood, and coolers are damaged.  
Some lamps are damaged.  
Othere misc damaged to fenders and lower body pieces.  
Large oil leak on the front of the engine that customer has  
to add engine oil to it every other day.  
CORRECTION:

Performed walk around and check fluid levels.  
Operated machine and all of it's functions.  
Recorded findings and wrote up story.  
ADDITIONAL DESCRIPTION:

- Machine Inspection.
- \_\_\_ Check machine over for any needed repairs or service.
  - \_\_\_ Check Fluid Levels.
  - \_\_\_ Check for leaks.
  - \_\_\_ Check A/C and Heater function.
  - \_\_\_ Check condition of hydraulic hoses and cylinders.
  - \_\_\_ Check and note any stored or active codes.
  - \_\_\_ Check for Loose or missing hardware.
  - \_\_\_ Check operation of machine.
  - \_\_\_ Check lights, wipers, and electrical system.
  - \_\_\_ Check condition of battery.
  - \_\_\_ Check condition of glass and sheet metal.
  - \_\_\_ Check safety items (horn, back up alarm, seat belt, signal lights).
  - \_\_\_ Check cutting edge's or bucket teeth (Ground Engagement).

CONTINUED ON PAGE 04

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
X956904	4WD TRACTOR (TRACK	3940	1RW9570RAGE801035	08/07/18
	9570RX S		CONSIGNMENT	08/05/20
				2000
				6000 P

\_\_\_ Check general condition of tires or tracks.  
Recommended Service or Repairs:

- 1.
- 2.
- 3.
- 4.
- 5.
- 6.
- 7.

Customer representative: \_\_\_\_\_  
Date: \_\_\_\_\_  
Approved or Declined: \_\_\_\_\_

24102017	740T1D17	LABOR	Internal
		SEGMENT TOTAL==>	Internal

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

INTERNAL	CUSTOMER	
		1186.68
PARTS		
LABOR	Internal	585.00
HAZARDOUS MTL		30.87
SRV ACCESSORIES		61.75
SUB TOTAL==>	Internal	1864.30
ND WILLIAMS COUNTY 6%		76.76
INTERNAL TOTAL	Internal	
CUSTOMER TOTAL		1941.06





Ship To  
N/A

Location

WILLISTON, ND

Date	Time	Page
03/03/21	21:08:08 (B)	01

Account Number	Phone Number	Invoice Number
3500116	7016643500	W1812017

Sold To  
RUACH RESOURCES, LLC  
1027 S WELO ST  
TIOGA ND 58852

Ship Via	Purchase Order
	PREPAIDNOTRAVEL

Tax Exemption Number	Federal ID Number

Salesperson
RAF

Description

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X956904	4WD TRACTOR (TRACK 9570RX S		X 1RW9570RAGE801035 CONSIGNMENT	08/07/18 08/05/20	2000 6000 P
SEGMENT# 1 C AR501 NA	4500 HOUR SERVICE	10/28/20	01/04/21	10/28/20	
CONDITION:					

Work was not completed machine was sold  
ADDITIONAL DESCRIPTION:

\*\*\*TRAVEL NOT PREPAID, MUST OPEN SEPARATE W/O FOR TRAVEL\*\*\*  
 Replace transmission vent filter.  
 Replace fuel tank vent filters.  
 Change transmission hydraulic reservoir suction screens  
 axle oil and filters.  
 Change DEF dosing unit filter  
 Check mid-rollers oil level.  
 Check idler wheel hub oil level.  
 Check axle end play.  
 Back flush fuel water separator (if equipped).  
 Service water separator filter (if equipped).  
 Change engine oil and filter.  
 Change fuel filters.  
 Check air intake system hoses and hose clamps for tightness.  
 Check drawbar mounting bolts torque.  
 Check drive wheel scraper clearance.  
 Check drive, mid-rollers, and idler wheels.  
 Check for track wear and trash build-up.  
 Check manual brakes.  
 Check neutral start system.  
 Check scraper hydraulic accumulator.  
 Check track alignment.  
 Check transmission PARK function.  
 Check transmission, hydraulic, and axle oil level(s).

CONTINUED ON PAGE 02

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X956904	4WD TRACTOR (TRACK 9570RX S		X 1RW9570RAGE801035 CONSIGNMENT	08/07/18 08/05/20	2000 6000 P
Check undercarriage articulation bumper stops. Clean dual beam radar sensor. Lubricate gudgeon bearings. Lubricate hinge pin(s). Lubricate hydraulic hose support bracket. Lubricate lower drive line bearings. Lubricate telescoping drive shaft(s). Lubricate PTO drive shaft(s). Lubricate steering pin(s). Lubricate tension cylinder. Tighten bolts on drive and idler wheels, mid-rollers, and weights.					

FRT	SHIP/HANDLING	1	139.94	139.94
RESTOCK	PARTS ORDERED	1	95.35	95.35
	PARTS			235.29
	LABOR			23.40
24102017	SEGMENT TOTAL==>			258.69

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

11/1/21, 3:22 PM

Invoice Detail

	PARTS	235.29
	LABOR	23.40
CUSTOMER	TOTAL	258.69