Washington Auto Center PO Box 874

PO Box 874 Washington, IA 52353 319-591-2886

		Invoic	e # 1023 8			Page:1
Knipfer 1408 E N	, Rusty & Sue Main St				Phone: 3	19-594-7502
Washing	ton, IA 52353			Service Writer	: Breb	
Vehicle	: 2007 Peterbilt 37	9 14.6 L 893 CID L6 Caterp	illar C15 Diesel			
VIN Fleet #/Driv Created Invoiced	: 1XP5DB9X97N74214 ver:: 33 / : 10/24/2022 8:01:22 : 10/28/2022 8:40:42	AM CDT		Tag/State Color Odometer In Odometer Out	: VC6284/IA : Blue : 2073436 : 2073436	
Code	/Tech*	<u>Description</u> Oil Filter (Gold)		Condition	Unit Price \$35.55	Price \$35.55
		Service and Lube				\$127.50
V	lote: Changed Oil, Greased ι	unit, visual inspection, checked and 15w 40 Diesel Oil	I filled rear ends and to	ansmission New	\$4.50	\$162.00
		JT 6 HI temp grease		INCAA	\$12.32	\$102.00 \$24.64
		Fuel Filter (Gold)			\$37.42	\$37,42
		Fuel Filter (Gold)			\$35.92	\$35.92
		Remove & Replace Fuel Filte	ers		400.02	\$47.50
		Labor Parts		less discount:	 \$205.65	\$175.00 \$295.53
		Shop Supplies	•		•	\$293.93 \$14.00
		Environmental Charge				\$7.88
		Sales Tax		AT.	X @ 6%	\$29.54
				Local Option	n @ 1%	\$4.93
					Total	\$526.88
			Check #5051: \$5	26.88 PA	YMENT	\$526.88
				BALAN	CE DUE	\$0.00
Technician C	ode <u>Certification</u> #			· , · · · · · · · · · · · · · · · · · ·		
damage to very permission to garage keep completed C	ehicle or articles left in vehic o operate the vehicle herein er's lien is hereby acknowle OULD INCUR A \$5.00 PER spection sheet.	n set forth to be done along with the cle in case of fire, theft or any other described on streets, highways or dged on above vehicle to secure to DAY STORAGE FEE. 12 Month	er cause beyond your or r elsewhere for the pu the amount or repairs	control. I hereby g rpose of testing ar thereto. All Vehicle	rant you and/or you nd/or Inspection. Ar es left over 48 hrs.	r employees express after repairs are
= 2000000000000000000000000000000000000	J					

Customer Signature:

		Invoic	e #10007			Page:1
Knipfer, I 1408 E Ma	Rusty & Sue				Phone: 3	319-594-7502
	on, IA 52353			Service Writer	: Breb	
Vehicle	: 2007 Peterbilt 379	L4.6 L 893 CID L6 Caterp	illar C15 Diesel			
VIN Fleet #/Drive Created Invoiced	: 1XP5DB9X97N742141 r:: 33 / : 9/19/2022 5:35:01 PM : 9/24/2022 11:49:25 A			Tag/State Color Odometer In Odometer Out	: VC6284/I. : Blue : 2066006 : 2066006	A
Code/Te	ech*	<u>Description</u> 1/2" Male Quick Coupler Set		<u>Condition</u> New	<u>Unit Price</u> \$43.09	<u>Price</u> \$86.18
		Bushing 1/2" Tube 3/8" Thre	ead Brass	New	\$4.41	\$17.64
		Reman Differential Assy		Rebuilt	\$1,961.75	\$1,961.75
	•	Core			\$690.00	\$690.00
		Core Credit			(\$690.00)	(\$690.00)
		Gasket		New	\$14.53	\$29.06
		Full Synthetic Gear Oil 75W-	90 QT	New	\$15.29	\$244.64
		Replace Rear Diff				\$380.00
		Bearing Strap Kit		New	\$21.14	\$42.28
		Labor Parts	***************************************		**********	\$380.00 \$2,381.55
		Shop Supplies Environmental Charge	***************************************		***************************************	\$30.00 \$17.10
		Sales Tax		TAX Local Option	(@ 6% @ 1%	\$168.52 \$28.09
			Check #5020: \$3,00	5.26 PAY BALANC	MENT	\$3,005.26 \$3,005.26 \$0.00

Technician Code kevinb

Certification # kevinb

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or Inspection. An express garagekeeper's lien is hereby acknowledged on above vehicle to secure the amount or repairs thereto. All Vehicles left over 48 hrs. after repairs are completed COULD INCUR A \$5.00 PER DAY STORAGE FEE. 12 Month or 12,000 Mile Warranty On Repairs. I have read and reviewed the multipoint inspection sheet.

Customer Signature	
Customer Signa	ure:

Page			72	Invoice #9		
L9-594-750	Phone: 319				Rusty & Sue	Knipfer, R
						1408 E Mai
	: Breb	Service Writer	S		n, IA 52353	Washingtor
			5 Diesel	14.6 L 893 CID L6 Caterpillar C	: 2007 Peterbilt 379	/ehicle
	: VC6284/IA	Fag/State			TN : 1XP5DB9X97N742141	
	: Blue : 2053029	Color Odometer In		M CDT	11:33 / -: 8/11/2022 11:09:36 A	leet #/Driver:
	: 2053029	Odometer Out			: 8/16/2022 4:59:55 PM	nvoiced
Pr	Unit Price	Condition		Description		Code/Tec
\$35.	\$35.55			Oil Filter (Gold)		3
\$127.				Service and Lube		
1460	+4.50		ar ends and trans	t, visual inspection, checked and filled re	e: Changed Oil, Greased uni	Note
\$162.0	\$4.50	New		15w 40 Diesel Oil	•	
\$21.	\$10.59			JT 6 HI temp grease		
\$36.0	\$36.60			Fuel Filter (Gold)		
\$33.9	\$33.90			Fuel Filter (Gold)		
\$47.				Remove & Replace Fuel Filters		
\$288.8	\$144.42	New		Air Filter		
\$47.				Replaced Air Filter		
\$330.2	\$82.55	New	oė	4709E2 2nd Design Relined Brake S		
\$144.0	\$36.00			Core		
(\$144.0	(\$36.00)			Core Credit		
\$933.0	\$233.25	New		16.5"x7" Brake Drum IH Fleetrite		
\$289.2	\$72.31	New		Oil Seal		
\$58.3	\$14.53	New		Gasket		
\$570.0				Remove and Replace All Drive Brake Seals		
\$23.7			ly for a failed	Replace Rear Right Tail Light assem bulb		
\$225.6	\$14.10	New			e: 4" Round provided by cus	Note
•	\$14.TO	IAGAA		Synthetic Transmission Fluid		
\$47.5	+20.00	N 1		Replaced Transmission Fluid		
\$39.9	\$39.98	New		ADSP ADIS Filter Cartridge		
\$47.5		- 1 11		Replace Air Drier Cartridge		
\$2,493.	\$2,493.75	Rebuilt		Rear Power Divider 3.36 Ratio		
\$1,110.0	\$1,110.00			Core		
(\$1,110.0	(\$1,110.00)			Core Credit		
\$236.3	\$236.30	New		1810 Series Half Round Yoke		
\$122.4	\$122.42	New		Through Shaft Output Seal		
\$32.2	\$16.10	New		Tapered Bearing Race		
\$52.9	\$26.48	New		Bearing Cone		
\$19.8	\$19.84	New		Through Shaft Lock Nut		
\$489.2	\$15.29	New		Full Synthetic Gear Oil 75W-90 QT		
\$21.1	\$21.14	New		Bearing Strap Kit		
\$570.0			in the rear Diff.	Replaced Front Power Divider and o		•
\$72.6	\$72.64	New		Piggyback SS Brake Chamber		
\$71.2			nber	Replaced Left Front Drive Brake Cha		

Invoice #6562 Page:1 Knipfer, Rusty & Sue Phone: 319-594-7502 1408 E Main St Washington IA, 52353 Service Writer : LindsyB Vehicle : 2007 Peterbilt 379 14.6 L 893 CID L6 Caterpillar C15 Diesel VIN : 1XP5DB9X97N742141 Tag/State : VC6284/IA Fleet #/Driver:: 33 / Color : Blue Created : 5/7/2021 4:30:48 PM Odometer In : 1931958 Invoiced : 5/27/2021 3:36:18 PM Odometer Out : 1931958 Oty Code/Tech* Description Condition **Unit Price** Price 1 Peterbilt 4 Row Radiator: 357 377 379 385 EA \$1,506.63 \$1,506.63 4 POLY KENWORTH RADIATOR MOUNT \$20.74 \$82.96 4 PETE POLY RADIATOR MOUNT \$4.56 \$18.24 4 Battery Box Insulator New \$14.32 \$57.28 2 Anaerobic Gasket Maker \$24.68 \$49.36 1 CAT CAM SHAFT CRANK TIMING POSITION \$100.24 \$100.24 BA921 CAT C15 AIR COMPRESSOR \$471.90 \$471.90 1 Core \$540.00 \$540.00 1 Core Credit (\$540.00)(\$540.00)2 KENWORTH MOTOR MOUNT BUSHING \$32.04 \$64.08 Belt - Serpentine \$43.78 \$43.78 Belt - Fan \$75.82 \$75.82 1 Vulco Straight Coolant Hose 3x3 \$40.76 \$40.76 1 CAT C15 ACERT Front Cover Gasket Kit Set \$416.35 \$416.35 1 Used Gear Housing \$1,593.75 \$1,593.75 7 Antifreeze 50/50 New \$13.12 \$91.84 40 15w 40 Diesel Oil New \$3.65 \$146.00 1 CAT Oil Filter New \$60.87 \$60.87 Remove and Replace Front Timing Cover \$2,280.00 1 CAT Fuel Filter New \$38.16 \$38.16 1 CAT Fuel Filter New \$44.53 \$44.53 Remove and Replaced High side A/C Line from \$47.50 Compressor to Condensor 1 A/C Disch Hose Assembly/Peterbilt \$343.75 \$343.75 A/C evacuate, vaccum and charge \$142.50 Note: Performance tested and all pressures were in spec for the outside temperature and humidity levels. 1 Drop Visor Windsheild Replacement Glass New \$622.98 \$622.98 Remove and Replaced Drop Visor For Glass Company \$47.50 Labor \$2,517.50 **Parts** \$5,869.28 Shop Supplies \$30.00 **Enviormental Charge** \$25.00 Sales Tax TAX @ 6% \$506.51 Local Option @ 1% \$84.42 Check #4973: \$9,032.71 **PAID** \$9,032.71

Technician Code kevinb

Certification # kevinb

mattm

Knipfer	Rusty & Sue	TU/	voice #7594			Page
1408 E M					Phone	: 319-594-75
Vehicle VIN	: 2007 Peterbilt 3	79 14.6 L 893 CID L6 Cate	Serv erpillar C15 Diesel	ice Writer	: kevinb	
Fleet #/Drive Created Invóiced		5 PM	Tag/ Color		: VC6284/ : Blue	ΊΑ
Qty Code/T		Description				
2		Pete Rigid Torque Rod 23	יל כ	ndition	Unit Price	Pr
2 12		Pete Rigid Torque Rod 24	1 605		\$183.77	\$367.
		Misc Bolt Hardware	Ne:	•	\$248.17	\$496.
Not	e: On Rear Axle	Removed and Replaced A	Men III 4 Torque Rods	v	\$16.00	\$192.
1	e. Of Rear Axie		- que nous			\$570.
36		CAT Oil Filter	Nev	V	\$43.03	\$43.0
2		15w 40 Diesel Oil	Nev	/	\$3.65	\$131.4
		JT 6 HI temp grease Service and Lube			\$8.82	\$17.6
Note	e: Changed Oil, Greased	unit, visual inspection, checked a	nd filled rear ends and transmissi			\$127.5
		CAT Fuel Filter				720,10
1		CAT Fuel Filter	New New		\$44.00	\$44.0
		Replaced Filters	INGW		\$26.96	\$26.9
		Labor				\$47.5
		Parts	***********************			\$745.00
		Shop Supplies	*******************************		1 1	\$1,318.91
		Enviormental Charge	******************************			\$30.00
		Sales Tax				\$25.00
			l a a	MAX @		\$127.13
				al Option @	1%	\$21.19
chnician Code	Certification #		Check #4985: \$2,267.23	P	AID \$	52,267.23

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or Inspection. An express garagekeeper's lien is hereby acknowledged on above vehicle to secure the amount or repairs thereto. All Vehicles left over 48 hrs. after repairs are completed COULD INCUR A \$5.00 PER DAY STORAGE FEE. 12 Month or 12,000 Mile Warranty On Repairs. I have read and reviewed the

Customer Signature ____





Peiffer Repair Chris Peiffer, Owner 22952 280th Avenue Harper, Iowa 52231 (641) 224-2406

			641) 224-2400				
CERNICE	□ PICK UP	PHONE		REPAIR IN	1 /	DATE OF ORDER	•
SERVICE INSTALL	DELIVER ,			☐ HOME ☐	SHOP C	TE PROMISE	
AME Die	Cal Va	· Dar			2	5-180-4	
MAS	<u>Sel 171</u>	pres				TRUCK NO.	
DDRESS /	08 E/	Jun J.	- 0 = 1		Di	ATE ORIG INSTA	ALL
ITY Was	ching HO	n. IA 5.	2353] ESTIMATE	\dashv
TAKED LA	hin	MODEL 319	SERIAL NO			☐ WARRANT	Υ
IN THE	42141		EAGE	·····		☐ CONTRA	.cT
	4011					☐ CASH	DCE
IATURE OF SERVICE	>					CHA	
REQUEST	_			Di	RICE	AMOUNT	
QUAN PA	ART NO	DESCRI	PTION		iic.	MIL	1007
	400	Clutch				111	0 1
-1-	100.1		•				
			The second secon				
			11:				
		A	, litt.				
		N- 1	1 2/				
		MND					
		-/-) 1 ^{cs}	- And Andrews - 16th Printerson - 18th Anne part & Andrews - 18th Printerson - 18th Anne Part Anne Part Anne Pa				
and the second							
							ļ
	- LOONED			٨	TOTAL MATERIAL	711	0
SERVICE PE	KFUKMEU			TI	CHNICAL VICE TIME	410C	-
				SER	VICETIME	1101	1/01
						13.11	4
					TAX	181	W,
– ///	0.1	DATE COMPLETED	CASH OF WOR	PLETION	TOTAL	1250	34
Thank	you:		AND CHARGES, AS BEI	NG SATISFACTO	DRY AND	ACKNOWLED	GE TH
EQUIPME	NT HAS BEEN LEF	TIN GOOD CONDITIO	.i.i.				
			CUSTOMER'S SIGNAT	URE	algebra of the second second second second	and the state of t	and the second second second
		programme (to provide a distance of submitted programme programme and the	- Comment Comment of the Comment of			YELLOW = C	FFICE C
WHITE = C	USTOMER COPY	•					
						•	

SERVICE ORDER INVOICE



Chris & Britt Peiffer 22952 280th Ave Harper, IA 52231

Qty.	. Description		Prile	e	Amo	μŒ		Harper, I		
	Head				50%		REPAIR	(641) 22	4-2406	
	OverhAUI KIT				5413	99	il verification and the second			
**************************************	TURBO	1			1949	123			Date	
	TURBO .			,	1908	14	Name RUSSEL KNIP	Fer	20)98
	EOM RIPHIN			4 4 8	3500		Address 1708 E Main	, 57		
	e/ Bow) 	2	43	WAShington 823	Phone	Date of Original	inal Installation P-2020
- Walter of Walter of Walter	TUBE 4554			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	30	32	Make, Ex. 3/1+	Model 279	□Estimate	
É	incertoes	e	550	1 1 1 1 2 a.gs	3300		MASH No ton 523 Makey Le Text 3:1+ Serial No. 7 N 7 42141 Nature of Service	Date Promised	☐ Warranty	
	spacer plate				507	71	Nature of Service			
6	Sleeve shims	(e_	78	//	468	66				
	Head BOIT KIT			1	282	62				
	Dimpik			1	465	1				
	Fuel pumo				2/3	05				
	Fuel pump Check Valve			1	Î,S	01				
3	There Mest Its	æ	53.	29	164	58				
	MAN, FOID STUDS				230	_		To	ital Materials	# 8 8 9 9
	NAN. FOID Spacer				230		Techni	cal Service Time 🔲 Shop	☐ Home	\$ 3 2 5 3
	WASher					02	Pick Up or Deliver	☐ Service Call Charge	77	\$ * :
CONTROL OF THE CONTRO	Hose					16	Technician			2 7 1
	Elek-up Ping			1	6	09	Date Completed	-	Tax	
TO CONTACTOR AND	Temp Carthol				93	45			Total	* * * * * * * * * * * * * * * * * * *
	/	Tota	ıl Mater	rials	CONT	D	Signature	en en version de marien de la chiefe de Marien de marien amendemande acceptar en acceptar acceptar de acceptar		And the state of t

Signature above constitutes acceptance of above work as being satisfactory and that equipment has been left in good condition.



SERVICE ORDER INVOICE



Chris & Britt Peiffer 22952 280th Ave Harper, IA 52231 (641) 224-2406

2	1

Qty.	Description	Pric	Θ.,	Amou	me		Harper, I			
	RADIATOR UDDER SEOI			59	77	REPAIR	(641) 224	1-2406		
	" L.H. Spield			175	36					
	" R.H. "			175		Email		Date		
	" Top		1 1 4 4 8	81	60	Name RVSSell KN.pk.	ie	21	99	
2	,	1 59	20	118	40	Address /	200			
	Boit				15		Phone	Date of Ori	ginal Instal	lation
14	adllow LL Coolant e	12	14	169	96	Make	Model	☐ Estimat	-	
	91515W480:1 @	1	13	137	72	Serial No.	Date Promised	Contrac	-	
f	55/808 F. 1700 - 0:1				46	Nature of Service				
4	85/000 " - Fool/4/1-tee			13	53					
•	0534905 " AIR 0	بنبه	99	وندا	98					
	19-0949 1 Fuel			29	مو تتما					
7.5	zip Hes e		سهيئ	2	25					
	primen print e	15	50	62					range responses to market the form to All All	
	CAT YELLOW PAUT &	1	148	4/1	92			um an dus s nous acodas est de constitue emiliabre o de s'estable de la constitue de la consti	agaige contains and a second particles in the second	
	/ /	10 mm					Тс	otal Materials	34028	65
		or spins and stage				Techni	cal Service Time Shop	☐ Home	7475	٠
		The state of the s	1			Pick Up or Deliver	Sérvice Call Charge) 6 4 2 2
						Technician	And the second s			
		To company	i : : :		1	Date Completed		Tax	3305	16
		9							23.708	
	To	tal Mate	rials	24058	6.5	Signature			1	
	To	tal Mate	rials	24038	65				,	7

Signature above constitutes acceptance of above work as being satisfactory and that equipment has been left in good condition.

Thank You

RECORD OF ANNUAL INSPECTION

(49 CFR, 396. 17-23)

		DATE
91	2	6606

			Prepare	e Separa	te Report	for Each Vehicle In	spected	d		D49:	193	ang.	
COMPANY NAME	COMPANY NAME							VEHICLE TYPE					
KUSTU	RUSTU KNIDTEV							☐ TRUCK ☐ TRACTOR ☐ TRAILER ☐ DOLLY					
STREET ADDRESS	VEHICLE MAKE					D.							
1408 L	1408 E. Main H.								270		TEA	7	
CITY		STATE	0	ZIP		VEHICLE IDENTIFICATION (Company No., State Tag No. or VIN)							
MANUALITY 6/200 11 VDED BUVOTING													
INSPECTOR'S NAM	INSPECTOR'S NAME (Please Print)												
								MPLOYEE	NO.				
REPORT OF	CONF	MOITIC	/For Dotailed In	· · ·									
	OOIVE	7111014	(FOI Detailed in	Tormation	on Inspe	ection Procedures s	ee FMC	SR Sect	tion 396, Ap	pendix G	i)		
BRAKES	OK	REPAIR		ОК	REPAIR			REPAIR			ОК	REPAIR	
			EXHAUST			STEERING			FRAME		OK	REPAIR	
Adjustment	V		Leaks			Adjustment	1		Members				
Mechan. Compon.	1		Placement	V	,	Column/Gear	1		Clearance				
Drum/Rotor	V		LIGHTING			Axle	1		2.22.41100				
Hose/Tubing		4	Headlights			Linkage			TIDEO				

Linkage

Other

Tank(s)

Springs

Attachments

Lines

Power Steering

FUEL SYSTEM

SUSPENSION

L

COUPLERS Tie-Downs Sliders Fifth-Wheel & Mount Headerboard WINDSHIELD Pin/Upper Plate Motorcoach Seats **MIRRORS** Pintle-Hook/Eye Other WINDSHLD, WIP. Safety Chain(s)

REMARKS

Lining

Antilock System

Low Air Warning

Trailer Air Supply

Compressor Parking Brakes

Other

Automatic Adjusters

Certification: This vehicle has passed all the inspection items for the annual vehicle inspection in accordance with 49 CFR Part 396.

QUALIFIED INSPECTOR'S SIGNATURE

Tail/Stop

Identification

CAB/BODY

Eqpt./Load Secure

Reflectors

Other

Access

Clearance/Marker

TIRES

Inflation

Damage

Fasteners

Disc/Spoke

Other

Speed Restrictions

WHEELS/RIM

Tread

APPLY LABEL TO A CLEAN, DRY SURFACE. USE WITH AN OVERLAMINATE (2402) TO IMPROVE DURABILITY UNDER NORMAL WEATHER CONDITIONS.

AN INDELIBLE INK MARKER IS RECOMMENDED FOR USE WHEN FILLING OUT THE LABEL. INDELIBLE INK IS PERMANENT AND WILL NOT WASH OFF, BUT MAY FADE DUE TO EXPOSURE TO ULTRAVIOLET LIGHT OVER TIME. CAREFUL DISCRETION IS ADVISED REGARDING APPLICATION OF LABEL TO AN AREA NOT EXPOSED TO EXCESSIVE ULTRAVIOLET LIGHT AND/OR ELEMENTS AND IT IS RECOMMENDED THAT THE READABILITY OF THE LABEL BE CHECKED PERIODICALLY.

> Copyright 2016 J. J. Keller & Associates, Inc. Neenah, WI • JJKeller.com • (800) 327-6868 Printed in the USA

3136 (Rev. 10/16)

EEDEDA	ABIRTORA	The state of the s	231 10 1
	ANNUAL	INICDEATI	
	- AININUAL	IIN 2 P E C. I II	
	The state of the s		

THIS VEHICLE HAS PASSED AN ANNUAL INSPECTION CONDUCTED IN ACCORDANCE WITH 49 CFR, PART 396, FMCSR

MONTH YEAR VEHICLE ID (Company No.)

STATE/TAG NO. OR VIN

LOCATION OF RECORDS:

Company

Street Address

City, State, Zip