

Invoice to:

RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718 For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

**Branch** 

HAZEN, ND

\*REPRINT\*

**Date** 03/23/21

Time 21:16:21 (B)

Page 01

Account No.

**Phone No.** 7017486300

Invoice No. W1604759

6300068 **Ship Via** 

Purchase Order

**Tax Exemption Number** 

Federal ID Number

Salesperson CF4

WAYNE CLARK 1270 50TH A

1270 50TH AVE SW HAZEN ND 58545-9697

#### SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS X258329 9630 525HP TRACTOR 3432 1RW9630PEAP016650 02/26/12 2000 9630 02/25/14 2000 P

- \* We're offering parts, services & sales during restrictions. Learn more at RDOequipment.com/COVID-19
- \*\* View your invoices and buy parts online at RDOequipment.com/mydealer Create your free account today.

SEGMENT# 1 C MGD01 RDO-900-010 03/05/21 03/08/21

4WD TRACTOR INSPECTION

**CONDITION:** 

Don't pull samples, coolant reservoir is full oil

Include a segment to do head gasket and separate to include

new injectors

ADDITIONAL DESCRIPTION:

Policy adjusted inspection due to hold up with radiator

issue

PROMOAG labor discount

Internal Internal

PARTS Internal

LABOR Internal

10404099 74502459 SEGMENT TOTAL==> Internal

03/08/21 03/08/21

SEGMENT# 2 C MGD01 RDO-660-010 03/08/21 03/08/21

UPDATE SF3000 OR SF6000

CONDITION:

Update SF3000

LABOR 29.00 10404099 SEGMENT TOTAL==> 29.00

10404099 SEGMENT TOTAL==> 29.

SEGMENT# 3 C MGD01 10-020-020

HEAD GASKET, R&R

**CONDITION:** 

CONTINUED ON PAGE 02



RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718 For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch

HAZEN, ND

 Date
 Time
 Page

 03/23/21
 21:16:21 (B)
 02

 Account No.
 Phone No.
 Invoice No.

 6300068
 7017486300
 W1604759

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson CF4

Invoice to: WAYNE CLARK

1270 50TH AVE SW HAZEN ND 58545-9697

# SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS X258329 9630 525HP TRACTOR 3432 1RW9630PEAP016650 02/26/12 2000 9630 02/25/14 2000 P

Oil in coolant.

CAUSE:

13.5L noted issue

CORRECTION:

Flipped hood up to service position. Drained coolant.
Removed side screens. Removed fan. Removed front cover\fan support. Removed camshaft timing gear. Removed turbocharger. Removed radiator hoses and thermostat cover.
Removed valve cover, rocker arm assembly and head bolts.
Lifted head off engine and set to the side. Cleaned deck of block and ran tap through head bolt holes to clean threads.
Cleaned up head surface. Installed new head gasket.
Installed new head bolts and torqued. Reinstalled Rocker arm assembly. Adjusted camshaft backlash, valve lash and injector preload. Installed valve cover. Installed turbo and other misc. components. Started up tractor and checked for leaks. Put hood back into normal position. Installed side shields.

#### ADDITIONAL DESCRIPTION:

#### Remove

- -Hood
- -Exhaust and intake pipes
- -Injection rack and leak-off lines
- -Fan support
- -Rocker arm cover and assembly  $% \left\{ \left\{ 1\right\} \right\} =\left\{ 1\right\} =\left\{ 1\right$

Remove cylinder head, check head and block flatness.

Install new gasket and install head to specification.

1 N 15.51 AT322214 FILLER CAP 15.51 AT326151 TANK 1 S 242.94 242.94 29.78 DZ103630 2 N 14.89 Hose CONTINUED ON PAGE 03



RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718 For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch HAZEN, ND

6300068

 Date
 Time
 Page

 03/23/21
 21:16:21 (B)
 03

 Account No.
 Phone No.
 Invoice No.

7017486300

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

 $\begin{array}{c} \textbf{Salesperson} \\ \textbf{CF4} \end{array}$ 

W1604759

Invoice to: WAYNE CLARK

1270 50TH AVE SW HAZEN ND 58545-9697

SERVICE INVOICE

STK#/FLEET#		HRS PIN/EIN	WARR	ANTY DATE	HRS	
X258329	9630 525HP TRACTOR	3432 1RW9630PEAP	016650	02/26/12	2000	
	9630			02/25/14	2000 P	
DZ112918		Filter Element	1	80.74		80.74
FRT		SHIP/HANDLING	2	5.00		10.00
M149638		BUSHING	1 M	4.39		4.39
RE527611		THERMOSTAT	1 S	30.76		30.76
RE527612		THERMOSTAT	2 S	28.88		57.76
RE530493		KIT	1 N	47.70		47.70
RE530816		GASKET KIT	1 N	652.18		652.18
RE530817		KIT	1	246.86		246.86
RE532952		FILTER	1	77.36		77.36
RE572785		Oil Filter	1	45.43		45.43
RE66534		CLAMP	1 N	19.57		19.57
R129867		HOSE	1 N	11.03		11.03
R136507		SCREW	12	3.27		39.24
R231549		RADIATOR HOSE	1 N	23.42		23.42
R240361		Reservoir	1 N	214.31		214.31
R243231		RADIATOR HOSE	1 N	37.12		37.12
R264593		HOSE	1 N	41.50		41.50
R522023		GASKET	3 S	7.55		22.65
R545233		Radiator Hose	2 N	23.17		46.34
TY26101		BRAK&PARTS	3	4.64		13.92
	Cleaning Solve	nt				
TY26682		PLUS-50 TM Engi	63	3.22		202.86
	PLUS-50 II OIL	15W40 CK4/SN				
TY27530		COOL-GARD	56	2.44		136.64
				PARTS		2350.01
				LABOR		4524.00
10404099			SEGMENT	TOTAL==>		6874.01

SEGMENT# 4 C MGD01 10-030-015 INJECTOR, R&R (13.5L) 03/08/21 03/09/21

CONTINUED ON PAGE 04



N/A Ship to:

**RDO Equipment Co.** PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

**Branch** HAZEN, ND

Date Time 03/23/21 21:16:21 (B)

Account No. Phone No. Invoice No. 6300068 7017486300 W1604759

Ship Via **Purchase Order** 

**Tax Exemption Number Federal ID Number** 

> Salesperson CF4

Page

WAYNE CLARK Invoice to:

1270 50TH AVE SW HAZEN ND 58545-9697

# SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS X258329 9630 525HP TRACTOR 3432 1RW9630PEAP016650 02/26/12 2000 9630 02/25/14 2000 P

CONDITION:

Hard starting. Black smoke.

CAUSE:

Injector unbalanced

**CORRECTION:** 

Removed injectors and cups while head was removed from engine. Installed new cups and injectors. Programed. Test ran engine

ADDITIONAL DESCRIPTION:

+Assist:MGD01 20 minutes

600.00-CRRM100251 Elect Unit Inje 6 -100.00 RM100251 Elect Unit Inje 6 S 948.25 5689.50 Elect Unit Injector Reman CRRM100251 Elect Unit Inje 100.00 600.00 5689.50 PARTS LABOR 870.00

10404099 SEGMENT TOTAL ==> 6559.50

SEGMENT# 5 C MGD01 NA 03/08/21 03/08/21

Replace Batteries

CONDITION:

Batteries failed testing.

**CORRECTION:** 

Replaced batteries. 2 bolts were rusted on battery cable

ends. Cut bolts out and replaced.

3 -27.00 81.00-CRTY25879A Wet Charged Bat RE170543 LAMP 1 47.64 47.64 TY25879A 3 170.51 511.53 Wet Charged Bat

Wet Charged Battery

CRTY25879A Wet Charged Bat 27.00 81.00

CONTINUED ON PAGE 05



WAYNE CLARK

1270 50TH AVE SW

HAZEN ND 58545-9697

Ship to: N/A

Invoice to:

RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718 For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch

HAZEN, ND

Date Time 21:16:21 (B)

invoice No.

**Account No.** 6300068

**Phone No.** 7017486300

W1604759

Page

Ship Via

Purchase Order

**Tax Exemption Number** 

Federal ID Number

Salesperson CF4

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS X258329 9630 525HP TRACTOR 3432 1RW9630PEAP016650 02/26/12 2000 9630 02/25/14 2000 H

02/25/14 2000 P PARTS

LABOR

559.17 145.00

SEGMENT TOTAL==> 704.17

SEGMENT# 6 C MGD01 10-060-011 03/08/21 03/08/21

BUSHINGS AND PINS, STEERING CYLINDER - R&R

**CONDITION:** 

10404099

Foam seals ripped from around pin.

CAUSE:

normal wear

**CORRECTION:** 

Pivoted tractor. Pushed pins out with jack. Replaced foam

seals. Greased. Repeated on other side.

R247735 SEAL

PARTS

13.07

8 N

LABOR
SEGMENT TOTAL==>

104.56 435.00 539.56

104.56

SEGMENT# 7 C MGD01 MISC

03/08/21 03/10/21

Extract/repair broken bolt/stud

CONDITION:

10404099

Turbo stud broke off during removal.

**CORRECTION:** 

Part of stud was left exposed from exhaust manifold. Headed manifold around stud and tried to work our. Was able to rotate stud 1 revolution but then progress stopped. Cut off stud flush with manifold. Drilled out remaining stud in manifold. Did not tap for ne stud. Hole is unable to accept original threads or Heli coil. Will use bolt and nut when turbo is reinstalled.

CONTINUED ON PAGE 06



N/A Ship to:

**RDO Equipment Co.** PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

**Branch** 

HAZEN, ND

Date 03/23/21 21:16:21 (B)

06

Account No. 6300068

Phone No. 7017486300 Invoice No. W1604759

Page

Ship Via

**Purchase Order** 

**Tax Exemption Number** 

**Federal ID Number** 

Salesperson CF4

WAYNE CLARK Invoice to:

1270 50TH AVE SW HAZEN ND 58545-9697

# SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN X258329

WARRANTY DATE 02/26/12

HRS 2000

9630

9630 525HP TRACTOR

3432 1RW9630PEAP016650

02/25/14

2000 P

ADDITIONAL DESCRIPTION:

+Assist:MGD01 105 minutes

LABOR

253.75

10404099

SEGMENT TOTAL ==>

253.75

SEGMENT# 8 C MGD01 10-030-170

03/05/21 03/08/21

COOLING SYSTEM FLUSH

CONDITION:

Parts on on head gasket segment. Flush oil residue out of cooling system.

CORRECTION:

Filled cooling system twice with mix of cleaner and water. ran solution mixes through system with no thermostats. Ran tractor up to operating temp. Left fan off. Ran clean water through system after to rinse out. Drained water. Refilled with coolant. Checked for leaks.

PMCC2610

COOLANT RESTORE

34.51

3

PARTS 103.53

LABOR

522.00 625.53

103.53

10404099 SEGMENT TOTAL ==>

SEGMENT# 9 C MGD01 10-030-010

03/05/21 03/08/21

RADIATOR, R&R

**CONDITION:** 

Punctured radiator due to otter fan sieve hitting it during repairs.

CAUSE:

Impact of object.

**CORRECTION:** 

Removed hood. Removed intercooler. Removed fan shroud.

CONTINUED ON PAGE 07



N/A Ship to:

**RDO Equipment Co.** PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708 Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

**Branch** 

HAZEN, ND

Date Time Page 03/23/21 21:16:21 (B)

Account No. Phone No. Invoice No. 6300068 7017486300 W1604759

Ship Via **Purchase Order** 

**Tax Exemption Number Federal ID Number** 

> Salesperson CF4

WAYNE CLARK Invoice to:

1270 50TH AVE SW HAZEN ND 58545-9697

SERVICE INVOICE

HRS PIN/EIN WARRANTY DATE HRS 9630 525HP TRACTOR 3432 1RW9630PEAP016650 02/26/12 2000

9630 02/25/14 2000 P

Hoisted radiator out of tractor. Installed new radiator.

Reassembled in reverse order. Checked for leaks.

ADDITIONAL DESCRIPTION:

+Assist:MGD01 30 minutes

FRT SHIP/HANDLING Internal Internal RE581666 Radiator 1 N Internal Internal

> PARTS Internal

LABOR Internal 10404099 74302459 SEGMENT TOTAL ==> Internal

SEGMENT#10 C MGD01 RDO-080-403 03/05/21 03/08/21

WASH EQUIPMENT

**CONDITION:** 

STK#/FLEET#

X258329

Wash after repairs.

**CORRECTION:** 

Washed tractor and floor after repairs.

LABOR 170.00 10404099 SEGMENT TOTAL ==> 170.00

WORK ORDER TOTALS \*\*\*\*\*

INTERNAL CUSTOMER Internal 8806.77 PARTS

LABOR Internal 6948.75 47.30 ND STATE TAX

INTERNAL TOTAL Internal

1240538142 15802.82 TOTAL MULTI-USE CHG

023200

This purchase(s) is subject to the terms of the Multi-Use Account, a CONTINUED ON PAGE 08



RDO Equipment Co. PO Box 604 5625 Highway 200W Hazen, ND 58545 701-748-2708

Fax: 701-748-2718

For Billing Inquiries or to receive invoices via E-mail or MyDealer website, please contact RDOAR@rdoequipment.com

Branch HAZEN, ND

 Date
 Time
 Page

 03/23/21
 21:16:21 (B)
 08

 Account No.
 Phone No.
 Invoice No.

 6300068
 7017486300
 W1604759

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson CF4

Invoice to: WAYNE CLARK

1270 50TH AVE SW HAZEN ND 58545-9697

### SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS X258329 9630 525HP TRACTOR 3432 1RW9630PEAP016650 02/26/12 2000 9630 02/25/14 2000 P

service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

\*

PLEASE REMIT TO: JOHN DEERE FINANCIAL

P.O. BOX 4450

CAROL STREAM, IL 60197-4450

\*