



**RDO Equipment Co.**  
PO Box 604  
5625 Highway 200W  
Hazen, ND 58545  
701-748-2708  
Fax: 701-748-2718

For Billing Inquiries or to  
receive invoices via E-mail or  
MyDealer website, please contact  
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK  
1270 50TH AVE SW  
HAZEN ND 58545-9697

Branch  
HAZEN, ND \*REPRINT\*

Date 02/19/21 Time 19:08:39 (B) Page 01

Account No. 6300068 Phone No. 7017486300 Invoice No. W1599859

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson  
CF4

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X746012	COMBINES	3161	1H09770SLB0741978	06/01/12	
	9770 STS	2274	RG6090L101593	07/18/15	1531 P

\* We're offering parts, services & sales during restrictions.  
Learn more at [RDOequipment.com/COVID-19](http://RDOequipment.com/COVID-19)  
\*\* View your invoices and buy parts online at [RDOequipment.com/mydealer](http://RDOequipment.com/mydealer)  
Create your free account today.

SEGMENT# 1 C DGE01 RDO-900-173 02/04/21 02/04/21

STS COMBINE INSPECTION

CONDITION:

-Combine inspection.

CAUSE:

Customer wants his combine inspected.

CORRECTION:

-Inspected combine.

-Made up a quote.

-Went over inspection with Wayne.

PROMOAG	labor discount	1-	561.00	561.00-
			PARTS	561.00-
			LABOR	1160.00
10404099		SEGMENT TOTAL==>		599.00

SEGMENT# 2 C DGE01 RDO-001-032 02/04/21 02/04/21

OIL SAMPLE, EACH WHEN MACHINE IS WARM

CONDITION:

-Fluid sampling.

CAUSE:

-Inspection promotion.

CORRECTION:

-Took fluid samples.

-Filled out paper work.

CONTINUED ON PAGE 02

Thank you for your business



**RDO Equipment Co.**  
 PO Box 604  
 5625 Highway 200W  
 Hazen, ND 58545  
 701-748-2708  
 Fax: 701-748-2718

For Billing Inquiries or to  
 receive invoices via E-mail or  
 MyDealer website, please contact  
 RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK  
 1270 50TH AVE SW  
 HAZEN ND 58545-9697

Branch  
 HAZEN, ND

Date 02/19/21 Time 19:08:39 (B) Page 02

Account No. 6300068 Phone No. 7017486300 Invoice No. W1599859

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson  
 CF4

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X746012	COMBINES	3161	1H09770SLB0741978	06/01/12	
	9770 STS	2274	RG6090L101593	07/18/15	1531 P
TY26859	SCAN TEST KIT			1 Internal	Internal
				PARTS	Internal
				LABOR	Internal
10404099	740T1D59			SEGMENT TOTAL==>	Internal

SEGMENT# 3 C DGE01 STT-15 02/04/21 02/04/21

TRAVEL, ROUND TRIP

CORRECTION:

- Drove to Wayne's to do inspection.
- Drove back to shop.
- Loaded tools and drove to Wayne's shop to do repairs.
- Drove back to shop and unloaded tools.

	LABOR	194.30
10404099	SEGMENT TOTAL==>	194.30

SEGMENT# 4 C DGE01 MISC 02/11/21 02/11/21 02/27/21

REVERSER SHEAVE AND CAM KIT.

CONDITION:

- Cams wore out in sheaves.

CAUSE:

- Natural wear.

CORRECTION:

- Removed feeder house drive belt.
- Removed sheave and cam assembly.
- Installed a new sheave and cam assembly.
- Installed and adjusted feeder house drive belt.

AH219369	PULLEY	1 N 1644.50	1644.50
		PARTS	1644.50
		LABOR	163.85
10404099	SEGMENT TOTAL==>		1808.35

CONTINUED ON PAGE 03

Thank you for your business



**RDO Equipment Co.**  
PO Box 604  
5625 Highway 200W  
Hazen, ND 58545  
701-748-2708  
Fax: 701-748-2718

For Billing Inquiries or to  
receive invoices via E-mail or  
MyDealer website, please contact  
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK  
1270 50TH AVE SW  
HAZEN ND 58545-9697

Branch  
HAZEN, ND

Date 02/19/21 Time 19:08:39 (B) Page 03

Account No. 6300068 Phone No. 7017486300 Invoice No. W1599859

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson  
CF4

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X746012	COMBINES	3161	1H09770SLB0741978	06/01/12	
	9770 STS	2274	RG6090L101593	07/18/15	1531 P

SEGMENT# 5 C DGE01 RDO-040-DIAG 02/11/21 02/11/21 02/27/21

ELECTRICAL DIAGNOSTICS

CONDITION:

-Sieve wont adjust.

CAUSE:

-Sieve actuator was not plugged in.

-Sunflower stalk may have knocked connector off of actuator.

CORRECTION:

-Went through diagnostics.

-Found connector was off of actuator.

-Plugged connector back in.

-Sieve would now adjust.

ADDITIONAL DESCRIPTION:

Sieve will not adjust.

	LABOR	98.60
10404099	SEGMENT TOTAL==>	98.60

SEGMENT# 6 C DGE01 10-171-250 02/11/21 02/27/21

FEEDER HOUSE CHAIN, ADJUST

CORRECTION:

-Customer declined repair.

SEGMENT# 7 C DGE01 MISC 02/11/21 02/11/21 02/27/21

Feeder house pivot locking washer.

CORRECTION:

-Customer declined repair.

-Take parts with.

-He will do repair himself.

ADDITIONAL DESCRIPTION:

CONTINUED ON PAGE 04

Thank you for your business



RDO Equipment Co.  
PO Box 604  
5625 Highway 200W  
Hazen, ND 58545  
701-748-2708  
Fax: 701-748-2718

For Billing Inquiries or to  
receive invoices via E-mail or  
MyDealer website, please contact  
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK  
1270 50TH AVE SW  
HAZEN ND 58545-9697

Branch  
HAZEN, ND

Date 02/19/21 Time 19:08:39 (B) Page 04

Account No. 6300068 Phone No. 7017486300 Invoice No. W1599859

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson  
CF4

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X746012	COMBINES	3161	1H09770SLB0741978	06/01/12	
	9770 STS	2274	RG6090L101593	07/18/15	1531 P
Feeder house pivot locking washer.					
E61191	BUSHING		1 N	4.87	4.87
H235756	WASHER		1 M	22.55	22.55
H237013	PLATE		1 N	14.77	14.77
T146246	WASHER		1 N	3.72	3.72
14M7291	M16 FLANGE NUT		1	3.22	3.22
19M9313	CAP SCREW		1 N	7.98	7.98
				PARTS	57.11
10404099			SEGMENT TOTAL==>		57.11

SEGMENT# 8 C DGE01 MISC 02/11/21 02/11/21 02/27/21

REVERSER BACKSHAFT R&R

CONDITION:

-Reverser oil is low.

CAUSE:

-Seal is leaking on backshaft.

CORRECTION:

-Removed feederhouse drive chain.

-Removed sprocket.

-Removed backshaft.

-Removed o-ring from backshaft.

-Installed a new seal.

-Assembled what was previously removed for repair.

H223849	RING	1	4.46	4.46
TY26408	HD460 QT	5	30.75	153.75

PARTS 158.21

LABOR 72.50

10404099 SEGMENT TOTAL==> 230.71

SEGMENT# 9 C DGE01 RDO-171-090 02/11/21 02/11/21 02/27/21

CONTINUED ON PAGE 05

Thank you for your business



**RDO Equipment Co.**  
PO Box 604  
5625 Highway 200W  
Hazen, ND 58545  
701-748-2708  
Fax: 701-748-2718

For Billing Inquiries or to  
receive invoices via E-mail or  
MyDealer website, please contact  
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK  
1270 50TH AVE SW  
HAZEN ND 58545-9697

Branch  
HAZEN, ND

Date 02/19/21 Time 19:08:39 (B) Page 05

Account No. 6300068 Phone No. 7017486300 Invoice No. W1599859

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson  
CF4

## SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
X746012 COMBINES	3161	1H09770SLB0741978	06/01/12	
9770 STS	2274	RG6090L101593	07/18/15	1531 P
FEEDER HOUSE CHAIN GUIDES, REPLACE				
<u>CORRECTION:</u>				
-Customer declined repair.				
-Take parts with.				
-He will do repair himself.				
H171960	STRIP	3	18.70	56.10
			PARTS	56.10
10404099		SEGMENT TOTAL==>		56.10

SEGMENT#10 C DGE01 MISC 02/11/21 02/11/21 02/27/21

Shoe drive pulleys and idler.

CONDITION:

-Shoe drive pulleys are wore.  
-Idler pulleys are rough when spun.

CAUSE:

-Natural wear.

CORRECTION:

-Removed drive pulleys and idlers.  
-Installed snap rings and new bearings in pulleys.  
-Installed pulleys, idlers, and a new shoe drive belt.

ADDITIONAL DESCRIPTION:

-Shoe drive pulleys and belt replace.

AH150900	IDLER	1	72.05	72.05
AH94450	IDLER	1	58.87	58.87
AH97031	IDLER	1	39.56	39.56
H161051	PULLEY	1	346.87	346.87
H175587	V-BELT	1	185.70	185.70
H211582	PULLEY	1 N	869.49	869.49
JD8576	ECCENTRIC	1	11.16	11.16

Eccentric Locking Collar

CONTINUED ON PAGE 06

Thank you for your business



**RDO Equipment Co.**  
PO Box 604  
5625 Highway 200W  
Hazen, ND 58545  
701-748-2708  
Fax: 701-748-2718

For Billing Inquiries or to  
receive invoices via E-mail or  
MyDealer website, please contact  
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK  
1270 50TH AVE SW  
HAZEN ND 58545-9697

Branch  
HAZEN, ND

Date 02/19/21 Time 19:08:39 (B) Page 06

Account No. 6300068 Phone No. 7017486300 Invoice No. W1599859

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson  
CF4

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
X746012	COMBINES	3161	1H09770SLB0741978	06/01/12		
	9770 STS	2274	RG6090L101593	07/18/15	1531 P	
JD9301		BALL BEARI	1 N	26.18		26.18
JD9356		BALL BEARI	1 O	33.30		33.30
			PARTS			1643.18
			LABOR			453.85
10404099			SEGMENT TOTAL==>			2097.03

SEGMENT#11 C DGE01 MISC 02/11/21 02/27/21  
REMOVE HALF LINK FROM CLEAN GRAIN ELEVATOR CHAIN, AND TAILIN  
CORRECTION:  
-Customer declined repair.  
-Customer will do repair himself.  
ADDITIONAL DESCRIPTION:  
Remove half link from tailings conveyor chain and clean  
grain elevator chain.

SEGMENT#12 C DGE01 10-030-010 02/11/21 02/11/21 02/27/21  
ROTARY SCREEN JACKSHAFT DRIVE BELT, REMOVE AND REPLACE

CONDITION:

-Rotary screen drive belt is cracked.  
-Alternator belt is cracked.

CAUSE:

-Natural wear.

CORRECTION:

-Replaced rotary screen drive belt engine side.  
-Replaced alternator belt.

HXE32806	V-Belt	1	58.15	58.15
H213353	V-BELT	1	29.58	29.58
			PARTS	87.73
			LABOR	348.00
10404099			SEGMENT TOTAL==>	435.73

CONTINUED ON PAGE 07

Thank you for your business



**RDO Equipment Co.**  
PO Box 604  
5625 Highway 200W  
Hazen, ND 58545  
701-748-2708  
Fax: 701-748-2718

For Billing Inquiries or to  
receive invoices via E-mail or  
MyDealer website, please contact  
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK  
1270 50TH AVE SW  
HAZEN ND 58545-9697

Branch  
HAZEN, ND

Date 02/19/21 Time 19:08:39 (B) Page 07

Account No. 6300068 Phone No. 7017486300 Invoice No. W1599859

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson  
CF4

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X746012	COMBINES	3161	1H09770SLB0741978	06/01/12	
	9770 STS	2274	RG6090L101593	07/18/15	1531 P

SEGMENT#13 C DGE01 10-230-020 02/11/21 02/11/21 02/27/21  
LOADING AUGER TUBE, AUGER, END BEARING, REMOVE AND REPLACE

CONDITION:

-Clean grain loading auger and drive lug are wore.

CAUSE:

-Natural wear.

CORRECTION:

-Replaced loading auger and drive lug.

AH230013	AUGER	1	680.25	680.25
H136186	DRIVER	1	59.61	59.61
JD10384	BEARING	1	43.46	43.46
	PARTS			783.32
	LABOR			261.00
10404099	SEGMENT TOTAL==>			1044.32

SEGMENT#14 C DGE01 10-172-010 02/11/21 02/11/21 02/27/21  
HAMMER, STRAW CHOPPER, R&R

CORRECTION:

-Customer declined repair.

-Take parts with.

-He will do repair himself.

AH225937	KIT	6	138.19	829.14
HXE118760	Lock Nut	22	1.08	23.76
	PARTS			852.90
10404099	SEGMENT TOTAL==>			852.90

SEGMENT#15 C DGE01 MISC 02/11/21 02/27/21  
Tail board fins.

CORRECTION:

CONTINUED ON PAGE 08

Thank you for your business



**RDO Equipment Co.**  
PO Box 604  
5625 Highway 200W  
Hazen, ND 58545  
701-748-2708  
Fax: 701-748-2718

For Billing Inquiries or to  
receive invoices via E-mail or  
MyDealer website, please contact  
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK  
1270 50TH AVE SW  
HAZEN ND 58545-9697

Branch  
HAZEN, ND

Date 02/19/21 Time 19:08:39 (B) Page 08

Account No. 6300068 Phone No. 7017486300 Invoice No. W1599859

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson  
CF4

## SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X746012	COMBINES	3161	1H09770SLB0741978	06/01/12	
	9770 STS	2274	RG6090L101593	07/18/15	1531 P

-Customer declined repair.  
-He will do repair himself.

ADDITIONAL DESCRIPTION:

-Tail board fins are in the wrong spots.

SEGMENT#16 C DGE01 MISC 02/11/21 02/11/21 02/27/21

CROSS AUGER DRIVE CHAIN AND SPROCKETS, R&R

CORRECTION:

-Customer declined repair.  
-Take parts with.  
-He will do repair himself.

ADDITIONAL DESCRIPTION:

CROSS AUGER DRIVE CHAIN AND SPROCKETS, R&R

JD39104	BALL BEARI	4	34.30	137.20
			PARTS	137.20
10404099		SEGMENT TOTAL==>		137.20

SEGMENT#17 C DGE01 MISC 02/11/21 02/11/21 02/27/21

Tailings bearing replace. Left side.

CORRECTION:

-Customer declined repair.  
-Take parts with.  
-Customer will do repair himself.

H103264	PRESSED FL	1	2.02	2.02
	Pressed Flanged Housing			
JD39102	BALL BEARI	1	20.48	20.48
			PARTS	22.50
10404099		SEGMENT TOTAL==>		22.50

SEGMENT#18 C DGE01 MISC 02/11/21 02/11/21 02/27/21

CONTINUED ON PAGE 09

Thank you for your business





**RDO Equipment Co.**  
PO Box 604  
5625 Highway 200W  
Hazen, ND 58545  
701-748-2708  
Fax: 701-748-2718

For Billing Inquiries or to  
receive invoices via E-mail or  
MyDealer website, please contact  
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK  
1270 50TH AVE SW  
HAZEN ND 58545-9697

Branch  
HAZEN, ND

Date 02/19/21 Time 19:08:39 (B) Page 09

Account No. 6300068 Phone No. 7017486300 Invoice No. W1599859

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson  
CF4

## SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
X746012 COMBINES	3161	1H09770SLB0741978	06/01/12	
9770 STS	2274	RG6090L101593	07/18/15	1531 P
Straw chopper belt idlers.				
<u>CORRECTION:</u>				
-Customer declined repair.				
-Take parts with.				
-Customer will do repair himself.				
AH210837	IDLER	2 N	158.23	316.46
			PARTS	316.46
10404099		SEGMENT TOTAL==>		316.46
SEGMENT#19 C DGE01 MISC 02/11/21 02/11/21 02/27/21				
Discharge beater pivot bushing.				
<u>CORRECTION:</u>				
-Customer declined repair.				
-Take part with.				
-Customer will do repair himself.				
H170141	PIVOT	1 N	14.74	14.74
			PARTS	14.74
10404099		SEGMENT TOTAL==>		14.74
SEGMENT#20 C DGE01 RDO-001-040 02/11/21 02/17/21 02/27/21				
RDO COMBINE MAINTENANCE PACKAGE, GOLD				
<u>CORRECTION:</u>				
-Customer declined repair.				
-Customer will do his own maintenance package.				

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*  
INTERNAL CUSTOMER  
PARTS Internal 5212.95  
CONTINUED ON PAGE 10

Thank you for your business



**RDO Equipment Co.**  
PO Box 604  
5625 Highway 200W  
Hazen, ND 58545  
701-748-2708  
Fax: 701-748-2718

For Billing Inquiries or to  
receive invoices via E-mail or  
MyDealer website, please contact  
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK  
1270 50TH AVE SW  
HAZEN ND 58545-9697

Branch  
HAZEN, ND

Date 02/19/21 Time 19:08:39 (B) Page 10

Account No. 6300068 Phone No. 7017486300 Invoice No. W1599859

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson  
CF4

### SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
X746012	COMBINES	3161	1H09770SLB0741978	06/01/12		
	9770 STS	2274	RG6090L101593	07/18/15	1531 P	
			LABOR	Internal		2752.10
			SUB TOTAL==>	Internal		7965.05
			ND STATE TAX 5%			7.69
			INTERNAL TOTAL	Internal		
296077	1240538142		TOTAL MULTI-USE CHG			7972.74

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

\*\*\*\*\*  
PLEASE REMIT TO: JOHN DEERE FINANCIAL  
P.O. BOX 4450  
CAROL STREAM, IL 60197-4450  
\*\*\*\*\*

Thank you for your business