



RDO Equipment Co.
PO Box 604
5625 Highway 200W
Hazen, ND 58545
701-748-2708
Fax: 701-748-2718

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK
1270 50TH AVE SW
HAZEN ND 58545-9697

Branch
HAZEN, ND

REPRINT

Date 01/28/21 Time 21:10:32 (B) Page 01

Account No. 6300068 Phone No. 7017486300 Invoice No. W1591959

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson
CF4

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X535215	AIR SEEDERS	13013	1A81895XJDH755154	04/02/15	
	1895				

- * We're offering parts, services & sales during restrictions.
Learn more at RDOequipment.com/COVID-19
- ** View your invoices and buy parts online at RDOequipment.com/mydealer
Create your free account today.

SEGMENT# 1 C MXU01 RDO-900-010 12/29/20 12/29/20

MACHINE INSPECTION - AIR CART AND NO-TILL DRILL

CONDITION:

Inspection.

CAUSE:

Customer request.

CORRECTION:

Inspected machine. Created estimate and discussed with
customer for approval.

PROMOAG	labor discount	1-	571.00	571.00-
			PARTS	571.00-
			LABOR	870.00
10404099			SEGMENT TOTAL==>	299.00

SEGMENT# 2 C MXU01 10-210-030 01/04/21 01/04/21

OPENER DISK, REMOVE AND REPLACE

CONDITION:

Worn disks.

CAUSE:

Normal wear.

CORRECTION:

Removed gauge wheels, removed disk, installed new disk and
reinstalled gauge wheel. Replaced hardware as needed.
Replace worn gauge wheels as needed.

CONTINUED ON PAGE 02

Thank you for your business



RDO Equipment Co.
PO Box 604
5625 Highway 200W
Hazen, ND 58545
701-748-2708
Fax: 701-748-2718

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK
1270 50TH AVE SW
HAZEN ND 58545-9697

Branch
HAZEN, ND

Date 01/28/21 Time 21:10:32 (B) Page 02

Account No. 6300068 Phone No. 7017486300 Invoice No. W1591959

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson
CF4

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
X535215 AIR SEEDERS 1895	13013	1A81895XJDH755154	04/02/15	
Install disks on back row of center frame. (KK)				
<u>ADDITIONAL DESCRIPTION:</u>				
Remove and replace middle and rear gang disks. Remove and replace gauge wheels as needed.				
AA66604	WHEEL	42 O	90.41	3797.22
AA96548	Bearing	2	22.42	44.84
AA98187	Wheel	3	143.99	431.97
A107506	WASHER	1 O	1.18	1.18
A58876	BRUSH	6	14.82	88.92
E55662	FLANGE NUT	11	1.01	11.11
N282625	CAP SCREW	1	2.52	2.52
N283308	SELF-LOCKI	28	1.33	37.24
Self-Locking Screw				
N283804	DISK	52	30.28	1574.56
N283976	NUT	38	1.56	59.28
N284055	LEAF SPRIN	1	4.48	4.48
N284086	SPACER	2	11.42	22.84
TY6341	GREASE	1	4.35	4.35
PARTS				6080.51
LABOR				2714.40
10404099	SEGMENT TOTAL==>			8794.91

SEGMENT# 3 C MXU01 10-210-030 01/04/21 01/04/21

OPENER DISK, REMOVE AND REPLACE

CONDITION:

Worn disks.

CAUSE:

Normal wear.

CORRECTION:

Removed gauge wheel. Removed fertilizer tube. Removed and

CONTINUED ON PAGE 03

Thank you for your business



RDO Equipment Co.
PO Box 604
5625 Highway 200W
Hazen, ND 58545
701-748-2708
Fax: 701-748-2718

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK
1270 50TH AVE SW
HAZEN ND 58545-9697

Branch
HAZEN, ND

Date 01/28/21 Time 21:10:32 (B) Page 03

Account No. 6300068 Phone No. 7017486300 Invoice No. W1591959

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson
CF4

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
X535215 AIR SEEDERS 13013 1A81895XJDH755154 04/02/15
1895

replaced disk. Installed tube and gauge wheel. Replaced
hardware and gauge wheels as needed.

ADDITIONAL DESCRIPTION:

Remove and replace front gang opener disks. Replace gauge
wheels as needed.

+Assist:KK501 91 minutes

AA66604	WHEEL	6 O	90.41	542.46
A107506	WASHER	10 O	1.18	11.80
M86436	TIE BAND	6	.52	3.12
N283804	DISK	26	30.28	787.28
R44302	TIE BAND	6	.15	.90
TY27167	Tube	1	13.39	13.39
03H2070	BOLT	10 O	1.18	11.80
	PARTS			1370.75
	LABOR			1357.20
10404099	SEGMENT TOTAL==>			2727.95

SEGMENT# 4 C MXU01 RDO-200-011 01/04/21 01/04/21
SEED BOOT STRAPS, R&R

CONDITION:

Worn straps. Retainer nuts and bolts rusted.

CAUSE:

Normal wear.

CORRECTION:

Removed and replaced seed boot straps. Replaced most
retainer nuts and bolts.

ADDITIONAL DESCRIPTION:

Remove and reinstall fifty two straps

N219982	STRAP	52	2.69	139.88
N283308	SELF-LOCKI	10	1.33	13.30

CONTINUED ON PAGE 04

Thank you for your business



RDO Equipment Co.
PO Box 604
5625 Highway 200W
Hazen, ND 58545
701-748-2708
Fax: 701-748-2718

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK
1270 50TH AVE SW
HAZEN ND 58545-9697

Branch
HAZEN, ND

Date 01/28/21 Time 21:10:32 (B) Page 04

Account No. 6300068 Phone No. 7017486300 Invoice No. W1591959

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson
CF4

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X535215	AIR SEEDERS	13013	1A81895XJDH755154	04/02/15	
	1895				
	Self-Locking Screw				
N283995	SPRING		1	10.10	10.10
				PARTS	163.28
				LABOR	435.00
10404099			SEGMENT TOTAL==>		598.28

SEGMENT# 5 C MXU01 10-200-010 01/04/21 01/04/21

R&R SEED DEFLECTOR BOOT

CONDITION:

Broken boot.

CAUSE:

Normal wear.

CORRECTION:

Removed seed tube and hose. Removed boot. Replaced with
new boot and reattached seed tube and hose.

ADDITIONAL DESCRIPTION:

Remove seed tube.

Remove seed deflector boot.

Ensure new deflector boot has leaf spring installed.

Install new deflector boot in previously removed position.

Install seed tube.

A99749	Bolt	3	1.22	3.66
N284024	SEED BOOT	1 O	83.84	83.84
N284025	SEED BOOT	2	83.84	167.68
N284055	LEAF SPRIN	1	4.48	4.48
			PARTS	259.66
			LABOR	174.00
10404099			SEGMENT TOTAL==>	433.66

SEGMENT# 6 C MXU01 10-200-020 01/04/21 01/04/21

CONTINUED ON PAGE 05

Thank you for your business



RDO Equipment Co.
PO Box 604
5625 Highway 200W
Hazen, ND 58545
701-748-2708
Fax: 701-748-2718

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK
1270 50TH AVE SW
HAZEN ND 58545-9697

Branch
HAZEN, ND

Date 01/28/21 Time 21:10:32 (B) Page 05

Account No. 6300068 Phone No. 7017486300 Invoice No. W1591959

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson
CF4

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X535215	AIR SEEDERS	13013	1A81895XJDH755154	04/02/15	
	1895				

R&R SFP BOOT

CONDITION:

Worn boots.

CAUSE:

Normal wear.

CORRECTION:

Removed retaining bolt. Removed boot. Removed NH3 tube
from old boot. Reinstalled tube on new boot with new
hardware as needed. Reinstalled boot and retaining bolt.

ADDITIONAL DESCRIPTION:

Loosen spring bolt.

Remove SFP boot.

Install new SFP boot.

Tighten spring bolt to compress spring to a compressed
width of 21mm (1316).

AA54445	1"air seeder	3	2.02	6.06
AA54446	2.5 green	20	6.10	122.00
AA58206	1.25 green	6	4.87	29.22
A87734	SCRAPER	13	90.60	1177.80
A87735	SCRAPER	13	90.55	1177.15
EVA050	HOSE	14	.71	9.94
HARD	BULK HARDWARE	2	5.94	11.88
			PARTS	2534.05
			LABOR	1131.00
10404099			SEGMENT TOTAL==>	3665.05

SEGMENT# 7 C MXU01 10-120-010 01/04/21 01/04/21
CLOSING OR PRESS WHEEL ARM AND SPRING, R&R

CONDITION:

Broken springs.

CONTINUED ON PAGE 06

Thank you for your business



RDO Equipment Co.
PO Box 604
5625 Highway 200W
Hazen, ND 58545
701-748-2708
Fax: 701-748-2718

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK
1270 50TH AVE SW
HAZEN ND 58545-9697

Branch
HAZEN, ND

Date 01/28/21 Time 21:10:32 (B) Page 06

Account No. 6300068 Phone No. 7017486300 Invoice No. W1591959

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson
CF4

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X535215	AIR SEEDERS	13013	1A81895XJDH755154	04/02/15	
	1895				

CAUSE:
Normal wear.

CORRECTION:
Install closing wheel arm springs that were broken, could not reach one opener on lh side. (KK)

ADDITIONAL DESCRIPTION:
Remove and install arm, install new spring, set spring tension.

+Assist:KK501 75 minutes
+Assist:KK501 120 minutes

N283994	SPRING	8	10.10	80.80
N283995	SPRING	7	10.10	70.70
			PARTS	151.50
			LABOR	522.00
10404099			SEGMENT TOTAL==>	673.50

SEGMENT# 8 C MXU01 RDO-080-012 01/04/21 01/04/21
CLOSING WHEEL BEARING R&R

CONDITION:
Frozen closing wheel.

CAUSE:
Normal wear.

CORRECTION:
Removed wheel. Removed and replaced bearing and installed wheel.

K40015	LOCK NUT	2	1.67	3.34
19H3306	CAP SCREW	2	11.32	22.64
			PARTS	25.98
			LABOR	203.00
10404099			SEGMENT TOTAL==>	228.98

CONTINUED ON PAGE 07

Thank you for your business



RDO Equipment Co.
PO Box 604
5625 Highway 200W
Hazen, ND 58545
701-748-2708
Fax: 701-748-2718

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK
1270 50TH AVE SW
HAZEN ND 58545-9697

Branch
HAZEN, ND

Date 01/28/21 Time 21:10:32 (B) Page 07

Account No. 6300068 Phone No. 7017486300 Invoice No. W1591959

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson
CF4

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X535215	AIR SEEDERS	13013	1A81895XJDH755154	04/02/15	
	1895				

SEGMENT# 9 C MXU01 MISC 01/04/21 01/04/21

Replace gauge wheel adjustment shaft.

CONDITION:

Frozen shaft.

CAUSE:

Normal wear.

CORRECTION:

Shaft froze, remove zerk and adjust arm, work shaft to get somewhat loose, use air hammer to get shaft out, clean up spindle, install new shaft and adjust arm, assemble boot.

(KK)

ADDITIONAL DESCRIPTION:

+Assist:KK501 60 minutes

AA92485	Arm	1	68.11	68.11
JD7844	LUBRICATIO	1	1.39	1.39

Lubrication Fitting

PARTS 69.50

LABOR 150.80

10404099 SEGMENT TOTAL==> 220.30

SEGMENT#10 C MXU01 MISC 01/04/21 01/04/21

Misc Repairs

CONDITION:

Replace broken orange lights. - Cart

Replace/repair RH red and orange lights/bulbs. Drill

Replace short 1" hose.

Replace rusted Z tube.

Reconnect two NH3 hoses.

CAUSE:

CONTINUED ON PAGE 08

Thank you for your business



RDO Equipment Co.
PO Box 604
5625 Highway 200W
Hazen, ND 58545
701-748-2708
Fax: 701-748-2718

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK
1270 50TH AVE SW
HAZEN ND 58545-9697

Branch
HAZEN, ND

Date 01/28/21 Time 21:10:32 (B) Page 08

Account No. 6300068 Phone No. 7017486300 Invoice No. W1591959

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson
CF4

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X535215	AIR SEEDERS	13013	1A81895XJDH755154	04/02/15	
	1895				

Normal wear.

CORRECTION:

Install 2 closing wheel bolts that were bent, had to cut one off to get out. Diagnose light on seeder, determined that a good portion of the harness missing, was able to route harness to get hooked up and spliced wires together, install new lamp on cart as well, run and check operations.

(KK)

Removed and replaced damaged hoses.

Replaced frozen up chain on front meter box drive.

ADDITIONAL DESCRIPTION:

Replace broken orange lights. - Cart

Replace/repair RH red and orange lights/bulbs. Drill

Replace short 1" hose.

Replace rusted Z tube.

Reconnect two NH3 hoses.

Tie up electrical harnesses above beams.

+Assist:KK501 142 minutes

AA54445	1"air seeder	10	2.02	20.20
AA56281	LAMP	1	34.93	34.93
A65218	LENS	1 M	9.70	9.70
A65348	TUBE	1 N	239.09	239.09
SW40COUS	CHAIN LINK	1	2.12	2.12
SW40X50US	ROLLER CHAIN	2	6.62	13.24
TY22472	CLAMP SAE44	1	1.50	1.50
	PARTS			320.78
	LABOR			350.90
10404099	SEGMENT TOTAL==>			671.68

SEGMENT#11 C MXU01 RDO-171-068 01/04/21 01/04/21

CONTINUED ON PAGE 09

Thank you for your business



RDO Equipment Co.
PO Box 604
5625 Highway 200W
Hazen, ND 58545
701-748-2708
Fax: 701-748-2718

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK
1270 50TH AVE SW
HAZEN ND 58545-9697

Branch
HAZEN, ND

Date 01/28/21 Time 21:10:32 (B) Page 09

Account No. 6300068 Phone No. 7017486300 Invoice No. W1591959

Ship Via Purchase Order

Tax Exemption Number Federal ID Number

Salesperson
CF4

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
X535215 AIR SEEDERS 13013 1A81895XJDH755154 04/02/15

1895

FRONT METER ROLL ASSEMBLY, R&R

CORRECTION:

Assemble green meter roller, install new end caps on meters
and install new brushes. (KK)

ADDITIONAL DESCRIPTION:

Replace worn bearing and other parts as needed.

+Assist:KK501 120 minutes

AA96548	Bearing	4	22.42	89.68
A59755	INSERT	2	8.42	16.84
BA29095	METER ROLL	1 M	1571.90	1571.90
	PARTS			1678.42
	LABOR			725.00
10404099	SEGMENT TOTAL==>			2403.42

***** WORK ORDER TOTALS *****

PARTS 12083.43

LABOR 8633.30

SUB TOTAL==> 20716.73

ND STATE TAX 5% .87

866000 1240538142 TOTAL MULTI-USE CHG 20717.60

This purchase(s) is subject to the terms of the Multi-Use Account, a
service of John Deere Financial, f.s.b. I grant the issuer a purchase
money security interest, except as limited in that agreement, in the goods
described.

PLEASE REMIT TO: JOHN DEERE FINANCIAL

CONTINUED ON PAGE 10

Thank you for your business



RDO Equipment Co.
PO Box 604
5625 Highway 200W
Hazen, ND 58545
701-748-2708
Fax: 701-748-2718

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: WAYNE CLARK
1270 50TH AVE SW
HAZEN ND 58545-9697

Branch
HAZEN, ND

Date	Time	Page
01/28/21	21:10:32 (B)	10

Account No.	Phone No.	Invoice No.
6300068	7017486300	W1591959

Ship Via	Purchase Order
----------	----------------

Tax Exemption Number	Federal ID Number
----------------------	-------------------

Salesperson
CF4

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
X535215	AIR SEEDERS	13013	1A81895XJDH755154	04/02/15	
	1895				

P.O. BOX 4450
CAROL STREAM, IL 60197-4450

Thank you for your business