

2005 Chev pickup



CUSTOMER #: 301850

41193

\*INVOICE\*

2527 Bridge Ave.  
 Albert Lea, MN 56007  
 Phone: (507) 373-5275  
 Fax: (507) 373-1273  
 www.wuerfleinchevybuickgmc.com

LARRY DEAN EDEN  
 1005 N 3RD AVE E  
 LAKE MILLS, IA 50450  
 HOME: 515-592-3456 CONT: 515-592-3456  
 BUS: 515-592-3456 CELL:

PAGE 1

SERVICE ADVISOR: 6140 SEAN CHAPEK

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
DRW-WRK-TR	05	CHEVROLET SILVERADO	1GCJK33275F970350		127708/127708	T2128	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN05 DD			17:00 15NOV21		0.00	CASH	18NOV21
R.O. OPENED	READY	OPTIONS: ENG:6.6_LITER_FI_DSL					
10:14 15NOV21	17:10 18NOV21						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CUSTOMER STATES THE VEHICLE IS LOSING COOLANT. CHECK AND ADVISE  
 DIAG GENERAL DIAGNOSIS FEE

6079	C					89.95	89.95
PARTS:	0.00	LABOR:	89.95	OTHER:	0.00	TOTAL LINE A:	89.95

TOOK VEHICLE FOR TEST DRIVE. AFTER TEST DRIVE CAME BACK TO SHOP TO INSPECT VEHICLE. FELT UPPER RADIATOR HOSE AND IT WAS AS HARD AS CAN BE. WENT TO TAKE CAP OFF OF THE COOLANT RESERVOIR, AND IT WAS UNDER EXTREME PRESSURE. LIFTED VEHICLE TO INSPECT IT AND FOUND THE WATER PUMP TO BE LEAKING. CAUSE OF WATER LEAK COULD BE DUE TO LARGE AMOUNT OF PRESSURE IN COOLING SYSTEM. RECOMMEND REMOVING AND REPLACING THE HEAD GASKETS AND WATER PUMP ASSEMBLY.

\*\*\*\*\*

B PERFORM MULTI-POINT INSPECTION  
 CAUSE: PERFORM MULTI-POINT INSPECTION  
 MPVI PERFORM MULTI-POINT INSPECTION

6079	C					0.00	0.00
PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE B:	0.00

\*\*\*\*\*

C\*\* CUSTOMER STATES REMOVE AND REPLACE BOTH CYLINDER HEAD GASKETS  
 MISC CUSTOMER STATES

6079	C					4320.00	4320.00
5	94013304	1079CT (S)	GASKET		20.74	20.74	103.70
1	97188663	1079 (S)	GASKET		5.78	5.78	5.78
1	94011702	1079CT (S)	GASKET		34.02	34.02	34.02
36	11610681	0293CT (S)	BOLT		6.47	6.47	232.92
16	97212994	0308CT (S)	SEAL		6.21	6.21	99.36
2	98002804	3270CT (S)	GASKET		44.09	44.09	88.18
8	94013303	3304CT (S)	SEAL		12.93	12.93	103.44
1	97327722	3304CT (S)	SEAL		21.93	21.93	21.93
2	97378825	3163 (S)	PIPE		109.66	109.66	219.32
2	97378826	3163 (S)	PIPE		115.19	115.19	230.38
2	97378827	3163 (S)	PIPE		111.10	111.10	222.20
1	97227012	3358CT	GASKET		2.63	2.63	2.63
2	97331137	3358CT	GASKET		4.44	4.44	8.88

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE VEHICLE MANUFACTURER OR THE PARTS MANUFACTURER OR DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.		* SHOP SUPPLY COSTS:	DESCRIPTION	TOTALS
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.		We have added a charge equal to 5% of the total cost of labor and parts, not to exceed \$29.00, to the Repair Order for shop supplies used in connection with this repair.	LABOR AMOUNT	
			PARTS AMOUNT	
			GAS, OIL, LUBE	
			SUBLET AMOUNT	
			MISC. CHARGES *	
			TOTAL CHARGES	
			LESS INSURANCE	
			SALES TAX	
			PLEASE PAY THIS AMOUNT	
			DATE	CUSTOMER SIGNATURE



CUSTOMER #: 301850

41193

2527 Bridge Ave.
Albert Lea, MN 56007
Phone: (507) 373-5275
Fax: (507) 373-1273

www.wuerfleinchevybuickgmc.com

\*INVOICE\*

LARRY DEAN EDEN
1005 N 3RD AVE E
LAKE MILLS, IA 50450

PAGE 2

HOME: 515-592-3456 CONT: 515-592-3456
BUS: 515-592-3456 CELL:

SERVICE ADVISOR: 6140 SEAN CHAPEK

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG. Row 1: DRW-WRK-TR 05 CHEVROLET SILVERADO 1GCJK33275F970350 127708/127708 T2128

Table with columns: DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Row 1: 01JAN05 DD 17:00 15NOV21 0.00 CASH 18NOV21

Table with columns: R.O. OPENED, READY, OPTIONS. Row 1: 10:14 15NOV21 17:10 18NOV21 ENG:6.6\_LITER\_FI\_DSL

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Lists various parts like GASKET, SEAL, PIPE, BOLT, PIN, CLAMP with their respective costs.

PARTS: 2603.08 LABOR: 4320.00 OTHER: 0.00 TOTAL LINE C: 6923.08

REMOVE AND REPLACE HEAD GASKETS AND ALL NECESSARY COMPONENTS. LET THE VEHICLE RUN IN THE FOR A WHILE AFTER REPAIRS. TOOK VEHICLE FOR TEST DRIVE, VEHICLE RUNS AND DRIVES AS IT SHOULD.

D\*\* CUSTOMER STATES REMOVE AND REPLACE WATER PUMP ASSEMBLY MISC CUSTOMER STATES

Table with columns: OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Row 1: 1 19168888 1069OPCKT (S) PUMP 359.35 359.35 359.35

PARTS: 359.35 LABOR: 360.00 OTHER: 0.00 TOTAL LINE D: 719.35

REMOVE AND REPLACE WATER PUMP ASSEMBLY. VERIFIED REPAIRS AFTER REPAIRS OF HEAD GASKETS.

ENVIRONMENTAL COMPLIANCE

Table with columns: WARRANTY DISCLAIMER, SHOP SUPPLY COSTS, DESCRIPTION, TOTALS. Includes environmental compliance text and a cost breakdown table.