



3150 5th Avenue East Moline, IL 61244-9526

Prione: 309-755-7203 Fax: 309-755-7355

www.rmsequipment.com

Seno payment to: SDS 12-0749 P.O. Box 86

Minneapolis MN 55486-0749

For billing inquiries call: 952-895-7040 Sales, Rental and Service of Construction, Forestry, and Mining Equipment Since 1926

 BLOUNT TREE SERVICE

 1214 49th Ave

 Camanche, IA 52730-9674

 +41.793895, -90.31582

 BLOUNT TREE SERVICE

 1214 49TH AVE

 CAMANCHE IA 52730

Branch					
EAST MOLINE					
Date	Time	1			Page
11/09/21	10:0	09:17	(0)		01
Account No.	Phone No			Invoi	ce No.
BLOUN006	5632129022		W2140514		
Ship Via		Custome N	er Purcha	se Ord	er
PSSR#		Tax Exen	npt#		
HOU					
			1	persor DW3	1

SERVICE PRELIMINARY

STK#/FLEET#

058460

EXCAVATOR

HRS PIN/EIN 6308 K30369

WARRANTY DATE

HRS

PC150-6

SEGMENT# 1 5 10851 N/A

09/20/21 09/22/21

THROTTLE ISSUES

COMPLAINT:

CUSTOMER CALLED SAID HE IS HAVING ISSUES WITH THE THROTTLE. MOVES THE DIAL AND NOTHING WORKS.

CORRECTION:

Arrived on site and spoke to customer. Unit had four codes. Two were for

LS and pump solenoid opened. Customer not concerned at this time

about that, wanted

throttle to work. Had two codes E316 and E317.

Troubleshot electrical. Checked resistance and continuity on connecter 2 at controller to connector 5 at governor step motor. Machine harness tested fine. Checked resistance at motor and it was low compared to table in service book. Ordered new motor.

Returned and plugged in governor motor and it still did not work.

Unplugged and put back away. Rechecked wires, fuel control dial and all was checking out. Came up with a bad pump controller, will get one listed for price and availability. Listed controller and ordered.

Returned and checked fuse and holder, it was good. Checked voltage was .03 to 4.9 volts as I moved the dial. Checked voltage at actuator there was no voltage. Found 2 wires rubbed

through and shorting out. Repaired wires and checked voltage at actuator again. Voltage from 0.1 to 4.8 at

CONTINUED ON PAGE 02

SIGNATURE

⁻ Past due accounts are subject to a service charge of 1.5% per month (18% per annum), or highest legal rate whichever is greater

⁻ A handling and restocking charge may be applied to all returned merchandise

All sales are final on special order and non-returnable parts RM145PRE





3150 5th Avenue East Moline, IL 61244-9526

Pnone: 309-755-7203 Fax: 309-755-7355 www.rmsequipment.com seno payment to: SDS 12-0749 P.O. Box 86 Minneapolis MN 55486-0749

For billing inquiries call: 952-895-7040 Sales, Rental and Service of Construction, Forestry, and Mining Equipment Since 1926

Ship to:	BLOUNT TREE SERVICE 1214 49th Ave Camanche, IA 52730-9674
	+41.793895, -90.31582
Invoice to:	BLOUNT TREE SERVICE 1214 49TH AVE CAMANCHE IA 52730

Branch				
EAST MOLINE				
Date	Time			Page
11/09/21	10:0	09:17 (0)	02
Account No.	Phone No. In		Invoice No.	
BLOUN006	5632129022		W2140514	
Ship Via		Customer Purchase Order		
		N		
PSSR#		Tax Exemp	t #	
HOU				
	······································		Sales	person
			Ι	DW3

SERVICE PRELIMINARY

STK#/FLEET#

PIN/EIN HRS

WARRANTY DATE

HRS

058460

EXCAVATOR

6308 K30369

PC150-6

actuator now. Actuator was still not working. I will pick up new one at the shop.

Arrived back and OHM'ed out wires from governor to controller. All checked out

good, found 2 more bare wires and repaired. Did continuity checks on back of controller between CO2 and CO3 plugs, all checked out. Checked voltage at throttle switch and voltage went from 0.1 to 4.9 volts. Checked voltage input at controller from throttle switch and voltage was the same. Did not have any signal voltage out of controller to governor. Had 5 volt supply and ground but no signal. Ordered controller.

Returned and removed old throttle controller. Replaced with new controller. Checked voltages and all are good. Plugged in old

governor for throttle, works as it should. Put cab back together. Ran machine and tested throttle functions, all working as they should.

Thank you for choosing Road Machinery & Supplies Co. ADDITIONAL DESCRIPTION:

CHARLIE 563-212-9022

CR7834-24-2005	CORE	1- 500.00	500.00-
FRTI	FREIGHT IN	1 48.37	48.37
R7834-24-2005	CONTROLLER	1 N 1163.76	1163.76
CR7834-24-2005	CORE	500.00	500.00
		PARTS	1212.13
		LABOR	2110.55
11280014		SEGMENT TOTAL ==>	3322.68

***** WORK ORDER TOTALS ***** CONTINUED ON PAGE 03

SIGNATURE _

RECEIVED THE ABOVE ITEMS IN GOOD CONDITION

⁻ Past due accounts are subject to a service charge of 1.5% per month (18% per annum), or highest legal rate whichever is greater

⁻ A handling and restocking charge may be applied to all returned merchandise

⁻ All sales are final on special order and non-returnable parts



Ship to:



3150 5th Avenue East Moline, IL 61244-9526

Pnone: 309-755-7203 Fax: 309-755-7355

www.rmsequipment.com

WARRANTY DATE

Seno payment to: SDS 12-0749 P.O. Box 86

Minneapolis MN 55486-0749

For billing inquiries call: 952-895-7040

Sales, Rental and Service of Construction, Forestry, and Mining Equipment Since 1926

BLOUNT TREE SERVICE
1214 49th Ave
Camanche, IA 52730-9674
+41.793895, -90.31582

BLOUNT TREE SERVICE
1214 49TH AVE
CAMANCHE IA 52730

Branch				
EAST MOLINE				
Date	Time			Page
11/09/21	10:0	09:17 (0)	03
Account No.	Phone No.		Invoice No.	
BLOUN006	5632129022		W2140514	
Ship Via		Customer Purchase Order		
	N			
PSSR#		Tax Exempt #		
HOU				
			Sales	person
			Ι	DW3

SERVICE PRELIMINARY

STK#/FLEET#

058460

EXCAVATOR PC150-6

HRS

PIN/EIN

K30369

6308

Ty Cel 563-529 3739

1,663.76 PARTS 1212.13 LABOR 2110.55 FIELD SUPPLIES 221.43 HAZMAT 80.52 **MILEAGE** 420.75 4045.38 SUB TOTAL ==> IA STATE TAX 242.73 TOTAL INVOICE 4288.11

HRS

- All sales are final on special order and non-returnable parts RM14SPRE

SIGNATURE _

⁻ Past due accounts are subject to a service charge of 1.5% per month (18% per annum), or highest legal rate whichever is greater

⁻ A handling and restocking charge may be applied to all returned merchandise



Road Machinery & Supplies Co. 606 W. 10th Avenue Milan, IL 61264

Phone: 309-787-1742 Fax: 309-787-2497 www.rmsequipment.com Send payment to: SDS 12-0749 P.O. Box 86

Minneapolis MN 55486-0749

For billing inquiries call: 515-471-3261

Sales.	Rental and Service of	Construction Fore	estry and Mining Equ	tinment Since 1926
Caics,	Trental and Delvice Of	CONSTRUCTION, FOR	souv. and willing Eul	JIDHIEHL SHILE 1920

·			· · · · · · · · · · · · · · · · · · ·	Salesperso	าท
1214 49TH AVE CAMANCHE, IA 52730	PSSR#		Tax Exemp	t#	
BLOUNT TREE SERVICE	Inbound By / Delivery	Ву			rder
	Account No. BLOUN006	Phone N 563	0.	Invoi	ce No.
	Date	Time 0.8	:43:25		Page 01
SAME AS BELOW				CNN	IYYY
	BLOUNT TREE SERVICE 1214 49TH AVE	SAME AS BELOW MILAN Date 04/24/09 Account No. BLOUN006 Inbound By / Delivery 1214 49TH AVE MILAN Date 04/24/09 Account No. BLOUN006 Inpound By / Delivery	MILAN Date Time O4/24/09 08 Account No. Phone N BLOUN006 563 Inbound By / Delivery By Delivery By 1214 49TH AVE PSSR #	MILAN Date Time 04/24/09 08:43:25 Account No. Phone No. BLOUN006 563 212902 Inbound By / Delivery By Customer F D/u CHARLI 1214 49TH AVE PSSR # Tax Exemption Tax Exemption	Date Time 04/24/09 08:43:25 (O) Account No. Phone No. Invoided BLOUN 006 563 2129022 S11 Inbound By / Delivery By Customer Purchase Company CHARLIE 1214 49TH AVE PSSR # Tax Exempt #

Part# DESCRIPTION Bin ORD ISS SHP B/O UTT Price Amount 6733-11-3100 XINJECTOR NOBIN 143.30 573.20CR 6731-11-3110 NOZZLE HOLDE T10183 4 4 4 143.30 573.20

TOTAL .00

- F.O.B. - Destination Freight Collect

- A handling and restocking charge may be applied to all returned merchandise

- All sales are final on special order and non-returnable parts

RECEIVED THE ABOVE ITEMS IN GOOD CONDITION

SIGNATURE

Filled By:

Pieces:

Date:

⁻ Past due accounts are subject to a service charge of 1.5% per month (18% per annum), or highest legal rate whichever is less